

Cecilia



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68652623
Accident Reporting Number : 68652672


Date Generated : 24/09/2019

User ID : GohKK2

Section A - Accident Details	
Registration Number	SMB3529H
Case Reference Number	BUS/09/19/1068
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Ng Yoow Chin
Type of Accident	Side Swipe
Accident Date and Time	19/9/2019 6:20 PM
Accident Reported Date and Time	20/9/2019 10:11 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB3529H-RIGHT REAR PORTION PC5942T (TP) INSURED WITH III
Prepared Date and Time	24/9/2019 3:49 PM
Chassis Number	SFD76CLR5EMTL3458
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$538.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,333.00	\$0.00
Lump Sum Total	\$1,350.00	\$0.00
Number of Repair Days	3.0	2
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	24/09/2019 3:56 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Repair Pay - 2 days
Steve @ 25/09/2019 @ 2.15pm
Lump Sum Repair, after spray
TP without Prejudice.

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 6662623
Accident Reporting Number : 6862672

Date Generated : 24/09/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR			Adjusted by Surveyor, if applicable				
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$795.00			530				
Total Labour		\$795.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$538.00			446				
Total Spray Painting & Panel Beating		\$538.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC			Adjusted by Surveyor, if applicable				
Total Other Costs					X				
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011069	VE	31155514	POD, TAIL LIGHT, RH, FOR ADL E500 DO BUS	1.00	\$1,703.25	100.00	\$0.00	Repair	R.
Total					\$1,703.25		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

530

446

976



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 27/09/2019

User ID : CatherineLee

Section A - Accident Details


Registration Number	SMB3529H
Case Reference Number	BUS/09/19/1068
Registration Date	1/9/2014
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	Ng Yeow Chin
Type of Accident	Side Swipe
Accident Date and Time	19/9/2019 6:20 PM
Accident Reported Date and Time	20/9/2019 10:11 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103527
Special Instruction to ARC, if any	SMB3529H-RIGHT REAR PORTION PC5942T (TP) INSURED WITH III
Prepared Date and Time	24/9/2019 3:49 PM
Chassis Number	SFD76CLR5EMTL3458
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$538.00	\$446.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,333.00	\$976.00
Lump Sum Total	\$1,350.00	\$0.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN
ARC / Surveyor Sign Off Date	24/09/2019 3:56 PM	25/09/2019 2:24 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/09/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$538.00	\$446.00
Total Spray Painting & Panel Beating	\$538.00	\$446.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011069	VE	31155514	POD, TAIL LIGHT, R/H, FOR ADL E500 DD BUS	1.00	\$1,703.25	100.00	\$0.00	Repair	Repair
Total					\$1,703.25		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									