

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-Sep-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6889 C

1 pc	Front bumper	← 50% @ 1028.00	\$ 531.00
1 pc	Front bumper emblem	X	\$ 44.00
1 pc	Front bumper tow hook cap	X	\$ 14.00
1 pc	Front bumper lip	X	\$ 52.00
2 pcs	Front n/s & o/s head lamp	@ \$1028.00 o/s 1 n/s X	\$ 2,056.00
1 pc	Front bumper n/s & o/s side retainer	@ \$16.00 X	\$ 32.00
1 pc	Front bumper n/s & o/s protector	@ \$51.00 X	\$ 102.00
1 pc	Front bumper o/s fog lamp cover	X	\$ 66.00
1 pc	Front bumper centre grille	X	\$ 174.00
1 pc	Bonnet grille	X repair	\$ 385.00
			\$ 3,456.00
Less 10%			\$ 345.60
			\$ 3,110.40

S/NETT

1 pc	Front bumper clips	1 Kahif 1100	\$ 48.00
	Sundry	24/9/19 1705 L	\$ 50.00 X
	To adjust/focus front n/s & o/s head lamps	2 Lys	\$ 30.00 X
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	415	\$ 180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.	At the Repair shop	\$ 550.00
	To putty and spray painting on front bumper	200	\$ 200.00 180
	To apply rustproofing on the repaired and replaced panels.		\$ 120.00 X

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Service notify
Painting
During resurvey
Information
Prejudice* basis
must be resurveyed and
approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: