PREMIER AUTOMOTIVE SERV

23 CHANGI SOUTH AVENU SINGAPORE 486443

the Repairer of the following:

I Coresumer before/after spray pain E 2 Parts prices are subject to confirmation

LKK Auto Consultants hence notify

TEL: 65446676 / 65446689 FAX: 62 141 No illegal modification(s) is allowed

CO. REG:200707743D GST REG:20 070 Supplementary item(s) must be resurveyed and is subject to finel approval from Insurance Company

Acknowledged by Repairer

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6839 Signature;

24-Sep-19

	^	-	THE RESERVE OF THE PARTY OF THE	
1 pc	Front bumper / deform 50 % Wot. 5	\$	531.00	
1 pc	Front bumper emblem × nn	\$	44.00	
1 pc	Front bumper tow hook cap $$ nn	\$	14.00	
1 pc	Front bumper lip × nn	\$	52.00	
2 pcs	Front n/s & o/s head lamp @ \$1028.00	\$	2,056.00	
1 pc	Front bumper n/s & o/s side retainer @ \$16.00 × nn	\$	32.00	
1 pc	Front bumper n/s & o/s protector @ \$51.00	\$	102.00	
1 pc	Front bumper o/s fog lamp cover	\$	66.00	
1 pc	Front bumper centre grille Xnn	\$	174.00	
1 pc	Bonnet grille x mpn	\$	385.00	
		\$	3,456.00	
	Less 10%	\$	345.60	
		\$	3,110.40	

S/NETT	- Kahaf Clay
1 pc	Front bumper clips nec \$ 48.00
	Sundry 24/9/19 1708 \$ 50.00 ×
	To adjust/focus front n/s & o/s head lamps \$ 30.00 ×
	To dismantle / refit the inner garnishes, inner linings, inner All April 180.00 \$
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc. \$ 550.00
	To putty and spray painting on front bumper \$ 200.00
	To apply rustproofing on the repaired and replaced panels. 120.00
	2 4,288.40
	(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

bewollt el must be resurveyed and is a production of approval from Insurance Company

Acknowledged by Repairer Signature:

Date: