



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To: Ng Huan Chieh Kevin
C/o: Blk 8 Sin Ming Ind Est #01-60/62
Singapore 575643

Date of report: 05.09.2018
Date of request: 16.08.2018
Date of inspection: 16.08.2018
Date of accident: 07.08.2018
Claim type: Third Party Claim

Report No: AAS/2018/349

Particulars of affected vehicle:

Registration no: SFY3172P
Make/Model: Volvo S40 2.0 (A)
Year of registration: 2009/10
Colour: Metallic Grey

Odometer: 164275 km
Engine Capacity: 1999 cc
Engine no: B4204S3182518
Chassis no: YV1MS434BA2502471

Condition of tires:

Front Left: 7mm
Make: Continental
Rear Left: 7mm
Make: Continental

Front Right: 7mm
Make: Continental
Rear Right: 7mm
Make: Continental

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork	: Good
Paintwork	: Good
Handbrake	: In order
Footbrake	: In order
Steering	: In order
Apparent engine modification	: Nil

The Assignment

The inspection was conducted at M/s. City Auto Pte Ltd
Blk 8 Sin Ming Ind Est #01-60/62
Singapore 575643

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:	\$ 16,498.05
Revised estimate:	\$ 12,460.91
Recommended reserve:	\$ 9,950.00 (Lump sum)

Estimated normal duration of repairs : 6 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SFY3172P

Report No: AAS/2018/349

W/O PREJUDICE

Point of impact

At the LHR portion.

General description of damages

The boot lid, LH tail lamp, rear bumper, rear bumper lower, rear end panel, LHR fender, exhaust silencer, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s City Auto Pte Ltd as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$12,460.91

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$9,950.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 6 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 70 photographs.

Your Faithfully
Absolute Appraisal Services Pte Ltd



Nicky Seah
Automobile Appraiser
MSAAA / MSMCTA



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
 160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
 Mobile: 9688-0413 Fax: 6266-7396
 Email: absolute.app.svcs@gmail.com

Vehicle No: SFY3172P

Report No: AAS/2018/349

Appraisement Schedule

S/N	Parts Description	Qty	Condition	Repairer's Est	Revised Est
1	Boot lid	1	Dented/Distorted	\$ 2,671.97	\$ 2,671.97
2	Boot lid nameplate 'Volvo'	1	Necessary	\$ 92.90	\$ 92.90
3	Boot lid nameplate 'S40'	1	Necessary	\$ 82.00	\$ 82.00
4	Boot lid nameplate '2.0'	1	Necessary	\$ 80.80	\$ 80.80
5	Boot lid lock	1	Serviceable	\$ 530.70	-
6	Boot lid weather-strip	1	Serviceable	\$ 166.90	-
7	Tail lamp LH	1	Cracked	\$ 820.30	\$ 820.30
8	Rear bumper	1	Dented/Torn	\$ 1,827.33	\$ 1,827.33
9	Rear bumper lower	1	Grazed/Cut	\$ 693.00	\$ 693.00
10	Rear bumper reflector LH	1	Broken	\$ 115.43	\$ 115.43
11	Rear bumper centre bracket	1	Dented	\$ 422.30	\$ 422.30
12	Rear bumper retainer LH	1	Cracked	\$ 97.57	\$ 97.57
13	Rear bumper support LH	1	Cracked	\$ 74.58	\$ 74.58
14	Rear bumper reinforcement	1	Dented	\$ 1,222.50	\$ 1,222.50
15	LHR fender inner shield	1	Broken	\$ 261.90	\$ 261.90
16	Rear end panel	1	Dented/Repair	\$ 1,127.18	-
17	Rear end panel trim	1	Serviceable	\$ 552.36	-
18	Exhaust silencer	1	Dented	\$ 968.33	\$ 968.33
List total:				\$ 11,808.05	\$ 9,430.91
1	Boot lid inner trim clips	1set	Necessary	\$ 50.00	\$ 50.00
2	Reverse sensor	1set	Malfunctioned	\$ 300.00	\$ 250.00
3	Joint sealant	1	Not Necessary	\$ 60.00	-
Special nett total:				\$ 410.00	\$ 300.00
Parts Total:				\$ 12,218.05	\$ 9,730.91



ABSOLUTE APPRAISAL SERVICES PTE LTD
LOSS ADJUSTERS & MOTOR APPRAISERS
160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722
Mobile: 9688-0413 Fax: 6266-7396
Email: absolute.app.svcs@gmail.com

Vehicle No: SFY3172P

Report No: AAS/2018/349

S/N Labour Description

Repairer's Est

Revised Est

1 Check rear lightings & wirings.

\$ 80.00

\$ 50.00

2 Remove & transfer boot lid fittings.

\$ 150.00

\$ 100.00

3 Renew reverse sensor.

\$ 50.00

\$ 50.00

4 Remove & refit rear upholsteries to enable replacement.

\$ 120.00

\$ 100.00

5 Renew exhaust silencer.

\$ 180.00

\$ 150.00

6 Anti rust treatment on rear affected panels.

\$ 100.00

\$ 80.00

7 To renew rear damaged parts, Panel beat, reform & realign affected area.

\$ 2,000.00

\$ 1,200.00

8 To respray rear affected panels.

\$ 1,600.00

\$ 1,000.00

Labour Total:

\$ 4,280.00

\$ 2,730.00

Grand Total:

\$ 16,498.05

\$ 12,460.91

The final adjusted lump sum amount is \$9,950.00

Under normal circumstances, the repair should be completed within a reasonable period of 6 working days.

70 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.