Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19016934/GGA3Q2

Date: 30/06/2020

REFERENCE

India International Insurance Pte Handling Insurer:

D18MPC0001208

Claimant Vehicle No:

SMG7062J

Insured Vehicle No:

SGV3862K

Date of Loss: 19/09/2019 Nature of Claim: TP Claim MPC2019D0001108 No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMG7062J Reg No:

Ltd

Make & Model: NISSAN NOTE, 1.2 CVT (A) Engine No: HR12262264J

Reg. Date: 28/12/2018 (Man. Year: 2018) Chassis No: JN1TAAE12Z0982648

Colour: Odometer: 27325 km Red

Engine Capacity: 1198 cc Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: No

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15 Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %	
0.00	0.00	0.00		
0.00	0.00	0.00		
1,085.00	765.00	320.00	29.49	
0.00	0.00	0.00		
0.00 0.00 0.0	0.00			
1,085.00	765.00	320.00	29.49	
75.95	53.55	22.40	29.49	
1,160.95	818.55	342.40	29.49	
\$50.00/day) (S\$)	150.00			
+ Doc/Search Fee (S\$)				
	0.00 0.00 1,085.00 0.00 0.00 1,085.00 75.95 1,160.95 \$50.00/day) (\$\$)	0.00 0.00 0.00 0.00 1,085.00 765.00 0.00 0.00 1,085.00 765.00 75.95 53.55 1,160.95 818.55 \$50.00/day) (\$\$) 150.00	0.00 0.00 0.00 0.00 0.00 0.00 1,085.00 765.00 320.00 0.00 0.00 0.00 0.00 0.00 0.00 1,085.00 765.00 320.00 75.95 53.55 22.40 1,160.95 818.55 342.40 \$50.00/day) (\$\$) 150.00	

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 27/09/2019 Inspected At: Autolution Industrial Pte Ltd (Ubi)

Nett Liability (S\$)

19 Ubi Road 4 Singapore 408623

970.55

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: XING GUO QIANG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Mar 2020)

Parts: 144 NISSAN NOTE 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG7062J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES TO REPAIR RR BUMPER & RH RR FENDER	New	585.00	390.00
2	CHARGES TO SPRAY PAINTING SAME	New	500.00	375.00
	Gross Labour Cost (S\$)		1,085.00	765.00
	Report was unsubmitted duri	ng this print-out		

< END OF ESTIMATES >