

ASS. REC. BY:

REF: CS/MSG 19016949/Kv3dz Special Instruction:

Surveior: Kenneth

ASSIGNMENT (Office)From (Person): Zung Han yang of MSLG Date/Time: 26.9.19 9549.7

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: SLE 2848P Insured: SLM 3083Eat Workshop m/s Chung Hoe Tel: 6481221of 10 AMK Ind Bmc 2A #01-04Policy No: 29114752MKF Claim No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 24.9.19  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 22.9.19 10.019.m Person Contacted: Dorlyn Vehicle IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	<u>SLE 2848P-X</u>
	<u>SLM 3083E - CC4/TP 19011691/Kvb3</u> <u>D.O.A - 30/06/2019</u>
<u>27/9/19</u>	<u>Send preli revised via merimen</u>
<u>15/11</u>	<u>814, 800 Confirm by email (Ref 7358.24, 33/9)</u>

ASS. REC. BY:

REF: MSG/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

B 63k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

21

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLE 2848P

Yr Regn:

07/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1498

Colour:

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading:

66810

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Rui

111 0193

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F: Dun

215/60R16

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

24/9/19

D.O.I.

26/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

8m

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

RECEIVED 19 NOV 2019

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

18/11 typst

Report Format:

merimen

Lump Sum / I.B.I: (\$

14,800p

Days Of Repair:

21

Resurvey No. of Trlp:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

F.M.A.S

Others

TOTAL

200

11

211

**...CLAIM SUBFOLDER...(New Assignment)**

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2019 15:32		26 Sep 2019 09:54 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

Show All

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Main Claimant:	RAJASEGARAN S/O RAJAGOPAL @ RAJASEGARAN S/O SANDA, ID: S1523215C		
Vehicle Reg. No.:	SLE2848P	Date of Loss:	24/09/2019 19:00 - :59 [38 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLM3083E	Policy No. (Claimant):	
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Zheng Hanyang - 6594 2547]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/09/2019]		
Adj Asg. Remarks:	on WP. NR case, please assign to LKK. Tks.		

## ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)

## Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--------------------------------------------------------------------------------------------------	-------	-----------------------------------------------------------------------------------------------------

Attn:	Zheng Hanyang	Date:	27 Sep 2019
-------	---------------	-------	-------------

**Preliminary Advice**

Insured Vehicle No	: SLM3083E	Accident Date	: 24/09/2019
TP Vehicle No	: SLE2848P	Assignment Date	: 26/09/2019
Make	: HONDA VEZEL	Est. Duration of Repair	: 21.00
Date of Inspection	: 26/09/2019		
Inspection At	: CHENG HOE MOTOR PTE LTD (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT SINGAPORE 568047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	22,158.24
Revised Amount	:S\$	18,550.87
Check Items (Estimated)	:S\$	2,321.60
Total	:S\$	20,872.47
Lump Sum Repair	:S\$	
<b>Total Loss Consideration</b>		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	215C
<b>Vehicle Details</b>	
Vehicle No.:	SLE2848P
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	L15B4030195
Chassis No.:	RU11110193
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,376.00
Original Registration Date:	15 Jul 2016
First Registration Date:	15 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$9,376.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2026
PARF Rebate Amount:	\$7,032.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$36,520.00
<b>Total Rebate Amount:</b>	<b>\$43,552.00</b>

The information contained herein is correct as at 25 Sep 2019

OK

**Free Car Valuation**

Unsure of how much your car is worth?

Let us tell you how much is the value - no charges &amp; no obligations!

HONDA VEZEL

Price Range

Depreciation

2016

Vehicle Type

Submit

Advanced Search

## Used Car Comparison

--- Comparing 2 Vehicles ---

Honda Vezel 1.5A X

Honda Vezel 1.5A X



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Use search bar above to select another car to compare.

Use search bar above to select another car to compare.

## CAR DETAILS

Price	\$63,800	\$64,400	-
Instalment	\$662	\$668	-
Registration Date	12-Jul-2016	18-Jul-2016	-
Manufactured	2016	2016	-
Mileage	45,000 km	31,218 km	-
Transmission	Auto	Auto	-
Engine Cap	1,496 cc	1,496 cc	-
Road Tax	\$682 /yr	\$682 /yr	-
Power	96.0 kW (128 bhp)	96.0 kW (128 bhp)	-
Curb Weight	1,190 kg	1,190 kg	-
Features	Fuel Efficient 1.5L I-VTEC Engine, Earth Dream Technology, Keyless Entry/Start, Auto Brake Hold, Cruise Control, CTBA, Electric Park Brake.	Earth Dream Technology 1.5i I-vtec Engine, 128bhp. Keyless Entry/start, Auto Brake Hold, Cruise Control, CTBA, Electric Parking Brake Etc.	-
Accessories	Pioneer DVD Player With Reverse Camera, Keyless Entry/Start, Cruise Control, Auto LED Headlamps, Auto Start/Stop, City Brake Assist.	Pioneer DVD Touch Screen Audio System, Full Leather Seats, Sports Rims, Reverse Camera With Sensors, Knockdown Rear Seats, Retractable Side Mirror Etc	-
Description	Popular Honda Vezel With 1.5L Engine Providing Adequate Power For Your Daily Drive! Compact Exterior Give You The Ability To Squeeze Through Tight Urban Confines, Yet Giving You The Sense Of Roominess On The Inside! Comfortable And Spacious Cabin For 5 Passengers! Split Fold Rear Seats Provide You With The Extra Load Space For Your Daily Luggage And Active Life Style! Come Down Now For Viewing!	Lowest Mileage Clocked With 1 Meticulous Owner! Well Maintained, NON PHV Unit. Unique Brown Interior Leather. Roadtax Till Jan 2020! Trade In, Inspection Welcome. Loan With Attractive Interest Rates On Different Packages. Call/text Now For More Info!	-
COE	\$47,020	\$52,301	-
OMV	\$20,600	\$19,781	-
ARF	\$10,840	\$9,781	-
Depreciation	\$8,590 /yr	\$8,730 /yr	-
No. of Owners			

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/09/2019 13:42
Date Of Accident	24/09/2019 19:45
Exact Location Of Accident	PIE TOWARDS TUAS (AFTER ADAM FLYOVER)
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE2848P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	RAJASEGARAN S/O RAJAGOPAL @ RAJASEGARAN S/O SANDA
NRIC No	S1523215C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98255565
Alternative Phone No	OTHERS-81270887

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 X (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082287997-03 DC
Cover Note Number	17/07/2019 - 16/07/2020

### Driver

Name of Driver	DHIWAKAR RAJASEGARAN
NRIC No	S9443384C
Date Of Birth	13/11/1994
Occupation	INDOOR
Date Of Driving Pass	29/05/2017
Driving Experience	2 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81270887
Fax Number	
Contact Number	
E-Mail Address	DHIWAKARRAJASEGARAN@YAHOO.COM.SG

Vehicle Registration Number	SMM7088D
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAM SHANON
NRIC/Passport Number	S7604088E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



Address	BLK 249 KIM KEAT LINK #06-87
Postcode	310249
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

MOTOR CAR SMM7088D JAM BRAKE TO STOP AND I FOLLOW TOO. NEXT MOMENT, FELT A GREAT IMPACT FROM THE REAR AND IT PUSHED MY VEHICLE TO THE FRONT AND COLLIDED ONTO THE BACK OF SMM7088D. NO ONE WAS INJURED.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM3083E
Vehicle Make/Model/Colour	WHITE TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE HIRE
Name of Driver	NG SEO CHENG
NRIC/Passport Number	S1629257E
Contact Number	98620909
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF OTHER VEHICLE PROPERTY 2

**SKETCH PLAN**


VEHICLE NO.: SLE 2848P  
INSURER : NITUC  
DATE & TIME: 24/09/2019 @ 1945


**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name: Nongyn (AMK)  
NRIC/FIN No.: 25/09/19

**SKETCH PLAN**

PIE → Tuas

↑ ↑ ↑ ↑

C  
A  
B

↓

Adam flyover

A: SLE 2848P  
(alone).

B: SLM 3083E (PHV)  
White Toyota  
Ng Seo Cheng  
S1629257E  
Hp: 98620909

C: SWM 7088D  
Toyota  
Tam Shanon  
S7604088E

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Vehicle No: SLE2848P (NTUC)  
Date & Time: 24/09/2019 @ 1945 (clear/dry)

Motor car Shm7088D jam brake to stop and i follow too. Next moment, felt a great impact from the rear and it pushed my vehicle to the front and collided onto the back of Shm7088D. No one was injured.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

I/We declare the foregoing particulars are true in every respect.

( ) Claim Own Policy ( ) Claim Third Party ( ) Reporting Only  
( ) Claim OD/TP at other workshop ( )



# Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 38304

## CASH SALE / JOB ORDER

Date: 25/9/19

Messrs: Cheng Hoe (AMK)  
车牌 SLE 2848P 车型 Honda vezel  
Vehicle No. SLE 2848P Model No. Honda vezel  
时间 (日/夜) Day 联络号码 98255565  
Time (day/night): Day Contact No: 98255565  
由 249 Kim Keat Link  
Location: 249 Kim Keat Link  
到 Autopoint #01-04  
To: Autopoint #01-04  
银额 50 其他  
Cash \$ 50 Others:  
经手人 Pi Tow Truck  
Authorised By: Pi Driver Name: Rikao

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 24/09/2019

TP Veh Reg No: SLM3083E

Estimate No: ES1992069/AMK

Date: 26 Sep 2019

Policy No: 5082287997-03 DC

Veh Reg No: SLE2848P

Make/Model: HONDA VEZEL 1.5X A

Chassis No: RU11110193

Engine No: L15B4030195

Reg. Date: 15/07/2016

## Estimate Repair Cost to Vehicle No :SLE2848P

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>List Price</b>				
1 FRONT BUMPER	459.00	1 PC	B <sub>1</sub> 459.00	✓
2 FRONT BUMPER CENTRE LOWER GRILLE	77.50	1 PC	CM 77.50	✓
3 FRONT BUMPER REINFORCEMENT	321.40	1 PC	B <sub>1</sub> 321.40	✓
4 FRONT BUMPER REINFORCEMENT TOP GARNISHS	24.20	2 PC	DIT 48.40	✓
5 FRONT BUMPER CLIP	3.50	4 PC	M 14.00	✓
6 FRONT BUMPER TOW HOOK COVER	29.50	1 PC	ND 29.50	✓
7 FRONT BUMPER LOWER SPOILER	195.20	1 PC	ND 195.20	✓
8 FRONT BUMPER SIDE RETAINER	20.60	2 PC	DIT 41.20	✓
9 FRONT BUMPER 'T' BRACKET	19.40	1 PC	B <sub>1</sub> 19.40	✓
10 FRONT BUMPER OUTER TEMPERATURE SENSOR	89.20	1 PC	CM 89.20	✓
11 FRONT BUMPER RH FOG LAMP	303.60	1 PC	SM 303.60	✓
12 FRONT BUMPER RH FOG LAMP COVER	45.20	1 PC	M 45.20	✓
13 FRONT BUMPER RH FOG LAMP HOLDER	50.40	1 PC	SM 50.40	✓
14 FRONT BUMPER CLIP	3.50	6 PC	M 21.00	✓
15 BONNET	892.40	1 PC	B <sub>1</sub> 892.40	✓
16 BONNET INNER LOCK	98.50	1 PC	DIT 98.50	✓
17 BONNET HINGE	45.80	2 PC	DIT CM 91.60	✓
18 BONNET INSULATOR	122.40	1 PC	CM 122.40	✓
19 BONNET CLIP	3.50	6 PC	M 21.00	✓
20 FRONT GRILLE HOUSING	268.40	1 PC	CM 268.40	✓
21 FRONT GRILLE GARNISH	203.40	1 PC	CM 203.40	✓
22 FRONT GRILLE CHROME MOULDING	48.50	2 PC	M 97.00	✓
23 FRONT GRILLE LOGO	29.40	1 PC	M 29.40	✓
24 FRONT GRILLE CENTRE BRACKET	45.80	1 PC	CM 45.80	✓
25 FRONT GRILLE SIDE BRACKETS	19.60	2 PC	CM 39.20	✓
26 HEADLAMP	1,820.40	2 PC	3,640.80	✓
27 HEADLAMP BRACKET	49.20	2 PC	B <sub>1</sub> 98.40	✓
28 FRONT LH FENDER CLIP	558.70	1 PC	B <sub>1</sub> 558.70	✓
29 FRONT LH FENDER WHEEL ARC GARNISH	160.20	1 PC	B <sub>1</sub> 160.20	✓
30 FRONT LH FENDER CLIP	3.50	6 PC	M 21.00	✓
31 HORN	59.20	1 PC	SM 59.20	✓
32 WIPER WASHER TANK	75.20	1 PC	ND 75.20	✓
33 FRT SUPPORT PANEL	576.20	1 PC	B <sub>1</sub> 576.20	✓
34 FRONT SUPPORT PANEL INNER TOP GARNISH	85.20	1 PC	SM 85.20	X
35 FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	3.50	10 PC	M 35.00	✓
36 FRONT SUPPORT PANEL LH AIR DUCT	77.50	1 PC	CM 77.50	✓
37 AIR-CON CONDENSER	568.20	1 PC	B <sub>1</sub> 568.20	✓
38 AIR-CON CONDENSER FAN COWLING	96.20	1 PC	SM 96.20	✓

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST: 201001158E RCB NO: 201001158E

**M/S :** MSIG INSURANCE (S) PTE LTD (SGX)  
 16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581  
 TEL: 68277660 FAX: 62257402  
 ATTN: Motor Claim Department  
 WS Ref: TP/MSIG/AMK  
 Claim Type: Third Party  
 Accident Date: 24/09/2019  
 TP Veh Reg No: SLM3083E

**Estimate No:** ES1992069/AMK  
**Date:** 26 Sep 2019  
**Policy No:** 5082287997-03 DC  
**Veh Reg No:** SLE2848P  
**Make/Model:** HONDA VEZEL 1.5X A  
**Chassis No:** RU11110193  
**Engine No:** L15B4030195  
**Reg. Date:** 15/07/2016

## Estimate Repair Cost to Vehicle No :SLE2848P

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
39 AIR-CON CONDENSER FAN MOTOR	308.20	1 PC	308.20	X
40 AIR-CON CONDENSER FAN BLADE	68.40	1 PC	68.40	X
41 AIR-CON CONDENSER LIQUID PIPE W/SWITCH	195.20	1 PC	195.20	X
42 AIR-CON CONDENSER DISCHARGE HOSE	210.40	1 PC	210.40	X
43 AIRCON CONDENSER TOP BRACKET	32.50	2 PC	65.00	1
44 RADIATOR	1,250.40	1 PC	1,250.40	1
45 RADIATOR FAN COWLING	124.20	1 PC	124.20	X
46 RADIATOR FAN MOTOR	398.40	1 PC	398.40	X
47 RADIATOR FAN BLADE	57.70	1 PC	57.70	X
48 RADIATOR SPARE TANK	62.50	1 PC	62.50	X
49 RADIATOR TOP BRACKET	32.50	2 PC	65.00	4
50 RADIATOR SIDE GARNISH	36.20	2 PC	72.40	1
51 REAR BUMPER	518.20	1 PC	518.20	1
52 REAR BUMPER REFLECTOR	148.20	2 PC	296.40	4
53 REAR BUMPER SIDE RETAINER	17.50	2 PC	35.00	X
54 REAR BUMPER CLIP	3.50	4 PC	14.00	1
55 REAR TAILGATE	1,050.40	1 PC	1,050.40	1
56 TAILGATE INNER LOCK	157.10	1 PC	157.10	1
57 TAILGATE INNER RUBBER	96.30	1 PC	96.30	501m 48-15
58 TAILGATE EMBLEM 'VEZEL'	43.20	1 PC	43.20	1
59 TAILGATE NUMBER PLATE LAMP GARNISH	395.20	1 PC	395.20	X
60 TAILGATE REFLECTOR	264.90	2 PC	529.80	1
61 TAILGATE WINDSCREEN GLASS MOULDING	149.20	1 SET	149.20	1
62 TAILLAMP	441.20	2 PC	882.40	X
63 REAR END PANEL	411.90	1 PC	411.90	1
64 REAR END PANEL INNER TOP GARNISH	92.30	1 PC	92.30	1
65 REAR END PANEL UNDER TRAY	190.20	1 PC	190.20	1
66 REAR END PANEL BUZZER SENSOR (INNER)	80.20	1 PC	80.20	1
67 REAR END PANEL BUZZER SENSOR (OUTER)	85.20	1 PC	85.20	X
68 REAR LUGGAGE COMPARTMENT PANEL	775.40	1 PC	775.40	1
69 REAR LUGGAGE COMPARTMENT INNER TOP BOARD	206.20	1 PC	206.20	1
70 REAR LUGGAGE COMPARTMENT PANEL SPONGE	126.40	1 PC	126.40	1
71 REAR MUFFLER	528.40	1 PC	528.40	1
72 REAR MUFFLER HEAT SHIELD	55.40	1 PC	55.40	1
73 REAR MUFFLER RUBBER MOUNTING	19.20	2 PC	38.40	1
74 EXHAUST MID PIPE	599.40	1 PC	599.40	1
			19,910.30	
		Less 20%	3,982.06	15,928.24

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

**M/S :** MSIG INSURANCE (S) PTE LTD (SGX)  
 16 RAFFLES QUAY  
 #24-01 HONG LEONG BUILDING  
 SINGAPORE 048581  
 TEL: 68277660 FAX: 62257402  
 ATTN: Motor Claim Department  
 WS Ref: TP/MSIG/AMK  
 Claim Type: Third Party  
 Accident Date: 24/09/2019  
 TP Veh Reg No: SLM3083E

**Estimate No:** ES1992069/AMK  
**Date:** 26 Sep 2019  
**Policy No:** 5082287997-03 DC  
**Veh Reg No:** SLE2848P  
**Make/Model:** HONDA VEZEL 1.5X A  
**Chassis No:** RU11110193  
**Engine No:** L15B4030195  
**Reg. Date:** 15/07/2016

## Estimate Repair Cost to Vehicle No :SLE2848P

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>Special Net</b>				
75 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
76 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
77 REVERSE SENSOR	200.00	1 SET	200.00	✓
78 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
79 REAR LUGGAGE COMPARTMENT PANEL TOP COAT	80.00	1 PC	80.00	✓
80 COOLANT	40.00	1 UNIT	40.00	501m 20
81 REAR END PANEL SEALANT	40.00	1 PC	40.00	✓
			470.00	470.00
<b>Labour</b>				
82 TOWING	50.00	1 LA	50.00	✓
83 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
84 REMOVE & REFIX FRT BUMPER & LOWER,GRILLE,BONNET & ATTACHMENTS,HEADLAMPS,FRT LH FENDER,TO CUT,WELD & RENEW FRT SUPPORT PANEL;KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	900.00	1 LA	900.00	750
85 PUTTY & RESPRAY FRT BUMPER,BONNET,BOTH FENDERS,FRT SUPPORT PANEL & ALL AFFECTED AREAS	900.00	1 LA	900.00	800
86 REMOVE & REFIX REAR BUMPER,SIDE BUMPERS,TAILGATE,SPOILER & ATTACHMENTS,TAILLAMPS;TO CUT,WELD & RENEW REAR END PANEL,REAR LUGGAGE PANEL,KNOCKING & REPAIR REAR FENDERS,REAR RH CHASSIS FRAMES & REALIGN THE SAME	1,500.00	1 LA	1,500.00	1300
87 PUTTY & RESPRAY REAR SIDE BUMPERS,PARKING SENSORS,TAILGATE,SPOILER,BOTH FENDERS,REAR END PANEL,REAR LUGGAGE PANEL,CHASSIS FRAMES & ALL AFFECTED AREAS	1,400.00	1 LA	1,400.00	1200
88 REMOVE & REFIX REVERSE CAMERA,RESET & REPOSITION	80.00	1 PC	80.00	✓
89 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
90 REMOVE & REFIX REAR MUFFLER,MID PIPE & REALIGN THE SAME	150.00	1 LA	150.00	120
91 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR	100.00	1 LA	100.00	✓
92 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN CHASSIS	250.00	1 LA	250.00	✓
93 RUSTPROOFING	210.00	1 LA	210.00	✓
			5,760.00	5,760.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

## Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

**M/S :** MSIG INSURANCE (S) PTE LTD (SGX)  
16 RAFFLES QUAY  
#24-01 HONG LEONG BUILDING  
SINGAPORE 048581  
TEL: 68277660 FAX: 62257402  
ATTN: Motor Claim Department  
WS Ref: TP/MSIG/AMK  
Claim Type: Third Party  
Accident Date: 24/09/2019  
TP Veh Reg No: SLM3083E

**Estimate No:** ES1992069/AMK  
**Date:** 26 Sep 2019  
**Policy No:** 5082287997-03 DC  
**Veh Reg No:** SLE2848P  
**Make/Model:** HONDA VEZEL 1.5X A  
**Chassis No:** RU11110193  
**Engine No:** L15B4030195  
**Reg. Date:** 15/07/2016

### Estimate Repair Cost to Vehicle No :SLE2848P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 22,158.24
			Add GST @ 7%	1,551.08
			Total Amount Payable	S\$ 23,709.32

\* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

*DORLYN LI*

AUTHORISED SIGNATURE



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2019 15:32		26 Sep 2019 09:54 <a href="#">Edit Adj Rpt</a>	<b>S\$14,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$14,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G

Main Claimant:

RAJASEGARAN S/O RAJAGOPAL @ RAJASEGARAN S/O SANDA, ID: S1523215C

Vehicle Reg. No.:

SLE2848P

Claim Type:

TP / 606911

Vehicle Reg. No. (Insured):

SLM3083E

Repairster:

Cheng Hoe Motor Pte Ltd (AMK) 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO KIO AUTOPOINT, 568047 Ang Mo Kio - Tel:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Zheng Hanyang - 6594 2547]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/10/2019]

Adj Asg. Remarks:

on WP. NR case, please assign to LKK. Tks.

Date of Loss:

24/09/2019 19:00 - :59  
[38 Months and 9 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

29114756 (Comprehensive)  
Coverage: 01/02/2019 - 31/01/2020

Policy No. (Claimant):

Excess:

Created by insurer

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

## Claim Documents

**\*SLE2848P (606911)**  
**[SLM3083E]**






































TP
































**RAJASEGARAN S/O RAJAGOPAL @ RAJASEGARAN S/O SANDA**

Sep 24 2019 7:00PM

**[GRAB RENTALS PTE LTD]**

**Cheng Hoe Motor Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Video						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	02/10/19 09:47	Video from GRAB				 Load MP4			
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	27/09/19 14:13	Accident Statement From: SC - Reg. No: SLM3083E, Claimant: GRAN RENTALS PTE LTD				 Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	27/09/19 14:12	Adjuster Immediate Advice				 Load HTM			
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
2	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
3	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
4	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
5	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
6	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
7	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
8	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
9	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
10	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
11	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
12	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
13	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
14	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
15	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
16	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
17	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
18	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
19	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
20	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
21	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
22	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
23	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
24	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
25	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
26	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
27	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
28	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
29	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
30	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
31	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
32	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
33	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	
34	18/11/19 14:32	General View				 Load JPG		<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
35	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
43	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
44	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
45	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
46	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
47	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
48	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
49	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
50	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
51	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
52	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
53	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
54	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
55	18/11/19 14:32	General View	 Load JPG	<input checked="" type="checkbox"/>
56	18/11/19 14:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	18/11/19 14:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	18/11/19 14:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	18/11/19 14:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	18/11/19 14:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/09/19 15:33	PRI from Cheng Hoe Motor Pte Ltd	 Load PDF	
2	25/09/19 15:37	email from workshop	 Load PDF	
3	25/09/19 15:38	email to workshop	 Load PDF	
4	25/09/19 16:47	TP SLE2848P GIA REPORT	 Load PDF	
5	25/09/19 16:52	email to workshop	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19016949/KVF3E2

Date: 19/11/2019

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No : SLE2848P

Insured Vehicle No : SLM3083E

Date of Loss: 24/09/2019

Nature of Claim: TP

Claim No: 606911

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE2848P

Make &amp; Model: HONDA VEZEL, 1.5 X (A)

Engine No: L15B4030195

Reg. Date: 15/07/2016 (Man. Year: 2015)

Chassis No: RU11110193

Colour: Metallic Black

Odometer: 66810 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 8 mm

Rear Left Side:

Falken 8 mm

Front Right Side: Dunlop 8 mm

Rear Right Side:

Falken 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,398.24	13,470.87	2,927.37	17.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,760.00	5,080.00	680.00	11.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>22,158.24</b>	<b>18,550.87</b>	<b>3,607.37</b>	<b>16.28</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>14,800.00</b>		
<b>(S\$)</b>	22,158.24	14,800.00	7,358.24	33.21
<b>+ GST 7.00/7.00% (S\$)</b>	1,551.08	1,036.00	515.08	33.21
<b>Nett Amount (S\$)</b>	<b>23,709.32</b>	<b>15,836.00</b>	<b>7,873.32</b>	<b>33.21</b>

### INSPECTION

Date of Assignment: 26/09/2019

Date Inspected: 26/09/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (AMK)  
10 ANG MO KIO IND PARK 2A, #01-04  
ANG MO KIO AUTOPOINT  
Singapore 568047

Estimated Period of Repair: 21.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 X (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE2848P)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	459.00 FL	*459.00 FL
2	1		*FRONT BUMPER CENTRE LOWER GRILLE	Cracked	77.50 FL	*77.50 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	321.40 FL	*321.40 FL
4	2		*FRONT BUMPER REINFORCEMENT TOP GARNISHS	Distorted	48.40 FL	*48.40 FL
5	4		*FRONT BUMPER CLIP	Necessary	14.00 FL	*14.00 FL
6	1		*FRONT BUMPER TOW HOOK COVER	Dented	29.50 FL	*29.50 FL
7	1		*FRONT BUMPER LOWER SPOILER	Dented	195.20 FL	*195.20 FL
8	2		*FRONT BUMPER SIDE RETAINER	Distorted	41.20 FL	*41.20 FL
9	1		*FRONT BUMPER T BRACKET	Bent	19.40 FL	*19.40 FL
10	1		*FRONT BUMPER OUTER TEMPERATURE SENSOR	Cracked	89.20 FL	*89.20 FL
11	1		*FRONT BUMPER RH FOG LAMP	Serviceable	303.60 FL	*- FL
12	1		*FRONT BUMPER RH FOG LAMP COVER	Dented	45.20 FL	*45.20 FL
13	1		*FRONT BUMPER RH FOG LAMP HOLDER	Serviceable	50.40 FL	*- FL
14	6		*FRONT BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
15	1		*BONNET	Buckled	892.40 FL	*892.40 FL
16	1		*BONNET INNER LOCK	Distorted	98.50 FL	*98.50 FL
17	2		*BONNET HINGE	Distorted	91.60 FL	*91.60 FL
18	1		*BONNET INSULATOR	Cracked	122.40 FL	*122.40 FL
19	6		*BONNET CLIP	Necessary	21.00 FL	*21.00 FL
20	1		*FRONT GRILLE HOUSING	Cracked	268.40 FL	*268.40 FL
21	1		*FRONT GRILLE GARNISH	Cracked	203.40 FL	*203.40 FL
22	2		*FRONT GRILLE CHROME MOULDING	Necessary	97.00 FL	*97.00 FL
23	1		*FRONT GRILLE LOGO	Necessary	29.40 FL	*29.40 FL
24	1		*FRONT GRILLE CENTRE BRACKET	Cracked	45.80 FL	*45.80 FL
25	2		*FRONT GRILLE SIDE BRACKETS	Cracked	39.20 FL	*39.20 FL
26	2		*HEADLAMP	Mtg Broken	3,640.80 FL	*3,640.80 FL
27	2		*HEADLAMP BRACKET	Bent	98.40 FL	*98.40 FL
28	1		*FRONT LH FENDER	Buckled	558.70 FL	*558.70 FL
29	1		*FRONT LH FENDER WHEEL ARC GARNISH	Buckled	160.20 FL	*160.20 FL
30	6		*FRONT LH FENDER CLIP	Necessary	21.00 FL	*21.00 FL
31	1		*HORN	Serviceable	59.20 FL	*- FL
32	1		*WIPER WASHER TANK	Dented	75.20 FL	*75.20 FL
33	1		*FRT SUPPORT PANEL	Bent	576.20 FL	*576.20 FL
34	1		*FRONT SUPPORT PANEL INNER TOP GARNISH	Serviceable	85.20 FL	*- FL
35	10		*FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	Necessary	35.00 FL	*35.00 FL
36	1		*FRONT SUPPORT PANEL LH AIR DUCT	Cracked	77.50 FL	*77.50 FL
37	1		*AIR-CON CONDENSER	Bent	568.20 FL	*568.20 FL
38	1		*AIR-CON CONDENSER FAN COWLING	Serviceable	96.20 FL	*- FL
39	1		*AIR-CON CONDENSER FAN MOTOR	Serviceable	308.20 FL	*- FL
40	1		*AIR-CON CONDENSER FAN BLADE	Serviceable	68.40 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*AIR-CON CONDENSER LIQUID PIPE W/SWITCH	Serviceable	195.20 FL	*- FL
42	1		*AIR-CON CONDENSER DISCHARGE HOSE	Serviceable	210.40 FL	*- FL
43	2		*AIRCON CONDENSER TOP BRACKET	Distorted	65.00 FL	*65.00 FL
44	1		*RADIATOR	Mtg Broken	1,250.40 FL	*1,250.40 FL
45	1		*RADIATOR FAN COWLING	Serviceable	124.20 FL	*- FL
46	1		*RADIATOR FAN MOTOR	Serviceable	398.40 FL	*- FL
47	1		*RADIATOR FAN BLADE	Serviceable	57.70 FL	*- FL
48	1		*RADIATOR SPARE TANK	Serviceable	62.50 FL	*- FL
49	1		*RADIATOR TOP BRACKET (2PCS)	Distorted (1Pc Only)	65.00 FL	*32.50 FL
50	2		*RADIATOR SIDE GARNISH	Cracked	72.40 FL	*72.40 FL
51	1		*REAR BUMPER	Buckled	518.20 FL	*518.20 FL
52	1		*REAR BUMPER REFLECTOR	O/S Cracked	296.40 FL	*148.20 FL
53	2		*REAR BUMPER SIDE RETAINER	Serviceable	35.00 FL	*- FL
54	4		*REAR BUMPER CLIP	Necessary	14.00 FL	*14.00 FL
55	1		*REAR TAILGATE	Bent	1,050.40 FL	*1,050.40 FL
56	1		*TAILGATE INNER LOCK	Dented	157.10 FL	*157.10 FL
57	1		*TAILGATE INNER RUBBER (\$96.30) (50%)	Cut	77.04 FS	*48.15 FS
58	1		*TAILGATE EMBLEM VEZEL	Necessary	43.20 FL	*43.20 FL
59	1		*TAILGATE NUMBER PLATE LAMP GARNISH	Serviceable	395.20 FL	*- FL
60	2		*TAILGATE REFLECTOR	Cut	529.80 FL	*529.80 FL
61	1		*SET TAILGATE WINDSCREEN GLASS MOULDING	Necessary	149.20 FL	*149.20 FL
62	2		*TAILLAMP	Serviceable	882.40 FL	*- FL
63	1		*REAR END PANEL	Bent	411.90 FL	*411.90 FL
64	1		*REAR END PANEL INNER TOP GARNISH	Dented	92.30 FL	*92.30 FL
65	1		*REAR END PANEL UNDER TRAY	Buckled	190.20 FL	*190.20 FL
66	1		*REAR END PANEL BUZZER SENSOR (INNER)	Cracked	80.20 FL	*80.20 FL
67	1		*REAR END PANEL BUZZER SENSOR (OUTER)	Serviceable	85.20 FL	*- FL
68	1		*REAR LUGGAGE COMPARTMENT PANEL	Bent / Buckled	775.40 FL	*775.40 FL
69	1		*REAR LUGGAGE COMPARTMENT INNER TOP BOARD	Dented	206.20 FL	*206.20 FL
70	1		*REAR LUGGAGE COMPARTMENT PANEL SPONGE	Cracked	126.40 FL	*126.40 FL
71	1		*REAR MUFFLER	Bent	528.40 FL	*528.40 FL
72	1		*REAR MUFFLER HEAT SHIELD	Bent	55.40 FL	*55.40 FL
73	2		*REAR MUFFLER RUBBER MOUNTING	Torn	38.40 FL	*38.40 FL
74	1		*EXHAUST MID PIPE	Bent	599.40 FL	*599.40 FL
75	1		*FRONT NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
76	1		*REAR NUMBER PLATE	Dented	35.00 FS	*35.00 FS
77	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
78	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
79	1		*REAR LUGGAGE COMPARTMENT PANEL TOP COAT	Necessary	80.00 FS	*80.00 FS
80	1		*COOLANT (50%)	Necessary	40.00 FS	*20.00 FS
81	1		*REAR END PANEL SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **20,361.04**    **16,714.05**  
 - List Item Discount on L Items 20.00/20.00% (\$\$)    3,962.80    3,243.18

Total Parts (\$\$) **16,398.24**    **13,470.87**

Report was unsubmitted during this print-out.
-----------------------------------------------

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS	New	100.00	100.00
3	REMOVE & REFIX FRT BUMPER & LOWER, GRILLE, BONNET & ATTACHMENTS, HEADLAMPS, FRT LH FENDER; TO CUT, WELD & RENEW FRT SUPPORT PANEL; KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	New	900.00	750.00
4	PUTTY & RESPRAY FRT BUMPER, BONNET, BOTH FENDERS, FRT SUPPORT PANEL & ALL AFFECTED AREAS	New	900.00	800.00
5	REMOVE & REFIX REAR BUMPER, SIDE BUMPERS, TAILGATE, SPOILER & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL, REAR LUGGAGE PANEL; KNOCKING & REPAIR REAR FENDERS, REAR RH CHASSIS FRAMES & REALIGN THE SAME	New	1,500.00	1,300.00
6	PUTTY & RESPRAY REAR SIDE BUMPERS, PARKING SENSORS, TAILGATE, SPOILER, BOTH FENDERS, REAR END PANEL, REAR LUGGAGE PANEL, CHASSIS FRAMES & ALL AFFECTED AREAS	New	1,400.00	1,200.00
7	REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	New	80.00	80.00
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
9	REMOVE & REFIX REAR MUFFLER, MID PIPE & REALIGN THE SAME	New	150.00	120.00
10	REMOVE & REFIX REAR SEAT, CARPET TO FACILITATE REPAIR	New	100.00	100.00
11	TO MOUNT ON CAR-O-LINER, JACK & STRAIGHTEN CHASSIS	New	250.00	250.00
12	RUSTPROOFING	New	210.00	210.00
<b>Gross Labour Cost (S\$)</b>			<b>5,760.00</b>	<b>5,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >