

Kp

26/9/19

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

Not Withheld
Punery Repair
5 days

8 4482.76

26,SEP 2019

India International Insurance PL
64 Cecil Street #04/05/06-02
IOB Building S 049711

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SH8463C
Accident involving vehicle no:SKR3827L/SH8463C
DOA: 24/09/2019 AT Entrance of Novotel Clarke Quay

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SKR3827L
To supply--

Description	Qty	Amount
Rh front door	1	1,079.00
Front door outer handle-long	1	133.90
Door handle-small	1	24.20
Front door outer chrome moulding (below door glass)	1	130.70
Rear door,Rh	1	1,069.20
Front fender,Rh	1	761.45
Fender VVTI emblem	1	38.40
Side mirror,Rh	1	1,006.20
Mirror cover	1	67.30
Parts		4,310.35
Parts less 25%		1,077.59
		3,232.76

To remove/transfer front n rear door power window mechanism,door glass n all attachments to new door.
To repair dented areas,replace above parts.
To spray paint.

180.00 601
800.00 5401
950.00 6501

5,162.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____