

15/5/2010

INS. CASE OWNER:

CC<sup>3</sup> / QBE1901

6977, Feb 2010

LKK:

IDAC:

Surveyor:

STEVE

DOI:

W/ALIA

Date / Time:

21/1/10

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YP 8159T

Name of Insured:

MONZONER AIR CONDITIONING P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

1A/1/10

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO: Driver Name / Age:

SMY WEE SHANH

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

BUTIT BATOKE WEST AVE 5

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHC 4177Y



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

| Date/ Time                                                                                                                                                          | STAGE                             | DATE / PIC                          |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------|-------------------------------------|
| 21-11-10                                                                                                                                                            | Non-Reporting ltr (1st):          |                                     |
|                                                                                                                                                                     | Non-Reporting ltr (2nd):          |                                     |
|                                                                                                                                                                     | Non-Reporting ltr (Final):        |                                     |
|                                                                                                                                                                     | Notification ltr (if non-pickup): |                                     |
|                                                                                                                                                                     | Call OI:                          | EMAIL NIO                           |
|                                                                                                                                                                     | After call ltr to OI:             |                                     |
|                                                                                                                                                                     | Documentation Check List:         | Handler Typist                      |
|                                                                                                                                                                     | Notification ltr (if non-pickup)  | <input type="checkbox"/>            |
|                                                                                                                                                                     | After call ltr to OI:             | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | Authorisation To Act:             | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | Release Voucher:                  | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | Final Repair Bill:                | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | Car Rental Invoice:               | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | Towing Invoice:                   | <input type="checkbox"/>            |
|                                                                                                                                                                     | LTA / GIA:                        | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | Medical Bill:                     | <input type="checkbox"/>            |
|                                                                                                                                                                     | PIR:                              | <input type="checkbox"/>            |
|                                                                                                                                                                     | Mandate/Reject Instruction:       | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | LOD:                              | <input checked="" type="checkbox"/> |
|                                                                                                                                                                     | Payment Breakdown Form:           | <input type="checkbox"/>            |
|                                                                                                                                                                     | Post-Repair Photos:               | <input type="checkbox"/>            |
|                                                                                                                                                                     | Others:                           | <input type="checkbox"/>            |
| PRELIMINARY ADVICE                                                                                                                                                  | Date/Time:                        | Sent By:                            |
| FINALIZATION                                                                                                                                                        | Date/Time:                        | Confirm with:                       |
| Repair Cost:                                                                                                                                                        | SS15,000                          | ( 14 days) Reduction: 69 %          |
| FINAL SETTLEMENT                                                                                                                                                    | Date/Time: 24.03.20               | Confirm with: SEVANA                |
| Final Liability:                                                                                                                                                    | % 100 (Agreed / Assessed)         | BOLA S/N No. : 31                   |
| Repair Cost:                                                                                                                                                        | SS15,000.00                       | OLD REAR ENDED TP.                  |
| Loss of Rental (LOR):                                                                                                                                               | SS 2,108.00 ( 20 days) x 105.40   |                                     |
| Loss of Use (LOU):                                                                                                                                                  | SS - (\$ x days)                  |                                     |
| Loss of Income (LOI):                                                                                                                                               | SS - (\$ x days)                  |                                     |
| LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one] |                                   |                                     |
| GLA/LTA Search                                                                                                                                                      | SS1-00                            |                                     |
| Medical:                                                                                                                                                            | SS -                              |                                     |
| Disbursement:                                                                                                                                                       | SS - (e.g. Tow/ Independent)      |                                     |
| Legal Cost                                                                                                                                                          | SS -                              |                                     |
| Total:                                                                                                                                                              | SS17,115.00                       | Global Sum SS:                      |
| FINAL PAYMENT                                                                                                                                                       | Date/Time: 24.03.20               | Confirm with: SEVANA                |
| Payee 1:                                                                                                                                                            | SS17,115.00                       | Name 1: SMRT TAXI PTE LTD           |
| Payee 2: (Strike if N.A.)                                                                                                                                           | SS                                | Name 2:                             |
| Payee 3: (Strike if N.A.)                                                                                                                                           | SS                                | Name 3:                             |

COPY SENT 3/3/2010

ASS. REC. BY:

Steve

REF:

QBE

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC4173 Y

Yr Regn:

29/11/13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

17148

Colour:

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

713022

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTOKN364 605708262

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallen

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

19/9/19

D.O.I.

25/09/2019

Survey held at

SMRT.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/9/19

repair part 15K

4s: +15,000 (RSD: +32,974.64 (61%))

T.P.  
09/19/2090  
YP8159T

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Rep. Formed:

Lump Sum / L.B.I. /

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

Police

Others

TOTAL

## Case Details

Case Reference Number : TAX/09/19/2090  
Type of Repair : Accident Repair  
Vehicle Registration Number : SHC4173Y

Company Type : SMRT Taxis Pte Ltd  
Estimation ID : EST-8635-ID  
Assigned By : Taxi Claims Manager Team

Insurance Company Name : QBE Insurance (International) Ltd  
Accident Date and Time : 19/09/2019 08:55 AM  
Vehicle Age(In Months) : 70

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

| BOM Type        | Costing Type | Portion | Material Number | SMRT Recommendation            |     |                         |                |        |                 | Surveyor Approval |                   |                          |                | Remarks |
|-----------------|--------------|---------|-----------------|--------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
|                 |              |         |                 | Part Name                      | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace |         |
| One Time Key In | Main         |         |                 | BUMPER REAR                    | 1   | 458.60                  | 458.60         | 25.00  | 343.95          | Replace           | 1                 | 343.95                   | Replace        | ✓ BR    |
| One Time Key In | Main         |         |                 | BUMPER CLIPS                   | 10  | 1.61                    | 16.10          | 25.00  | 12.08           | Replace           | 10                | 12.08                    | Replace        | ✓ REC   |
| One Time Key In | Main         |         |                 | BUMPER REINFORCEMENT REAR      | 1   | 205.70                  | 205.70         | 25.00  | 154.27          | Replace           | 1                 | 154.27                   | Replace        | ✓ DO    |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, RR BUMPER LH     | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace           | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In | Main         |         |                 | ARM SUB-ASSY, RR BUMPER RH     | 1   | 139.60                  | 139.60         | 25.00  | 104.70          | Replace           | 1                 | 104.70                   | Replace        | ✗ NN    |
| One Time Key In | Main         |         |                 | ANTENNA, ELECTRICAL LOWER REAR | 1   | 157.40                  | 157.40         | 10.00  | 141.66          | Replace           | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In | Main         |         |                 | SENSOR REVERSE                 | 1   | 180.00                  | 180.00         | 0.00   | 180.00          | Replace           | 1                 | 180.00                   | Replace        | ✓ BR    |
| One Time Key In | Main         |         |                 | PIXEL STICKER                  | 2   | 60.00                   | 120.00         | 0.00   | 120.00          | Replace           | 2                 | 120.00                   | Replace        | ✓ REC   |
| One Time Key In | Main         |         |                 | BUMPER LIP COVER RR/LH         | 1   | 72.20                   | 72.20          | 25.00  | 54.15           | Replace           | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In | Main         |         |                 | BUMPER LIP COVER RR/RH         | 1   | 118.10                  | 118.10         | 25.00  | 88.57           | Replace           | 1                 | 88.57                    | Replace        | ✓ CRA   |

Total Spare Part Cost 24,278.03

Surveyor Total 9,165.18

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 19,420.82

Final Sur Total 7,332.14

119867.19

| SMRT Recommendation   |              |         |                 |                                     |     |                         |                |        |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|-------------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                           | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | BUMPER LIP REAR                     | 1   | 228.90                  | 228.90         | 25.00  | 171.68          | Replace                  | 1                 | 171.68                   | Replace        | ✓ CRH   |
| One Time Key In       | Main         |         |                 | BUMPER SEAL, RR LH                  | 1   | 88.90                   | 88.90          | 25.00  | 66.68           | Replace                  | 0                 | 0                        | Not Give       | • X NN  |
| One Time Key In       | Main         |         |                 | BUMPER SEAL, RR RH                  | 1   | 65.70                   | 65.70          | 25.00  | 49.28           | Replace                  | 1                 | 49.28                    | Replace        | ✓ CRH   |
| One Time Key In       | Main         |         |                 | BUMPER SIDE RETAINER RR/LH          | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace                  | 1                 | 71.10                    | Replace        | ✓ BR    |
| One Time Key In       | Main         |         |                 | BUMPER SIDE RETAINER RR/RH          | 1   | 94.80                   | 94.80          | 25.00  | 71.10           | Replace                  | 1                 | 71.10                    | Replace        | ✓ BR    |
| One Time Key In       | Main         |         |                 | UNDER COVER SUBASSY, RR FLOOR       | 1   | 514.50                  | 514.50         | 25.00  | 385.88          | Replace                  | 0                 | 0                        | Not Give       | • X NN  |
| One Time Key In       | Main         |         |                 | EXHAUST HEAT SHIELD, REAR           | 1   | 107.40                  | 107.40         | 25.00  | 80.55           | Replace                  | 0                 | 0                        | Not Give       | • X NN  |
| One Time Key In       | Main         |         |                 | EXHAUST TAIL PIPE                   | 1   | 656.20                  | 656.20         | 25.00  | 492.15          | Replace                  | 0                 | 0                        | Not Give       | • X NN  |
| One Time Key In       | Main         |         |                 | SUPPORT EXHAUST PIPE, NO.4          | 2   | 40.30                   | 80.60          | 25.00  | 60.45           | Replace                  | 0                 | 0                        | Not Give       | • X NN  |
| One Time Key In       | Main         |         |                 | SUPPORT, EXHAUST REAR               | 2   | 33.60                   | 67.20          | 25.00  | 50.40           | Replace                  | 0                 | 0                        | Not Give       | • X NN  |
| One Time Key In       | Main         |         |                 | TAILGATE ASY                        | 1   | 1,007.90                | 1,007.90       | 25.00  | 755.92          | Replace                  | 1                 | 755.92/3                 | Replace        | ✓ DD    |
| One Time Key In       | Main         |         |                 | DAM, BACK DOOR GLASS ADHESIVE, NO.1 | 1   | 27.30                   | 27.30          | 25.00  | 20.48           | Replace                  | 1                 | 20.48                    | Replace        | ✓ APC   |
| One Time Key In       | Main         |         |                 | TAIL GATE DOOR GLASS MOULDING, LH   | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace                  | 1                 | 22.05                    | Replace        | ✓ APC   |
| One Time Key In       | Main         |         |                 | TAIL GATE DOOR GLASS MOULDING, RH   | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace                  | 1                 | 22.05                    | Replace        | ✓ APC   |
| One Time Key In       | Main         |         |                 | MOULDING BACK WINDOW, LOWER NO.1    | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace                  | 1                 | 22.05                    | Replace        | ✓ APC   |
| One Time Key In       | Main         |         |                 | DAM, BACK DOOR GLASS ADHESIVE, NO.2 | 1   | 17.40                   | 17.40          | 25.00  | 13.05           | Replace                  | 1                 | 13.05                    | Replace        | ✓ APC   |
| Total Spare Part Cost |              |         |                 |                                     |     |                         |                |        | 24,276.03       | Surveyor Total 9,165.18  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                     |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                     |     |                         |                |        | 19,420.82       | Final Sur Total 7,332.14 |                   |                          |                |         |

| SMRT Recommendation |              |         |                 |                                        |     |                         |                |        |                 |                | Surveyor Approval |                          |                |         |
|---------------------|--------------|---------|-----------------|----------------------------------------|-----|-------------------------|----------------|--------|-----------------|----------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name                              | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/Replace | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | MOULDING, BACK WINDOW, LOWER NO.2      | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace        | 1                 | 22.05                    | Replace        | ✓ APC   |
| One Time Key In     | Main         |         |                 | MOULDING, BACK WINDOW, OUTSIDE LH NO.2 | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace        | 1                 | 22.05                    | Replace        | ✓ APC   |
| One Time Key In     | Main         |         |                 | MOULDING, BACK WINDOW, OUTSIDE RH NO.2 | 1   | 29.40                   | 29.40          | 25.00  | 22.05           | Replace        | 1                 | 22.05                    | Replace        | ✓ APC   |
| One Time Key In     | Main         |         |                 | TAILGATE DOOR GLASS                    | 1   | 1,090.90                | 1,090.90       | 25.00  | 818.18          | Replace        | 1                 | 818.18                   | Replace        | ✓ DR    |
| One Time Key In     | Main         |         |                 | TAILGATE LOWER WINDOW GLASS            | 1   | 721.30                  | 721.30         | 25.00  | 540.97          | Replace        | 1                 | 540.97                   | Replace        | ✓ DR    |
| One Time Key In     | Main         |         |                 | SEALANT W/SCREEN                       | 3   | 37.00                   | 111.00         | 0.00   | 111.00          | Replace        | 3                 | 111.00                   | Replace        | ✓ APC   |
| One Time Key In     | Main         |         |                 | TAILGATE DOOR HINGE LH/RH              | 2   | 58.30                   | 116.60         | 25.00  | 87.45           | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In     | Main         |         |                 | TAILGATE DOOR LOCK                     | 1   | 444.10                  | 444.10         | 25.00  | 333.08          | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In     | Main         |         |                 | TAILGATE DOOR STAY LH                  | 1   | 241.50                  | 241.50         | 25.00  | 181.13          | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In     | Main         |         |                 | TAILGATE DOOR STAY RH                  | 1   | 241.50                  | 241.50         | 25.00  | 181.13          | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In     | Main         |         |                 | TAILGATE DOOR WEATHER STRIP            | 1   | 353.40                  | 353.40         | 25.00  | 265.05          | Replace        | 1                 | 265.05                   | Replace        | ✓ CRU   |
| One Time Key In     | Main         |         |                 | TAILGATE LOCK COVER                    | 1   | 15.70                   | 15.70          | 25.00  | 11.77           | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In     | Main         |         |                 | TAILGATE OUTSIDE GARNISH               | 1   | 504.90                  | 504.90         | 25.00  | 378.67          | Replace        | 1                 | 378.67                   | Replace        | ✓ OR    |
| One Time Key In     | Main         |         |                 | STRIKER, BACK DOOR                     | 1   | 48.90                   | 48.90          | 25.00  | 36.67           | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In     | Main         |         |                 | TAILGATE TRIM, LH                      | 1   | 85.90                   | 85.90          | 25.00  | 64.43           | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |
| One Time Key In     | Main         |         |                 | TAILGATE TRIM, LOWER                   | 1   | 180.70                  | 180.70         | 25.00  | 135.52          | Replace        | 0                 | 0                        | Not Give       | ✗ NN    |

Total Spare Part Cost 24,276.03

Surveyor Total 9,165.18

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 19,420.82

Final Sur Total 7,332.14

| SMRT Recommendation   |              |         |                 |                                 |     |                         |                |        |                 | Surveyor Approval        |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|---------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                       | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/Replace           | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | TAILGATE, BOARD ASSY            | 1   | 246.90                  | 246.90         | 25.00  | 185.18          | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| One Time Key In       | Main         |         |                 | WIRE, BACK DOOR, NO.1           | 1   | 582.40                  | 582.40         | 10.00  | 524.16          | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| One Time Key In       | Main         |         |                 | ARM, RR WIPER                   | 1   | 84.70                   | 84.70          | 25.00  | 63.53           | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| One Time Key In       | Main         |         |                 | BLADE ASSY, REAR WIPER          | 1   | 55.00                   | 55.00          | 25.00  | 41.25           | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| One Time Key In       | Main         |         |                 | EMBLEM REAR                     | 1   | 60.30                   | 60.30          | 25.00  | 45.22           | Replace                  | 1                 | 45.22/3                  | Replace        | * / APC |
| One Time Key In       | Main         |         |                 | NAME PLATE (HYBRID)             | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace                  | 1                 | 38.92/3                  | Replace        | * / APC |
| One Time Key In       | Main         |         |                 | NAME PLATE (PRNUS)              | 1   | 60.80                   | 60.80          | 25.00  | 45.60           | Replace                  | 1                 | 45.60                    | Replace        | * / APC |
| One Time Key In       | Main         |         |                 | NAME PLATE (TOYOTA)             | 1   | 51.90                   | 51.90          | 25.00  | 38.92           | Replace                  | 1                 | 38.92/3                  | Replace        | * / APC |
| One Time Key In       | Main         |         |                 | SPOILER REAR                    | 1   | 953.70                  | 953.70         | 25.00  | 715.28          | Replace                  | 1                 | 715.28                   | Replace        | * / OR  |
| One Time Key In       | Main         |         |                 | 3RD BRAKE LAMP                  | 1   | 231.30                  | 231.30         | 10.00  | 208.17          | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| One Time Key In       | Main         |         |                 | SMRT LOGO                       | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace                  | 1                 | 7.80                     | Replace        | * / APC |
| One Time Key In       | Main         |         |                 | STICKER DECAL 6555 8888         | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace                  | 1                 | 21.60                    | Replace        | * / APC |
| One Time Key In       | Main         |         |                 | ROOF PANEL                      | 1   | 1,102.80                | 1,102.80       | 25.00  | 827.10          | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| One Time Key In       | Main         |         |                 | MLDG DRIP RH, ROOF              | 1   | 78.80                   | 78.80          | 25.00  | 59.10           | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| One Time Key In       | Main         |         |                 | END PANEL                       | 1   | 602.10                  | 602.10         | 25.00  | 451.58          | Replace                  | 1                 | 451.58                   | Replace        | * / OR  |
| One Time Key In       | Main         |         |                 | END PANEL COVER, DECK TRIM HOLE | 1   | 46.10                   | 46.10          | 25.00  | 34.58           | Replace                  | 0                 | 0                        | Not Give       | * X NAI |
| Total Spare Part Cost |              |         |                 |                                 |     |                         |                |        | 24,276.03       | Surveyor Total 9,165.18  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                 |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                 |     |                         |                |        | 19,420.82       | Final Sur Total 7,332.14 |                   |                          |                |         |

| SMRT Recommendation   |              |         |                 |                                |     |                         |                |        |                 | Surveyor Approval        |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|--------------------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                      | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | END PANEL COVER, DECK TRIM, RR | 1   | 121.10                  | 121.10         | 25.00  | 90.82           | Replace                  | 1                 | 90.82                    | Replace        | ✓ CR4   |
| One Time Key In       | Main         |         |                 | REINFORCEMENT, RR              | 1   | 34.60                   | 34.60          | 25.00  | 25.95           | Replace                  | 0                 | 0                        | Not Give       | ✗ N/A   |
| One Time Key In       | Main         |         |                 | SEALANT SIKAFLEX               | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace                  | 1                 | 37.00                    | Replace        | ✓ APC   |
| One Time Key In       | Main         |         |                 | SPARE TYRE PANEL               | 1   | 667.70                  | 667.70         | 25.00  | 500.78          | Replace                  | 1                 | 0                        | Repair         | ✗ X R   |
| One Time Key In       | Main         |         |                 | MEMBER SUB-ASSY, RR RH         | 1   | 174.10                  | 174.10         | 25.00  | 130.57          | Replace                  | 0                 | 0                        | Check          | ✗ X N/A |
| One Time Key In       | Main         |         |                 | FLOOR PANEL RR/RH              | 1   | 209.90                  | 209.90         | 25.00  | 157.43          | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| One Time Key In       | Main         |         |                 | BOX, DECK FLOOR, RR            | 1   | 649.70                  | 649.70         | 25.00  | 487.28          | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| One Time Key In       | Main         |         |                 | BOX, RR FLOOR, BOARD           | 1   | 679.60                  | 679.60         | 25.00  | 509.70          | Replace                  | 1                 | 509.70                   | Replace        | ✓ CR4   |
| One Time Key In       | Main         |         |                 | BOARD, RR FLOOR                | 1   | 392.30                  | 392.30         | 25.00  | 294.23          | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| One Time Key In       | Main         |         |                 | BOARD ASSY, RR RH              | 1   | 379.20                  | 379.20         | 25.00  | 284.40          | Replace                  | 1                 | 284.40                   | Replace        | ✓ CR4   |
| One Time Key In       | Main         |         |                 | SPACER, RR FLOOR               | 1   | 130.60                  | 130.60         | 25.00  | 97.95           | Replace                  | 1                 | 97.95                    | Replace        | ✓ CR4   |
| One Time Key In       | Main         |         |                 | COVER ASSY, TONNEAU            | 1   | 602.10                  | 602.10         | 25.00  | 451.58          | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| One Time Key In       | Main         |         |                 | CUSHION, SPARE WHEEL           | 1   | 230.80                  | 230.80         | 25.00  | 173.10          | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| One Time Key In       | Main         |         |                 | PROTECTOR, SPARE               | 1   | 143.70                  | 143.70         | 25.00  | 107.77          | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| One Time Key In       | Main         |         |                 | CARRIER, SPARE                 | 1   | 19.70                   | 19.70          | 25.00  | 14.77           | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| One Time Key In       | Main         |         |                 | CAP SUB-ASSY, WHEEL            | 4   | 174.10                  | 696.40         | 25.00  | 522.30          | Replace                  | 0                 | 0                        | Not Give       | ✗ X N/A |
| Total Spare Part Cost |              |         |                 |                                |     |                         |                |        | 24,276.03       | Surveyor Total 9,165.18  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                                |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                                |     |                         |                |        | 19,420.82       | Final Sur Total 7,332.14 |                   |                          |                |         |

| SMRT Recommendation |              |         |                 |                         |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|---------------------|--------------|---------|-----------------|-------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type            | Costing Type | Portion | Material Number | Part Name               | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/Replace    | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In     | Main         |         |                 | BREAKDOWN SIGN          | 1   | 35.00                   | 35.00          | 0.00   | 35.00           | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | PANEL ASSY, DECK RH     | 1   | 307.00                  | 307.00         | 25.00  | 230.25          | Replace           | 1                 | 230.25                   | Replace        | * / CR  |
| One Time Key In     | Main         |         |                 | GARNISH SIDE UPPER, LHR | 1   | 261.70                  | 261.70         | 25.00  | 196.27          | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | BATTERY                 | 1   | 278.00                  | 278.00         | 10.00  | 250.20          | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | BATTERY CLAMP           | 1   | 16.10                   | 16.10          | 25.00  | 12.08           | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | BATTERY TRAY            | 1   | 42.80                   | 42.80          | 25.00  | 32.10           | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | WIRE, FRAME             | 1   | 1,680.90                | 1,680.90       | 10.00  | 1,512.81        | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | WIRE, ENGINE, NO.3      | 1   | 74.00                   | 74.00          | 10.00  | 66.60           | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | WIRE, FLOOR             | 1   | 1,675.00                | 1,675.00       | 10.00  | 1,507.50        | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | WIRE, FLOOR, NO.2       | 1   | 1,305.40                | 1,305.40       | 10.00  | 1,174.86        | Replace           | 0                 | 0                        | Not Give       | * X N/A |
| One Time Key In     | Main         |         |                 | PANEL SUB-ASSY, QTR     | 1   | 326.70                  | 326.70         | 25.00  | 245.02          | Replace           | 0                 | 0                        | Check          | * X N/A |
| One Time Key In     | Main         |         |                 | PANEL SUB-ASSY, QTR     | 1   | 588.40                  | 588.40         | 25.00  | 441.30          | Replace           | 0                 | 0                        | Check          | * X N/A |
| One Time Key In     | Main         |         |                 | TAIL LAMP BRACKET, RH   | 1   | 30.70                   | 30.70          | 25.00  | 23.02           | Replace           | 1                 | 23.02                    | Replace        | * / OR  |
| One Time Key In     | Main         |         |                 | TAIL LAMP RH            | 1   | 557.80                  | 557.80         | 10.00  | 502.02          | Replace           | 1                 | 502.02                   | Replace        | * / OR  |
| One Time Key In     | Main         |         |                 | TROUGH, BACK DOOR       | 1   | 110.90                  | 110.90         | 25.00  | 83.18           | Replace           | 1                 | 83.18                    | Replace        | * / OR  |
| One Time Key In     | Main         |         |                 | FENDER RR/RH            | 1   | 766.80                  | 766.80         | 25.00  | 575.10          | Replace           | 1                 | 575.10                   | Replace        | * / OR  |

Total Spare Part Cost 24,276.03

Surveyor Total 9,165.18

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 19,420.82

Final Sur Total 7,332.14

| SMRT Recommendation   |              |         |                 |                                 |     |                         |                |        |                 | Surveyor Approval |                   |                          |                |         |
|-----------------------|--------------|---------|-----------------|---------------------------------|-----|-------------------------|----------------|--------|-----------------|-------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name                       | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace   | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | SMRT LOGO                       | 1   | 7.80                    | 7.80           | 0.00   | 7.80            | Replace           | 1                 | 7.80                     | Replace        | • / NPC |
| One Time Key In       | Main         |         |                 | STICKER DECAL 8555 8888         | 1   | 21.60                   | 21.60          | 0.00   | 21.60           | Replace           | 1                 | 21.60                    | Replace        | • / NPC |
| One Time Key In       | Main         |         |                 | FENDER LINER RR/RH              | 1   | 141.30                  | 141.30         | 25.00  | 105.98          | Replace           | 1                 | 105.98                   | Replace        | • / CR4 |
| One Time Key In       | Main         |         |                 | REINFORCEMENT, BACK             | 1   | 89.50                   | 89.50          | 25.00  | 67.13           | Replace           | 0                 | 0                        | Check          | • X NAI |
| One Time Key In       | Main         |         |                 | REINFORCEMENT, BELT             | 1   | 103.20                  | 103.20         | 25.00  | 77.40           | Replace           | 0                 | 0                        | Check          | • X NAI |
| One Time Key In       | Main         |         |                 | REINFORCEMENT, ROOF             | 1   | 60.30                   | 60.30          | 25.00  | 45.22           | Replace           | 0                 | 0                        | Not Give       | • X NAI |
| One Time Key In       | Main         |         |                 | REINFORCE, ROOF SIDE            | 1   | 91.90                   | 91.90          | 25.00  | 68.93           | Replace           | 0                 | 0                        | Not Give       | • X NAI |
| One Time Key In       | Main         |         |                 | PANEL, ROOF SIDE,               | 1   | 134.80                  | 134.80         | 25.00  | 101.10          | Replace           | 0                 | 0                        | Not Give       | • X NAI |
| One Time Key In       | Main         |         |                 | EXTENSION, QUARTER              | 1   | 55.70                   | 55.70          | 25.00  | 41.78           | Replace           | 1                 | 41.78                    | Replace        | • / NPC |
| One Time Key In       | Main         |         |                 | EXTENSION, QUARTER              | 1   | 83.50                   | 83.50          | 25.00  | 62.63           | Replace           | 1                 | 62.63                    | Replace        | • / NPC |
| One Time Key In       | Main         |         |                 | DUCT ASSY, QUARTER              | 1   | 70.40                   | 70.40          | 25.00  | 52.80           | Replace           | 1                 | 52.80                    | Replace        | • / BR  |
| One Time Key In       | Main         |         |                 | PANEL, ROOF SIDE INNER FRONT RH | 1   | 134.80                  | 134.80         | 25.00  | 101.10          | Replace           | 0                 | 0                        | Not Give       | • X NAI |
| One Time Key In       | Main         |         |                 | PANEL, ROOF SIDE OUTER RH       | 1   | 134.80                  | 134.80         | 25.00  | 101.10          | Replace           | 0                 | 0                        | Not Give       | • X NAI |
| One Time Key In       | Main         |         |                 | RAIL, ROOF SIDE                 | 1   | 273.60                  | 273.60         | 25.00  | 205.20          | Replace           | 0                 | 0                        | Not Give       | • X NAI |
| One Time Key In       | Main         |         |                 | QUARTER GLASS RR/RH             | 1   | 646.50                  | 646.50         | 25.00  | 634.88          | Replace           | 1                 | 634.88                   | Replace        | • / NPC |
| One Time Key In       | Main         |         |                 | SEALANT W/SCREEN                | 1   | 37.00                   | 37.00          | 0.00   | 37.00           | Replace           | 1                 | 37.00                    | Replace        | • / NPC |
| Total Spare Part Cost |              |         |                 |                                 |     |                         |                |        | 24,276.03       | Surveyor Total    |                   | 9,165.18                 |                |         |
| Lump Sum Discount (%) |              |         |                 |                                 |     |                         |                |        | 20.00           | Lump Sum Dis (%)  |                   | 20                       |                |         |
| Final Spare Part Cost |              |         |                 |                                 |     |                         |                |        | 19,420.82       | Final Sur Total   |                   | 7,332.14                 |                |         |

| SMRT Recommendation   |              |         |                 |                      |     |                         |                |        |                 |                          | Surveyor Approval |                          |                |         |
|-----------------------|--------------|---------|-----------------|----------------------|-----|-------------------------|----------------|--------|-----------------|--------------------------|-------------------|--------------------------|----------------|---------|
| BOM Type              | Costing Type | Portion | Material Number | Part Name            | Qty | List Price Per Unit(\$) | List Price(\$) | Dis(%) | Final Price(\$) | Repair/ Replace          | Surveyor Quantity | Surveyor Final Price(\$) | Repair/Replace | Remarks |
| One Time Key In       | Main         |         |                 | DOOR RR/RH           | 1   | 954.50                  | 954.50         | 25.00  | 715.88          | Replace                  | 1                 | 0                        | Repair         | * X R   |
| One Time Key In       | Main         |         |                 | DOOR LOCK RR/RH      | 1   | 709.30                  | 709.30         | 25.00  | 531.97          | Replace                  | 0                 | 0                        | Not Give       | * X NM  |
| One Time Key In       | Main         |         |                 | CHECK ASSY, RR DOOR, | 1   | 150.30                  | 150.30         | 25.00  | 112.73          | Replace                  | 0                 | 0                        | Not Give       | * X NM  |
| One Time Key In       | Main         |         |                 | TYRE                 | 1   | 126.74                  | 126.74         | 0.00   | 126.74          | Replace                  | 0                 | 0                        | Not Give       | * X NM  |
| One Time Key In       | Main         |         |                 | FENDER LINER RR/LH   | 1   | 141.30                  | 141.30         | 25.00  | 105.98          | Replace                  | 0                 | 0                        | Not Give       | * X NM  |
| Total Spare Part Cost |              |         |                 |                      |     |                         |                |        | 24,276.03       | Surveyor Total 9,165.18  |                   |                          |                |         |
| Lump Sum Discount (%) |              |         |                 |                      |     |                         |                |        | 20.00           | Lump Sum Dis (%) 20      |                   |                          |                |         |
| Final Spare Part Cost |              |         |                 |                      |     |                         |                |        | 19,420.82       | Final Sur Total 7,332.14 |                   |                          |                |         |

#### Labour's Cost Detail

| S.No.  | Costing Type | Job Scope                 | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|---------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO REPAIR RH REAR PORTION | 1,690.00                | 1,200                   |         |
| Total: |              |                           | 1,690.00                | 1,200.00                |         |

$$+ 80 + 200 (\text{Supp}) = 1480$$

#### Spray Cost Detail

| S.No.  | Costing Type | Job Scope                           | SMRT Recommendation(\$) | Surveyor Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------|-------------------------|-------------------------|---------|
| 1      | Main         | TO RESPRAY REAR BUMPER              | 378.00                  | 200                     |         |
| 2      | Main         | TO RESPRAY BUMPER BEAM              | 180.00                  | 50                      |         |
| 3      | Main         | TO RESPRAY REAR PANEL               | 180.00                  | 100                     |         |
| 4      | Main         | TO RESPRAY REAR SPARE TYRE PANEL    | 180.00                  | 100                     |         |
| 5      | Main         | TO RESPRAY TAIL GATE                | 378.00                  | 200                     |         |
| 6      | Main         | TO RESPRAY TAILGATE OUTSIDE GARNISH | 180.00                  | 80                      |         |
| 7      | Main         | TO RESPRAY REAR SPOILER             | 180.00                  | 80                      |         |
| 8      | Main         | TO RESPRAY REAR MEMBER RH           | 180.00                  | 0                       |         |
| Total: |              |                                     | 4,590.00                | 1,260.00                |         |

| S.No.  | Coating Type | Job Scope                              | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks                   |
|--------|--------------|----------------------------------------|----------------------------|----------------------------|---------------------------|
| 9      | Main         | TO RESPRAY RH REAR WHEEL HOUSE         | 180.00                     | 0                          |                           |
| 10     | Main         | TO RESPRAY REAR FLOOR SIDE PANEL<br>RH | 180.00                     | 0                          |                           |
| 11     | Main         | TO RESPRAY BATTERY PANEL               | 180.00                     | 0                          |                           |
| 12     | Main         | TO RESPRAY RH RAIL ROOF SIDE           | 180.00                     | 0                          |                           |
| 13     | Main         | TO RESPRAY ROOF TOP PANEL              | 378.00                     | 0                          |                           |
| 14     | Main         | TO RESPRAY TROUGH BACK DOOR RH         | 180.00                     | 50                         | Taillamp panel RH         |
| 15     | Main         | TO RESPRAY REAR FENDER RH              | 378.00                     | 200                        |                           |
| 16     | Main         | RESPRAY WHEEL CAP                      | 720.00                     | 0                          |                           |
| 17     | Main         | TO RESPRAY RH REAR DOOR                | 378.00                     | 200                        |                           |
| Total: |              |                                        | 4,590.00                   | 1,260.00                   | + 100 + 200 (Supp) = 1560 |

#### Other Cost Detail

| S.No.  | Coating Type | Job Scope                                                                     | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|-------------------------------------------------------------------------------|----------------------------|----------------------------|---------|
| 1      | Main         | TOWING CHARGE                                                                 | 126.00                     | 90                         | AK      |
| 2      | Main         | TO CHECK WIRING AND SYSTEM<br>FUNCTION                                        | 80.00                      | 20                         | AK      |
| 3      | Main         | TO APPLY RUST-PROOFING ON<br>AFFECTED AREA                                    | 100.00                     | 20                         | AK      |
| 4      | Main         | TO DO WHEEL ALIGNMENT / TYRE<br>BALANCING                                     | 120.00                     | 60                         | AK      |
| 5      | Main         | TO REMOVE / REFIT SEAT                                                        | 120.00                     | 30                         | AK      |
| 6      | Main         | TO ALIGN CHASSIS                                                              | 350.00                     | 0                          |         |
| 7      | Main         | TO REMOVE & REFIT EXHAUST                                                     | 120.00                     | 0                          |         |
| 8      | Main         | TO PROVIDE LABOUR & MATERIAL FOR<br>SOLAR FILM (NET)                          | 600.00                     | 600.00                     | AK SJ   |
| 9      | Main         | TO TRANSFER REAR TAILGATE<br>MECHANISM                                        | 120.00                     | 20                         | AK      |
| 10     | Main         | TO TEST AND REFIX REVERSE SENSOR<br>SYSTEM                                    | 120.00                     | 20                         | AK      |
| 11     | Main         | TO REMOVE AND INSTALL LUGGAGE<br>COMPARTMENT TRIM TO FACILITATE<br>REPAIR.    | 120.00                     | 30                         | AK      |
| 12     | Main         | TO INSPECT RR LIGHTING,<br>MECHANISMS & WATER TEST RR<br>LIGHTING FOR LEAKAGE | 120.00                     | 20                         | AK      |
| Total: |              |                                                                               | 3,036.00                   | 1,040.00                   |         |

| S.No.  | Costing Type | Job Scope                                          | SMRT<br>Recommendation(\$) | Surveyor<br>Adjustment(\$) | Remarks |
|--------|--------------|----------------------------------------------------|----------------------------|----------------------------|---------|
| 13     | Main         | TO REMOVE AND REFIT TYRE RIM<br>(SPRAYING PURPOSE) | 120.00                     | 20                         | AK      |
| 14     | Main         | TO REMOVE AND REFIT REAR<br>WINDSCREEN             | 240.00                     | 100                        | AK      |
| 15     | Main         | TO REMOVE & REFIT REAR QUARTER<br>GLASS RH         | 120.00                     | 50                         | AK      |
| 16     | Main         | TO REMOVE AND REFIT WIRE HARDESS                   | 300.00                     | 20                         | AK      |
| 17     | Main         | TO REPLACE SUNDRY PARTS                            | 100.00                     | 30                         | AK      |
| 18     | Main         | TO WASH AND VACUUM                                 | 60.00                      | 0                          |         |
| Total: |              |                                                    | 3,036.00                   | 1,040.00                   |         |

+ 90 (towing) + (150) = 1280

## Summary

47974.64

|                          | Estimator Assessment(\$)                                                            | Surveyor Assessment(\$)                                                              |
|--------------------------|-------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------|
| Total Spare Part Detail  | 19,420.82                                                                           | 7,332.14                                                                             |
| Total Labour Cost        | 1,690.00                                                                            | 1,200.00                                                                             |
| Total Spray Painting     | 4,590.00                                                                            | 1,260.00                                                                             |
| Other                    | 3,036.00                                                                            | 1,040.00                                                                             |
| Overall Total            | 28,736.82                                                                           | 10,832.14                                                                            |
| Lump Sum Repair Option   |                                                                                     |                                                                                      |
| Lump Sum Total           | 28,750.00                                                                           | 10,850.00                                                                            |
| Surveyor Approved Amount |                                                                                     | 10,850.00                                                                            |
| No of Repair Days*       | 14                                                                                  | ✓ 14                                                                                 |
| Remarks                  |                                                                                     | L/S repair, take after spray. Request Purchase Value                                 |
| Surveyor Name            |                                                                                     | STEVE CHEN                                                                           |
| Signature                |  |  |
| Survey Date              | 25/09/2019                                                                          |                                                                                      |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# **REQUEST FOR SUPPLEMENT PARTS**

|                      |                |                                   |            |
|----------------------|----------------|-----------------------------------|------------|
| Contractor:          |                |                                   |            |
| Accident Case Number | TAX/09/19/2000 | Date of Collection                | 1 1        |
| Vehicle No           | SHC 4173 Y     | Date of Request                   | 01/10/2019 |
| Vehicle Model        | TOYOTA PRIMS   | Number of Days to Extend (If any) | 4          |

PHOTO  
1/10/19

| S/N  | Part Number      | Part Description        | Quantity | Unit Price |       |
|------|------------------|-------------------------|----------|------------|-------|
| 5611 | 5612             | TAILGATE HINGE RH       | 1pc      | \$ 43.73   | / OO  |
|      | 5613             | TAILGATE HINGE LH       | 1pc      | \$ 43.73   | / OO  |
| 5635 | 5636, 5637       | TAILGATE BOARD ASSY     | 1pc      | \$ 185.18  | / CR4 |
| 5639 | 5640, 5641, 5642 | BOX/DECK FLOOR REAR     | 1pc      | \$ 487.28  | / OR  |
| 5643 | 5644, 5645       | BOARD, REAR FLOOR       | 1pc      | \$ 294.23  | / OR  |
| 5625 | 5626, 5628       | CARNISH SIDE UPPER, RHR | 1pc      | \$ 192.30  | / CR4 |

<<<Please submit photographs for damaged parts>>>

I, (Name) Steve (LKK)

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.



1/10/19, 7:55 pm

Signature of person making this declaration  
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO                                       | Date of submission                        |

pg 1/2

# REQUEST FOR SUPPLEMENT PARTS

|                      |                |                                   |            |
|----------------------|----------------|-----------------------------------|------------|
| Contractor:          |                |                                   |            |
| Accident Case Number | TAX/09/19/2070 | Date of Collection                | 1 1        |
| Vehicle No           | SHC 4133 Y     | Date of Request                   | 01/10/2019 |
| Vehicle Model        | TOYOTA PRIUS   | Number of Days to Extend (If any) | 4          |


| S/N        | Part Number | Part Description                          | Quantity | Unit Price |         |
|------------|-------------|-------------------------------------------|----------|------------|---------|
| 5632       | 5633        | BATTERY                                   | 1pc      | \$250.20   | / CRU   |
| 5618, 5619 | 5620, 5621  | HV BATTERY                                | 1pc      | \$4989.96  | / BR/DO |
| 5649       | 5648        | LABOR TO REPAIR ROOF TOP PANEL            |          | \$200      | 80/     |
| 5649       | 5653, 5657  | LABOR TO SPRAY ROOF TOP PANEL             |          | \$378      | 200/    |
| 5623       |             | LABOR TO REPAIR WHEEL HOUSE PANEL REAR RH |          | \$200      | ✓       |
| 5624       |             | LABOR TO SPRAY WHEELHOUSE PANEL REAR RH   |          | \$200      | 100/    |

\*\*\*Please submit photographs for damaged parts\*\*\*

I, (Name) Stan (LKK)

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

 1/10/19 7:55pm  
Signature of person making this declaration  
(to be signed in front of an authorized witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO                                       | Date of submission                        |

PG 3

# **REQUEST FOR SUPPLEMENT PARTS**

|                      |                |                                   |            |
|----------------------|----------------|-----------------------------------|------------|
| Contractor           |                |                                   |            |
| Accident Case Number | TDK/09/19/2070 | Date of Collection                | 1 / 1      |
| Vehicle No           | SHL 4173 Y     | Date of Request                   | 01/10/2019 |
| Vehicle Model        | TOYOTA PRIUS   | Number of Days to Extend (If any) | 4          |

| S/N | Part Number | Part Description                    | Quantity | Unit Price |
|-----|-------------|-------------------------------------|----------|------------|
|     |             | LABOR TO REMOVE & REFIX HV BATTERY. |          | \$ 350     |
|     |             |                                     |          |            |
|     |             |                                     |          |            |
|     |             |                                     |          |            |
|     |             |                                     |          |            |
|     |             |                                     |          |            |
|     |             |                                     |          |            |

150 /

<<<Please attach photographs for damaged parts>>>

I, (Name) Stem (LKK)

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

  
 11/10/19 7:55pm  
 Signature of person making this declaration  
 (to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

|                 |                                                |                                           |
|-----------------|------------------------------------------------|-------------------------------------------|
| Acknowledge By  | ARC Executive / Supervisor / SA                |                                           |
| Approval By     | Surveyor / In-house Staff                      |                                           |
| Parts Ordering  | SMRT Store / Contractor Supply / Form 22 / WOC | Form 22 / PO / WOC / Reservation / Number |
| Photo Submitted | YES / NO                                       | Date of submission                        |


953/3

### Section A - Accident Details

|                                    |                        |
|------------------------------------|------------------------|
| Registration Number                | SHC4173Y               |
| Case Reference Number              | TAX/09/19/2090         |
| Registration Date                  | 29/11/2013             |
| Company Type                       | SMRT Taxis Pte Ltd     |
| Make                               | TOYOTA                 |
| Model                              | PRIUS                  |
| Name of Driver                     | SEE TOH WING HOY       |
| Type of Accident                   | Head to Rear           |
| Accident Date and Time             | 19/9/2019 4:55 PM      |
| Accident Reported Date and Time    | 24/9/2019 4:19 PM      |
| Is Surveyor Required?              | Yes                    |
| Survey by                          |                        |
| Vehicle is Towed Back?             | Yes                    |
| Towed Back Date and Time           | 19/9/2019 4:56 PM      |
| Replacement Vehicle Issued?        | No                     |
| Job Card Number                    | 24103512               |
| Special Instruction to ARC, if any | TOWED \$90(KING DOLLY) |
| Prepared Date and Time             | 25/9/2019 10:36 AM     |
| Chassis Number                     |                        |
| Mileage                            |                        |
| Work Shop                          |                        |
| Repair Completion Date and Time    |                        |

### Section B - Summary of Repair Estimates

#### Summary of Repair Estimates

|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Total Labour Cost            | \$2,090.00                                                                          | \$1,480.00                                                                          |
| Total Spray Cost             | \$5,148.00                                                                          | \$1,560.00                                                                          |
| Total Spare Part Cost        | \$24,610.10                                                                         | \$12,521.51                                                                         |
| Total Other Cost             | \$3,385.00                                                                          | \$1,280.00                                                                          |
| <b>TOTAL COST</b>            | <b>\$35,234.10</b>                                                                  | <b>\$16,841.51</b>                                                                  |
| Lump Sum Total               | \$35,250.00                                                                         | \$16,850.00 (L/S)                                                                   |
| Number of Repair Days        | 15.0                                                                                | 14.0                                                                                |
| Prepared / Adjusted By       | Tuck Foo Kok                                                                        | STEVE CHEN (LKK) / QBE                                                              |
| ARC / Surveyor Sign Off Date | 03/10/2019 9:01 AM                                                                  | 02/10/2019 1:34 PM                                                                  |
| Signature                    |  |  |
| Remarks                      | Total number of repair days = 14 days.<br>SUP = + 4 days.                           | L/S repair, take after spray. Request<br>Purchase Value. Repair Limit \$15,000.00   |

## Section C - Quotation and Accident Invoice Details

|                  |              |                |  |
|------------------|--------------|----------------|--|
| Quotation Number | QN-1910-0498 | Invoice Number |  |
| Quotation Date   | 26.10.2019   | Invoice Date   |  |
| Invoice Amount   |              | Prepared Date  |  |

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

| Job Scope                     | Quotation from AR | Adjusted by Surveyor, if applicable |
|-------------------------------|-------------------|-------------------------------------|
| TO REPAIR ROOF TOP PANEL      | \$200.00          | \$80.00 (Supp)                      |
| TO REPAIR RH REAR WHEEL HOUSE | \$200.00          | \$200.00 (Supp)                     |
| TO REPAIR RH REAR PORTION     | \$1,690.00        | \$1,200.00                          |
| <b>Total Labour</b>           | <b>\$2,090.00</b> | <b>\$1,480.00</b>                   |

## Part 2 - Spray Painting &amp; Panel Beating Related Works

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY RH REAR WHEEL HOUSE                  | \$180.00           | \$100.00 (Supp)                     |
| TO RESPRAY ROOF TOP PANEL                       | \$378.00           | \$200.00 (Supp)                     |
| TO RESPRAY REAR BUMPER                          | \$378.00           | \$200.00                            |
| TO RESPRAY BUMPER BEAM                          | \$180.00           | \$50.00                             |
| TO RESPRAY REAR PANEL                           | \$180.00           | \$100.00                            |
| TO RESPRAY REAR SPARE TYRE PANEL                | \$180.00           | \$100.00                            |
| TO RESPRAY TAIL GATE                            | \$378.00           | \$200.00                            |
| TO RESPRAY TAILGATE OUTSIDE GARNISH             | \$180.00           | \$80.00                             |
| TO RESPRAY REAR SPOILER                         | \$180.00           | \$80.00                             |
| TO RESPRAY REAR MEMBER, RH                      | \$180.00           | \$0.00                              |
| TO RESPRAY RH REAR WHEEL HOUSE                  | \$180.00           | \$0.00                              |
| TO RESPRAY REAR FLOOR SIDE PANEL RH             | \$180.00           | \$0.00                              |
| TO RESPRAY BATTERY PANEL                        | \$180.00           | \$0.00                              |
| TO RESPRAY RH RAIL ROOF SIDE                    | \$180.00           | \$0.00                              |
| TO RESPRAY ROOF TOP PANEL                       | \$378.00           | \$0.00                              |
| TO RESPRAY TROUGH BACK DOOR RH                  | \$180.00           | \$50.00                             |
| TO RESPRAY REAR FENDER RH                       | \$378.00           | \$200.00                            |
| RESPRAY WHEEL CAP                               | \$720.00           | \$0.00                              |
| TO RESPRAY RH REAR DOOR                         | \$378.00           | \$200.00                            |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$5,148.00</b>  | <b>\$1,560.00</b>                   |

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-----------------------------------------|--------------------|-------------------------------------|
| TOWING CHARGE                           | \$126.00           | \$90.00 (Add)                       |
| TO CHECK WIRING AND SYSTEM FUNCTION     | \$80.00            | \$20.00                             |
| TO APPLY RUST-PROOFING ON AFFECTED AREA | \$100.00           | \$20.00                             |
| TO DO WHEEL ALIGNMENT / TYRE BALANCING  | \$120.00           | \$60.00                             |
| TO REMOVE / REFIT SEAT                  | \$120.00           | \$30.00                             |

|                                                                         |                   |                   |
|-------------------------------------------------------------------------|-------------------|-------------------|
| TO ALIGN CHASSIS                                                        | \$350.00          | \$0.00            |
| TO REMOVE & REFIT EXHAUST                                               | \$120.00          | \$0.00            |
| TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)                       | \$600.00          | \$600.00          |
| TO TRANSFER REAR TAILGATE MECHANISM                                     | \$120.00          | \$20.00           |
| TO TEST AND REFIX REVERSE SENSOR SYSTEM                                 | \$120.00          | \$20.00           |
| TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.    | \$120.00          | \$30.00           |
| TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE | \$120.00          | \$20.00           |
| TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)                         | \$120.00          | \$20.00           |
| TO REMOVE AND REFIX REAR WINDSCREEN                                     | \$240.00          | \$100.00          |
| TO REMOVE & REFIT REAR QUARTER GLASS RH                                 | \$120.00          | \$50.00           |
| TO REMOVE AND REFIT WIRE HARDESS                                        | \$300.00          | \$20.00           |
| TO REPLACE SUNDRY PARTS                                                 | \$100.00          | \$30.00           |
| TO WASH AND VACUUM                                                      | \$60.00           | \$0.00            |
| TO REMOVE AND REFIT BATTERY ASSY HV                                     | \$350.00          | \$150.00 (SVP)    |
| <b>Total Other Costs</b>                                                | <b>\$3,386.00</b> | <b>\$1,280.00</b> |

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number | Part Name                           | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|-------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52159-47905  | BUMPER REAR                         | 1.00     | \$458.60        | 25.00        | \$343.95         | Replace            | Replace ✓         |
|             |         | 52161-16010  | BUMPER CLIPS                        | 10.00    | \$1.61          | 25.00        | \$12.08          | Replace            | Replace ✓         |
|             |         | 52023-12240  | BUMPER REINFORCEMENT REAR           | 1.00     | \$205.70        | 25.00        | \$154.28         | Replace            | Replace ✓         |
|             |         | 52016-47030  | ARM SUB-ASSY, RR BUMPER LH          | 0.00     | \$139.60        | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         | 52015-47050  | ARM SUB-ASSY, RR BUMPER RH          | 1.00     | \$139.60        | 25.00        | \$104.70         | Replace            | Replace ✓         |
|             |         | 89997-30070  | ANTENNA, ELECTRICAL LOWER REAR      | 0.00     | \$157.40        | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         |              | SENSOR REVERSE                      | 1.00     | \$180.00        | 0.00         | \$180.00         | Replace            | Replace ✓         |
|             |         |              | PIXEL STICKER                       | 2.00     | \$60.00         | 0.00         | \$120.00         | Replace            | Replace ✓         |
|             |         | 76088-47020  | BUMPER LIP COVER RR/LH              | 0.00     | \$72.20         | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         | 76087-47020  | BUMPER LIP COVER RR/RH              | 1.00     | \$118.10        | 25.00        | \$88.58          | Replace            | Replace ✓         |
|             |         | 76891-47020  | BUMPER LIP REAR                     | 1.00     | \$228.90        | 25.00        | \$171.68         | Replace            | Replace ✓         |
|             |         | 52592-47021  | BUMPER SEAL, RR LH                  | 0.00     | \$88.90         | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         | 52591-47021  | BUMPER SEAL, RR RH                  | 1.00     | \$65.70         | 25.00        | \$49.28          | Replace            | Replace ✓         |
|             |         | 52576-47020  | BUMPER SIDE RETAINER RR/LH          | 1.00     | \$94.80         | 25.00        | \$71.10          | Replace            | Replace ✓         |
|             |         | 52575-47020  | BUMPER SIDE RETAINER RR/RH          | 1.00     | \$94.80         | 25.00        | \$71.10          | Replace            | Replace ✓         |
|             |         | 58308-47011  | UNDER COVER SUBASSY, RR FLOOR       | 0.00     | \$514.50        | 0.00         | \$0.00           | Replace            | Not Given ✓       |
|             |         | 58327-47020  | EXHAUST HEAT SHIELD, REAR           | 0.00     | \$107.40        | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         | 17430-37380  | EXHAUST TAIL PIPE                   | 0.00     | \$656.20        | 0.00         | \$0.00           | Replace            | Not Given ✓       |
|             |         | 17565-28010  | SUPPORT EXHAUST PIPE, NO.4          | 0.00     | \$40.30         | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         | 17565-22030  | SUPPORT, EXHAUST REAR               | 0.00     | \$33.60         | 0.00         | \$0.00           | Replace            | Not Given X       |
|             |         | 67005-47241  | TAILGATE ASY                        | 1.00     | \$1,007.90      | 25.00        | \$755.93         | Replace            | Replace ✓         |
|             |         | 56117-50140  | DAM, BACK DOOR GLASS ADHESIVE, NO.1 | 1.00     | \$27.30         | 25.00        | \$20.48          | Replace            | Replace ✓         |
|             |         | 75574-47020  | TAIL GATE DOOR GLASS MOULDING, LH   | 1.00     | \$29.40         | 25.00        | \$22.05          | Replace            | Replace ✓         |

# SMRT Accident Vehicle Repair Estimates

|                                                   |
|---------------------------------------------------|
| SMRT Automotive Services Pte Ltd                  |
| 50 Woodlands Industrial Park E4, Singapore 757605 |
| FAX Number : 63655502                             |
| Estimator Telephone Number : 66562023             |
| Accident Reporting Number : 68652072              |

Date Generated : 05/11/2019

User ID : PehBuan

|                |                                     |      |            |        |          |         |           |   |
|----------------|-------------------------------------|------|------------|--------|----------|---------|-----------|---|
| 75573-47080    | TAIL GATE DOOR GLASS MOULDING, RH   | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
| 75575-47030    | MOULDING BACK WINDOW, LOWER NO.1    | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
| 68294-47050    | DAM, BACK DOOR GLASS ADHESIVE, NO.2 | 1.00 | \$17.40    | 25.00  | \$13.05  | Replace | Replace   | ✓ |
| 75575-47020    | MOULDING, BACK WINDOW, LOWER NO.2   | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
| 75574-47010    | MOULDING, BACK WINDOW, OUTSIDE LH   | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
| 75573-47090    | MOULDING, BACK WINDOW, OUTSIDE RH   | 1.00 | \$29.40    | 25.00  | \$22.05  | Replace | Replace   | ✓ |
| 68105-47122    | TAILGATE DOOR GLASS                 | 1.00 | \$1,090.90 | 25.00  | \$818.18 | Replace | Replace   | ✓ |
| 64821-47030    | TAILGATE LOWER WINDOW GLASS         | 1.00 | \$721.30   | 25.00  | \$540.98 | Replace | Replace   | ✓ |
|                | SEALANT W/SCREEN                    | 3.00 | \$37.00    | 0.00   | \$111.00 | Replace | Replace   | ✓ |
| 68810-47010    | TAILGATE DOOR HINGE LH/RH           | 0.00 | \$58.30    | 0.00   | \$0.00   | Replace | Not Given | X |
| 69350-47030    | TAILGATE DOOR LOCK                  | 0.00 | \$444.10   | 0.00   | \$0.00   | Replace | Not Given | X |
| 68960-0W532    | TAILGATE DOOR STAY LH               | 0.00 | \$241.50   | 0.00   | \$0.00   | Replace | Not Given | X |
| 68950-0W542    | TAILGATE DOOR STAY RH               | 0.00 | \$241.50   | 0.00   | \$0.00   | Replace | Not Given | X |
| 67881-47022    | TAILGATE DOOR WEATHER STRIP         | 1.00 | \$353.40   | 25.00  | \$265.05 | Replace | Replace   | ✓ |
| 69415-47020    | TAILGATE LOCK, COVER                | 0.00 | \$15.70    | 0.00   | \$0.00   | Replace | Not Given | X |
| 76801-47070-B0 | TAILGATE OUTSIDE GARNISH            | 1.00 | \$504.90   | 25.00  | \$378.68 | Replace | Replace   | ✓ |
| 69431-47010    | STRIKER, BACK DOOR                  | 0.00 | \$48.90    | 0.00   | \$0.00   | Replace | Not Given | X |
| 67938-47031C0  | TAILGATE TRIM, LH                   | 0.00 | \$85.90    | 0.00   | \$0.00   | Replace | Not Given | X |
| 67751-47040C0  | TAILGATE TRIM, LOWER                | 0.00 | \$180.70   | 0.00   | \$0.00   | Replace | Not Given | X |
| 67750-47071C0  | TAILGATE, BOARD ASSY                | 0.00 | \$246.90   | 0.00   | \$0.00   | Replace | Not Given | X |
| 82184-47370    | WIRE, BACK DOOR, NO.1               | 0.00 | \$582.40   | 0.00   | \$0.00   | Replace | Not Given | X |
| 85241-47030    | ARM, RR WIPER                       | 0.00 | \$84.70    | 0.00   | \$0.00   | Replace | Not Given | X |
| 85242-47040    | BLADE ASSY, REAR WIPER              | 0.00 | \$55.00    | 0.00   | \$0.00   | Replace | Not Given | X |
| 75310-47020    | EMBLEM REAR                         | 1.00 | \$60.30    | 25.00  | \$45.23  | Replace | Replace   | ✓ |
| 75374-47051    | NAME PLATE (HYBRID)                 | 1.00 | \$51.90    | 25.00  | \$38.93  | Replace | Replace   | ✓ |
| 75442-47030    | NAME PLATE (PRIUS)                  | 1.00 | \$60.80    | 25.00  | \$45.60  | Replace | Replace   | ✓ |
| 75443-47030    | NAME PLATE (TOYOTA)                 | 1.00 | \$51.90    | 25.00  | \$38.93  | Replace | Replace   | ✓ |
| 78085-47910    | SPOILER REAR                        | 1.00 | \$953.70   | 25.00  | \$715.28 | Replace | Replace   | ✓ |
| 81006-47011    | 3RD BRAKE LAMP                      | 0.00 | \$231.30   | 0.00   | \$0.00   | Replace | Not Given | X |
|                | SMRT LOGO                           | 1.00 | \$7.80     | 0.00   | \$7.80   | Replace | Replace   | ✓ |
|                | STICKER DECAL 6555 6868             | 1.00 | \$21.60    | 0.00   | \$21.60  | Replace | Replace   | ✓ |
| 63111-47030    | ROOF PANEL                          | 0.00 | \$1,102.80 | 0.00   | \$0.00   | Replace | Not Given | X |
| 75555-47030    | MLDG DRIP RH, ROOF                  | 0.00 | \$78.80    | 0.00   | \$0.00   | Replace | Not Given | X |
| 58307-47060    | END PANEL                           | 1.00 | \$602.10   | 25.00  | \$451.58 | Replace | Replace   | ✓ |
| 64718-47031B0  | END PANEL COVER, DECK TRIM HOLE     | 0.00 | \$46.10    | 0.00   | \$0.00   | Replace | Not Given | X |
| 64716-47031B0  | END PANEL COVER, DECK TRIM, RR      | 1.00 | \$121.10   | 25.00  | \$90.83  | Replace | Replace   | ✓ |
| 58336-12090    | REINFORCEMENT, RR                   | 0.00 | \$34.60    | 0.00   | \$0.00   | Replace | Not Given | X |
|                | SEALANT SIKAFLEX                    | 1.00 | \$37.00    | 0.00   | \$37.00  | Replace | Replace   | ✓ |
| 58311-47071    | SPARE TYRE PANEL                    | 1.00 | \$667.70   | 100.00 | \$0.00   | Replace | Repair    | ✓ |
| 57603-47030    | MEMBER SUB-ASSY, RR RH              | 0.00 | \$174.10   | 0.00   | \$0.00   | Replace | Check     | X |
| 58302-47030    | FLOOR PANEL RR/RH                   | 0.00 | \$209.90   | 0.00   | \$0.00   | Replace | Not Given | X |

|                |                                 |      |            |       |          |         |           |   |
|----------------|---------------------------------|------|------------|-------|----------|---------|-----------|---|
| 64993-47020    | BOX, DECK FLOOR, RR             | 0.00 | \$649.70   | 0.00  | \$0.00   | Replace | Not Given | X |
| 58416-47030B3  | BOX, RR FLOOR, BOARD            | 1.00 | \$679.60   | 25.00 | \$509.70 | Replace | Replace   |   |
| 58415-47030    | BOARD, RR FLOOR                 | 0.00 | \$392.30   | 0.00  | \$0.00   | Replace | Not Given | X |
| 58490-47140B0  | BOARD ASSY, RR RH               | 1.00 | \$379.20   | 25.00 | \$284.40 | Replace | Replace   |   |
| 58427-47040    | SPACER, RR FLOOR                | 1.00 | \$130.60   | 25.00 | \$97.95  | Replace | Replace   |   |
| 64910-47020-B0 | COVER ASSY, TONNEAU             | 0.00 | \$602.10   | 0.00  | \$0.00   | Replace | Not Given | X |
| 64777-47090    | CUSHION, SPARE WHEEL            | 0.00 | \$230.80   | 0.00  | \$0.00   | Replace | Not Given | X |
| 64778-47050    | PROTECTOR, SPARE                | 0.00 | \$143.70   | 0.00  | \$0.00   | Replace | Not Given | X |
| 51931-47020    | CARRIER, SPARE                  | 0.00 | \$19.70    | 0.00  | \$0.00   | Replace | Not Given | X |
| 42602-47060    | CAP SUB-ASSY, WHEEL             | 0.00 | \$174.10   | 0.00  | \$0.00   | Replace | Not Given | X |
|                | BREAKDOWN SIGN                  | 0.00 | \$35.00    | 0.00  | \$0.00   | Replace | Not Given | X |
| 64730-47031B2  | PANEL ASSY, DECK RH             | 1.00 | \$307.00   | 25.00 | \$230.25 | Replace | Replace   |   |
| 62480-47050-B0 | GARNISH SIDE UPPER, LHR         | 0.00 | \$261.70   | 0.00  | \$0.00   | Replace | Not Given | X |
|                | BATTERY                         | 0.00 | \$278.00   | 0.00  | \$0.00   | Replace | Not Given | X |
| 74481-47050    | BATTERY CLAMP                   | 0.00 | \$16.10    | 0.00  | \$0.00   | Replace | Not Given | X |
| 74440-47030    | BATTERY TRAY                    | 0.00 | \$42.80    | 0.00  | \$0.00   | Replace | Not Given | X |
| 82164-47070    | WIRE, FRAME                     | 0.00 | \$1,680.90 | 0.00  | \$0.00   | Replace | Not Given | X |
| 82123-47040    | WIRE, ENGINE, NO.3              | 0.00 | \$74.00    | 0.00  | \$0.00   | Replace | Not Given | X |
| 82161-47B22    | WIRE, FLOOR                     | 0.00 | \$1,675.00 | 0.00  | \$0.00   | Replace | Not Given | X |
| 82162-47B20    | WIRE, FLOOR, NO.2               | 0.00 | \$1,305.40 | 0.00  | \$0.00   | Replace | Not Given | X |
| 61605-47010    | PANEL SUB-ASSY, QTR             | 0.00 | \$326.70   | 0.00  | \$0.00   | Replace | Check     | X |
| 61607-47060    | PANEL SUB-ASSY, QTR             | 0.00 | \$588.40   | 0.00  | \$0.00   | Replace | Check     | X |
| 52562-47010    | TAIL LAMP BRACKET, RH           | 1.00 | \$30.70    | 25.00 | \$23.03  | Replace | Replace   |   |
| 61551-47180    | TAIL LAMP RH                    | 1.00 | \$557.80   | 10.00 | \$502.02 | Replace | Replace   |   |
| 61621-47030    | TROUGH, BACK DOOR               | 1.00 | \$110.90   | 25.00 | \$83.18  | Replace | Replace   |   |
| 61604-47090    | FENDER RR/RH                    | 1.00 | \$766.80   | 25.00 | \$575.10 | Replace | Replace   |   |
|                | SMRT LOGO                       | 1.00 | \$7.80     | 0.00  | \$7.80   | Replace | Replace   |   |
|                | STICKER DECAL 6555 8888         | 1.00 | \$21.60    | 0.00  | \$21.60  | Replace | Replace   |   |
| 65637-47021    | FENDER LINER RR/RH              | 1.00 | \$141.30   | 25.00 | \$105.98 | Replace | Replace   |   |
| 61743-47010    | REINFORCEMENT, BACK             | 0.00 | \$89.50    | 0.00  | \$0.00   | Replace | Check     | X |
| 61765-47020    | REINFORCEMENT, BELT             | 0.00 | \$103.20   | 0.00  | \$0.00   | Replace | Check     | X |
| 6173747020     | REINFORCEMENT, ROOF             | 0.00 | \$60.30    | 0.00  | \$0.00   | Replace | Not Given | X |
| 61713-47020    | REINFORCE, ROOF SIDE            | 0.00 | \$91.90    | 0.00  | \$0.00   | Replace | Not Given | X |
| 61731-47020    | PANEL, ROOF SIDE,               | 0.00 | \$134.80   | 0.00  | \$0.00   | Replace | Not Given | X |
| 61625-47040    | EXTENSION, QUARTER              | 1.00 | \$55.70    | 25.00 | \$41.78  | Replace | Replace   |   |
| 61623-47010    | EXTENSION, QUARTER              | 1.00 | \$83.50    | 25.00 | \$62.63  | Replace | Replace   |   |
| 62940-16060    | DUCT ASSY, QUARTER              | 1.00 | \$70.40    | 25.00 | \$52.80  | Replace | Replace   |   |
| 61733-47020    | PANEL, ROOF SIDE INNER FRONT RH | 0.00 | \$134.80   | 0.00  | \$0.00   | Replace | Not Given | X |
| 61711-47020    | PANEL, ROOF SIDE OUTER RH       | 0.00 | \$134.80   | 0.00  | \$0.00   | Replace | Not Given | X |
| 61217-47010    | RAIL, ROOF SIDE                 | 0.00 | \$273.60   | 0.00  | \$0.00   | Replace | Not Given | X |
| 62710-47130    | QUARTER GLASS RR/RH             | 1.00 | \$846.50   | 25.00 | \$634.88 | Replace | Replace   |   |

|       |             |                      |      |             |        |            |         |           |   |
|-------|-------------|----------------------|------|-------------|--------|------------|---------|-----------|---|
|       |             | SEALANT W/SCREEN     | 1.00 | \$37.00     | 0.00   | \$37.00    | Replace | Replace   | ✓ |
|       | 67003-47080 | DOOR RR/RH           | 1.00 | \$954.50    | 100.00 | \$0.00     | Replace | Repair    | R |
|       | 69050-47080 | DOOR LOCK RR/RH      | 0.00 | \$709.30    | 0.00   | \$0.00     | Replace | Not Given | X |
|       | 68630-47031 | CHECK ASSY, RR DOOR, | 0.00 | \$150.30    | 0.00   | \$0.00     | Replace | Not Given | X |
|       |             | TYRE                 | 0.00 | \$126.74    | 0.00   | \$0.00     | Replace | Not Given | X |
|       | 65636-47021 | FENDER LINER RR/LH   | 0.00 | \$141.30    | 0.00   | \$0.00     | Replace | Not Given | X |
| Total |             |                      |      | \$30,021.35 |        | \$9,165.28 |         |           |   |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number  | Part Name                 | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |       |
|-------------|---------|---------------|---------------------------|----------|---------------|--------------|------------------|-----------|----------------|-------|
|             |         | 68810-47010   | TAILGATE DOOR HINGE LH/RH | 1.00     | \$58.30       | 25.00        | \$43.73          | Replace   | Replace        | DD    |
|             |         | 68810-47010   | TAILGATE DOOR HINGE LH/RH | 1.00     | \$58.30       | 25.00        | \$43.73          | Replace   | Replace        | DD    |
|             |         | 67750-47071C0 | TAILGATE, BOARD ASSY      | 1.00     | \$246.90      | 25.00        | \$185.18         | Replace   | Replace        | CRU   |
|             |         | 64993-47020   | BOX, DECK FLOOR, RR       | 1.00     | \$649.70      | 25.00        | \$487.28         | Replace   | Replace        | BR    |
|             |         | 58415-47030   | BOARD, RR FLOOR           | 1.00     | \$392.30      | 25.00        | \$294.23         | Replace   | Replace        | BR    |
|             |         | 62470-47110B0 | GARNISH ASSY, ROOF RH     | 1.00     | \$256.40      | 25.00        | \$192.30         | Replace   | Replace        | CRU   |
|             | 15%     |               | BATTERY                   | 1.00     | \$278.00      | 10.00        | \$250.20         | Replace   | Replace        | CRU   |
|             | 15%     | G9510-47060   | BATTERY ASSY, HV          | 1.00     | \$5,544.40    | 10.00        | \$4,989.96       | Replace   | Replace        | BR/DD |
| Total       |         |               |                           |          | 7,484.30      |              | 6,486.61         |           |                |       |

15,651.89

- 202

+ 12,521.51  
+ 1,480.00  
+ 2,840.00

16,841.51

US \$16,850.00  
- \$1,850.00

\$15,000.00

(Repair cost exceed salvage value  
beared by SMRT  
Taxi)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC3/QBE19016977/Eeb3

Date: 26.09.2019

The Motor Claims Department  
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**


**SHC4173Y**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25.09.2019 at the premises of M/s SMRT Automotive Services Pte Ltd and have the following to report:-

|                          |       |           |
|--------------------------|-------|-----------|
| Workshop Estimate Amount | : S\$ | 33,592.03 |
| Revised Estimate Amount  | : S\$ | 12,560.48 |
| "Check" Items Amount     | : S\$ | -         |
| Market Value             | : S\$ | -         |
| LTA Reimbursement Value  | : S\$ | -         |
| Nett Value               | : S\$ | -         |

Description of Damage:  
The vehicle sustained damages at the  
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10 days

Yours faithfully,

STEVE CHEN  
Licensed Appraiser