

Case Details

Case Reference Number : TAX/09/19/2090
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4173Y

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8635-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : QBE Insurance (International) Ltd
Accident Date and Time : 19/09/2019 08:55 AM
Vehicle Age(In Months) : 70

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓ BR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ REC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace	✓ DO
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	X NN
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	X NN
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	X NN
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	✓ BR
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ REC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	X NN
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace	✓ CRN

Total Spare Part Cost	24,276.03	Surveyor Total	9,165.18
Lump Sum Discount (%)	20.00	Lump Sum Dis (%)	20
Final Spare Part Cost	19,420.82	Final Sur Total	7,332.14

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace ▾	/ CRH
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace ▾	/ CRH
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾	/ BR
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾	/ BR
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			SUPPORT EXHAUST PIPE, NO.4	2	40.30	80.60	25.00	60.45	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace ▾	/ DO
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace ▾	/ APC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	/ APC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	/ APC
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	/ APC
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace ▾	/ APC
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	✓ APC
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	✓ APC
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	✓ APC
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	1	818.18	Replace ▾	✓ DR
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace ▾	✓ DR
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace ▾	✓ APC
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	1	265.05	Replace ▾	✓ CRW
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.67	Replace ▾	✓ DR
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Not Give ▾	X NN
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Not Give ▾	X NN
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Give	X N/A
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Not Give	X N/A
One Time Key In	Main			ARM, RR WIPER	1	84.70	84.70	25.00	63.53	Replace	0	0	Not Give	X N/A
One Time Key In	Main			BLADE ASSY, REAR WIPER	1	55.00	55.00	25.00	41.25	Replace	0	0	Not Give	X N/A
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace	/ APC
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ APC
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	/ APC
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	/ APC
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	1	715.28	Replace	/ BR
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	X N/A
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	/ APC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	/ APC
One Time Key In	Main			ROOF PANEL	1	1,102.80	1,102.80	25.00	827.10	Replace	0	0	Not Give	X N/A
One Time Key In	Main			MLDG DRIP RH, ROOF	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	X N/A
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.58	Replace	/ DA
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	X N/A
Total Spare Part Cost									24,276.03	Surveyor Total			9,165.18	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									19,420.82	Final Sur Total			7,332.14	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	1	90.82	Replace ▾	✓ CR4
One Time Key In	Main			REINFORCEMENT, RR	1	34.60	34.60	25.00	25.95	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace ▾	✓ REC
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	1	0	Repair ▾	X R
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check ▾	X N/A
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	1	509.70	Replace ▾	✓ CR4
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	1	284.40	Replace ▾	✓ CR4
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	1	97.95	Replace ▾	✓ CR4
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			CAP SUB-ASSY, WHEEL	4	174.10	696.40	25.00	522.30	Replace	0	0	Not Give ▾	X N/A
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	1	230.25	Replace ▾	/ CR
One Time Key In	Main			GARNISH SIDE UPPER, LHR	1	261.70	261.70	25.00	196.27	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			WIRE, FRAME	1	1,680.90	1,680.90	10.00	1,512.81	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	326.70	326.70	25.00	245.02	Replace	0	0	Check ▾	X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0	Check ▾	X N/A
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	1	23.02	Replace ▾	/ BR
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.02	Replace ▾	/ BR
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	1	83.18	Replace ▾	/ ON Tail lamp pa
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	575.10	Replace ▾	/ ON
Total Spare Part Cost									24,276.03	Surveyor Total		9,165.18		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									19,420.82	Final Sur Total		7,332.14		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ nrc
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ nrc
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	1	105.98	Replace	✓ CR4
One Time Key In	Main			REINFORCEMENT, BACK	1	89.50	89.50	25.00	67.13	Replace	0	0	Check	X NAI
One Time Key In	Main			REINFORCEMENT, BELT	1	103.20	103.20	25.00	77.40	Replace	0	0	Check	X NAI
One Time Key In	Main			REINFORCEMENT, ROOF	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	X NAI
One Time Key In	Main			REINFORCE, ROOF SIDE	1	91.90	91.90	25.00	68.93	Replace	0	0	Not Give	X NAI
One Time Key In	Main			PANEL, ROOF SIDE,	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	X NAI
One Time Key In	Main			EXTENSION, QUARTER	1	55.70	55.70	25.00	41.78	Replace	1	41.78	Replace	✓ nrc
One Time Key In	Main			EXTENSION, QUARTER	1	83.50	83.50	25.00	62.63	Replace	1	62.63	Replace	✓ nrc
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	1	52.80	Replace	✓ BR
One Time Key In	Main			PANEL, ROOF SIDE INNER FRONT RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	X NAI
One Time Key In	Main			PANEL, ROOF SIDE OUTER RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	X NAI
One Time Key In	Main			RAIL, ROOF SIDE	1	273.60	273.60	25.00	205.20	Replace	0	0	Not Give	X NAI
One Time Key In	Main			QUARTER GLASS RR/RH	1	846.50	846.50	25.00	634.88	Replace	1	634.88	Replace	✓ nrc
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ nrc
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair ▾	X R
One Time Key In	Main			DOOR LOCK RR/RH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			CHECK ASSY, RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give ▾	X N/A
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	1,690.00	1,200	
Total:			1,690.00	1,200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	50	
3	Main	TO RESPRAY REAR PANEL	180.00	100	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	100	
5	Main	TO RESPRAY TAIL GATE	378.00	200	
6	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80	
7	Main	TO RESPRAY REAR SPOILER	180.00	80	
8	Main	TO RESPRAY REAR MEMBER,RH	180.00	0	
Total:			4,590.00	1,260.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0	
10	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
11	Main	TO RESPRAY BATTERY PANEL	180.00	0	
12	Main	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	
13	Main	TO RESPRAY ROOF TOP PANEL	378.00	0	
14	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	50	Taillamp panel RH
15	Main	TO RESPRAY REAR FENDER RH	378.00	200	
16	Main	RESPRAY WHEEL CAP	720.00	0	
17	Main	TO RESPRAY RH REAR DOOR	378.00	200	
Total:			4,590.00	1,260.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	126.00	0	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	AK
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	AK
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	AK
5	Main	TO REMOVE / REFIT SEAT	120.00	30	AK
6	Main	TO ALIGN CHASSIS	350.00	0	
7	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
8	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	600.00	600.00	AK
9	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	20	AK
10	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	AK
11	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30	AK
12	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	AK
Total:			3,036.00	1,040.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
13	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	AK
14	Main	TO REMOVE AND REFIT REAR WINDSCREEN	240.00	100	AK
15	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	50	AK
16	Main	TO REMOVE AND REFIT WIRE HARDESS	300.00	20	AK
17	Main	TO REPLACE SUNDRY PARTS	100.00	30	AK
18	Main	TO WASH AND VACUUM	60.00	0	
Total:			3,036.00	1,040.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	19,420.82	7,332.14
Total Labour Cost	1,690.00	1,200.00
Total Spray Painting	4,590.00	1,260.00
Other	3,036.00	1,040.00
Overall Total	28,736.82	10,832.14
Lump Sum Repair Option	☒	☒
Lump Sum Total	28,750.00	10,850.00
Surveyor Approved Amount		10,850.00
No of Repair Days*	14	10
Remarks	-	L/S repair, take after spray. Request Purchase Value
Surveyor Name		STEVE CHEN
Signature		
Survey Date	25/09/2019	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: