

Section A - Accident Details

Registration Number	SHC4173Y
Case Reference Number	TAX/09/19/2090
Registration Date	29/11/2013
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	SEE TOH WING HOY
Type of Accident	Head to Rear
Accident Date and Time	19/9/2019 4:55 PM
Accident Reported Date and Time	24/9/2019 4:19 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	19/9/2019 4:56 PM
Replacement Vehicle issued?	No
Job Card Number	24103512
Special Instruction to ARC, if any	TOWED \$90(KING DOLLY)
Prepared Date and Time	25/9/2019 10:36 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,090.00	\$1,480.00
Total Spray Cost	\$5,148.00	\$1,560.00
Total Spare Part Cost	\$24,610.10	\$12,521.51
Total Other Cost	\$3,386.00	\$1,280.00
TOTAL COST	\$35,234.10	\$16,841.51
Lump Sum Total	\$35,250.00	\$16,850.00 (L/S)
Number of Repair Days	15.0	14.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / QBE
ARC / Surveyor Sign Off Date	03/10/2019 9:01 AM	02/10/2019 1:34 PM
Signature		
Remarks	Total number of repair days = 14 days. SUP = + 4 days.	L/S repair, take after spray. Request Purchase Value. Repair Limit \$15,000.00

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0498	Invoice Number	
Quotation Date	26.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR ROOF TOP PANEL	\$200.00	\$80.00 (Supp)
TO REPAIR RH REAR WHEEL HOUSE	\$200.00	\$200.00 (Supp)
TO REPAIR RH REAR PORTION	\$1,690.00	\$1,200.00
Total Labour	\$2,090.00	\$1,480.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RH REAR WHEEL HOUSE	\$180.00	\$100.00 (Supp)
TO RESPRAY ROOF TOP PANEL	\$378.00	\$200.00 (Supp)
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$50.00
TO RESPRAY REAR PANEL	\$180.00	\$100.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$100.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$80.00
TO RESPRAY REAR SPOILER	\$180.00	\$80.00
TO RESPRAY REAR MEMBER, RH	\$180.00	\$0.00
TO RESPRAY RH REAR WHEEL HOUSE	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL RH	\$180.00	\$0.00
TO RESPRAY BATTERY PANEL	\$180.00	\$0.00
TO RESPRAY RH RAIL ROOF SIDE	\$180.00	\$0.00
TO RESPRAY ROOF TOP PANEL	\$378.00	\$0.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$50.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
RESPRAY WHEEL CAP	\$720.00	\$0.00
TO RESPRAY RH REAR DOOR	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$5,148.00	\$1,560.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$126.00	\$80.00 (add)
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO REMOVE / REFIT SEAT	\$120.00	\$30.00

TO ALIGN CHASSIS	\$350.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$600.00	\$600.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$30.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$20.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$20.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$100.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$50.00
TO REMOVE AND REFIT WIRE HARDESS	\$300.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REMOVE AND REFIT BATTERY ASSY HV	\$350.00	\$150.00 (Supp)
Total Other Costs	\$3,386.00	\$1,280.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.51	25.00	\$12.08	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given
		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		52591-47021	BUMPER SEAL, RR RH	1.00	\$65.70	25.00	\$49.28	Replace	Replace
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace
		58308-47011	UNDER COVER SUBASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given
		58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	\$107.40	0.00	\$0.00	Replace	Not Given
		17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	0.00	\$0.00	Replace	Not Given
		17565-28010	SUPPORT EXHAUST PIPE, NO.4	0.00	\$40.30	0.00	\$0.00	Replace	Not Given
		17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	0.00	\$0.00	Replace	Not Given
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	25.00	\$755.93	Replace	Replace
		56117-50140	DAM, BACK DOOR GLASS ADHESIVE, NO.1	1.00	\$27.30	25.00	\$20.48	Replace	Replace
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685682
Estimator Telephone Number : 98582623
Accident Reporting Number : 68662612

Date Generated : 05/11/2019

User ID : PohSuan

75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75575-47030	MOULDING BACK WINDOW, LOWER NO.1	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
68294-47050	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1.00	\$17.40	25.00	\$13.05	Replace	Replace	✓
75575-47020	MOULDING, BACK WINDOW, LOWER NO.2	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75574-47010	MOULDING, BACK WINDOW, OUTSIDE LH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
75573-47090	MOULDING, BACK WINDOW, OUTSIDE RH	1.00	\$29.40	25.00	\$22.05	Replace	Replace	✓
68105-47122	TAILGATE DOOR GLASS	1.00	\$1,090.90	25.00	\$818.18	Replace	Replace	✓
64821-47030	TAILGATE LOWER WINDOW GLASS	1.00	\$721.30	25.00	\$540.98	Replace	Replace	✓
	SEALANT W/SCREEN	3.00	\$37.00	0.00	\$111.00	Replace	Replace	✓
68810-47010	TAILGATE DOOR HINGE LH/RH	0.00	\$58.30	0.00	\$0.00	Replace	Not Given	X
69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given	X
68960-0W532	TAILGATE DOOR STAY LH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X
68950-0W542	TAILGATE DOOR STAY RH	0.00	\$241.50	0.00	\$0.00	Replace	Not Given	X
67881-47022	TAILGATE DOOR WEATHER STRIP	1.00	\$353.40	25.00	\$265.05	Replace	Replace	✓
69415-47020	TAILGATE LOCK, COVER	0.00	\$15.70	0.00	\$0.00	Replace	Not Given	X
76801-47070-B0	TAILGATE OUTSIDE GARNISH	1.00	\$504.90	25.00	\$378.68	Replace	Replace	✓
69431-47010	STRIKER, BACK DOOR	0.00	\$48.90	0.00	\$0.00	Replace	Not Given	X
67938-47031C0	TAILGATE TRIM, LH	0.00	\$85.90	0.00	\$0.00	Replace	Not Given	X
67751-47040C0	TAILGATE TRIM, LOWER	0.00	\$180.70	0.00	\$0.00	Replace	Not Given	X
67750-47071C0	TAILGATE, BOARD ASSY	0.00	\$246.90	0.00	\$0.00	Replace	Not Given	X
82184-47370	WIRE, BACK DOOR, NO.1	0.00	\$582.40	0.00	\$0.00	Replace	Not Given	X
85241-47030	ARM, RR WIPER	0.00	\$84.70	0.00	\$0.00	Replace	Not Given	X
85242-47040	BLADE ASSY, REAR WIPER	0.00	\$55.00	0.00	\$0.00	Replace	Not Given	X
75310-47020	EMBLEM REAR	1.00	\$60.30	25.00	\$45.23	Replace	Replace	✓
75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
75442-47030	NAME PLATE (PRIUS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace	✓
75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace	✓
76085-47910	SPOILER REAR	1.00	\$953.70	25.00	\$715.28	Replace	Replace	✓
81006-47011	3RD BRAKE LAMP	0.00	\$231.30	0.00	\$0.00	Replace	Not Given	X
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
63111-47030	ROOF PANEL	0.00	\$1,102.80	0.00	\$0.00	Replace	Not Given	X
75555-47030	MLDG DRIP RH, ROOF	0.00	\$78.80	0.00	\$0.00	Replace	Not Given	X
58307-47060	END PANEL	1.00	\$602.10	25.00	\$451.58	Replace	Replace	✓
64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	0.00	\$0.00	Replace	Not Given	X
64716-47031B0	END PANEL COVER, DECK TRIM, RR	1.00	\$121.10	25.00	\$90.83	Replace	Replace	✓
58336-12090	REINFORCEMENT, RR	0.00	\$34.60	0.00	\$0.00	Replace	Not Given	X
	SEALANT SIKAFLEX	1.00	\$37.00	0.00	\$37.00	Replace	Replace	✓
58311-47071	SPARE TYRE PANEL	1.00	\$667.70	100.00	\$0.00	Replace	Repair	R
57603-47030	MEMBER SUB-ASSY, RR RH	0.00	\$174.10	0.00	\$0.00	Replace	Check	X
58302-47030	FLOOR PANEL RR/RH	0.00	\$209.90	0.00	\$0.00	Replace	Not Given	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757708
FAX Number : 63885592
Estimator Telephone Number : 66662623
Accident Reporting Number : 66662672

Date Generated : 08/11/2019
User ID : PohBuen

64993-47020	BOX, DECK FLOOR, RR	0.00	\$649.70	0.00	\$0.00	Replace	Not Given	X
58416-47030B3	BOX, RR FLOOR, BOARD	1.00	\$679.60	25.00	\$509.70	Replace	Replace	
58415-47030	BOARD, RR FLOOR	0.00	\$392.30	0.00	\$0.00	Replace	Not Given	X
58490-47140B0	BOARD ASSY, RR RH	1.00	\$379.20	25.00	\$284.40	Replace	Replace	
58427-47040	SPACER, RR FLOOR	1.00	\$130.60	25.00	\$97.95	Replace	Replace	
64910-47020-B0	COVER ASSY, TONNEAU	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X
64777-47090	CUSHION, SPARE WHEEL	0.00	\$230.80	0.00	\$0.00	Replace	Not Given	X
64778-47050	PROTECTOR, SPARE	0.00	\$143.70	0.00	\$0.00	Replace	Not Given	X
51931-47020	CARRIER, SPARE	0.00	\$19.70	0.00	\$0.00	Replace	Not Given	X
42602-47060	CAP SUB-ASSY, WHEEL	0.00	\$174.10	0.00	\$0.00	Replace	Not Given	X
	BREAKDOWN SIGN	0.00	\$35.00	0.00	\$0.00	Replace	Not Given	X
64730-47031B2	PANEL ASSY, DECK RH	1.00	\$307.00	25.00	\$230.25	Replace	Replace	
62480-47050-B0	GARNISH SIDE UPPER, LHR	0.00	\$261.70	0.00	\$0.00	Replace	Not Given	X
	BATTERY	0.00	\$278.00	0.00	\$0.00	Replace	Not Given	X
74481-47050	BATTERY CLAMP	0.00	\$16.10	0.00	\$0.00	Replace	Not Given	X
74440-47030	BATTERY TRAY	0.00	\$42.80	0.00	\$0.00	Replace	Not Given	X
82164-47070	WIRE, FRAME	0.00	\$1,680.90	0.00	\$0.00	Replace	Not Given	X
82123-47040	WIRE, ENGINE, NO.3	0.00	\$74.00	0.00	\$0.00	Replace	Not Given	X
82161-47B22	WIRE, FLOOR	0.00	\$1,675.00	0.00	\$0.00	Replace	Not Given	X
82162-47B20	WIRE, FLOOR, NO.2	0.00	\$1,305.40	0.00	\$0.00	Replace	Not Given	X
61605-47010	PANEL SUB-ASSY, QTR	0.00	\$326.70	0.00	\$0.00	Replace	Check	X
61607-47060	PANEL SUB-ASSY, QTR	0.00	\$588.40	0.00	\$0.00	Replace	Check	X
52562-47010	TAIL LAMP BRACKET, RH	1.00	\$30.70	25.00	\$23.03	Replace	Replace	
81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	
61621-47030	TROUGH, BACK DOOR	1.00	\$110.90	25.00	\$83.18	Replace	Replace	
61604-47090	FENDER RR/RH	1.00	\$766.80	25.00	\$575.10	Replace	Replace	
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
65637-47021	FENDER LINER RR/RH	1.00	\$141.30	25.00	\$105.98	Replace	Replace	
61743-47010	REINFORCEMENT, BACK	0.00	\$89.50	0.00	\$0.00	Replace	Check	X
61766-47020	REINFORCEMENT, BELT	0.00	\$103.20	0.00	\$0.00	Replace	Check	X
6173747020	REINFORCEMENT, ROOF	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
61713-47020	REINFORCE, ROOF SIDE	0.00	\$91.90	0.00	\$0.00	Replace	Not Given	X
61731-47020	PANEL, ROOF SIDE,	0.00	\$134.80	0.00	\$0.00	Replace	Not Given	X
61625-47040	EXTENSION, QUARTER	1.00	\$55.70	25.00	\$41.78	Replace	Replace	
61623-47010	EXTENSION, QUARTER	1.00	\$83.50	25.00	\$62.63	Replace	Replace	
62940-16060	DUCT ASSY, QUARTER	1.00	\$70.40	25.00	\$52.80	Replace	Replace	
61733-47020	PANEL, ROOF SIDE INNER FRONT RH	0.00	\$134.80	0.00	\$0.00	Replace	Not Given	X
61711-47020	PANEL, ROOF SIDE OUTER RH	0.00	\$134.80	0.00	\$0.00	Replace	Not Given	X
61217-47010	RAIL, ROOF SIDE	0.00	\$273.60	0.00	\$0.00	Replace	Not Given	X
62710-47130	QUARTER GLASS RR/RH	1.00	\$846.50	25.00	\$634.88	Replace	Replace	

			SEALANT W/SCREEN	1.00	\$37.00	0.00	\$37.00	Replace	Replace	✓
		67003-47080	DOOR RR/RH	1.00	\$954.50	100.00	\$0.00	Replace	Repair	✓
		89050-47080	DOOR LOCK RR/RH	0.00	\$709.30	0.00	\$0.00	Replace	Not Given	X
		68830-47031	CHECK ASSY, RR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given	X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		65638-47021	FENDER LINER RR/LH	0.00	\$141.30	0.00	\$0.00	Replace	Not Given	X
Total					\$30,021.35		\$9,165.28			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		68810-47010	TAILGATE DOOR HINGE LH/RH	1.00	\$58.30	25.00	\$43.73	Replace	Replace	✓
		68810-47010	TAILGATE DOOR HINGE LH/RH	1.00	\$58.30	25.00	\$43.73	Replace	Replace	✓
		67750-47071C0	TAILGATE, BOARD ASSY	1.00	\$246.90	25.00	\$185.18	Replace	Replace	✓
		64993-47020	BOX, DECK FLOOR, RR	1.00	\$649.70	25.00	\$487.28	Replace	Replace	✓
		58415-47030	BOARD, RR FLOOR	1.00	\$392.30	25.00	\$294.23	Replace	Replace	✓
		62470-47110B0	GARNISH ASSY, ROOF RH	1.00	\$256.40	25.00	\$192.30	Replace	Replace	✓
			BATTERY	1.00	\$278.00	10.00	\$250.20	Replace	Replace	✓
		G9510-47060	BATTERY ASSY, HV	1.00	\$5,544.40	10.00	\$4,989.96	Replace	Replace	✓
Total					7,484.30		6,486.61			

15,651.89
 - 202

 + 12,521.51
 + 1,480.00
 + 2,840.00

 16,841.51
 US \$16,850.00
 - \$1,850.00 (Repair cost exceed salvage value
 \$15,000.00 borne by smrt
 Taxi)



Case Details

Case Reference Number : TAX/09/19/2090
Type of Repair : Accident Repair
Vehicle Registration Number : SHC4173Y

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-8635-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : OBE Insurance (International) Ltd
Accident Date and Time : 19/09/2019 08:55 AM
Vehicle Age(In Months) : 70

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	✓ BR
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	✓ MC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace	✓ DD
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace	✗ NN
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	✓ BR
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ MC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace	✓ CRN
Total Spare Part Cost									24,276.03	Surveyor Total 9,185.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	✓ CR4
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	✗ X NN
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace	✓ CR4
One Time Key In	Main			BUMPER SIDE RETAINER RRLH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ BR
One Time Key In	Main			BUMPER SIDE RETAINER RRRH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	✓ BR
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.80	514.80	25.00	385.88	Replace	0	0	Not Give	✗ X NN
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0	Not Give	✗ X NN
One Time Key In	Main			EXHAUST TAIL PIPE	1	658.20	658.20	25.00	492.15	Replace	0	0	Not Give	✗ X NN
One Time Key In	Main			SUPPORT EXHAUST PIPE, NO.4	2	40.30	80.60	25.00	60.45	Replace	0	0	Not Give	✗ X NN
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0	Not Give	✗ X NN
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace	✓ DD
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace	✓ APC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace	✓ APC
Total Spare Part Cost									24,278.03	Surveyor Total 8,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMART Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace	✓ APC
One Time Key In	Main			TAILGATE DOOR GLASS	1	1,090.90	1,090.90	25.00	818.18	Replace	1	818.18	Replace	✓ BR
One Time Key In	Main			TAILGATE LOWER WINDOW GLASS	1	721.30	721.30	25.00	540.97	Replace	1	540.97	Replace	✓ BR
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	3	111.00	Replace	✓ APC
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	265.40	265.40	25.00	200.05	Replace	1	200.05	Replace	✓ CRV
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	378.67	378.67	25.00	284.00	Replace	1	284.00	Replace	✓ BR
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0	Not Give	✗ NN
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0	Not Give	✗ NN
						Total Spare Part Cost	24,276.03				Surveyor Total	9,165.18		
						Lump Sum Discount (%)	20.00				Lump Sum Dis (%)	20		
						Final Spare Part Cost	19,420.82				Final Sur Total	7,332.14		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	10.00	524.16	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			ARM, RR WIPER	1	84.70	84.70	25.00	63.53	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			BLADE ASSY, REAR WIPER	1	55.00	55.00	25.00	41.25	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.23	Replace	* / OK
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.93	Replace	* / OK
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.60	60.60	25.00	45.60	Replace	1	45.60	Replace	* / OK
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.93	Replace	* / OK
One Time Key In	Main			SPOILER REAR	1	963.70	963.70	25.00	715.28	Replace	1	715.28	Replace	* / OK
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / OK
One Time Key In	Main			STICKER DECAL 6556 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / OK
One Time Key In	Main			ROOF PANEL	1	1,102.80	1,102.80	25.00	827.10	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			MLDG DRIP RH, ROOF	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	* X N/A
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.58	Replace	* / OK
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0	Not Give	* X N/A

Total Spare Part Cost 24,276.03

Surveyor Total 9,166.18

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 19,420.82

Final Sur Total 7,332.14

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	1	90.82	Replace	✓ CR4
One Time Key In	Main			REINFORCEMENT, RR	1	34.60	34.60	25.00	25.95	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ / N/A
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	1	0	Repair	✓ X R
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0	Check	✓ X N/A
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	1	509.70	Replace	✓ / CR4
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	1	284.40	Replace	✓ / CR4
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	1	97.95	Replace	✓ / CR4
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0	Not Give	✓ X N/A
One Time Key In	Main			CAP SUB-ASSY, WHEEL	4	174.10	696.40	25.00	522.30	Replace	0	0	Not Give	✓ X N/A
						Total Spare Part Cost		24,276.03		Surveyor Total		9,165.15		
						Lump Sum Discount (%)		20.00		Lump Sum Dis (%)		20		
						Final Spare Part Cost		19,420.82		Final Sur Total		7,332.14		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	1	230.25	Replace	• / CR
One Time Key In	Main			GARNISH SIDE UPPER, LHR	1	261.70	261.70	25.00	196.27	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			WIRE, FRAME	1	1,680.90	1,680.90	10.00	1,512.81	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			WIRE, ENGINE, NO.3	1	74.00	74.00	10.00	66.60	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0	Not Give	• X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	326.70	326.70	25.00	245.02	Replace	0	0	Check	• X N/A
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0	Check	• X N/A
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	1	23.02	Replace	• / OR
One Time Key In	Main			TAIL LAMP RH	1	557.90	557.90	10.00	502.02	Replace	1	502.02	Replace	• / OR
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	1	83.18	Replace	• / ON Taillamp pa
One Time Key In	Main			FENDER RR/RH	1	756.80	756.80	25.00	575.10	Replace	1	575.10	Replace	• / ON
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disa(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ APC
One Time Key In	Main			STICKER DECAL 8888 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ APC
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	1	105.98	Replace	✓ (R4)
One Time Key In	Main			REINFORCEMENT, BACK	1	88.50	88.50	25.00	67.13	Replace	0	0	Check	✗ X NAI
One Time Key In	Main			REINFORCEMENT, BELT	1	103.20	103.20	25.00	77.40	Replace	0	0	Check	✗ X NAI
One Time Key In	Main			REINFORCEMENT, ROOF	1	60.30	60.30	25.00	45.22	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			REINFORCE, ROOF SIDE	1	91.90	91.90	25.00	68.93	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			PANEL, ROOF SIDE,	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			EXTENSION, QUARTER	1	55.70	55.70	25.00	41.78	Replace	1	41.78	Replace	✓ APC
One Time Key In	Main			EXTENSION, QUARTER	1	83.50	83.50	25.00	62.63	Replace	1	62.63	Replace	✓ APC
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	1	52.80	Replace	✓ BR
One Time Key In	Main			PANEL, ROOF SIDE INNER FRONT RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			PANEL, ROOF SIDE OUTER RH	1	134.80	134.80	25.00	101.10	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			RAIL, ROOF SIDE	1	273.60	273.60	25.00	205.20	Replace	0	0	Not Give	✗ X NAI
One Time Key In	Main			QUARTER GLASS RR/RH	1	634.50	634.50	25.00	475.88	Replace	1	475.88	Replace	✓ APC
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace	✓ APC
Total Spare Part Cost									24,278.03	Surveyor Total		9,165.18		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									19,420.82	Final Sur Total		7,332.14		

SMRT Recommendation											Surveyor Approval			
SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR RRRH	1	954.50	954.50	25.00	715.88	Replace	1	0	Repair	* X R
One Time Key In	Main			DOOR LOCK RRRH	1	709.30	709.30	25.00	531.97	Replace	0	0	Not Give	* X NA
One Time Key In	Main			CHECK ASSY. RR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0	Not Give	* X NA
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0	Not Give	* X NA
One Time Key In	Main			FENDER LINER RRLH	1	141.30	141.30	25.00	105.98	Replace	0	0	Not Give	* X NA
Total Spare Part Cost									24,276.03	Surveyor Total 9,165.18				
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20				
Final Spare Part Cost									19,420.82	Final Sur Total 7,332.14				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	1,690.00	1,200	
Total:			1,690.00	1,200.00	

+ 80 + 200 (Supp) = 1480

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	50	
3	Main	TO RESPRAY REAR PANEL	180.00	100	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	100	
5	Main	TO RESPRAY TAIL GATE	378.00	200	
6	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80	
7	Main	TO RESPRAY REAR SPOILER	180.00	80	
8	Main	TO RESPRAY REAR MEMBER,RH	180.00	0	
Total:			4,590.00	1,260.00	

S.No.	Costing Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0	
10	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0	
11	Main	TO RESPRAY BATTERY PANEL	180.00	0	
12	Main	TO RESPRAY RH RAIL ROOF SIDE	180.00	0	
13	Main	TO RESPRAY ROOF TOP PANEL	378.00	0	
14	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	50	Taillamp panel RH
15	Main	TO RESPRAY REAR FENDER RH	378.00	200	
16	Main	RESPRAY WHEEL CAP	720.00	0	
17	Main	TO RESPRAY RH REAR DOOR	378.00	200	
Total:			4,590.00	1,260.00	

+ 100 + 200 (Supp) = 1560

Other Cost Detail

S.No.	Costing Type	Job Scope	SMART Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TOWING CHARGE	128.00	80 / n/c	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	n/c
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	n/c
4	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60	n/c
5	Main	TO REMOVE / REFIT SEAT	120.00	30	n/c
6	Main	TO ALIGN CHASSIS	350.00	0	
7	Main	TO REMOVE & REFIT EXHAUST	120.00	0	
8	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	600.00	600.00	n/c
9	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	20	n/c
10	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	n/c
11	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	30	n/c
12	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	20	n/c
Total:			3,038.00	1,040.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
13	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	20	AK
14	Main	TO REMOVE AND REFIT REAR WINDSCREEN	240.00	100	AK
15	Main	TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	50	AK
16	Main	TO REMOVE AND REFIT WIRE HARDESS	300.00	20	AK
17	Main	TO REPLACE SUNDRY PARTS	100.00	30	AK
18	Main	TO WASH AND VACUUM	80.00	0	
Total:			3,036.00	1,040.00	+ 90 (towing) + (150) = 1280

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	19,420.82	7,332.14
Total Labour Cost	1,690.00	1,200.00
Total Spray Painting	4,590.00	1,260.00
Other	3,036.00	1,040.00
Overall Total	28,736.82	10,832.14
Lump Sum Repair Option		✓
Lump Sum Total	28,750.00	10,850.00
Surveyor Approved Amount		10,850.00
No of Repair Days*	14	14
Remarks		L/S repair, take after spray. Request Purchase Value
Surveyor Name		STEVE CHEN
Signature		
Survey Date	25/09/2019	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX/09/19/2020	Date of Collection	1 1
Vehicle No	SHC 4173 Y	Date of Request	01/10/2019
Vehicle Model	TOYOTA PRUUS	Number of Days to Extend (If any)	5 4

PHOTO
J186

S/N	Part Number	Part Description	Quantity	Unit Price	
5611	5612	TAILGATE HINGE RH	1pc	\$ 43.73	/ DD
	5613	TAILGATE HINGE LH	1pc	\$ 43.73	/ DD
5635	5636, 5637	TAILGATE BOARD ASSY	1pc	\$ 185.18	/ CR4
5639	5640, 5641, 5642	BOX/DECK FLOOR REAR	1pc	\$ 487.28	/ BR
5643	5644, 5645	BOARD, REAR FLOOR	1pc	\$ 294.23	/ BR
5625	5626, 5628	BARNISH SIDE UPPER, RHR	1pc	\$ 192.30	/ CR4

<<Please submit photographs for damaged parts>>

I, (Name) Steve (LKK)

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.


Signature of person making this declaration
(to be signed in front of an authorised witness)

1/10/19, 7:55 pm

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

Pg 1/2

REQUEST FOR SUPPLEMENTARY PARTS

Contractor:			
Accident Case Number	TAX/09/19/2070	Date of Collection	1 1
Vehicle No	SHC 4173 Y	Date of Request	01/10/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	5 4

S/N	Part Number	Part Description	Quantity	Unit Price	
5632	5633	BATTERY	1pc	\$250.20	CRU
5618, 5619	5620, 5621	HV BATTERY	1pc	\$4989.96	BR/100
5648, 5649	5648	LABOR TO REPAIR ROOF TOP PANEL		\$ 200	80/
5649, 5653	5657	LABOR TO SPRAY ROOF TOP PANEL		\$ 378	200/
5623		LABOR TO REPAIR WHEEL HOUSE PANEL REAR	RM	\$ 200	✓
5624		LABOR TO SPRAY WHEELHOUSE PANEL REAR RM	RM	\$ 200	100/

←Please submit photographs for damaged parts→

I, (Name) Stan (LKR)
 (Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

 1/10/19 7:55pm
 Signature of person making this declaration
 (to be signed in front of an authorized witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMART Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMART Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

PSB/3

REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TDK 09/19/2020	Date of Collection	1/1
Vehicle No	SHL 4133 Y	Date of Request	01/10/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Respond (If any)	4

S/N	Part Number	Part Description	Quantity	Unit Price
		LABOR TO REMOVE & REFIX HV BATTERY.		\$ 350

150/

<<Please submit photographs for damaged parts>>

I, (Name) Steve (LKR)

(Position) _____

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

1/10/19 7:55pm
Signature of person making this declaration
(to be signed in front of an authorised witness)

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

pg 3/3