

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0852/2019/KK
Date : 12-Jul-19

Vehicle not IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Mr. Clive Gordon Scott
Address : 2 Marina Blvd
#65-01
Singapore 018987
Telephone : HP +65 83188136
Type of Claim : OWN DAMAGE CLAIM
Policy No. : 1800096299
Vehicle No : **S 9105 CD**
Model Code : Audi Q5 2.0 TFSI QU
Model / Year : Aug-12
Engine No : CDN 282963
Chassis No : WAUZZZ8RXCA126012
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Jul-19
Place of Accident : Aedmore Park Condo Basement 2 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle S 9105 CD

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlight, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00 1250
3	To respray front bumper, front bumper spoiler and lhs front fender. ✓ X	\$ 3,000.00 1100. 1650
4	To renew lhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 6,752.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. S 9105 CD

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>deland</i>	\$ 2,432.00 ✓	1945.60
2	FRONT BUMPER SPOILER <i>Not in</i>	\$ 249.00 x	
3	FRONT BUMPER SIDE RETAINER - LH <i>Not in</i>	\$ 569.00 x	
4	FRONT BUMPER AIR GUIDE DRILLE - LH <i>Not in</i>	\$ 123.00 x	
5	FRONT BUMPER GUIDE SECTION <i>Byd</i>	\$ 34.00 ✓	27.12
6	FRONT BUMPER REINFORCEMENT <i>Not in</i>	\$ 598.00 x	
7	FOAM FILLER PIECE <i>Not in</i>	\$ 103.00 +	
8	FRONT BUMPER SENSOR <i>Not in</i>	\$ 231.00 +	
9	FRONT BUMPER SENSOR SEAL RING <i>Not in</i>	NEC \$ 20.00 +	
10	FRONT FENDER - LH <i>Dented</i>	4 \$ 913.00 ✓	730
11	FRONT FENDER ATTACHEMENT PARTS <i>Not in</i>	\$ 61.00 ?	
12	SEALING FRAME - LH <i>Not in</i>	\$ 59.00 +	
13	FRONT FENDER BRACKET - LH <i>Not in</i>	\$ 49.00 ?	
14	FRONT FENDER BRACKET - CENTER <i>Not in</i>	\$ 45.00 ?	
15	POP ROVERT <i>Not in</i> NN	6 \$ 108.00 ✓	X
16	FRONT FENDER BRACE - LH <i>But</i>	\$ 79.00 ✓	62.64
17	WHEEL HOUSING LINER <i>Not in</i> torn	\$ 246.00 + ✓	196.40
18	WHEEL HOUSING LINER ATTACHEMENT PARTS <i>Not in</i> needs	\$ 94.00 + ✓	74.96
19	WHEEL SPOILER <i>Not in</i>	\$ 60.00 x	
20	HEADLIGHT MOUNTING <i>Not in</i> Nec	\$ 107.00 +	
SUB SPARE PARTS CHARGES		\$ 6,180.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. S 9105 CD

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	RETAINING PLATE <i>2 from new</i>	\$ 2,432.00 .66. X	
22	HEADLIGHT GAS DISCHARGE <i>cut</i>	\$ 66.00 2432 ✓ 2119.20	
23	HALOGEN FOG LAMP <i>new</i>	\$ 203.00 X	
24	HEADLIGHT LIFT CYLINDER <i>new</i>	\$ 227.00 X	
25	ALUMINIUM RIM <i>new</i> CUT	\$ 75.00 819. X ✓ 844.00	
26	RUBBER VALVE <i>new</i>	\$ 819.00 + 75. X.	
27	SUNDRIES <i>new</i>	\$ 25.00 ? ✓ 14.40	
TOTAL SPARE PARTS CHARGES		: \$ 10,027.00	
TOTAL LABOUR CHARGES		: \$ 6,752.00	
GRAND TOTAL		: <u>\$ 16,779.00</u>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 26/09/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, OS Reps

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant