

Surveyor:

Adrian.

DOI:

ASSIGNMENT

11/10/19

Date / Time : 26/09/2019

Registered in Merimen: 26/09/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : GBG 702Y
 Name of Insured : PLINIO VISONA SINGAPORE

Claim No. : 914508069SG

Policy No. : 1800074513

Insured Tel No. : HP:

Make / Model : NISSAN NV350-2.5 (A)

Excess Sec II : S\$

D.O.A : 26/09/2019 01:15

Place of Accident : INTERSECTION OF HENDERSON ROAD & JALAN BUKIT MERAH

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : NG WEI JIAN

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : +65-96916231

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SBG 676P



INSRS:
WSP: PREMIUM
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/Time	STAGE	DATE / PIC
SBG 676P - CC3/AIG17024624/T1hb3q2; DOA: 27.12.17	Non-Reporting ltr (1st):	
- CC3/AIG18000102/Aqbn2; DOA: 27.12.17	Non-Reporting ltr (2nd):	
GBG 702Y - X	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	15/10/19
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA :	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: p/r S\$ 7,559.20 (5 days) Reduction: 73 %	Email ☐ Call ☐	
FINAL SETTLEMENT Date/Time: 5/3/2020 Confirm with Tony	Email ☒ Call ☐	
Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : NIL	If NO or B 28, Ass. Lia :	
Repair Cost: (w/450) S\$ 8,088.34		
Loss of Rental (LOR): S\$ 600 (6 days) x \$100		
Loss of Use (LOU): S\$ - (5 - 8 - days)		
Loss of Income (LOI): S\$ - (5 - 8 - days)		
LOR only ☒ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ (Tick only one)		
GIA/LTA Search: S\$ 2.00		
Medical: S\$ -		
Disbursement: S\$ - (e.g. Tow/ Independent)		
Legal Cost: S\$ -		
Total: S\$ 8,690.34 Global Sum S\$:		
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: S\$ 8,690.34 Name 1: PREMIUM AUTOMOBILES PTE LTD		
Payee 2: (Strike if N.A.) S\$ Name 2:		
Payee 3: (Strike if N.A.) S\$ Name 3:		

COPY SENT
9/3/2020

12/30

Adrian

11/10/19

Ala

16998/Ala

ASSIGNMENT

Date:

Time:

1/10/19

Vehicle:

SBG676P

To Date: 2016 Dec

Transfer Cost:

Type: ☒ M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ TP / WS / TP RES / OO RES / EVA / RV / MV

Truck / Trailer /

Inspected Vehicle No:

SBG 676P

Make:

Andi A4

ACC 1395

at Workshop no:

premium

Color:

Black

ACC Insured / Std / NI / NA

at

55 ubi Road 1

Sp Reading:

43692

Trailer Insured / Std / NI / NA

Insured:

Engine:

Policy No:

CIN:

WAU222F48HA055603

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Claim Insured:

Excess:

Steering: ☒ In order / Jammed / Locked / Burnt /

(Client's Record)

Brake: ☒ In order / Jammed / Locked / Burnt /

Make of Veh:

2pm

Model: ☒ Nil / ☒ STD Air / STD Air /

Tyre Size:

F: 205/60 R16

R: 205/60 R16

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ OKO /

Est. or Market Value:

Front

Rear

DAC Accident Report

Consisted? Yes or No

R/Ral

06

mm

R/Ral

06

mm

QA: ☒ PP: ☒ ☒ ☒

Consisted? Yes or No

L/Ral

06

mm

L/Ral

06

mm

Est. Repairs:

5

days

Rec:

Yes or No

D.O.A

D.O.A

01/10/19

Turn Sum:

%

3 Val

Yes or No

Survey held at

Premium

CA / REV / REP. / 24HRS

up

Des. of Damage: ☒ Frt / ☒ Rear / ☒ N/S / ☒ U/C / ☒ Rooftop /

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TPA16.

CP 1P \$ 7,559.20 / Red \$ 20,252.80 / 73 %

5 days + 1 Sunday = 6 days

Insurance File No:

☐

Partl. Report

Days Of Repair:

at

☐

Final Report

Resturvey No. of Trip:

Insurance File No:

2nd File:

☐

Site Ins

05

☐

Interview

05

☐

Check Ins

05

☐

Final Ins

05

Survey Fee:

Completion:

2 - 15

05

05

05

Survey Fee:

Survey Fee / 11.11

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13850

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1165/2019/KS
Date : 9-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SBG 676 P**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Nicholas Tan Jun Han
Address : Blk 84 Telok Blangah Heights
#11-323
Singapore 100084
Telephone : (HP) +65 91516486
Type of Claim : Third Party Claims
Policy No. : 2100495976-02
Vehicle No : **SBG 676 P**
Model Code : Audi A4 1.4 TFSI S
Model / Year : 30/12/2016
Engine No : CVN 021806
Chassis No : WAUZZZF48HA055603
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Sep-19
Place of Accident : Intersection of Henderson Road & Jln Bukit Merah

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBG 676 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	/
2	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓	} overlapped ?? X
3	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N \$ 300.00 X	
4	To dismantle and renew front bumper, rhs front fender, rha headlight and rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00	1500 -
5	To respray front bumper, bonnet, rhs front fender, lhs front door, door handle and rhs wing mirror cover.	\$ 4,500.00	1900 / 3 x 550 = 1650 Handle 100 Mirror 150 1900
6	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 X	
7	To carry out diagnostic checks.	S/N \$ 192.00 ✓	/
TOTAL LABOUR CHARGES		\$ 9,062.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBC 676 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair</i>	S 1,946.00	✓
2	FRONT BUMPER FIXING PARTS	S 258.00	✓
3	LOCK CARRIER AIR GUIDE RH	S 56.00	✓
4	FRONT BUMPER GUIDE SECTION RH	S 34.00	✓
5	FRONT FENDER RH <i>Dented</i>	S 700.00	✓ 559.60
6	FRONT FENDER ATTACHMENTS PARTS RH	S 183.00	} X NY
7	FRONT FENDER CLOSING ELEMENT RH	S 45.00	
8	FRONT FENDER BRACKET - REAR RH	S 32.00	
9	FRONT FENDER DEFORMATION BRACKET RH	S 45.00	
10	FRONT FENDER POP RIVET RH	S 18.00	
11	FRONT FENDER BRACKET RH	S 29.00	} X NY
12	FRONT FENDER BRACE RH	S 107.00	
13	FRONT WHEEL HOUSING LINER RH	S 220.00	✓
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS RH	S 82.00	✓
15	FRONT WHEEL SPOILER RH	S 66.00	✓
16	FRONT WHEEL SPOILER TRIM RH	S 33.00	✓
17	FRONT STONE CHIP GUARD RH	S 46.00	✓ 36.64
18	FRONT FENDER LEDGE COVER INNER	S 28.00	} X NY
19	FRONT FENDER LEDGE COVER OUTER	S 21.00	
20	FRONT DOOR RHS <i>Dented</i>	S 2,152.00	✓ 1,721.60
SUB TOTAL SPARE PARTS		S 6,101.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 676 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT DOOR SEAL RH <i>NEW</i>	\$ 185.00	✓ 147.60
22	BONDING AGENT ?	\$ 45.00	} X NH
23	CLEANING SOLUTION ?	\$ 65.00	
24	APPLICATOR ?	\$ 7.00	
25	FRONT DOOR ATTACHMENTS PARTS RH ?	\$ 488.00	
26	FRONT DOOR CATCH RH <i>NEW</i>	\$ 96.00	✓
27	FRONT DATA PLATE PRESSURE <i>NEW</i>	\$ 35.00	✓ 27.36
28	FRONT DOOR HANDLE TRIM PLATE <i>Regr</i>	\$ 80.00	✓
29	FRONT DOOR HANDLE BEZEL COVER RH <i>Regr</i>	\$ 6.00	✓
30	FRONT DOOR LOCK CYLINDER <i>NEW</i>	\$ 492.00	✓
31	FRONT WING MIRROR MOUNTING RH <i>NEW</i>	\$ 824.00	✓ 658.80
32	FRONT WING MIRROR CAP RH <i>NEW</i>	\$ 220.00	✓ 175.60
33	FRONT WING MIRROR GLASS RH <i>NEW</i>	\$ 1,533.00	✓
34	FRONT WINDOW CHROME SLOT SEAL RH <i>NEW</i>	\$ 280.00	✓
35	FRONT WINDOW GUIDE TRIM RH <i>NEW</i>	\$ 235.00	✓
36	ALUMINIUM RIM RH } <i>NEW</i>	\$ 558.00	✓
37	RUBBER VALVE }	\$ 13.00	✓
38	LED HEADLIGHT RH <i>NEW</i>	\$ 7,087.00	✓
39	SUNDRIES ?	\$ 400.00	X NH
TOTAL SPARE PARTS		\$ 18,750.00	
TOTAL LABOUR CHARGES		\$ 9,062.00	
GRAND TOTAL		\$ 27,812.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

- Repairs must be notified to the insurer at the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *01/10/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 Days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Khanchna (LKK Auto)

From: jiayee.yap@premiumauto.com.sg
Sent: Wednesday, 4 December 2019 11:05 AM
To: Adrian Ling (LKKAUTO); SUR; Admin A; CS A Team
Cc: 'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'
Subject: FINAL REVISION - SBG676P - TP AIG - SURVEYED 1 OCT 19
Attachments: WhatsApp Image 2019-11-25 at 11.51.27 AM.jpeg; WhatsApp Image 2019-11-25 at 11.51.26 AM.jpeg; PA11652019 - SBG 676 P - AUDI A4 1.4 TFSI S - FRONT - TP (AIG).xlsx

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$7559.20 @ 5 days of repairs.

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902272W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiayee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13850

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1165/2019/KS
Date : 9-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : **SBG 676 P**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

5 days - ok - Jy - 04 Dec 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Nicholas Tan Jun Han
Address : Blk 84 Telok Blangah Heights
#11-323
Singapore 100084
Telephone : (HP) +65 91516486
Type of Claim : Third Party Claims
Policy No. : 2100495976-02
Vehicle No : **SBG 676 P**
Model Code : Audi A4 1.4 TFSI S
Model / Year : 30/12/2016
Engine No : CVN 021806
Chassis No : WAUZZZF48HA055603
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 26-Sep-19
Place of Accident : Intersection of Henderson Road & Jln Bukit Merah

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6386 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBG 676 P

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$ 360.00
2	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	\$ 280.00
3	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N	\$ 300.00	
4	To dismantle and renew front bumper, rhs front fender, rha headlight and rhs front door. Re-organise crash management components. Reinstall all parts removed.		\$ 3,150.00	\$ 1,500.00
5	To respray front bumper, bonnet, rhs front fender, rhs front door, door handle and rhs wing mirror cover.		\$ 4,500.00	\$ 1,900.00
6	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00	
7	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 9,062.00	\$ 4,232.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 676 P

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
1	FRONT BUMPER	\$ 1,946.00	
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	LOCK CARRIER AIR GUIDE RH	\$ 56.00	
4	FRONT BUMPER GUIDE SECTION RH	\$ 34.00	
5	FRONT FENDER RH	\$ 700.00	\$ 559.60
6	FRONT FENDER ATTACHMENTS PARTS RH	\$ 183.00	
7	FRONT FENDER CLOSING ELEMENT RH	\$ 45.00	
8	FRONT FENDER BRACKET - REAR RH	\$ 32.00	
9	FRONT FENDER DEFORMATION BRACKET RH	\$ 45.00	
10	FRONT FENDER POP RIVET RH	\$ 18.00	
11	FRONT FENDER BRACKET RH	\$ 29.00	
12	FRONT FENDER BRACE RH	\$ 107.00	
13	FRONT WHEEL HOUSING LINER RH	\$ 220.00	
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS RH	\$ 82.00	
15	FRONT WHEEL SPOILER RH	\$ 66.00	
16	FRONT WHEEL SPOILER TRIM RH	\$ 33.00	
17	FRONT STONE CHIP GUARD RH	\$ 46.00	\$ 36.64
18	FRONT FENDER LEDGE COVER INNER	\$ 28.00	
19	FRONT FENDER LEDGE COVER OUTER	\$ 21.00	
20	FRONT DOOR RHS	\$ 2,152.00	\$ 1,721.60
SUB TOTAL SPARE PARTS		\$ 6,101.00	\$ 2,317.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 676 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
	<i>c/f</i>		\$ 2,317.84
21	FRONT DOOR SEAL RH	\$ 185.00	\$ 147.60
22	BONDING AGENT	\$ 45.00	
23	CLEANING SOLUTION	\$ 65.00	
24	APPLICATOR	\$ 7.00	
25	FRONT DOOR ATTACHMENTS PARTS RH	\$ 488.00	
26	FRONT DOOR CATCH RH	\$ 96.00	
27	FRONT DATA PLATE PRESSURE	\$ 35.00	\$ 27.36
28	FRONT DOOR HANDLE TRIM PLATE	\$ 80.00	
29	FRONT DOOR HANDLE BEZEL COVER RH	\$ 6.00	
30	FRONT DOOR LOCK CYLINDER	\$ 492.00	
31	FRONT WING MIRROR MOUNTING RH	\$ 824.00	\$ 658.80
32	FRONT WING MIRROR CAP RH	\$ 220.00	\$ 175.60
33	FRONT WING MIRROR GLASS RH	\$ 1,533.00	
34	FRONT WINDOW CHROME SLOT SEAL RH	\$ 280.00	
35	FRONT WINDOW GUIDE TRIM RH	\$ 235.00	
36	ALUMINIUM RIM RH	\$ 558.00	
37	RUBBER VALVE	\$ 13.00	
38	LED HEADLIGHT RH	\$ 7,087.00	
39	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS		\$ 18,750.00	\$ 3,327.20
TOTAL LABOUR CHARGES		\$ 9,062.00	\$ 4,232.00
GRAND TOTAL		\$ 27,812.00	\$ 7,559.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 19 December 2019 6:31 PM
To: jiayee.yap@premiumauto.com.sg
Cc: Admin A; Adrian Ling (LKKAuto); Boo seng yak; Carrine Leong; Claims
Subject: FW: FINAL REVISION - SBG676P - TP AIG - SURVEYED 1 OCT 19
Attachments: WhatsApp Image 2019-11-25 at 11.51.27 AM.jpeg; WhatsApp Image 2019-11-25 at 11.51.26 AM.jpeg; PA11652019 - SBG 676 P - AUDI A4 1.4 TFSI S - FRONT - TP (AIG).xlsx

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter and e-mails as trailed.

For COR, recommended amount at **P/P \$ 7,559.20(before GST)** with 5 repair days.

**** Kindly forward your LOD and final repair bill to us (LKK) for our necessary action.**

Please note that all the finalisation subject to insurer approval.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jiayee.yap@premiumauto.com.sg <jiayee.yap@premiumauto.com.sg>
Sent: Wednesday, 4 December 2019 11:05 AM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SBG676P - TP AIG - SURVEYED 1 OCT 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$7559.20 @ 5 days of repairs.

Your early closure is well appreciated.

Thanks & Best Regard
JiaYee Yap
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902771W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiajee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer:

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

[> Back to OneMotoring](#)

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.

SBG676P

Make / Model

AUDI / A4 1.4 TFSI S TRONIC

Vehicle Type :

P10 - Passenger Motor Car

Vehicle Attachment 1 :

No Attachment

Vehicle Scheme :

Normal

Chassis No. :

WAUZZZF48HA055603

Propellant :

Petrol

Engine No. :

CVN021806

Motor No. :

-

Engine Capacity :

1395 cc

Power Rating :

-

Maximum Power Output :

110.0 kW (147 bhp)

Maximum Laden Weight :

1945 kg

Unladen Weight :

1450 kg

Year Of Manufacture :

2016

Original Registration Date :

30 Dec 2016

Lifespan Expiry Date :

-

COE Category :

E - Open Category

Quota Premium :

\$54,901.00

COE Expiry Date :

29 Dec 2026

Road Tax Expiry Date :

29 Dec 2019

PARF Eligibility Expiry Date :

29 Dec 2026

Inspection Due Date :

29 Dec 2019

Intended Transfer Date :

26 Sep 2019

CO2 Emission :

119.00 (g/km)

CEV/VES Rebate Utilised Amount :

\$10,000.00

CO Emission :

-

HC Emission :

-

NOx Emission :

-

PM Emission :

Fees To Be Paid For Transfer

Transfer Fees

\$25.00

Print

OK →

Save as PDF

Copy as Text

BREAKDOWN OF PAYMENT

Vehicle No: SBG676P

Accident on 26/09/2019 at JUNC OF HENDERSON ROAD & JALAN BUKIT MERAH

Involving vehicle/s GBG702Y

1) Repair cost \$ 8088.34 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 600.00 Payable to: NICHOLAS TAN JUN HAN

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN JUN HAN, NICHOLAS (CHEN JUNHAN)
Period of Insurance : 30 Dec 2018 To 29 Dec 2019
Engine No. : CVN021806
Chassis No. : WAUZZZF48HA055603

Vehicle No. : SBG676P
Policy No. : 2100495976-02
Endorsement No. :
Issued Date : 19 Dec 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN JUN HAN, NICHOLAS (CHEN JUNHAN) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125208

PREMIUM LEASING - SLOH

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159638

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

ESPMAL

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	26 Sep 2019 19:23	Cim Dtl Modified	Claimant's Name: -> NICHOLAS TAN JUN HAN, Claimant's ID: -> S8824638A.	[A] HOW MEI KWAN
2	26 Sep 2019 19:23	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] HOW MEI KWAN
3	26 Sep 2019 19:23	Cim Created	Reg No: S8G676P, Acct Date: 2019/09/26, Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), TP Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Premium Automobiles Pte Ltd (UBI)	[A] HOW MEI KWAN
4	26 Sep 2019 19:23	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); Suggested Adj. : LKK Auto Consultants Pte Ltd.	[A] HOW MEI KWAN
5	26 Sep 2019 19:23	Adj Next Rpt Changed	Next Rpt:Final Rpt, Due Date:2019/10/07	[A] HOW MEI KWAN
6	26 Sep 2019 19:23	Adj Mandate Set	Approved:0.00,Reinspr:Adj decides.	[A] HOW MEI KWAN
7	26 Sep 2019 19:23	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (E xpress)	[I] Merimen Administrator
8	26 Sep 2019 19:24	Label Added	(23):Express.	[A] HOW MEI KWAN
9	26 Sep 2019 19:24	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
10	01 Oct 2019 11:57	Video Downloaded	Downloaded OI VIDEO	[A] HOW MEI KWAN
11	01 Oct 2019 11:57	Video Downloaded	Downloaded OI VIDEO	[A] HOW MEI KWAN
12	01 Oct 2019 12:01	Video Downloaded	Downloaded OI VIDEO	[A] Khanchna Pothuraj
13	05 Nov 2019 10:22	Video Downloaded	Downloaded OI VIDEO	[I] Loh, Chee-Heng
14	26 Nov 2019 14:12	Video Downloaded	Downloaded OI VIDEO	[I] Khoo, Kay-Eng
15	26 Nov 2019 14:12	Video Downloaded	Downloaded TP VIDEO	[I] Khoo, Kay-Eng
16	26 Nov 2019 14:13	Video Downloaded	Downloaded OI VIDEO	[I] Khoo, Kay-Eng
17	26 Nov 2019 14:13	Video Downloaded	Downloaded OI VIDEO	[I] Khoo, Kay-Eng
18	07 Feb 2020 15:37	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
19	07 Feb 2020 15:37	Cim Dtl Modified	Claim Conclusion: -> 3.	[A] JOANNE LEE KHANG MIN
20	07 Feb 2020 15:37	Cim Dtl Modified	JPJ Reg. Date: -> 2016/12/30.	[A] JOANNE LEE KHANG MIN
21	07 Feb 2020 15:37	Cim Details Notified		[A] JOANNE LEE KHANG MIN
22	24 Feb 2020 19:01	Video Downloaded	Downloaded OI VIDEO	[A] Khanchna Pothuraj
23	24 Feb 2020 19:02	Video Downloaded	Downloaded TP VIDEO	[A] Khanchna Pothuraj
24	24 Feb 2020 19:17	Adj Mandate Request	Cur.Req:8690.34:OID changed lane. Liability down against OID. ** 5 days recommendation for repair + 1 Sunday = 6 days	[A] Khanchna Pothuraj

Date From



Date To



Audit Type None



Go

ACTIVITY

No record

Print Received Message

This mail is associated with :

***SBG676P (5914508069SG)**

[GBG702Y]

TP

NICHOLAS TAN JUN HAN

Sep 26 2019 1:00AM

[PLINIO VISONA SINGAPORE]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 25/02/2020 07:51 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8690.34) - SBG676P - Claim Handler: Loh, Chee-Heng

Approved:8690.34.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 5 March 2020 1:21 PM
To: Claims Dept
Cc: Admin A
Subject: RE: ACCIDENT INVOLVING SBG 676 P AND YOUR INSURED GBG 702 Y

Without Prejudice

(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as per your LOD **(S\$8,690.34 (all in))**.

We will proceed to do the necessary.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Thursday, 3 October 2019 8:52 AM
To: Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: ACCIDENT INVOLVING SBG 676 P AND YOUR INSURED GBG 702 Y

Dear Khanchna,

Noted. We accept your offer on direct settlement with 100% liability in our client's favour and For LOU/LOR rate. We will follow the benchmark rate by NIMA protocol.

Thank you.

Best Regards,

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019 Edit Reg		01 Oct 2019 00:00 Edit Adj Rpt	\$47,559.20 Edit Estimates	\$47,559.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: PLINIO VISONA SINGAPORE , Co. Reg. No.: 853310790C									
Main Claimant: NICHOLAS TAN JUN HAN , ID: S8824638A									
Vehicle Reg. No.: SBG676P		Date of Loss: 26/09/2019 01:00 - :59	[32 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type: TP / 5914508069SG		Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured): GBG702Y		Policy No. (Claimant):	2100495976-02						
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (25/02/2020): Alert - Adj Mandate Approved (\$48690.34) - SBG676P - Claim Handler: Loh, Chee-He...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SBG676P (5914508069SG)
[GBG702Y]

TP

NICHOLAS TAN JUN HAN
Sep 26 2019 1:00AM
[PLINIO VISONA SINGAPORE]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Video					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	15/11/19 17:22	TP VIDEO		Load MP4		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	27/09/19 12:14	OI VIDEO		Load MOV		

Letters/Correspondences					1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	24/02/20 18:52	General View		Load JPG	☒	
2	24/02/20 18:52	General View		Load JPG	☒	
3	24/02/20 18:52	General View		Load JPG	☒	
4	24/02/20 18:52	General View		Load JPG	☒	
5	24/02/20 18:52	General View		Load JPG	☒	
6	24/02/20 18:52	General View		Load JPG	☒	
7	24/02/20 18:52	General View		Load JPG	☒	
8	24/02/20 18:52	General View		Load JPG	☒	
9	24/02/20 18:52	General View		Load JPG	☒	
10	24/02/20 18:52	General View		Load JPG	☒	
11	24/02/20 18:52	General View		Load JPG	☒	
12	24/02/20 18:52	General View		Load JPG	☒	
13	24/02/20 18:52	General View		Load JPG	☒	
14	24/02/20 18:52	General View		Load JPG	☒	
15	24/02/20 18:52	General View		Load JPG	☒	
16	24/02/20 18:52	General View		Load JPG	☒	
17	24/02/20 18:52	General View		Load JPG	☒	
18	24/02/20 18:52	General View		Load JPG	☒	
19	24/02/20 18:52	General View		Load JPG	☒	
20	24/02/20 18:52	General View		Load JPG	☒	
21	24/02/20 18:52	General View		Load JPG	☒	
22	24/02/20 18:52	General View		Load JPG	☒	
23	24/02/20 18:52	General View		Load JPG	☒	
24	24/02/20 18:52	General View		Load JPG	☒	
25	24/02/20 18:52	General View		Load JPG	☒	
26	24/02/20 18:52	General View		Load JPG	☒	
27	24/02/20 18:52	General View		Load JPG	☒	
28	24/02/20 18:52	General View		Load JPG	☒	
29	24/02/20 18:52	General View		Load JPG	☒	

Documentation					1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	26/09/19 19:24	TP ESTIMATE		Load PDF		
2	26/09/19 19:24	TP GIA REPORT		Load PDF		
3	08/10/19 11:08	TP ESTIMATE - MARKED		Load PDF		
4	15/11/19 17:21	LETTER TO OI		Load PDF		

Video				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
5	10/02/20 12:34	GIA SEARCH		Load PDF	
6	10/02/20 12:34	RENTAL RECEIPT		Load PDF	
7	10/02/20 12:34	LOD		Load PDF	
8	12/03/20 11:30	WORKSHOP INVOICE		Load PDF	
9	12/03/20 11:30	AUTHORISATION TO ACT FORM		Load PDF	
10	12/03/20 11:30	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	27/09/19 12:12	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBG702Y (Insd veh)	Model:	AUDI A4 1.4 TFSI S TRONIC
	SBG676P (TP veh)		(A)
Date of Accident:	26/09/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	29,758.84
Final Repair Cost	:	\$	8,088.34
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	600.00 6 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	8,690.34

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 8,690.34
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

12 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19016998/AKA3Q2

Date: 12/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SBG676P

Insured Vehicle No : GBG702Y

Vehicle No : SBG676P

Date of Loss: 26/09/2019

Nature of Claim: TP

Claim No: 5914508069SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBG676P

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A)

Engine No: CVN021806

Reg. Date: 30/12/2016 (Man. Year: 2016)

Chassis No: WAUZZZF48HA055603

Colour: Black

Odometer: 43692 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,750.00	3,327.20	15,422.80	82.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,062.00	4,232.00	4,830.00	53.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	27,812.00	7,559.20	20,252.80	72.82
+ GST 7.00/7.00% (S\$)	1,946.84	529.14	1,417.70	72.82
Nett Amount (S\$)	29,758.84	8,088.34	21,670.50	72.82
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,690.34		

INSPECTION

Date of Assignment: 01/10/2019

Date Inspected: 01/10/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,946.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1		*LOCK CARRIAGE AIR GUIDE RH	Not Necessary	56.00 FS	*- FS
4	1		*FRONT BUMPER GUIDE SECTION RH	Not Necessary	34.00 FS	*- FS
5	1		*FRONT FENDER RH	Dented	700.00 FS	*559.60 FS
6	1		*FRONT FENDER ATTACHMENTS PARTS RH	Not Necessary	183.00 FS	*- FS
7	1		*FRONT FENDER CLOSING ELEMENT RH	Not Necessary	45.00 FS	*- FS
8	1		*FRONT FENDER BRACKET -REAR RH	Not Necessary	32.00 FS	*- FS
9	1		*FRONT FENDER DEFORMATION BRACKET RH	Not Necessary	45.00 FS	*- FS
10	1		*FRONT FENDER POP RIVET RH	Not Necessary	18.00 FS	*- FS
11	1		*FRONT FENDER BRACKET RH	Not Necessary	29.00 FS	*- FS
12	1		*FRONT FENDER BRACE RH	Not Necessary	107.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER RH	Not Necessary	220.00 FS	*- FS
14	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS RH	Not Necessary	82.00 FS	*- FS
15	1		*FRONT WHEEL SPOILER RH	Not Necessary	66.00 FS	*- FS
16	1		*FRONT WHEEL SPOILER TRIM RH	Not Necessary	33.00 FS	*- FS
17	1		*FRONT STONE CHIP GUARD RH	Necessary	46.00 FS	*36.64 FS
18	1		*FRONT FENDER LEDGE COVER INNER	Not Necessary	28.00 FS	*- FS
19	1		*FRONT FENDER LEDGE COVER OUTER	Not Necessary	21.00 FS	*- FS
20	1		*FRONT DOOR RHS	Dented	2,152.00 FS	*1,721.60 FS
21	1		*FRONT DOOR SEAL RH	Necessary	185.00 FS	*147.60 FS
22	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
23	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
24	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
25	1		*FRONT DOOR ATTACHMENTS PARTS RH	Not Necessary	488.00 FS	*- FS
26	1		*FRONT DOOR CATCH RH	Not Necessary	96.00 FS	*- FS
27	1		*FRONT DATA PLATE PRESSURE	Necessary	35.00 FS	*27.36 FS
28	1		*FRONT DOOR HANDLE TRIM PLATE	Repair	80.00 FS	*- FS
29	1		*FRONT DOOR HANDLE BEZEL COVER RH	Repair	6.00 FS	*- FS
30	1		*FRONT DOOR LOCK CYLINDER	Not Necessary	492.00 FS	*- FS
31	1		*FRONT WING MIRROR MOUNTING RH	Cut	824.00 FS	*658.80 FS
32	1		*FRONT WING MIRROR CAP RH	Cracked	220.00 FS	*175.60 FS
33	1		*FRONT WING MIRROR GLASS RH		1,533.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
34	1		*FRONT WINDOW CHROME SLOT SEAL RH	Not Necessary	280.00 FS	*- FS
35	1		*FRONT WINDOW GUIDE TRIM RH	Not Necessary	235.00 FS	*- FS
36	1		*ALUMINIUM RIM RH	Not Necessary	558.00 FS	*- FS
37	1		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
38	1		*LED HEADLIGHT RH	Not Necessary	7,087.00 FS	*- FS
39	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					18,750.00	3,327.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES .INSPECT FOR DAMAGES)	New	280.00	280.00
3	TO DISMANTLE RHS FRONT DOOR PANEL TRIM ,TO REMOVE AND RENEW RHS WING MIRROR ASSY)	New	300.00	0.00
4	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER ,RHA HEADLIGHT AND RHS FRONT DOOR .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	3,150.00	1,500.00
5	TO RESPRAY FRONT BUMPER ,BONNET ,RHS FRONT FENDER ,RHS FRONT DOOR ,DOOR HANDLE AND RHS WING MIRROR ASSY	New	4,500.00	1,900.00
6	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			9,062.00	4,232.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >