

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13850

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/1165/2019/KS
Date	:	9-Sep-19

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : : SBG 676 P

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Nicholas Tan Jun Han
Address	:	Blk 84 Telok Blangah Heights #11-323 Singapore 100084
Telephone	:	(HP) +65 91516486
Type of Claim	:	Third Party Claims
Policy No.	:	2100495976-02
Vehicle No	:	SBG 676 P
Model Code	:	Audi A4 1.4 TFSI S
Model / Year	:	30/12/2016
Engine No	:	CVN 021806
Chassis No	:	WAUZZZF48HA055603
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	26-Sep-19
Place of Accident	:	Intersection of Henderson Road & Jln Bukit Merah

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SBG 676 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and transfer rhs front door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 280.00 ✓	} Overlapped ?? X
3	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy.	S/N \$ 300.00 X	
4	To dismantle and renew front bumper, rhs front fender, rha headlight and rhs front door. Re-organise crash management components. Reinstall all parts removed.	\$ 3,150.00	1500
5	To respray front bumper, bonnet, rhs front fender, rhs front door, door handle and rhs wing mirror cover.	\$ 4,500.00	3 x 550 = 1650 Handle 100 Mirror 150 1900.
6	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 X	
7	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 9,062.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 676 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Repair</i>	\$ 1,946.00	X
2	FRONT BUMPER FIXING PARTS	\$ 258.00	X
3	LOCK CARRIER AIR GUIDE RH	\$ 56.00	X
4	FRONT BUMPER GUIDE SECTION RH	\$ 34.00	X
5	FRONT FENDER RH <i>Dented</i>	\$ 700.00	✓
6	FRONT FENDER ATTACHMENTS PARTS RH	\$ 183.00	?
7	FRONT FENDER CLOSING ELEMENT RH	\$ 45.00	?
8	FRONT FENDER BRACKET - REAR RH	\$ 32.00	?
9	FRONT FENDER DEFORMATION BRACKET RH	\$ 45.00	?
10	FRONT FENDER POP RIVET RH	\$ 18.00	?
11	FRONT FENDER BRACKET RH	\$ 29.00	?
12	FRONT FENDER BRACE RH	\$ 107.00	?
13	FRONT WHEEL HOUSING LINER RH	\$ 220.00	X
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS RH	\$ 82.00	X
15	FRONT WHEEL SPOILER RH	\$ 66.00	X
16	FRONT WHEEL SPOILER TRIM RH	\$ 33.00	✓
17	FRONT STONE CHIP GUARD RH	\$ 46.00	✓
18	FRONT FENDER LEDGE COVER INNER	\$ 28.00	?
19	FRONT FENDER LEDGE COVER OUTER	\$ 21.00	?
20	FRONT DOOR RHS <i>Dented</i>	\$ 2,152.00	✓
SUB TOTAL SPARE PARTS		\$ 6,101.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBG 676 P

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT DOOR SEAL RH <i>new</i>	\$ 185.00	✓
22	BONDING AGENT ?	\$ 45.00	?
23	CLEANING SOLUTION ?	\$ 65.00	?
24	APPLICATOR ?	\$ 7.00	?
25	FRONT DOOR ATTACHMENTS PARTS RH ?	\$ 488.00	?
26	FRONT DOOR CATCH RH <i>new</i>	\$ 96.00	+
27	FRONT DATA PLATE PRESSURE <i>new</i>	\$ 35.00	✓
28	FRONT DOOR HANDLE TRIM PLATE <i>Regi</i>	\$ 80.00	+
29	FRONT DOOR HANDLE BEZEL COVER RH <i>Regi</i>	\$ 6.00	+
30	FRONT DOOR LOCK CYLINDER <i>new</i>	\$ 492.00	+
31	FRONT WING MIRROR MOUNTING RH <i>cut</i>	\$ 824.00	✓
32	FRONT WING MIRROR CAP RH <i>cut</i>	\$ 220.00	✓
33	FRONT WING MIRROR GLASS RH <i>new</i>	\$ 1,533.00	+
34	FRONT WINDOW CHROME SLOT SEAL RH <i>new</i>	\$ 280.00	+
35	FRONT WINDOW GUIDE TRIM RH <i>new</i>	\$ 235.00	✓
36	ALUMINIUM RIM RH } <i>new</i>	\$ 558.00	+
37	RUBBER VALVE }	\$ 13.00	+
38	LED HEADLIGHT RH <i>Not New</i>	\$ 7,087.00	+
39	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS		\$ 18,750.00	
TOTAL LABOUR CHARGES		\$ 9,062.00	
GRAND TOTAL		\$ 27,812.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim.*
Surveyed Date : *01/10/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 Days.*

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant