

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Notarised
U/Sr 87
Resurvey After Paint
4 days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____

26.09.2019

Date: _____

Accident Date : 25.09.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Subaru Forester" Reg. No. SJV7544S Claiming Against Your Insured Reg. No. SLZ7916H			
1pc	Bonnet (Aluminium) M- 508sn		
1pc	Bonnet Insulation		
1pc	Grille		
1pc	Grille Emblem		
1pc	Grille Badge "STI"		
1pc	Front Bumper		
1pc	Front Bumper Clip		
1pc	Front Bumper Top Retainer		
1pc	Front Bumper Reinforcement		
2pcs	Front Bumper Stickers "STI Subaru Technical"		
1pc	Front Bumper Sponge		
1pc	Headlamp RH (HID)		
1pc	Headlamp Bulb RH		
1pc	Front Number Plate		
	Less 20%		
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	Labour Charge - Panel Beating, Repairing Of Support Panel, and Parts Replacement		600.00 4001
	To Respray Affected Areas		600.00 4501
	Total :		1,230.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____