

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9539M**AAD1909-221***Not Authorised
Henry Bapaing*

Vehicle No.:

Chassis No.:

26 SEP 2019

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD 9539M

JTDKB3FU003081675

TOYOTA

PRIUS

25.9.19

TOKIO MARINE

27/6/2019

		PART			LIST
1	1	REAR BUMPER	\$	<i>✓</i>	442.60 <i>X</i>
2	1	REAR BUMPER RE-INFORCEMENT	\$		332.70 <i>✓</i>
3	1	REAR BUMPER TOWING COVER	\$	<i>✓</i>	15.40 <i>X</i>
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	<i>ndt</i>	576.30 <i>✓</i>
5	1	REAR BUMPER SIDE RETAINER LH	\$	<i>✓</i>	116.50
6	1	REAR BUMPER SIDE RETAINER RH	\$	<i>✓</i>	117.70
7	1	REAR TAILGATE	\$	<i>✓</i>	1,147.80
8	1	REAR TAILGATE OUTER GARNISH	\$	<i>✓</i>	925.60
9	1	COVER, REAR COMBINATION LAMP, RH	\$	<i>✓</i>	64.50
10	1	COVER, REAR COMBINATION LAMP, LH	\$	<i>✓</i>	64.50
11	1	GARNISH, BACK DOOR SIDE, LH	\$	<i>✓</i>	95.60
12	1	GARNISH, BACK DOOR SIDE, RH	\$	<i>✓</i>	95.60
13	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>✓</i>	56.50
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>✓</i>	56.50
15	1	BOARD ASSY, BACK DOOR TRIM	\$	<i>✓</i>	259.20
16	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	<i>✓</i>	52.10
17	1	REAR TAILGATE WEATHERSTRIP	\$	<i>✓</i>	372.30
18	1	PANEL SUB-ASSY, BODY LOWER BACK	\$	<i>✓</i>	650.30
19	1	TAILLAMP LOWER RH	\$	<i>✓</i>	502.00
20	1	TAILLAMP UPPER RH	\$	<i>✓</i>	451.80
21	1	REAR BUMPER SIDE RH	\$	<i>✓</i>	123.70
22	1	REAR BUMPER SIDE LH	\$	<i>✓</i>	123.70
23	1	TAILLAMP LOWER LH	\$	<i>✓</i>	502.00
24	1	TAILLAMP UPPER LH	\$	<i>✓</i>	443.30
25	1	BOARD, BACK DOOR TRIM	\$	<i>✓</i>	225.20
26	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	<i>✓</i>	355.90
27	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	<i>✓</i>	355.90

Trans-cab Auto Services Pte Ltd**AAD1909-221**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9539M

28 1 COVER, DECK TRIM, REAR

	\$	<i>Sn</i> 126.70 <i>X</i>
TOTAL	\$	8,651.90
25%	\$	2,162.98
	\$	6,488.93

Special Nett

1 1SET PARKING AID	\$	<i>Sn</i> 700.00	<i>X</i>
2 1SET REAR BUMPER CLIP	\$	<i>nn</i> 55.00	
3 2 REAR WINDSCREEN SEALANT	\$	<i>nn</i> 80.00	
4 1 WINDSCREEN MOULDING	\$	<i>Sn</i> 100.00	
5 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00	
6 1 REAR TAILGATE TOYOTA LOGO	\$	<i>nn</i> 47.00	
7 1 REAR TAILGATE WORDING 'PRIUS'	\$	<i>nn</i> 52.90	
8 1 REAR TAILGATE WORDING 'HYBRID'	\$	<i>nn</i> 53.50	
9 1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	<i>nn</i> 80.00	
10 1 REAR TAILGATE STICKER '6555-3333'	\$	<i>nn</i> 80.00	
11 1 REAR BUMPER PROTECTOR	\$	<i>nn</i> 100.00	
12 1 REAR WHEEL RIM	\$	<i>Sn</i> 1,570.55	
13 1 REAR TYRE 195/65/15	\$	<i>Sn</i> 350.00	
14 1 REAR WHEEL RIM COVER	\$	<i>Sn</i> 175.80	
TOTAL	\$	3,544.75	

TOTAL PARTS \$ 10,033.68**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 170.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 *2200*

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ *nn* 170.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 *1000*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 170.00 *X*

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ *nn* 170.00 *X*

Trans-cab Auto Services Pte Ltd**AAD1909-221**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9539M

To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00	X
To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	X
TOTAL	\$	14,340.00	
Over All Total	\$	24,373.68	

(PART-BY-PART) Repair Days**20 Days***1 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: