

ASS. REC. BY:

REF:

TNI/
03/TMI19017036/Knd3n2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: SJD2196RPolicy No. M3002456Claims No. M1907567

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 875k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 1/2 days Res.: Yes or NoLum Sum: 1.3.1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: S1D 9539A Yr Regn: 0619

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Prox c.c. 1788Colour M. White / Red A/C: Insured / Std / NI / NASp. Reading 27246 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK B31-U 003081675

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 8 mmR/Bal. 8 mmL/Bal. 8 mmD.O.A. 25/9/19D.O.I. 26/9/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ File pass to

S1D9539A-M-03/AXA13008526/K1b3

SJD2196R-03/LPC18004393/Avd3n2

DOA: 8/5/2013

DOA: 26/2/2018

27/9/19

Email GIA and preli revised to TMS RECEIVED 10 OCT 2019

17/10/19

8752.23 amount (Reel 23,621.45, 96%) confirmed by email

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 17/10 - typist

Days Of Repair: 1 1/2Resurvey No. of Trip: -Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S - RS - SI

Fees:

Others:

TOTAL

250

11

261

Report Format :

M. Riman

Lump Sum / I.B.I. (\$) 752.23



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: PLEASE ADVISED

Our ref: CC3/TMI19017036/Kvd3

Date :27/9/2019

The Motor Claims Department
M/S TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SHD 9539M

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/9/2019 at the premises of M/ TRANS-CAB AUTO SERVICES PTE TLD and have the following to report:-

Workshop Estimate Amount	: S\$24,373.68
Revised Estimate Amount	: S\$752.23
"Check" Items Amount	: S\$249.53
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019		27 Sep 2019 14:24 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LIM HO HENG, ID: S1480610E, Tel: +6598553412, Email: NOEMAIL		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD9539M	Date of Loss:	25/09/2019 09:00 - :59
Claim Type:	TP / M1907567	Policy/Cover Note No.:	MS002456 (Comprehensive) Coverage: 13/03/2019 - 12/03/2020
Vehicle Reg. No. (Insured):	SJD2196R	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Trans Cab Auto Services Pte Ltd - Amk (HQ) No 2 Ang Mo Kio St 63, 569111 Ang Mo Kio - Tel:		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 08/10/2019]		
Driver/Custodian (Insured):	LIM HO HENG (57 / Male), NRIC: S1480610E, Tel: +6598553412 Email: NOEMAIL		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 September 2019 11:44 AM
To: motorclaims@tokiomarine.com.sg; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP -TRANS-CAB AUTO SERVICES PTE LTD, DOA:25/9/2019, SHD 9539M (TP VEHICLE), SJD 2196R (OI VEHICLE)
Attachments: GIA.pdf; MARK EST.pdf; PRELI REVISED.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 9539M at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 26/9/2019

Enclosed herewith a copy of TP's GIA report, estimated cost of repair and preliminary revised.

Kindly create claim in merimen for our necessary action.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 17 October 2019 10:40 AM
To: Ng Wai Yin; SUR
Cc: jasminetan@transcab.com.sg
Subject: FINALISE-2 VEHICLES
Attachments: SHC 5628X EST.pdf; SHD 9539M MARK_EST.pdf

Dear Wai Yin,

WITHOUT PREJUDICE

- 1) SHC 5628X-DOA: 11/10/19 Lump Sum \$11,450 before GST @ 14 working days.
- 2) SHD 9539M-DOA:25/9/19 Final amount \$752.23 before GST @ 1.5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 17 October 2019 3:38 PM
To: Veron Chen (LKKAUTO)
Cc: jasminetan@transcab.com.sg; SUR
Subject: FW: FINALISE-2 VEHICLES
Attachments: SHC 5628X EST.pdf; SHD 9539M MARK_EST.pdf

Hi Veron

Please see below my replied.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 17 October, 2019 10:40 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; SUR <sur@lkkauto.com>
Cc: jasminetan@transcab.com.sg
Subject: FINALISE-2 VEHICLES

Dear Wai Yin,

WITHOUT PREJUDICE

- 1) SHC 5628X-DOA: 11/10/19 Lump Sum \$11,450 before GST @ 14 working days. - amount confirmed \$ 11,450 (before GST)
- 2) SHD 9539M-DOA:25/9/19 Final amount \$752.23 before GST @ 1.5 days – amount confirmed \$ 752.23 (before GST)

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD9539M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C30621
Chassis No.:	JTDKB3FU003081675
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	27 Jun 2019
First Registration Date:	27 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	26 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,872.00
COE Rebate Amount:	\$19,097.00
Total Rebate Amount:	\$29,782.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 25 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/09/2019 14:57
Date Of Accident	25/09/2019 08:55
Exact Location Of Accident	KEPPEL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9539M
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.5 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P2203857
Cover Note Number	

Driver

Name of Driver	CHONG KOK YONG
NRIC No	S7039973C
Date Of Birth	03/11/1970
Occupation	OUTDOOR
Date Of Driving Pass	19/06/1995
Driving Experience	24 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91076554
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 161 BUKIT MERAH CENTRAL #03-3709
Postcode	150161
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MS MA - 96708721 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 25.09.2019 at about 0854hours, I was stationary straight on the Centre lane along Keppel Road due to congestions ahead. While stationary, suddenly I felt an impact. Vehicle B (SJD2196R) hit onto my taxi's rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD2196R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM HO HENG
NRIC/Passport Number	S1480610E
Contact Number	98553412
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Koppel Road

A. SHO 9539M
B. SJO 2195R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see other GA report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9539M**AAD1909-221***Not Authorised**Resony Bepaint**8752.23*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

26 SEP 2019

SHD 9539M

JTDKB3FU003081675

TOYOTA

PRIUS

25.9.19

TOKIO MARINE

27/6/2019

		PART	LIST
1	1	REAR BUMPER	\$ 442.60 X
2	1	REAR BUMPER RE-INFORCEMENT	\$ 332.70 X
3	1	REAR BUMPER TOWING COVER	\$ 15.40 X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$ 576.30
5	1	REAR BUMPER SIDE RETAINER LH	\$ 116.50
6	1	REAR BUMPER SIDE RETAINER RH	\$ 117.70
7	1	REAR TAILGATE	\$ 1,147.80
8	1	REAR TAILGATE OUTER GARNISH	\$ 925.60
9	1	COVER, REAR COMBINATION LAMP, RH	\$ 64.50
10	1	COVER, REAR COMBINATION LAMP, LH	\$ 64.50
11	1	GARNISH, BACK DOOR SIDE, LH	\$ 95.60
12	1	GARNISH, BACK DOOR SIDE, RH	\$ 95.60
13	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$ 56.50
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$ 56.50
15	1	BOARD ASSY, BACK DOOR TRIM	\$ 259.20
16	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$ 52.10
17	1	REAR TAILGATE WEATHERSTRIP	\$ 372.30
18	1	PANEL SUB-ASSY, BODY LOWER BACK	\$ 650.30
19	1	TAILLAMP LOWER RH	\$ 502.00
20	1	TAILLAMP UPPER RH	\$ 451.80
21	1	REAR BUMPER SIDE RH	\$ 123.70
22	1	REAR BUMPER SIDE LH	\$ 123.70
23	1	TAILLAMP LOWER LH	\$ 502.00
24	1	TAILLAMP UPPER LH	\$ 443.30
25	1	BOARD, BACK DOOR TRIM	\$ 225.20
26	1	PANEL ASSY, DECK TRIM SIDE, RH	\$ 355.90
27	1	PANEL ASSY, DECK TRIM SIDE, LH	\$ 355.90

Trans-cab Auto Services Pte Ltd

AAD1909-221

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9539M

28 1 COVER, DECK TRIM, REAR

	\$	Sn 126.70 X
TOTAL	\$	8,651.90
25%	\$	2,162.98
	\$	6,488.93

Special Nett

- 1 1SET PARKING AID
- 2 1SET REAR BUMPER CLIP
- 3 2 REAR WINDSCREEN SEALANT
- 4 1 WINDSCREEN MOULDING
- 5 1 REAR WINDSCREEN INNER SPONGE SEAL
- 6 1 REAR TAILGATE TOYOTA LOGO
- 7 1 REAR TAILGATE WORDING 'PRIUS'
- 8 1 REAR TAILGATE WORDING 'HYBRID'
- 9 1 REAR TAILGATE STICKER 'TRANS-CAB'
- 10 1 REAR TAILGATE STICKER '6555-3333'
- 11 1 REAR BUMPER PROTECTOR
- 12 1 REAR WHEEL RIM
- 13 1 REAR TYRE 195/65/15
- 14 1 REAR WHEEL RIM COVER

\$	Sn 700.00	}	X
\$	nn 55.00		
\$	nn 80.00		
\$	Sn 100.00		
\$	nn 100.00		
\$	nn 47.00		
\$	nn 52.90		
\$	nn 53.50		
\$	nn 80.00		
\$	nn 80.00		
\$	nn 100.00		
\$	Sn 1,570.55		
\$	Sn 350.00		
\$	Sn 175.80		

TOTAL \$ 3,544.75**TOTAL PARTS \$ 10,033.68****LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 2201

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ nn 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,000.00 1001

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

To transfer of rear windscreen glass to facilitate bodywork repair.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9539M**AAD1909-221**

To reinstall rear bumper parking sensor.	\$	~ 170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
To Check Electrical Lighting Concerned.	\$	~ 170.00 X
TOTAL	\$	14,340.00
Over All Total	\$	24,373.68

(PART-BY-PART) Repair Days**20 Days***1 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19017036/KVD3N2

Date: 23/10/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS002456
Claimant Vehicle No :	SHD9539M	Insured Vehicle No :	SJD2196R
Date of Loss:	25/09/2019	Nature of Claim:	TP
		Claim No:	M1907567

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9539M	Engine No:	2ZR2C30621
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID CVT (A)	Chassis No:	JTDKB3FU003081675
Reg. Date:	27/06/2019 (Man. Year: 2018)	Odometer:	27246 km
Colour:	Metallic White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,033.68	432.23	9,601.45	95.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,340.00	320.00	14,020.00	97.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,373.68	752.23	23,621.45	96.91
+ GST 7.00/7.00% (S\$)	1,706.16	52.66	1,653.50	96.91
Nett Amount (S\$)	26,079.84	804.89	25,274.95	96.91

INSPECTION

Date of Assignment: 27/09/2019

Date Inspected: 26/09/2019 Inspected At:

Trans Cab Auto Services Pte Ltd - Amk (HQ)
No 2 Ang Mo Kio St 63
Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Oct 2019)
Parts:	144	TOYOTA PRIUS 1.5 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD9539M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	442.60 FL	*- FL
2	1		*REAR BUMPER RE-INFORCEMENT	Repair	332.70 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
6	1		*REAR TAILGATE	Repair	1,147.80 FL	*- FL
7	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
8	1		*COVER,REAR COMBINATION LAMP,RH	Serviceable	64.50 FL	*- FL
9	1		*COVER,REAR COMBINATION LAMP,LH	Serviceable	64.50 FL	*- FL
10	1		*GARNISH,BACK DOOR SIDE,LH	Serviceable	95.60 FL	*- FL
11	1		*GARNISH,BACK DOOR SIDE,RH	Serviceable	95.60 FL	*- FL
12	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	56.50 FL	*- FL
13	1		*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER LH	Serviceable	56.50 FL	*- FL
14	1		*BOARD ASSY,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
15	1		*PANEL ASSY,BACK DOOR TRIM,UPPER	Serviceable	52.10 FL	*- FL
16	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
17	1		*PANEL SUB-ASSY,BODY LOWER BACK	Serviceable	650.30 FL	*- FL
18	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
19	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
20	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
21	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
22	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
23	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
24	1		*BOARD,BACK DOOR TRIM	Serviceable	225.20 FL	*- FL
25	1		*PANEL ASSY,DECK TRIM SIDE,RH	Serviceable	355.90 FL	*- FL
26	1		*PANEL ASSY,DECK TRIM SIDE,LH	Serviceable	355.90 FL	*- FL
27	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	*- FL
28	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Not Necessary	55.00 FS	*- FS
30	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*WINDSCREEN MOULDING	Serviceable	100.00 FS	*- FS
32	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
33	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
34	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
35	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
36	1		*REAR TAILGATE STICKER TRANS-CAB	Not	80.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Necessary		
37	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*-FS
38	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*-FS
39	1		*REAR WHEEL RIM	Serviceable	1,570.55 FS	*-FS
40	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*-FS
41	1		*REAR WHEEL RIM COVER	Serviceable	175.80 FS	*-FS
42	1		*REAR BUMPER UNDER COVER (BLACK)	Dented	432.23 FS	*432.23 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,052.58 432.23

- List Item Discount on L Items 25.00/25.00% (\$\$) 2,018.90 0.00

Total Parts (\$\$) 10,033.68 432.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF TAILGATE FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
3	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	100.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
6	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
11	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
13	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
Gross Labour Cost (S\$)			14,340.00	320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >