

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
 78 Shenton Way #07-16
 Singapore 079120
 Tel : 6419 - 3000
 Fax : 6835 - 7416

Jia Le.

Quotation
 DATE : 26.09.2019
 VEH NO : SGB2787G
 MODEL : Kia Cerato
 D O A : 23.09.2019
 YR REF : SMA3439P

671J

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SGB2787G (KIA CERATO)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Number Plate Garnish <i>could</i>	1	40.30 ✓
2	Front Bumper <i>Distorted</i>	1	575.00 ✓
3	Front Bumper Clips <i>re</i>	1	30.00 ✓
4	Front Bumper Side Holder - LH & RH <i>re</i>	2	71.80 ✓
5	Front Bumper Reinforcement <i>Bent</i>	1	242.50 ✓
6	Front Bumper Sponge <i>could</i>	1	162.00 ✓
7	Front Bumper Lower Grille <i>re re</i>	1	68.50 +
8	Front Bumper Side Grille - LH & RH <i>re re</i>	2	80.60 +
9	Front Bumper Fog Lamp - LH & RH <i>re re</i>	2	296.00 +
10	Front Grille <i>could</i>	1	227.00 ✓
11	Front Grille Logo <i>re</i>	1	35.00 ✓
12	Head Lamp - LH & RH <i>could</i>	2	1,120.80 ✓
13	Head Lamp Lower Bracket - LH & RH <i>Bent</i>	2	68.00 ✓
14	Bonnet <i>Distorted</i>	1	771.60 ✓
15	Bonnet Lock <i>Damaged</i>	1	72.00 ✓
16	Bonnet Inner Trim <i>re re</i>	1	168.00 +
17	Bonnet Inner Trim Clips <i>re</i>	1	30.00 ✓
18	Front Fender - LH & RH <i>Repair</i>	2	920.60 X
19	Front Support Panel <i>Distorted</i>	1	688.20 ✓
20	Air Con Condenser <i>Bent</i>	1	787.00 ✓
21	Air Con Condenser Side Garnish - LH & RH <i>Distorted</i>	2	68.00 ✓
22	Radiator <i>Not new</i>	1	755.30 X
23	Rear Bumper <i>Distorted</i>	1	586.50 ✓
24	Rear Bumper Clips <i>re</i>	1	30.00 ✓
25	Rear Bumper Side Holder - LH & RH <i>re</i>	2	65.20 ✓
26	Rear Bumper Lower Garnish <i>Distorted</i>	1	421.00 ✓
27	Rear Bumper Reinforcement <i>Distorted</i>	1	279.00 ✓
28	Rear Bumper Reinforcement Stay - LH & RH <i>Bent</i>	2	270.00 ✓

RE: ESTIMATE FOR ACCIDENT REPAIR SGB2787G (KIA CERATO)

29	Rear Bumper Reinforcement Bracket - LH & RH	2	120.00 ✓
30	Rear Bumper Sponge	1	174.00 ✓
31	Reverse Sensor Wire Harness	1	191.40 ✗
32	Rear End Panel	1	481.00 ✓
33	Rear End Panel Top Garnish	1	169.20 ✓
34	Tail Lamp - LH & RH	2	492.00 ✓
35	Tail Lamp Panel - LH & RH	2	210.00 ✓
36	Boot Lid	1	792.00 ✓
37	Boot Lid Lock	1	104.70 ✓
38	Boot Lid Weatherstripe	1	81.90 ✓
39	Boot Lid Hinges - LH & RH	2	124.00 ✓
40	Boot Lid Reflector - LH & RH	2	261.80 ✓ 130.90
41	Boot Lid Outer Chrome Moulding	1	210.00 ✓
42	Boot Lid Inner Trim Board	1	168.00 ✗
43	Boot Lid Inner Trim Board Clips	1	30.00 ✓
44	Kia Logo	1	46.00 ✓
45	cycle and carriage logo	1	35.00 ✓
46	Rear Fender - LH	1	987.00 ✓
47	Rear Fender Inner Trim - LH & RH	2	537.00 ✓
48	Rear Fender Inner Trim Clips	1	60.00 ✓
49	Rear Windscreen Moulding	1	120.60 ✓
50	Spare Tyre Panel	1	696.00 ✓ 12242.20
51	Spare Tyre Panel Top Cover	1	179.00 ✗ 11017.98
52	Spare Tyre Panel Lock Screw	1	46.00 ✗
53	Rear Exhaust Pipe	1	686.00 ✗
54	Rear Exhaust Mounting	1	44.00 ✗

15,976.50

Less 20%

(3,195.30)

\$ 12,781.20

S/NETT ITEMS

1	Front Number Plate	1	30.00 ✓
2	Front Number Plate Holder	1	30.00 ✓
3	Radiator Coolant	1	60.00 40
4	Rear Number Plate	1	30.00 ✓
5	Rear Number Plate Holder	1	30.00 ✓
6	Reverse Sensor	4	880.00 380
7	Rear End Panel Sealant	1	60.00 ✓ 660
8	Bootlid Top Spoiler	1	680.00 ✗
9	Rear Camera	1	480.00 ✗
10	Rear Windscreen Sealant	1	60.00 ✓
11	Spare Tyre Panel Insulation Pad	1	280.00 ✗

2,620.00

Total Parts

\$ 15,401.20

LABOUR CHARGE

RE : ESTIMATE FOR ACCIDENT REPAIR SGB2787G (KIA CERATO)

1	To knocking & pull out front & rear portion & renew above parts	\$	3,000.00 2400
2	To putty & spray up paint works	\$	2,600.00 2000
3	To check wiring	\$	100.00 60
4	To underseal	\$	250.00 100
5	To remove reverse sensor	\$	100.00 50
6	To remove rear camera	\$	100.00 50
7	To remove upholstery and rear seat	\$	300.00 120
8	To remove rear windscreen	\$	180.00 120
9	To remove fuel tank	\$	150.00 80
10	To remove exhaust pipe	\$	150.00 X
11	To transfer bootlid fittings	\$	150.00 60
12	To remove condenser, radiator & top up air con gas	\$	180.00 120
Total Labour		\$	7,260.00
Grand Total		\$	22,661.20

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

total: 16837.58

L/S 13.4K

16 Days.