

INSURANCE

INS. CASE OWNER:

CC 3 /AIG1901 7064, FEB 9/

LKK:
IDAC:

Surveyor:

Steve

DOI:

ASSIGNMENT

15/10/19

Date / Time:

27/1/19

Registered in Meritum:

27/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 7341C

Claim No.:

873089119359

Name of Insured:

HO ONLY SENDER DAVID

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

27/1/19

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OT GIA REPORT YES / NO : TP GIA REPORT YES / NO

Insured Liability: % Final ? Yes / No

SKS 1237



INSRS:
WSP:
Tel:
Liability:
RMKS:

performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	STAGE	DATE/ PIC
10/10	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
10.10.19	Call OE:	ASHEE 10.10.19
	After call Itr to OE:	
	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	
	After call Itr to OE:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PDR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	PIP \$5,444.25	(3 days) Reduction: 43 %
FINAL SETTLEMENT	Date/Time: 10.12.19	Confirm with: CAROLINE
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. : 51
Repair Cost:	\$5,831.49	01 REPAIR ENDED TP
Loss of Rental (LOR):	\$5 -	(3 days)
Loss of Use (LOU):	\$5 300.00	(5 100 x 3 days)
Loss of Income (LOI):	\$5 -	(5 x days)
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LO <input type="checkbox"/>	[Tick only one]
GIA/LTA Search	\$5 2.00	
Medical:	\$5 -	
Disbursement:	\$5 -	(e.g. Tow/ Independent)
Legal Cost	\$5 -	
Total:	\$5 6,129.49	Global Sum \$5:
FINAL PAYMENT	Date/Time: 10.12.19	Confirm with: CAROLINE
Payee 1:	\$5 6,129.49	Name 1: PERFORMANCE MODELS LIMITED
Payee 2: (Strike if N.A.)	\$5	Name 2:
Payee 3: (Strike if N.A.)	\$5	Name 3:

Surveyor

Steve

REF:

AIG

e

ASSIGNMENT

From:

Date:

Veh No: SKS 1232

Yr Regn: 29/7/16

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make: BMW 73041

c.c 1998

at Workshop m/s

Colour: Blue

A/C: Insured / Std / NI / NA

of

Sp. Reading: 51925

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

CiNo: WDA 7E07010 6244984

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:


Mod: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 245/50R18

R:

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Pirelli

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal. 5 mm

R/Bal. 5 mm

GIA / PR. Seen:

Consistent? : Yes or No

L/Bal. 5 mm

L/Bal. 5 mm

Est. Repairs:

3 days Res.: Yes or No

D.O.A. 25/9/19

D.O.I. 15/10/19

Lum Sum:

% 3 Val.: Yes or No

Survey held at Performance

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-220K

PIP: + 5,446.25 (RED) + 396.96 (25%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

) S + RS - SI

Report Format :

☐ : Interview (\$

) Photos

Lump Sum / I.B.I: (\$

☐ : Tech Invs (\$

) Others

☐ : Weekend (\$

)

TOTAL

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255289)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (MotorRAD)



GST REG. NO : M2 - 0020081 - X

26 SEP 2019

ESTIMATE

Estimate No. : b1 52875
Date Estimated : 26/09/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ho Kah Siong
119 Fidelio Street

Singapore 458494

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS123Z	WBA7E02010G244984	29/07/2016	730Li	0

DESCRIPTION

To replace rear bumper and attachment include knocking cause by the accident.

Painting rear bumper

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

VALUE

850 / 1,700.00

934 / 1,038.00

150 / 177.00

80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER ADAPTER

REAR BUMPER CARRIER

REAR BUMPER CENTRE GUIDE

REAR LH MOUNT LATERAL

REAR RH MOUNT LATERAL

LH TRIM EXHAUST TAILPIPE

RH TRIM EXHAUST TAILPIPE

REAR BUMPER CENTRE GUARD

REAR BUMPER GUARD

LH RUBBER STRIP

RH RUBBER STRIP

REAR BUMPER COVER

REAR BUMPER TRIM PRIMED

REAR BUMPER PANEL PRIMED (PDC/PMA)

REAR BUMPER TOWING EYE COVER PRIMED

REAR SILENCER HEAT INSULATOR

Sound insula

HEAT INSULATOR FLOOR PANEL TRUNK

DECOUPING RING PDC TORQUE CONVERTER

ULTRASONIC TRANSDUCER JATOBA WB65

QTY

PRIC

VALUE

1 84.50 84.50

1 971.25 971.25

1 67.45 67.45

1 160.55 160.55

1 160.55 160.55

1 248.80 248.80

1 248.80 248.80

1 83.85 83.85

1 109.70 109.70

1 86.75 86.75

1 86.75 86.75

1 110.00 110.00

1 216.45 216.45

1 1,746.65 1,746.65

1 57.10 57.10

1 133.40 133.40

1 115.60 115.60

1 37.10 37.10

4 5.05 20.20

4 380.65 1,522.60

Total Parts : 6,268.05

Rear diffuser

STEVE LKK

WORKSHOP QUOTATION

GST REG NO : M2 - 0020081 - X

Vehicle No : SKS123Z
assis No : _____
A Name : Garry Bh
del Year : _____

Quotation No : 0000535455
Date : 16/10/2019
Time : 09:38:39
Page : 1
Partsman : p97lomi
Del Doc : 003825968

STK	PDC	ISS.	SELLING	DIS	NET	
CT	AT	SOH	QTY	PRICE	PRICE	
1	51757340186	REAR DIFFUSER	P	1	152.80	152.80

cr

(Supp)

Ramu

16/10/19

A Signature : _____
te : _____
ne : _____

Parts Total : 152.80
Labour Charges :

Sub Total :
Add 7% GST :

Customer's Name : _____
Contact Person : _____

TOTAL AMOUNT :

- Notes:
- (1) The above quotation is based on visual inspection only and may change based on further checks.
 - (2) The validity of this quotation is 14 days from the above date.
 - (3) Parts are subject to availability.
 - (4) Any prices change is without prior notice.

If the quotation is acceptable to you, please confirm your authorization for to proceed with the job on the understanding that prior approval will be obtained from you before we carry out any further repair or replacement of

Performance Motors Limited

A member of the Sime Darby Group
Co Reg No: 197401559N GST Reg No: M2-0020081-X



Final Report

Estimate No. : **b1 52875**
Date Estimated : **26/09/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -
Ho Kah Siong
119 Fidelio Street

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 458494

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS123Z	WBA7E02010G2449	29/07/2016	730Li	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachment including to remove and install body parts in order to carry out painting job.	850.00	0	850.00 /
To respray rear bumper	934.00	0	934.00 /
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 /
Sundries.	80.00	0	80.00 /

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR BUMPER ADAPTER		1.00		84.50
REAR BUMPER CARRIER		1.00		971.25
REAR BUMPER CENTRE GUARD		1.00		83.85
REAR BUMPER GUARD		1.00		109.70
LH RUBBER STRIP		1.00		86.75
RH RUBBER STRIP		1.00		86.75
REAR BUMPER COVER		1.00		110.00
REAR BUMPER PANEL PRIMED (PDC/PMA)		1.00		1,746.65
# REAR DIFFUSER		1.00		152.80

SUPPLEMENTARY ITEMS

TO	DATE	DAYS
Steve LKK	5/11/19	3
PAID TO		
PAID TO		
TO		
CONFIRMED DATE		

Total Labour :	2,014.00
Total Parts :	3,432.25
Total Labour & Parts :	5,446.25 /
GST @7%:	381.24
Grand Total :	5,827.49

LOSS OF USE = \$100 X 3 DAYS.
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52875**
Date Estimated : **26/09/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Ho Kah Siong
119 Fidelio Street

Singapore 458494

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS123Z	WBA7E02010G2449	29/07/2016	730Li	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# REAR DIFFUSER		1.00		152.80

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	152.80
Total Labour & Parts :	152.80

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197481559W GST Reg. No. M2-0020081-X
Toll-Free Number (1800-2255269)

191, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

26 SEP 2019

ESTIMATE

Estimate No. : b1 52875
Date Estimated : 26/09/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Ho Kah Siong
119 Fidelio Street

Singapore 458494

- ACCOUNT - 40000

Cash Sales - Service
Singapore

NLY

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS123Z	WBA7E02010G244984	29/07/2016	730Li	0

DESCRIPTION

To replace rear bumper and attachment include knocking
cause by the accident.

850 1,700.00

Painting rear bumper

974 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries.

80.00

Total Labour 1: 2,995.00

DESCRIPTION

REAR BUMPER ADAPTER
REAR BUMPER CARRIER
REAR BUMPER CENTRE GUIDE
REAR LH MOUNT LATERAL
REAR RH MOUNT LATERAL
LH TRIM EXHAUST TAILPIPE X
RH TRIM EXHAUST TAILPIPE X
REAR BUMPER CENTRE GUARD
REAR BUMPER GUARD 2 (Chase) CAT
LH RUBBER STRIP
RH RUBBER STRIP
REAR BUMPER COVER 2
REAR BUMPER TRIM PRIMED 2 / OR (lower body)
REAR BUMPER PANEL PRIMED (PDC/PMA) / PD
REAR BUMPER TOWING EYE COVER PRIMED X
REAR SILENCER HEAT INSULATOR X
Sound insula
HEAT INSULATOR FLOOR PANEL TRUNK
DECOUPING RING PDC TORQUE CONVERTER / OR
ULTRASONIC TRANSDUCER JATOBA WB65

QTY	PRIC	VALUE
1	84.50	84.50
1	971.25	971.25
1	67.45	67.45
1	160.55	160.55
1	160.55	160.55
1	248.80	248.80
1	248.80	248.80
1	83.85	83.85
1	109.70	109.70
1	86.75	86.75
1	86.75	86.75
1	110.00	110.00
1	216.45	216.45
1	1,746.65	1,746.65
1	57.10	57.10
1	133.40	133.40
1	115.60	115.60
1	37.10	37.10
4	5.05	20.20
4	380.65	1,522.60

Total Parts : 6,268.05



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64794601 (AfterSales)
64794624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 52875
Date Estimated : 26/09/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS123Z	WBA7E02010G244984	29/07/2016	730Li	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date&Time 15/10/15, 4:40pm Excess S\$ _____

Surveyor's Name Steve (LKK) Sign _____

Surveyor's Tel 8322 8813 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P/M Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended _____

MR. P/P
By BEL sm
3 dy

Labour 1	:	2,995.00
Parts	:	6,268.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	648.41
Grand Total	:	9,911.46

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	026Z
Vehicle Details	
Vehicle No.:	SKS123Z
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Oct 2019
Vehicle Make:	B.M.W.
Vehicle Model:	730LI LED NAV HUD SR
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	27759595B48B20B
Chassis No.:	WBA7E02010G244984
Maximum Power Output:	190.0 kW (254 bhp)
Open Market Value:	\$69,825.00
Original Registration Date:	29 Jul 2016
First Registration Date:	29 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$97,685.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2026
PARF Rebate Amount:	\$73,263.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,501.00
COE Rebate Amount:	\$39,014.00
Total Rebate Amount:	\$112,277.00

The information contained herein is correct as at 15 Oct 2019

OK

View Received Message

This mail is associated with :

***SKS123Z (8570891193SG)**
[SLX3341C]

TP
RICKY HO KAH SIONG
Sep 25 2019 8:00PM
[HO ENG SENG DAVID]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 30/09/2019 15:54 PM.
To LKK_HQ
Subject No OI GIA Report

Hi,

Pls be advice that no OI GIA report received.
Pls find OI details below for your further actions.

OI name : Ho Eng Seng David

Address : 61, Upper Seragoon view,
#16-19,
Singapore 534015

Mobile No: 98326445

Thank you.

Regards,
Divya

DOCUMENTS SUMMARY

There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG19017064/eb3

01 October, 2019

Ho Eng Seng David

61, Upper Serangoon view #16-19,
Singapore 534015

Dear Sirs,

**ACCIDENT INVOLVING SLX 3341C AND SKS 123Z ON 25/09/2019 ALONG/
AT EUNOS ROAD 5**

We, LKK Auto Consultants Pte Ltd has been appointed to act on the behalf of your insurer, AIG Asia Pacific Insurance Pte Ltd (AIG) to settle a THIRD PARTY claim against you for an accident which happened on the above-mentioned date and location.

Kindly proceed to lodge your GIA report within five (05) working days of receipt of this letter, giving the version of the accident amongst other things related to the accident. The GIA report can be lodged at any of AIG reporting centres. You may refer to your Certificate of Insurance for the list of the reporting centres.

If you have any information to add or any amendments to make, please contact the undersigned within five days from the date of this letter.

Please note that the standing of your insurance policy such as NCD, premium & etc would be affected.

Yours faithfully,

Asher Sng
Claims
Tel : 6841 6051
Fax: 6741 4108
Email : AsherSng@lkkauto.com

c.c. *Claims Manager*
AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Thursday, 10 October 2019 5:50 PM
To: PBSP
Cc: Admin A
Subject: RE: REQUEST FOR DIRECT SETTLEMENT - SKS123Z & SLX3341C ON 25/09/2019 ***LKK
REF:CC3/AIG19017064/eb3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Wednesday, 9 October 2019 5:32 PM
To: Asher Sng (LKKAuto) <AsherSng@lkkauto.com>; Shu Pei (LKKAuto) <shupe@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: Re: REQUEST FOR DIRECT SETTLEMENT - SKS123Z & SLX3341C ON 25/09/2019 ***LKK
REF:CC3/AIG19017064/eb3

Dear Asher

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Chan, Kian-Meng

Your Ref : 8570891193SG
Our Ref : CC3/AIG19017064/EEB3
Date : 14 Nov 2019

"WITHOUT PREJUDICE"**ACCIDENT INVOLVING SLX3341C & SKS123Z ON 25/09/2019**

Refer to the above accident.

The accident occurred when insured rear ended third party vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SLX3341C) and third party claimant (vehicle no. SKS123Z).

Summary of offer made to workshop Performance Motors Limited is as follows :

	Claimed	Revised
Cost of Repairs	\$ 9,415.85	\$ 5,827.49
Loss of Use (3days x \$100)	\$ 300.00	\$ 300.00 (3days x \$100)
LTA Search Fee	\$ 2.00	\$ 2.00

Amount of claim at **Liability 100%** \$ 6,129.49

Our surveyor recommended 3days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

12/10/2019

Merimen e-Claims

Print Received Message

This mail is associated with :

***SKS123Z (8570891193SG)**
[SLX3341C]

TP
RICKY HO KAH SIONG
Sep 25 2019 3:15PM
[HO ENG SENG DAVID]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/12/2019 14:43 PM
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6129.49) - SKS123Z - Claim Handler: Chan, Kian-Meng

Approved:6129.49.



LETTER OF AUTHORISATION

ACCIDENT INVOLVING 8KS 123 Z & SLX 3341C ON 25/9/19.

I, Mr KAH SIONG RICHY owner of Vehicle Registration No. 5KS 123 Z hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name: Mr KAH SIONG

(Date) 26/9/19

NRIC No.: 56338026 Z

In the presence of:



Name :

(Date)

NRIC No.:

Certificate of Insurance**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D19MTPV01009532
Insured : HO KAH SIONG
Motor Car (Registration No.) : SKS123Z
Cover : Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date : 29 JULY 2019 00:00
Policy Expiry Date : 28 JULY 2020 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$1200 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : Buy Down : \$500 - Section I
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting


It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act [Chapter 189] and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.



Authorised Signatory

Date/Time of Issue : 17 JUNE 2019 15:10

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Sep 2019 Edit Reg		15 Oct 2019 00:00 Edit Adj Rpt	\$5,446.25 Edit Estimates	\$5,446.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HO ENG SENG DAVID, ID: -								
Main Claimant:	RICKY HO KAH SIONG, ID: S6B38026Z								
Vehicle Reg. No.:	SKS123Z	Date of Loss:	25/09/2019 15:00 - :59 [37 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8570891193SG	Policy/Cover Note No.:	1800063792-01 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLX3341C	Policy No. (Claimant):	D19MTPV01009532						
	Excess:								
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 08/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (06/12/2019): Alert - Adj Mandate Approved (\$6129.49) - SKS123Z - Claim Handler: Chan, Kian-M... AIG_SG (30/09/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS123Z (8570891193SG)
[SLX3341C]
TP
RICKY HO KAH SIONG
Sep 25 2019 3:15PM
[HO ENG SENG DAVID]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit				
Assessment Reports														1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	14/11/19 12:28	Adjuster Immediate Advice											Load HTM				
Photos/Images														3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print			
1	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
2	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
3	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
4	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
5	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
6	06/11/19 09:21	Chassis Number											Load JPG	<input checked="" type="checkbox"/>			
7	06/11/19 09:21	Odometer Reading											Load JPG	<input checked="" type="checkbox"/>			
8	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
9	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
10	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
11	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
12	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
13	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
14	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
15	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
16	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
17	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
18	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
19	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
20	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
21	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
22	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
23	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
24	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
25	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
26	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
27	06/11/19 09:21	General View											Load JPG	<input checked="" type="checkbox"/>			
28	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
29	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
30	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
31	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
32	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
33	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
34	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
35	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
36	06/11/19 09:21	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
38	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
39	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
40	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
41	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
42	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
43	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
44	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
45	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
46	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
47	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
48	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
49	06/11/19 09:21	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
50	06/11/19 09:22	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
51	06/11/19 09:22	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
52	06/11/19 09:22	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	27/09/19 15:16	TP GIA REPORT		Load PDF	
2	27/09/19 15:16	TP ESTIMATE		Load PDF	
3	01/10/19 10:13	Non reporting letter		Load PDF	
4	14/11/19 12:25	TP ESTIMATE - MARKED		Load PDF	
5	14/11/19 12:25	TP LOD		Load PDF	
6	17/12/19 15:09	WORKSHOP INVOICE		Load PDF	
7	17/12/19 15:09	AUTHORISATION TO ACT FORM		Load PDF	
8	17/12/19 15:09	Release Voucher		Load PDF	
9	17/12/19 15:09	GIA SEARCH		Load PDF	
10	17/12/19 15:09	LOD		Load PDF	
11	17/12/19 15:09	LETTER TO OI		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	10/10/19 09:23	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX3341C (Insd veh)	Model:	BMW 730LI 3.0 (A)
	SKS123Z (TP veh)		
Date of Accident:	25/09/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	10,074.96
Final Repair Cost	:	\$	5,827.49
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,129.49

3.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 27

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 6,129.49
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

17 Dec
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19017064/EEB3Q2

Date: 17/12/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800063792-01

Claimant

Vehicle No : SKS123Z

Insured Vehicle No : SLX3341C

Date of Loss: 25/09/2019

Nature of Claim: TP

Claim No: 8570891193SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS123Z

Make & Model: BMW 730Li, 3.0 (A)

Engine No: 27759595B48B20B

Reg. Date: 29/07/2016 (Man. Year: 2016)

Chassis No: WBA7E02010G244984

Colour: Brown

Odometer: 51925 km

Engine Capacity: 1998 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size: 245/50 R18

Front Left Side: Pirelli 5 mm

Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm

Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,500.85	3,512.25	2,988.60	45.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,415.85	5,446.25	3,969.60	42.16
+ GST 7.00/7.00% (S\$)	659.11	381.24	277.87	42.16
Nett Amount (S\$)	10,074.96	5,827.49	4,247.47	42.16
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,129.49		

INSPECTION

Date of Assignment: 15/10/2019

Date Inspected: 15/10/2019 Inspected At:

Performance Motors Limited

(Alexandra)

303 Alexandra Road, Sime Darby

Performance Centre

Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*REAR BUMPER ADAPTER	Cracked	84.50 FS	*84.50 FS
3	1		*REAR BUMPER CARRIER	Bent	971.25 FS	*971.25 FS
4	1		*REAR BUMPER CENTRE GUIDE	Not Necessary	67.45 FS	*- FS
5	1		*REAR LH MOUNT LATERAL	Not Necessary	160.55 FS	*- FS
6	1		*REAR RH MOUNT LATERAL	Not Necessary	160.55 FS	*- FS
7	1		*LH TRIM EXHAUST TAILPIPE	Not Necessary	248.80 FS	*- FS
8	1		*RH TRIM EXHAUST TAILPIPE	Not Necessary	248.80 FS	*- FS
9	1		*REAR BUMPER CENTRE GUARD	Cracked	83.85 FS	*83.85 FS
10	1		*REAR BUMPER GUARD	Cut	109.70 FS	*109.70 FS
11	1		*LH RUBBER STRIP	Cracked	86.75 FS	*86.75 FS
12	1		*RR BUMPER STRIP	Cracked	86.75 FS	*86.75 FS
13	1		*REAR BUMPER COVER	Cracked	110.00 FS	*110.00 FS
14	1		*REAR BUMPER TRIM PRIMED	Not Necessary	216.45 FS	*- FS
15	1		*REAR BUMPER PANEL PRIMED (PDC/PMA)	Dented	1,746.65 FS	*1,746.65 FS
16	1		*REAR BUMPER TOWING EYE COVER PRIMED	Not Necessary	57.10 FS	*- FS
17	1		*REAR SILENCER HEAT INSULATOR	Not Necessary	133.40 FS	*- FS
18	1		*SOUND INSULA	Not Necessary	115.60 FS	*- FS
19	1		*HEAT INSULATOR FLOOR PANEL TRUNK	Not Necessary	37.10 FS	*- FS
20	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
21	4		*ULTRASONIC TRANSDUCER JATOBA WB65	Not Necessary	1,522.60 FS	*- FS
22	1		*REAR DIFFUSER	Cracked	152.80 FS	*152.80 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,500.85** **3,512.25**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	1,700.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,915.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >