

ASS. REC BY: Hock Ann REF: CS/AN-17014503 Agd31 DAR & Days

From (Person): Chock Lee wai of ALH ASSIGNMENT (Office) Date/Time: 18/09/2019

Estimated Cost: _____ Bill to: _____

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 537X Insured: SKT 44097

at Workshop n/z: SL Automotae Tel: 9182 0077

of: 10 Ditu lane 8

Policy No: 0991995184 Claim No: 965304685456

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 25072017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

Date/Time: 27/07/17 1037am Person Contacted: Sam H.O.D. Endorsement: _____

Vehicle: IS/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>Anything pls check virus memo.</u>
	<u>SLN 537X</u>
	<u>SKT 44097 / CS / AN-1505163 / Kiyon 2.</u>
	<u>Don: 040715</u>
	<u>Final fig @ 13424.82, 6 days cred @ 2401.83, 15%.</u>

Hock Ann,

RECEIVED 10 DEC 2019

Pls see MP.

[Signature]
4/12

[Handwritten note on a piece of paper, partially obscured and tilted]

Celine Fong (LKKAUTO)

From: Cheok, Lee Wai <Cheok.Leewai@aig.com>
Sent: Thursday, 18 April 2019 10:55 AM
To: SUR; Hsiao Tong (LKKAUTO)
Subject: #9653046854SG003#023# // Your ref : CL/170789/T/KDY.sg // Accident along Whampoa Driver on 25.7.17 involving SLN 582X and SKT 4409T

Your ref : CS3/AIG17014503/SBE2

Dear Sir,

We refer to the abovementioned accident which you have conducted a pre-repair inspection.

We would like to appoint your side to conduct a physical inspection of vehicle SLN 582X.

Kindly liaise with Shirley of Catherine Lim LLC who is copied in this email on the schedule of the re-inspection.

Thank you.

Regards,

Kathlyn Cheok
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191880 | Fax +68357416
cheok.leewai@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. [Click here to find out more](#)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

From: Cheok, Lee Wai
Sent: Thursday, 18 April 2019 10:51 AM
To: 'Shirley' <info@catherinelimllc.com>
Subject: #9653046854SG003#023# // Your ref : CL/170789/T/KDY.sg // Accident along Whampoa Driver on 25.7.17 involving SLN 582X and SKT 4409T

Without Prejudice, Save as to Cost

Dear Shirley,

We refer to our earlier email.

Kindly note that we have appointed LKK Auto Consultants Pte Ltd to conduct a physical inspection of your client's vehicle.

They will liaise with you on re-inspection.

Thank you.

Regards,

Kathlyn Cheok

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +64191880 | Fax +68357416

cheok.leewai@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards. [Click here to find out more](#)

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Nivitha (LKK Auto)

From: Cheok, Lee Wai <Cheok.Leewai@aig.com>
Sent: Wednesday, 25 September 2019 10:29 AM
To: Admin-D (LKKAuto)
Cc: assignments; Celine Fong (LKKAuto)
Subject: RE: #9653046854SG003#023# // Your ref : CL/170789/T/KDY.sg // Accident along Whampoa Driver on 25.7.17 involving SLN 582X and SKT 4409T

Dear Sir,

As the vehicle is not available for a physical re-inspection, kindly proceed with a paper survey instead.

Kindly let us have the report in due course.

Thank you.

Regards,

Kathlyn Cheok
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120
Tel +64191880 | Fax +68357416
cheok.leewai@aig.com | www.aig.com.sg

AIG Asia Pacific won General Insurance Company of the Year at the 22nd Asia Insurance Industry Awards.
[Click here to find out more](#)

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Monday, 29 July 2019 2:41 PM
To: Cheok, Lee Wai <Cheok.Leewai@aig.com>
Cc: assignments <assignments@lkkauto.com>; Celine Fong (LKKAuto) <celinefong@lkkauto.com>
Subject: [EXTERNAL] RE: #9653046854SG003#023# // Your ref : CL/170789/T/KDY.sg // Accident along Whampoa Driver on 25.7.17 involving SLN 582X and SKT 4409T

This message is from an external sender; be cautious with links and attachments.

Dear Kathlyn,

Noted with thanks.

Best Regards

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : SL Automotive Pte Ltd
184 Woodlands Industrial Park E5
#01-02
Singapore 757514

5. Estimated normal period of repair : 10 working days to complete.

6. Enclosed number of photograph : 173 copies.

7. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey was done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us within 2 weeks, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

PHOTOCOPY

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Billing Name & Address
Grab Rentals Pte Ltd
c/o 184 Woodlands Industrial Park E5
#01-02
Singapore 757514

Invoice No 07-17086/DY

Date 26 Mar 2018

Vehicle No : SLN 582 X

Model : Toyota Prius

Item	Descriptions	Amount S\$
1	Date of inspection : <u>26 Jul 2017</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>173</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1048.00</u>
	SDLS : ONE THOUSAND AND FORTY-EIGHT ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 07-17086/DY / 2017
Date of Report : 26 Mar 2018

Grab Rentals Pte Ltd
c/o 184 Woodlands Industrial Park E5
#01-02
Singapore 757514

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 25 Jul 2017

As per your instruction dated 26 Jul 2017 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLN 582 X. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLN 582 X
Model : Toyota Prius
Year / Capacity : 2017/1798
Chassis No : JTDKB3FU703556271
Engine No : 2ZRS039855
Mileage : 16644
Colour : Silver

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	195/65 R15	Yokohama	6.00	mm	Sport
REAR	O/S	:	195/65 R15	Yokohama	6.00	mm	Sport
FRONT	N/S	:	195/65 R15	Yokohama	6.00	mm	Sport
REAR	N/S	:	195/65 R15	Yokohama	6.00	mm	Sport

Vehicle No: SLN 582 X
Report No: TP/ 07-17086/DY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Bonnet ✓ <i>at</i>	Damage	\$ 938.40	\$ 938.40 <i>812140 ✓</i>
3	Bonnet hinge ✓ <i>LH (CRU)</i>	N/S Damage	\$ 112.80	\$ 56.40 ✓
1	Bonnet lock ✓ <i>Im</i>	Damage	\$ 89.50	\$ 89.50 ✓
1	Bonnet rubber X <i>(SVC)</i>	Intact	\$ 25.00	\$
1	Front headlamps ✓ <i>LH (CRU)</i>	N/S Damage	\$ 5063.20	\$ 2536.60 <i>2531.60 ✓</i>
2	Front headlamp top panels ✓ <i>LH (at)</i>	N/S Damage	\$ 152.20	\$ 76.10 ✓
1	Front headlamp (ECU) ✓ <i>CRU</i>	Damage	\$ 480.00	\$ 480.00 <i>430 ✓</i>
1	Front grille ✓ <i>(CRU)</i>	Damage	\$ 331.90	\$ 331.90 ✓
1	Front bumper ✓ <i>(cut)</i>	Damage	\$ 495.50	\$ 495.50 <i>450.80 ✓</i>
1	Front bumper fog lamp assy ✓ <i>(CRU)</i>	Damage	\$ 910.70	\$ 910.70 ✓
1	Front bumper reinforcement ✓ <i>at</i>	Damage	\$ 691.50	\$ 691.50 ✓
1	Front bumper side retainers ✓ <i>LH (CRU)</i>	N/S Damage	\$ 230.20	\$ 115.10 <i>80.10 ✓</i>
1	Front bumper tow hook cover ✓ <i>(CRU)</i>	Damage	\$ 28.10	\$ 28.10 ✓
1	Front bumper sponge ✓ <i>(CRU)</i>	Intact	\$ 69.80	\$ 69.80 ✓
1	Front bumper 'TOYOTA' emblem X <i>(SVC)</i>	Intact	\$ 87.60	\$
1	Front n/s fender ✓ <i>(at)</i>	Damage	\$ 933.10	\$ 933.10 <i>868.70 ✓</i>
1	Front n/s fender inner shield ✓ <i>(CRU)</i>	Damage	\$ 198.50	\$ 198.50 ✓
1	Front n/s fender quarter garnish ✓ <i>(CRU)</i>	Damage	\$ 89.50	\$ 89.50 ✓
1	Battery base ✓ <i>(CRU)</i>	Damage	\$ 154.50	\$ 154.50 ✓
1	Battery sensor ✓ <i>(CRU)</i>	Damage	\$ 189.50	\$ 189.50 ✓
1	Front wiper garnish (1 set) ✓ <i>(CRU)</i>	Damage	\$ 219.20	\$ 219.20 ✓
1	Front wheel cap ✓ <i>(CRU)</i>	Damage	\$ 175.80	\$ 175.80 ✓
1	Front wire harness ✓ <i>cut</i>	Damage	\$ 6138.00	\$ 6138.00 <i>5800 ✓</i>
1	Front n/s door ✓ <i>(at)</i>	Damage	\$ 1238.50	\$ 1238.50 <i>1138.50 ✓</i>
1	Front n/s door rubber X	Intact	\$ 221.70	\$
1	Front n/s door side mirror X	Intact	\$ 1374.20	\$
1	Rear n/s fender X <i>(NC)</i>	Repair	\$ 817.50	\$
1	Rear n/s wheel hub cap X <i>(NC)</i>	Damage	\$ 175.80	\$ 175.80
			\$ 21632.20	\$ 16262.20
Discount 25.0%			\$ 5408.05	\$ 4065.55
			\$ 16224.15	\$ 12196.65
<u>Special Nett Items</u>				
1	Front n/s fender inner shield clip (1 set) ✓ <i>Van</i>	Necessary	\$ 50.00	\$ 50.00 <i>20 ✓</i>
1	Battery ✓ <i>cut</i>	Damage	\$ 220.00	\$ 220.00 <i>180 ✓</i>
			\$ 270.00	\$ 270.00

Spare Parts Total \$ 16494.15 \$ 12466.65

Vehicle No: SLN 582 X
Report No: TP/ 07-17086/DY / 2017

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
Spare Parts Total c/f		\$ 16494.15	\$ 12466.65
1	To provide towing service charge. ✓	\$ 80.00	\$ 80.00 60
2	To remove and refit damage parts, test for proper functioning and focus of headlamps. X	\$ 100.00	\$ 40.00
3	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts. ✓	\$ 100.00	\$ 50.00 20
4	To check and re-adjust (Computerized) all wheel alignment. ✓	\$ 200.00	\$ 120.00 60
5	To remove and refit air-con system, refill gas and test for leakages. X	\$ 120.00	\$ 120.00
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1800.00	\$ 1320.00 700
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1800.00	\$ 1540.00 800
8	To apply undercoating on the repaired and replaced panels for rust protection. ✓	\$ 150.00	\$ 90.00 40
Total		\$ 20844.15	\$ 15826.65

Recommended PART BY PART Repair Amount of:

\$ 15826.65

SDLS: FIFTEEN THOUSAND EIGHT HUNDRED TWENTY SIX AND CENTS SIXTY FIVE ONLY

LKK Auto Consultancy hence notify the Repairer of the following:
• To resurvey before and after spray painting
• To display damage on the car
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Page 4

Parts 15393.10

Parts less 25%

11544.82

Spa out 200

labor 1680

Total \$ 13424.82
P/P part

Paper survey by H. ANW LKW 9/12/19 P/P repair 6 days

9/12/19

Vehicle No: SLN 582 X
Report No: TP/ 07-17086/DY / 2017

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Bonnet	Damage	\$ 938.40	\$ 938.40
1	Bonnet hinge	N/S Damage	\$ 112.80	\$ 56.40
1	Bonnet lock	Damage	\$ 89.50	\$ 89.50
1	Bonnet rubber	Intact	\$ 25.00	\$
2	Front headlamps	N/S Damage	\$ 5063.20	\$ 2536.60
2	Front headlamp top panels	N/S Damage	\$ 152.20	\$ 76.10
1	Front headlamp (ECU)	Damage	\$ 480.00	\$ 480.00
1	Front grille	Damage	\$ 331.90	\$ 331.90
1	Front bumper	Damage	\$ 495.50	\$ 495.50
1	Front bumper fog lamp assy	Damage	\$ 910.70	\$ 910.70
1	Front bumper reinforcement	Damage	\$ 691.50	\$ 691.50
2	Front bumper side retainers	N/S Damage	\$ 230.20	\$ 115.10
1	Front bumper tow hook cover	Damage	\$ 28.10	\$ 28.10
1	Front bumper sponge	Intact	\$ 69.80	\$
1	Front bumper 'TOYOTA' emblem	Intact	\$ 87.60	\$
1	Front n/s fender	Damage	\$ 933.10	\$ 933.10
1	Front n/s fender inner shield	Damage	\$ 198.50	\$ 198.50
1	Front n/s fender quarter garnish	Damage	\$ 89.50	\$ 89.50
1	Battery base	Damage	\$ 154.50	\$ 154.50
1	Battery sensor	Damage	\$ 189.50	\$ 189.50
1	Front wiper garnish (1 set)	Damage	\$ 219.20	\$ 219.20
1	Front wheel cap	Damage	\$ 175.80	\$ 175.80
1	Front wire harness	Damage	\$ 6138.00	\$ 6138.00
1	Front n/s door	Damage	\$ 1238.50	\$ 1238.50
1	Front n/s door rubber	Intact	\$ 221.70	\$
1	Front n/s door side mirror	Intact	\$ 1374.20	\$
1	Rear n/s fender	Repair	\$ 817.50	\$
1	Rear n/s wheel hub cap	Damage	\$ 175.80	\$ 175.80
			<u>\$ 21632.20</u>	<u>\$ 16262.20</u>
	Discount	25.0%	\$ 5408.05	\$ 4065.55
			<u>\$ 16224.15</u>	<u>\$ 12196.65</u>
<u>Special Nett Items</u>				
1	Front n/s fender inner shield clip (1 set)	Necessary	\$ 50.00	\$ 50.00
1	Battery	Damage	\$ 220.00	\$ 220.00
			<u>\$ 270.00</u>	<u>\$ 270.00</u>

Spare Parts Total \$ 16494.15 \$ 12466.65

Vehicle No: **SLN 582 X**
Report No: **TP/ 07-17086/DY / 2017**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 16494.15	\$ 12466.65
1	To provide towing service charge.	\$ 80.00	\$ 80.00
2	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 100.00	\$ 40.00
3	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 100.00	\$ 50.00
4	To check and re-adjust (Computerized) all wheel alignment.	\$ 200.00	\$ 120.00
5	To remove and refit air-con system, refill gas and test for leakages.	\$ 120.00	\$ 120.00
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1800.00	\$ 1320.00
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1800.00	\$ 1540.00
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00
Total		\$ 20844.15	\$ 15826.65
Recommended PART BY PART Repair Amount of:		\$ 15826.65	

SDLS: FIFTEEN THOUSAND EIGHT HUNDRED
TWENTY SIX AND CENTS SIXTY FIVE ONLY


Qualified Appraiser

PHOTOCOPY

SL Automotive Pte Ltd

184 Woodlands Industrial Park E5 #01-02 Singapore 757514

Tel : 63654741 / 6365 4742 Fax : 63684750

Vehicle No : SLN 582 X Date : 26-Mar-2018
 Make/Model : Toyota Prius
 Name : Grab Rentals Pte Ltd
 Address : c/o 184 Woodlands Industrial Park E5
 #01-02
 Singapore 757514
 Accident Date : 25-Jul-2017

Part By Part repair of SLN 582 X

QTY	ITEM	AMOUNT (S\$)
-----	------	--------------

<u>List Items</u>		
1 pc	Bonnet	\$ 938.40
1 pc	Bonnet hinge	\$ 56.40
1 pc	Bonnet lock	\$ 89.50
1 pc	Front headlamp	\$ 2,536.60
1 pc	Front headlamp top panel	\$ 76.10
1 pc	Front headlamp (ECU)	\$ 480.00
1 pc	Front grille	\$ 331.90
1 pc	Front bumper	\$ 495.50
1 pc	Front bumper fog lamp assy	\$ 910.70
1 pc	Front bumper reinforcement	\$ 691.50
1 pc	Front bumper side retainer	\$ 115.10
1 pc	Front bumper tow hook cover	\$ 28.10
1 pc	Front n/s fender	\$ 933.10
1 pc	Front n/s fender inner shield	\$ 198.50
1 pc	Front n/s fender quarter garnish	\$ 89.50
1 pc	Battery base	\$ 154.50
1 pc	Battery sensor	\$ 189.50
1 pc	Front wiper garnish (1 set)	\$ 219.20
1 pc	Front wheel cap	\$ 175.80
1 pc	Front wire harness	\$ 6,138.00
1 pc	Front n/s door	\$ 1,238.50
1 pc	Rear n/s wheel hub cap	\$ 175.80
		\$ 16,262.20
	Less 25.0%	\$ 4,065.55
		\$ 12,196.65

<u>Special Nett Items</u>		
1 pc	Front n/s fender inner shield clip (1 set)	\$ 50.00
1 pc	Battery	\$ 220.00
		\$ 270.00

PHOTOCOPY

<u>S/N</u>	<u>Labour</u>	
1	Towing.	
2	To remove and refit headlamps.	\$ 80.00
3	To check wiring.	\$ 40.00
4	To remove and refit wheel alignment.	\$ 50.00
5	To remove and refit air-con system.	\$ 120.00
6	Panel beating	\$ 120.00
7	Spray painting	\$ 1,320.00
8	To underseal	\$ 1,540.00
		\$ 90.00
		<u>\$ 3,360.00</u>

\$ 15,826.65

Dollar : Fifteen Thousand Eight Hundred Twenty Six And Cents Sixty Five Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	200G
Vehicle Details	
Vehicle No.:	SLN582X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZRS039855
Chassis No.:	JTDKB3FU703556271
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	21 Apr 2017
First Registration Date:	21 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	20 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,300.00
COE Rebate Amount:	\$39,323.00
Total Rebate Amount:	\$43,073.00

The information contained herein is correct as at 04 Dec 2019

OK

F1 AUTO CARS

SPECIALISTS IN LUXURY AND PERFORMANCE CARS

☎ 6250 6696 / 9637 5329

CLICK HERE for best deals in town!



Toyota

Min Price ▼

to No Max ▼

Depreciation ▼

Vehicle Type ▼

Category ▼



Home » New Cars » New Car Brands » Toyota » Toyota Prius Hybrid

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Prius Hybrid (Parallel Imported)

Select Another Make ▼

Select The Make ▼

Overview

Pricing

Photos

Research

Reviews

Specs

Features

Similar

Accessories

Promo

Add to Shortlist

Submit a Review

Report Error

Share



Details

Sold by

3 dealers » Show full list

Built in

Japan (launched 2016)

Variants

1 submodel(s) » Show pricelist

Promotion

No current promotions. Alert me when new promotions are in

USER RATINGS:

(7 reviews)

» View all other promotions

Add to Shortlist

Get the dealers selling the Toyota Prius Hybrid to contact me with their best deals.

Name*

☐ I'm not a robot

Contact No*

reCAPTCHA
Privacy Terms

Submit

Featured Merchants



Related Articles



5 Parallel Importers with biggest variety of cars



Eight best buys at the Singapore Motor Show 2019



Toyota recalls one million Prius and C-HR models



Compare

Submodel

1.8 S (A)

RRP

\$110,000

Depreciation

ECO

n/a

Power

97bhp

Detailed

Specs | Fe

Showing 3 dealers selling this vehicle

Prime Motor & Leasing

Tel: 64440088 / 88680011

Autopoint Automobile Pte Ltd

Tel: 91288877

Prime Car Traders

Tel: 63666000 / 86666565

Showing 3 dealers selling this Toyota Prius Hybrid

Full List of Dealers

Photos & Review



+ View All 43 Toyota Prius Hybrid Photos

CONSUMER REVIEWS

The Unique & Classy Prius

The Toyota Prius had set a new benchmark in the luxury hybrid car

Rides well and reliable

Have driven this car for 1 year covering over 35,000 kms. Pros: 1

(N)None (D)Deleted (C)Checked (F)Fit (R)Revised (P)Deleted
 (S)Selling (B)Bought (I)Inventory (M)Missing (T)Time
 (L)Lowest (H)Highest (V)Value

MOTOR CAR (Frt)

ACTERIAL
 (1)Rapid (2) (3)Rapid (4) (5)Rapid (6)
 (7)Rapid (8) (9)Rapid (10)

Vehicle No: SLN582X

Front Portion

NAC	INC	Item	CON	ACQ	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CRK	✓	
1005	992341	Frt Bumper Clips	NEL	✓	
1006	991325	Frt Bumper Bracket	NEL	✓	
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	RT	✓	
1009	991318	Frt Bumper Bush	NEL	✓	
1010	991468	Frt Bumper Spoons	CRK	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad Low Pressure	RT	✓	
1013	991363	Frt Bumper Grille	CRK	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	991100	Frt LH Bumper Fog Lamp Cover	CRK	✓	
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	RR	✓	
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991223	Frt Apron Panel			
1025	992013	Frt Support Panel	RT	✓	
1026	992025	Frt Support Panel Top Garnish Cover	RT	✓	
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRK	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	RT	✓	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	RT	✓	
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge	RT	✓	
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber	NEL	✓	
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Frt Exhaust Pipe			
1067	990219	Battery	CRK	✓	
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	ACQ	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender	RT	✓	
1097	995072	Frt LH Fender Inner Panel	RT	✓	
1098	995147	Frt LH Fender Lamp Endless	NEL	✓	
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield	RT	✓	
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover	CRK	✓	
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish	Defence	✓	
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Socket			
		Frt LH Door	RT	✓	

No of Items: 33

Address:

REFUGEE COPY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/07/2017 09:16
Date Of Accident	25/07/2017 14:35
Exact Location Of Accident	WHAMPOA DRIVE TOWARDS JALAN BAHAGIA
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN582X
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	ENQUIRIES.SG@GRABCAR.COM
Mobile Phone No	(LOCAL) +65-90977736
Alternative Phone No	Office-65703925

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID-1.8 E (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	GREAT AMERICAN INSURANCE COMPANY
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	MTGRAB20171284

Driver

Name of Driver	CHARLENE ANGELA ZENG SHUHUI
NRIC No	S8120993F
Date Of Birth	29/06/1981
Occupation	OUTDOOR
Date Of Driving Pass	04/01/2005
Driving Experience	12 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-81128120

Fax Number	
Contact Number	
EMail Address	NOEMAIL
Address	BLK 141 LORONG 2TOA PAYOH #20-156 SINGAPORE 311141
Postcode	311141
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	GEYLANG N.P.C
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 20/07/2017 AT ABOUT 14:33HRS, I WAS DRIVING MY VEHICLE (SLN582X) ALONG WHAMPOA DRIVE TOWARDS JALAN BAHAGIA. WHEN A VEHICLE (SKT4409T) SUDDENLY TRIES TO MAKE AN ILLEGAL U-TURN. I COULD NOT REACT ON TIME AND COLLIDED ON TO THE RIGHT FRONT OF (SKT4409T). AFTER THE ACCIDENT, I HAD EXPERIENCE SOME DISCOMFORT AND WILL SEEK MEDICAL CONSULTATION IF NECESSARY.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT4409T	- lciis / spordyn 2.0(A)
Vehicle Make/Model/Colour		
Details Of Properties		SUV
Name of Driver		
NRIC/Passport Number		
Contact Number		
Address		

Postcode

Insurance Company Name

Nature Of Damage

FRONT RIGHT

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

Sketch Plan

1. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

2. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

3. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

4. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

5. The sketch plan is a plan of the road layout and the location of the market and the bus stop.


6. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

7. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

8. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

9. The sketch plan is a plan of the road layout and the location of the market and the bus stop.

10. The sketch plan is a plan of the road layout and the location of the market and the bus stop.



Describe Circumstances of the Accident:

ON 25/07/2017 AT ABOUT 1433HRS, I WAS DRIVING MY VEHICLE (SLN582X) ALONG WHAMPOA DRIVE TOWARDS JALAN BAHAGIA. WHEN A VEHICLE (SKT4409T) SUDDENLY TRIES TO MAKE AN ILLEGAL U-TURN. I COULD NOT REACT ON TIME AND COLLIDED ON TO THE RIGHT FRONT OF (SKT4409T).

AFTER THE ACCIDENT, I HAD EXPERIENCE SOME DISCOMFORT AND WILL SEEK MEDICAL CONSULTATION IF NECESSARY.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the Policyholder)
Signature / Date & Time

Witnessed by Reporting Centre Personnel



**SINGAPORE
POLICE FORCE**



T/20170725/2001

Police Station Of Origin:
Geylang N.P.C.
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8488999

Page 1 of 1
Report No: T/20170725/2001

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 26/07/2017 00:08		Vide Report No.		Station Diary No. 1	
Informant's Particulars					
Name of Informant: CHARLENE ANGELA ZENG SHUMUI		Address: APT BLK 141 LORONG 2 TOA PAYOH #20-156 SINGAPORE 311141			
ID Type / ID No. NRIC NO / S8120993F		Contact No. Home/Office:		Mobile: 81128120	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Female	Age: 36	Date of Birth: 29/06/1981	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3		Date of Expiry:	

General information of the Accident

Type of Accident:	Injury: Others:	Drink Drive: No	Date/Time of Accident: 25/07/2017 14:30	Type of Location: Straight Road
Location: Along Road 1 WHAMPOA DRIVE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKT4408T	Car				Slightly Damaged	0
SLN582X	Car				Seriously Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20170725/2001

Police Station Of Origin
Geylang N.P.C.
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-6485999

2 of 3

Report No: T/20170725/2001

CONTINUATION OF REPORT

Driver				
Name	NEO TOO KIAT		ID No	S0493845C
Related Vehicle	SKT4409T (Car)		Contact No	96851380
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	CHARLENE ANGELA ZENG SHUHUI		ID No	S8120993F
Related Vehicle	SLN582X (Car)		Contact No	81128120
Hospital/Clinic	RAFFLES HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	25/07/2017		Date Discharge	25/07/2017
No. of Days granted Medical Leave	03	Degree of Injury	Slight	

Brief Details.

On 25/07/2017 at around 1433hrs, I was driving along Vihampoa Drive. I was on my way to pick up a passenger. While I was driving, there was a vehicle which had suddenly turned right to make a U-turn. With this action, he had hit the left portion of my vehicle.

I then went out of my vehicle to make a check. There is scratches and dents on both the front left portion of my vehicle. There is also cracks on the front bumper. There is also some oil spillage but I am unable to determine where it came from. I then exchanged particulars with the other driver.



SINGAPORE
POLICE FORCE



T/20170725/2001

Police Station Of Origin:
Geylang N.P.C.
132 Paya Lebar Road SINGAPORE 409014
Tel No. 1800-8488999

Page 3 of 3
Report No. T/20170725/2001

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474865 stating the report number as reference.

Signature Of Officer Recording The Report: G/ Staff Sgt MUHAMMAD HAZWAN BIN ADNAN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 26/07/2017 00:08
Officer In Charge Of Case: TP / AEIT / SSI 2 SITIMARS/TA BINTE BOHAR/ Contact No. 65476219	Classification Of Case:
Authentication Stamp: NP158 	

MEDICAL CERTIFICATE

MEDICAL CERTIFICATE

MRIC : SR120993F
NAME : CHARLENE ANGELA ZENG SHUHUI

VISIT DATE : 25 Jul 2017 (22:16)
VISIT NO : SR17021501

This is to certify that the above mentioned has been given:

OUTPATIENT SICK LEAVE for 3 days from 25 Jul 2017 to 27 Jul 2017

DOCTOR : RAVINDRA KUMAR KARUTURI (M145506)
CLINIC : 24 HR EMERGENCY CLINIC
ADDRESS : 565 NORTH BRIDGE ROAD LEVEL -01-00 RAFFLES HOSPITAL 168770

This certificate is not valid for absence from court or other judicial proceedings unless specifically stated.
This certificate is electronically generated; no signature is required.

Printed: 25 Jul 2017, 11:17PM

Accident Photo 1



Accident Photo 2



Accident Photo 3



Accident Photo 4



Accident Photo 5



Accident Photo 6



Accident Photo 7



Addendum Sheet

GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE

IMPORTANT NOTE : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MIE 117098302 Vehicle Registration No : SLN 582X
Name(as shown in NRIC): CHARLENE ANGELA ~~THE~~ ZENG SHU HUI
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
NRIC/Passport No : 88120993 F
Address : BLK 141 LORONG 2 TOA PAYOH #20-166 8(311141)
Contact (Tel) : _____ (H/P) : 81128120
(Email) : _____
Date of Accident : 25/07/2017 Time of Accident : 14:35
Place of Accident : NHAMPAN DRIVE TOWARDS JALAN BAHAGIA
Insurance Company : GAIC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Additional attachments

1. POLICE REPORT.

2. MEDICAL DOCUMENTS.



Signature of Vehicle Owner / Driver
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 25/07/2017 17:19
Date Of Accident 25/07/2017 15:05
Exact Location Of Accident WHAMPOA MAKAN PLACE 90 WHAMPOA DRIVE, (S)320090
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKT4409T
Insured/Policyholder
Name Of Registered Owner DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.
Co Reg No 199803778Z
Email Address BENNY.CHONG@DAIMLER.COM
Mobile Phone No
Alternative Phone No Office-92203185

Vehicle Particulars

Manufacturer KIA
Model SPORTAGE 2.0(A) SUNROOF
Exact Purpose for which vehicle was being used at time of accident PRIVATE

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number 999995580
Cover Note Number

Driver

Name of Driver NEO TOO KIAT
NRIC No S0493845C
Date Of Birth 31/03/1948
Occupation INDOOR
Date Of Driving Pass 11/10/1984
Driving Experience 32 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96851380

Fax Number	
Contact Number	
E-Mail Address	NOEMAIL
Address	
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I (SKT4409T) JUST MOVED OFF AT A SMALL STOP LINE JUNCTION OUTSIDE WHAMPOA MARKET WHEN SUDDENLY A CAR (SLN582X) HIT ME FROM THE BACK. SLIGHT INJURY TO MY HAND DUE TO THE IMPACT.

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN582X
Vehicle Make/Model/Colour	TOYOTA / PRIUS HYBRID 1.8 CVT / SILVER
Details Of Properties	NA
Name of Driver	CHARLENE ANGELA ZENG SHUHUI
NRIC/Passport Number	S8120993F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name

Phone Number

Email Address

DETAILS OF INJURED PERSON 1

Name

NEO TOO KIAT

Approximate Age

Injuries Sustain

SLIGHT INJURY TO HAND

Injured person in which vehicle?

SKT4409T

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims involving the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, collectively the "Purposes";
 - (ii) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/are be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MOHAMMAD SULHANDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



Sketch Plan #2

ACCIDENT STATEMENT (2000 characters)

I (SKT4409T) JUST MOVED OFF AT A SMALL STOP LINE JUNCTION OUTSIDE WHAMPOA MARKET WHEN SUDDENLY A CAR (SLN582X) HIT ME ON THE FRONT RIGHT SIDE OF MY CAR. SLIGHT INJURY TO MY HAND DUE TO THE IMPACT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

25 July 2017 at 4:10 PM

Date/Time:

25 July 2017 at 4:10 PM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG17014503/Hqd3e2-1

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 11-12-2019



ATTN : CHEOK LEE WAI

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 4409T	Veh. Inspected	SLN 582X
Policy No.	0999995184	Coverage (\$)	0.00
Claim No.	9653046854SG	Excess (\$)	0.00
Assign From	CHEOK LEE WAI	Assign Date	18/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU703556271	Colour	SILVER
Odometer	16644	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/07/2017	Inspection Date	27/07/2017
Survey held at	SL AUTOMOTIVE-10 DEFU LANE 8		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 582X

Page No.:1 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	BENT		
2	BONNET HINGE	N/S CRUSHED	938.40	812.40
1	BONNET LOCK	JAMMED	112.80	56.40
1	BONNET RUBBER	SERVICEABLE	89.50	89.50
2	FRONT HEADLAMPS	N/S CRACKED	25.00	-
2	FRONT HEADLAMP TOP PANELS	N/S BENT	5,063.20	2,531.60
1	FRONT HEADLAMP (ECU)	CRUSHED	152.20	76.10
1	FRONT GRILLE	CRACKED	480.00	430.00
1	FRONT BUMPER	CUT	331.90	331.90
1	FRONT BUMPER FOG LAMP ASSY	CRACKED	495.50	450.80
1	FRONT BUMPER REINFORCEMENT	BENT	910.70	910.70
2	FRONT BUMPER SIDE RETAINERS	N/S CRUSHED	691.50	691.50
1	FRONT BUMPER TOW HOOK COVER	CRUSHED	230.20	80.10
1	FRONT BUMPER SPONGE	CRACKED	28.10	28.10
1	FRONT BUMPER 'TOYOTA' EMBLEM	SERVICEABLE	69.80	69.80
1	FRONT N/S FENDER	BENT	87.60	-
1	FRONT N/S FENDER INNER SHIELD	CRUSHED	933.10	868.70
1	FRONT N/S FENDER QUARTER GARNISH	CRUSHED	198.50	198.50
1	BATTERY BASE	CRUSHED	89.50	89.50
1	BATTERY SENSOR	DAMAGED	154.50	154.50
1	SET FRONT WIPER GARNISH	CRUSHED	189.50	189.50
1	FRONT WHEEL CAP	SCRATCHED	219.20	219.20
1	FRONT WIRE HARNESS	CUT	175.80	175.80
1	FRONT N/S DOOR	BENT	6,138.00	5,800.00
1	FRONT N/S DOOR RUBBER	INTACT	1,238.50	1,138.50
1	FRONT N/S DOOR SIDE MIRROR	INTACT	221.70	-
1	REAR N/S FENDER (TO REPAIR SEE LABOUR)	NOT CONSISTENT WITH THE IMPACT	1,374.20	-
1	REAR N/S WHEEL HUB CAP (DAMAGED)	NOT CONSISTENT WITH THE IMPACT	817.50	-
			175.80	-

Report Ref No. CS3/AIG17014503/Hqd3e2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT			
	SPECIAL NETT ITEMS			
1	SET FRONT N/S FENDER INNER SHIELD CLIP (SN)	NECESSARY CUT	-5,408.05	-3,848.28
1	BATTERY (SN)		16,224.15	11,544.82
			50.00	20.00
			220.00	180.00
			270.00	200.00
	LABOUR			
	TO PROVIDE TOWING SERVICE CHARGE	NOT NECESSARY	80.00	60.00
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		100.00	-
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS.		100.00	20.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.	NOT NECESSARY	200.00	60.00
	TO REMOVE AND REFIT AOR-CON SYSTEM, REFILL GAS AND TEST FOR LEAKAGES.		120.00	-
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR N/S FENDER.		1,800.00	700.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,800.00	800.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	40.00
			4,350.00	1,680.00
GRAND TOTAL			20,844.15	13,424.82
RECOMMENDED COST OF REPAIRS				13,424.82

Report Ref No. CS3/AIG17014503/Hqd3e2-1

LEE HOCK ANN
Asst. Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A.M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.