

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0904/2019/NS
Date : 3-Jul-19

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no. : **SCP 9893 K**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Goh Jun Yi Irving
Address : Blk 9 Joo Seng Road
#10-18
Singapore 360009
Telephone : HP +65 96419046
Type of Claim : ~~Third Party Claims~~ *Own Damage Claim.*
Policy No. : 1900103643
Vehicle No : **SJS 8227 S**
Model Code : A4 Sedan 2.0 TFSI
Model / Year : May-19
Engine No : CVK079120
Chassis No : WAUZZZF48KA054975
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-19
Place of Accident : Wan Tho Ave Outside St John's Home

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJS 8227 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy	S/N \$ 300.00 ✓	
2	To remove and change rhs front door window glass.	\$ 400.00 100. ✓	
3	To respray rhs wing mirror cover.	\$ 500.00 150. ✓	
4	To reapply solar film for front rh door glass	S/N \$ 400.00 ✓	
5	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 1,792.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJS 8227 S

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	
1	MIRROR MOUNTING WITH ELECTRIC ADJUSTING UNIT - RH <i>wt</i>	\$	824.00 ✓
2	MIRROR CAP - RH <i>could</i>	\$	220.00 ✓
3	MIRROR GLASS WITH PLATE - RH <i>seen</i>	\$	1,553.00 ✓
4	DOOR WINDOW - RH FRONT <i>wt</i>	\$	265.00 ✓
5	WINDOW SLOT SEAL WITH TRIM STRIP - RH <i>seen wt</i>	\$	280.00 ✓
6	SUNDRIES <i>?</i>	\$	200.00 ?
TOTAL SPARE PARTS CHARGES		:	\$ 3,342.00
TOTAL LABOUR CHARGES		:	\$ 1,792.00
GRAND TOTAL		:	\$ 5,134.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Lim*
Surveyed Date : *27/09/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 02 Days*

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant