

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 13541

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1157/2019/NS
Date : 25-Sep-19

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Wu Lingmin
Address : 51 Tampines Avenue 1
#05-04
Singapore 529771
Telephone : (HP) +65 82334523
Type of Claim : Own damage Claim
Policy No. : 2100491987-02
Vehicle No : **SFU 9199 U**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : 29/11/2016
Engine No : CVN 024719
Chassis No : WAUZZZF4XHA070667
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Sep-19
Place of Accident : Banda Street Carpark Lot 14

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFU 9199 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. To repair bonnet. Re-organise crash management components. Reinstall all parts removed. ✓ ✗ ✓	\$ 2,800.00 1250	
3	To respray front bumper, bonnet and rhs front fender. ✓ ✗ ✓	\$ 2,900.00 1100	
4	To carry out diagnostic check.	S/N \$ <u>192.00</u> ✓	
TOTAL LABOUR CHARGES		: \$ <u><u>6,252.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFU 9199 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>rehd</i>	\$ 1,946.00	✓
2	FRONT BUMPER FIXING PARTS <i>} new</i>	\$ 258.00	X
3	FRONT BUMPER SECURING STRIP	\$ 32.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>} new</i>	\$ 191.00	X
5	FRONT BUMPER AIR GUIDE - RH	\$ 56.00	X
6	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 123.00	X
7	FRONT BUMPER CARRIER	\$ 733.00	X
8	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	X
9	FRONT BUMPER GUIDE SECTION - RH ?	\$ 34.00	?
10	FRONT BUMPER COVER <i>} new</i>	\$ 116.00	X
11	CAUTION SIGN STICKER	NEC \$ 13.00	X
12	AIRCON STICKER	NEC \$ 7.00	X
13	FRONT BUMPER LOCK CARRIER BRACKET <i>new</i>	\$ 125.00	X
14	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2 \$ 52.00	X
15	FRONT FENDER - RH <i>Dented</i>	\$ 700.00	✓
16	FRONT FENDER ATTACHMENT PARTS ?	\$ 183.00	?
17	FRONT FENDER CLOSING ELEMENT - RH ?	\$ 45.00	?
18	FRONT FENDER BRACKET - RH ?	\$ 32.00	?
19	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH ?	\$ 45.00	?
20	FRONT FENDER BRACE - RH ?	\$ 107.00	?
SUB TOTAL SPARE PARTS CHARGES		\$ 4,911.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFU 9199 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	FRONT WHEEL HOUSING LINER - RH <i>new</i>	\$ 220.00	+
22	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 82.00	+
23	WHEEL SPOILER	\$ 66.00	+
24	WHEEL SPOILER END PLATE - RH <i>new</i>	\$ 33.00	+
25	STONE CHIP GUARD ?	\$ 46.00	?
26	FENDER LEDGE COVER - INNER ?	\$ 28.00	?
27	FENDER LEDGE COVER - OUTER ?	\$ 21.00	?
28	LED HEADLIGHT - RH <i>at</i>	\$ 7,087.00	✓
29	HEADLIGHT LIFT CYLINDER - RH <i>new</i>	\$ 192.00	+
30	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 12,986.00	
TOTAL LABOUR CHARGES		\$ 6,252.00	
GRAND TOTAL		\$ 19,238.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian King

Surveyed Date

: 27/09/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 04 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant