

# PREMIER APPRAISER SERVICES

Our Ref: PT1907005-L

Vehicle No : SMD 4827 E

Qty	Parts Descriptions	Conditions	Repairer's Est.	Our Revised
LIST ITEMS:				
1	rear bumper	dented/distorted <del>DD</del> ✓	S\$ 1,280.00	S\$ 1,280.00 ✓
1	rear bumper outer mldg - centre	damaged <del>xnn</del> ND ✓	386.00	386.00 <del>xnn</del>
2	rear bumper reflectors	fractured <del>cra</del> ✓	110.00	110.00 <del>\$55</del>
4	rear bumper parking sensors @195	damaged <del>sc</del> ✓	1,340.00	1,340.00 <del>\$656</del>
4	rear bumper parking sensor seals	damaged <del>nec</del> ✓	100.00	100.00 ✓
4	rear bumper parking sensor mtgs	damaged <del>XND</del> ✓	140.00	140.00 ✓
1	rear bumper tow cover	serviceable <del>xnn</del> ND ✓	33.40	-
1	rear bumper reinforcement	dented/bent <del>xnn</del> (Repair) ✓	599.00	599.00 <del>xnn</del>
1	rear bumper reinforcement garnish	damaged <del>cra</del> ✓	113.90	113.90 ✓
2	rear bumper side attachments	damaged <del>bs</del> ✓	110.00	110.00 ✓
2	rear bumper side retainers	damaged <del>nec</del> ✓	97.00	97.00 ✓
1	rear bumper centre retainer	damaged <del>nec</del> ✓	122.00	122.00 ✓
1	rear end panel	dented - repair <del>xnn</del> (Repair) ✓	597.00	-
1	rear end panel top trim	serviceable <del>xnn</del> ND ✓	188.00	-
			S\$ 5,216.30	S\$ 2,247.94, 397.90
			LESS 0%	5% 12.37 219.90
			5,216.30	\$2135.51 4,178.01
S/NETT ITEMS:				
12	rear bumper clips	necessary <del>nec</del> ✓	60.00	60.00 <del>\$50</del>
4	rear end panel top trim clips	necessary <del>nec</del> ✓	20.00	20.00 ✓
TOTAL S/PARTS			S\$ 5,296.30	S\$ 70 4,258.01
Labour charges to repair, panel beat and straighten damaged parts and replace the above-mentioned parts.			800.00	\$400 500.00
To replace reverse sensor.			120.00	60.00 <del>\$50</del>
To check wiring functions.			50.00	30.00 ✓
To putty, apply primer & spray-paint the affected areas.			1,100.00	750.00 <del>\$500</del>
To apply rust-proofing on repaired/replaced panels.			60.00	30.00 ✓
TOTAL			S\$ 7,426.30	S\$ 5,628.01

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **S\$ 4,500.00 lump sum** corresponding to supply of parts, labour and spray painting charges.  
The estimated period of repairs is **FOUR (4) days**. Pursuant to your instruction we have **not** authorised repairs on your behalf.

List Item: \$2135.51  
 Net Item: \$70  
 Labor: \$990  
 Total: \$3195.51  
 45 20%: \$2550.00 #

PREMIER APPRAISER SERVICES

LESLIE K C LIM CAE (UK), MIMI (UK)  
 MSAAA, Automotive Appraiser  
 Dip.MFTM. Automotive Engineer