



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III19012672/Fyf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 09-10-2019



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 8944G	Veh. Inspected	SMD 4827E
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19070375	Excess (\$)	0.00
Assign From	STANLEY LAI	Assign Date	28/09/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A16070NS36166	Colour	WHITE
Odometer	115812	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	13/07/2019	Inspection Date	18/07/2019
Survey held at	160 SIN MING DRIVE #07-18/19		
Repairer	A T PERFORMANCE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------