

ASS. REC. BY:

REF: CS/SMO 19017D5 / DVf3m2

Special Instruction:

Survivor: Bryan

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMO

Date/Time: 31.9.19 8.56a.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 7518K

Insured: SGW 4546L

at Workshop m/s Chunn

Tel: 65426119

of BIK 10 1 01-05/06 MK Autopaint.

Policy No: DI9MPV 01002247

Claim No: CMTD 1904533

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 31.9.19 9.19a.m

Person Contacted: Irene

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SH 7518K - CS/PG B010201/Ky402

D.O. - 04/06/2018

SGW 4546L-X

2/10/19

Send preli. revised via merimen

ASSIGNMENT

OE 2023 NAV

Nov 2015

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

9

days

Res.: _____

Yes or No

Lum Sum: _____

20

%

3 Val.: _____

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: _____

SH 7518 K

Yr Regn: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Hyundai I40

C.C

1685

Colour: _____

Blue

A/C: _____

Insured / Std / NI / NA

Sp. Reading: _____

548634

T/Radio: _____

Insured / Std / NI / NA

Eng/No: _____

D4FDEU475028

C/No: _____

KMHLEB41UMGU080463

Gen. Cond: _____

Good / Fair / Poor / Burnt

Steering: _____

In order / Jammed / Leaked / Burnt or

Brake: _____

In order / Jammed / Leaked / Burnt or

Modi: _____

Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

205 / 60 R16

R: _____

— " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Flenkaak

Front

Rear

R/Bal. _____

S

mm

R/Bal. _____

S

mm

L/Bal. _____

S

mm

L/Bal. _____

S

mm

D.O.A. _____

27/09/2019

D.O.I. _____

30/09/2019

Survey held at _____

Chennai AUK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop of

Rent 4 Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sompo SGW 4546L

07/11/2019

Invoice 2/5 12300/- with 9 days of repair (Recd 10, 814.40, 4710)

RECEIVED 11 NOV 2019

Date/Time, File Pass to:

☐

: Preli. Report

11

☐

: Final Report

Date/Time, File Return to:

8/11 - typist

Days Of Repair: _____

9

Resurvey No. of Trip: _____

2

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS: _____

Photos: _____

Others: _____

TOTAL: _____

Report Form: _____

Meriman

Loop 2000 / 1000

12,300/2

450

11

461

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	Sompo Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
-----	--	-------	---

Attn:	CHAN SHU HUI AGNES	Date:	02 Oct 2019
-------	--------------------	-------	-------------

Preliminary Advice

Insured Vehicle No	: SGW4546L	Accident Date	: 27/09/2019
TP Vehicle No	: SH7518K	Assignment Date	: 30/09/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 9
Date of Inspection	: 30/9/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,114.40
Revised Amount	:S\$	15,427.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,427.24
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

<input type="checkbox"/>	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
<input type="checkbox"/>	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
<input checked="" type="checkbox"/>	Other comments : The above survey was conducted on a 'Without Prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Iris Auth'd	Status
Main	27 Sep 2019		30 Sep 2019 08:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YEO SUNG SIEN ADRIAN, ID: S7937561F								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH7518K	Date of Loss:	27/09/2019 07:00 - :59						
Claim Type:	TP / CMTD1904533	Policy/Cover Note No.:	D19MTPV01002247 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGW4546L	Policy No. (Claimant):							
	Excess:								
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2019]								
Driver/Custodian (Insured):	CHEW PAMELA HUAN PEI (), NRIC: S8070089Z, Tel: +6596847750 Email:								
Adj Asg. Remarks:	WS: Lynn or Irene 6542 5119 or 7162								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD619128549 / ComfortDelGro Engineering Pte Ltd - Loyalist
 ENTRY DATE & TIME: 27/09/2019 13:45
 SUBMITTED BY: Catherine For May Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2019 13:45
Date Of Accident	27/09/2019 07:30
Exact Location Of Accident	BENCOOLEN STREET TWDS MIDDLE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH7518K
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	SHANKER S/O JAGANATHAN
NRIC No	S8141993J
Date Of Birth	15/12/1981
Occupation	OUTDOOR
Date Of Driving Pass	14/10/2015
Driving Experience	3 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81025211
Fax Number	
Contact Number	
EMail Address	ROMEO_81@OUTLOOK.COM

Address 180A #07-341 RIVERVALE CRESCENT
Postcode 541180
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 4
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 4
Passenger 1
NAME: : -
GENDER: : MALE
Passenger 2
NAME: : -
GENDER: : FEMALE
Passenger 3
NAME: : -
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGW4546L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHEW PAMELA HUAN PEI
NRIC/Passport Number

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT & REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLN2378G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver LAM CHEE YEONG
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLP3864C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver HO KAH WAI
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SHANKER S/O JAGANATHAN
Approximate Age 38
Injuries Sustain HEADACHE
Injured person in which vehicle? SH7518K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time: 27.09.2019@1230HRS



Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____
June

SKETCH PLAN



A- SH 7518K
 B- SGW 4546L
 C- SLN 2378G
 D- SLP 3864C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27.09.2019 @ 0730HRS I was travelling along Bencoolen ST Twds Middle Rd with one male and two female onboard.

As veh(C) SLN 2378G stopped and I followed suddenly veh(B) SGW 4546L hit onto my rear and caused my vehicle to surge forward and hit onto veh(C). There's 4 vehicles involved.

I have company photo and video at scene to support my claims.

After the accident I suffered headache and I will consult a doctor later.

Veh(B) SGW 4546L- MS Chew Pamela Huan Pei

Veh(C) SLN 2378G - MR Lam Chee Yeong

Veh(D) SLP 3864C - MR Ho Kah Wei

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
 CO. REG. NO. 199303821R

COMFORT TRANSPORTATION PTE LTD

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 27.09.2019@1230HRS

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: June

REPAIR ESTIMATE*

DATE : 27.09.2019

TEL : 6542 5119

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille <i>crack</i>			\$ 1,110.10 ✓
	Radiator Grille H Emblem <i>NH</i>			\$ 39.50 ✓
	Front Bumper Cover <i>mondy crack</i>			\$ 1,052.20 ✓
	Front Bumper Sponge <i>SZ</i>			\$ 99.20 X
	Front Bumper Reinforcement <i>SVC</i>			\$ 402.10 X
	Front Bumper Bracket Top (LH/RH) <i>NH</i>	\$	22.40	\$ 44.80 X
	Front Bumper Bracket (LH/RH) <i>NH</i>	\$	24.60	\$ 49.20 X
	Headlamp Support Top Cover <i>NH</i>			\$ 222.60 X
	Headlamp Support Panel Assy <i>→ BT</i>			\$ 907.40 <i>Z.L</i>
	Headlamp (LH/RH) <i>mondy crack</i>	\$	1,388.00	\$ 2,776.00 ✓
	Radiator <i>NH photo taken</i>			\$ 698.30 X
	Radiator Fan Blade,Cowling,Motor Assy <i>NH</i>			\$ 792.95 X
	Radiator Bracket (RH/LH) <i>NH</i>	\$	6.50	\$ 13.00 X
	Radiator Guard <i>NH</i>	\$	20.00	\$ 40.00 X
	Horn Unit (LH/RH) <i>NH</i>	\$	73.80	\$ 147.60 X
	Aircon Condenser <i>NH photo taken</i>			\$ 927.50 X
	Inter Cooler <i>NH photo taken</i>			\$ 1,032.50 X
	Inter Cooler Mounting (2 PCS) <i>NH</i>			\$ 25.90 X
	SUB TOTAL		5885.20	\$ 10,380.85
	LESS 20%			\$ 2,076.17
	DISCOUNTED TOTAL		4708.16	\$ 8,304.68
	Front Number Plate <i>crack</i>			\$ { 25.00 Net ✓
	Front No Plate Trim Cover <i>crack</i>			\$ { 30.00 Net ✓
			45/-	
			45.00	\$ 55.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 400/-
	Spray Painting Charge			\$ 250.00 200/-
	Wiring Charge			\$ 50.00 30/-
	Remove/Refix Aircon & Refill Gas		630.00	\$ 150.00 NH
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00 NH
	TOTAL LABOUR			\$ 1,930.00

SH 7518K

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid <i>Vst</i>			\$ 2,174.90
	Boot Lid Rubber <i>distorted</i>			\$ 96.50
	Boot Lid Hinge (LH/RH) <i>NH</i>		\$ 142.30	\$ 284.60
	Boot Lid Lock Upper <i>Dem</i>			\$ 102.60
	Boot Lid Lock Lower <i>dem</i>			\$ 31.70
	Boot Lid 'H' Emblem <i>NH</i>			\$ 28.70
	Boot Lid CRDI Plate <i>NH</i>			\$ 27.90
	Boot Lid Lamp (LH/RH) <i>circle</i>		\$ 565.60	\$ 1,131.20
	Boot Lid Trimboard <i>NH</i>			\$ 116.40
	Boot Lid Trimboard Clips (10pcs) <i>NH</i>			\$ 11.00
	Bootlid Moulding <i>NH</i>			\$ 85.00
	Bootlid i40 Emblem <i>NH</i>			\$ 27.90
	Bootlid Lower Garnish <i>NH</i>			\$ 227.90
	Rear Bumper <i>distorted</i>			\$ 553.00
	Rear Bumper Reinforcement <i>circle</i>			\$ 428.40
	Rear Bumper Reinforcement Bracket (LH/RH) <i>NH</i>		\$ 80.30	\$ 160.60
	Rear Bumper Clip 10 pcs <i>NH</i>			\$ 22.00
	Rear Bumper Bracket <i>NH</i>		\$ 35.60	\$ 71.20
	Rear Bumper Sponge <i>form</i>			\$ 118.40
	Rear Bumper Under Cover <i>distorted</i>			\$ 228.00
	Tail Lamp (LH/RH) <i>circle</i>		\$ 697.80	\$ 1,395.60
	Rear Panel <i>Distorted</i>			\$ 526.70
	Rear Panel Garnish <i>src</i>			\$ 57.70
	Rear Panel Lower Panel <i>Distorted</i>			\$ 495.50
	Exhaust Pipe Insulator <i>NH</i>		\$ 58.55	\$ 117.10
	Exhaust Silencer <i>Vst</i>		\$ 967.70	\$ 1,935.40
	Exhaust Pipe Hanger <i>NH</i>		\$ 58.55	\$ 117.10
	Exhaust Pipe Centre <i>NH</i>			\$ 730.10
	Spare Tyre Panel <i>Distorted</i>			\$ 852.80
			10117.60	
			8094.08	
	SUB TOTAL			\$ 12,155.90
	LESS 20%			\$ 2,431.18
	DISCOUNTED TOTAL			\$ 9,724.72
	Boot Lid Comfort Logo & Tel No. Sticker <i>NH</i>			\$ 30.00
	Boot Lid Advertisement Logo <i>NH</i>			\$ 100.00
	Rear Bumper Advertisement Logo <i>NH</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>NH</i>		\$ 100.00	\$ 200.00
			380.00	
				\$ 380.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,000.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Exhaust Pipe			\$ 300.00
			1570.00	
			15427.24	
			12300.00	
			9 days.	
	TOTAL LABOUR			\$ 2,720.00
	ESTIMATE TOTAL			\$ 23,114.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Resurvey is on a "Without Prejudice" basis

Legal modification(s) is allowed

Supplementary work(s) must be resurveyed and approved by Repairer and Insurance Company

30/09/2019 @ 10:15 AM

NA Arthur

2 LKK Auto

Nett ✓

Nett ✓

Nett ✓

Nett ✓

700/-

700/-

30/-

40/-

40/-

60/-

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19017125/DVF3N2
Date: 12/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01002247
Claimant Vehicle No :	SH7518K	Insured Vehicle No :	SGW4546L
Date of Loss:	27/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904533

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7518K	Engine No:	D4FDEU475028
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU080463
Reg. Date:	19/11/2015 (Man. Year: 2015)	Odometer:	548634 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	18,464.40	13,227.24	5,237.16	28.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,200.00	2,450.00	52.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,114.40	15,427.24	7,687.16	33.26
Approved Total (Overridden) (S\$)		12,300.00		
(S\$)	23,114.40	12,300.00	10,814.40	46.79
+ GST 7.00/7.00% (S\$)	1,618.01	861.00	757.01	46.79
Nett Amount (S\$)	24,732.41	13,161.00	11,571.41	46.79

INSPECTION

Date of Assignment:	30/09/2019	
Date Inspected:	30/09/2019	Inspected At: Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	9.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2019)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH7518K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	1,110.10 FL	*1,110.10 FL
2	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
3	1		*FRONT BUMPER COVER	Mounting Cracked	1,052.20 FL	*1,052.20 FL
4	1		*FRONT BUMPER SPONGE	Serviceable	99.20 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Serviceable	402.10 FL	*- FL
6	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
7	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
8	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
9	1		*HEADLAMP SUPPORT PANEL ASSY	Bent	907.40 FL	*907.40 FL
10	2		*HEADLAMP (LH/RH)	Mounting Cracked	2,776.00 FL	*2,776.00 FL
11	1		*RADIATOR	Not Necessary	698.30 FL	*- FL
12	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
13	2		*RADIATOR BRACKET (RH/LH)	Not Necessary	13.00 FL	*- FL
14	2		*RADIATOR GUARD	Not Necessary	40.00 FL	*- FL
15	2		*HORN UNIT (LH/RH)	Not Necessary	147.60 FL	*- FL
16	1		*AIRCON CONDENSER	Not Necessary	927.50 FL	*- FL
17	1		*INTER COOLER	Not Necessary	1,032.50 FL	*- FL
18	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
19	1		*BOOT LID	Bent	2,174.90 FL	*2,174.90 FL
20	1		*BOOT LID RUBBER	Deformed	96.50 FL	*96.50 FL
21	2		*BOOT LID HINGE (LH/RH)	Not Necessary	284.60 FL	*- FL
22	1		*BOOT LID LOCK UPPER	Damaged	102.60 FL	*102.60 FL
23	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
24	1		*BOOT LID H EMBLEM	Necessary	28.70 FL	*28.70 FL
25	1		*BOOT LID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
26	2		*BOOT LID LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
27	1		*BOOTLID TRIMBOARD	Not Necessary	116.40 FL	*- FL
28	1		*BOOTLID TRIMBOARD CLIPS (10 PCS)	Not Necessary	11.00 FL	*- FL
29	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
30	1		*BOOTLID I40 EMBLEM	Not Necessary	27.90 FL	*- FL
31	1		*BOOTLID LOWER GARNISH	Not Necessary	227.90 FL	*- FL
32	1		*REAR BUMPER	Distorted	553.00 FL	*553.00 FL
33	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
34	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	160.60 FL	*- FL
35	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
36	2		*REAR BUMPER BRACKET	Not Necessary	71.20 FL	*- FL
37	1		*REAR BUMPER SPONGE	Torn	118.40 FL	*118.40 FL
38	1		*REAR BUMPER UNDER COVER	Distorted	228.00 FL	*228.00 FL
39	2		*TAIL LAMP (LH/RH)	Cracked	1,395.60 FL	*1,395.60 FL
40	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*REAR PANEL GARNISH	Serviceable	57.70 FL	*- FL
42	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
43	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
44	2		*EXHAUST SILENCER	Bent	1,935.40 FL	*1,935.40 FL
45	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
46	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
47	1		*SPARE TYRE PANEL	Dented	852.80 FL	*852.80 FL
48	1		*FRONT NO PLATE TRIM COVER }	Cracked	30.00 FS	*45.00 FS
49	1		*FRONT NUMBER PLATE }	Cracked	25.00 FS	*- FS
50	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
51	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
52	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
53	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) 22,971.75 16,427.80
 - List Item Discount on L Items 20.00/20.00% (S\$) 4,507.35 3,200.56

Total Parts (S\$) 18,464.40 13,227.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,200.00	1,100.00
2	SPRAY PAINTING CHARGE	New	1,250.00	900.00
3	WIRING CHARGE	New	100.00	60.00
4	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
5	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	480.00	0.00
6	TUFF KOTE	New	50.00	40.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	300.00	60.00
Gross Labour Cost (S\$)			4,650.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >