

ASS. REC. BY:

REF: CS/SMO19 017127/ Eyf302

Special Instruction:

Surveyor: Sevi

ASSIGNMENT (Office)

From (Person): Graa TAO

of SMO

Date/Time: 30.9.19 11.19 A.M

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC 47673

Insured:

SGA 206B

at Workshop m/s SMRT

Tel:

68662671

of 60 Woodland Industrial Park E4

Policy No:

Claim No: CMTD 19 04538

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 30.9.19 11.23 A.M

Person Contacted:

Shanti

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 47673 - (23) AXA 1401764 / Klu 392
	SGA 206B - x
1/10/19	Sent Preli by Merimen

photo 6.5

Sompo

## 240

11

261

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Hwang Shiang Yi

Date: 07 Oct 2019

**Preliminary Advice**

Insured Vehicle No	: SGQ206B	Accident Date	: 27/09/2019
TP Vehicle No	: SHC4767J	Assignment Date	: 30/09/2019
Make	: TOYOTA PRIUS TAXI	Est. Duration of Repair	: 2.00
Date of Inspection	: 30/09/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (HQ) NO. 61 WOODLANDS INDUSTRIAL PARK E9, #04-04 PREMIUM BUILDING SINGAPORE 757047		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages REAR portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,250.00
Revised Amount	:S\$	1,100.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :THE ABOVE SURVEY WAS CONDUCTED ON A WITHOUT "PREJUDICE" BASIS

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Sep 2019		30 Sep 2019 11:22 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	CHEONG KUO YEW, ID: S7831047B, Tel: +6581337642, Email: CHEONGHOUSE@YAHOO.COM								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHC4767J	Date of Loss:	27/09/2019 19:00 - :59						
Claim Type:	TP / CMTD1904538	Policy/Cover Note No.:	D19MTPV01011467 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGQ206B	Policy No. (Claimant):							
		Excess:							
Repairer:	Smt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... <b>[Final Rpt due 09/10/2019]</b>								
Driver/Custodian (Insured):	CHEONG KUO YEW (40 / Male), NRIC: S7831047B, Tel: +6581337642 Email: CHEONGHOUSE@YAHOO.COM								
Adj Asg. Remarks:	WS: SHANTI 68662671/2								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Summer Lee (LKK Auto)

---

**From:** Teo, Grace <grace.teo@sompo.com.sg>  
**Sent:** Monday, 30 September, 2019 11:19 AM  
**To:** Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis); Hwang, Shiang Yi; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'  
**Cc:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis); Koo Yew Chung (Auto Svcs/ARC/ARC); Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis); Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis); angbangkien@smrt.com.sg; Henry, Irene James  
**Subject:** CMTD1904538/SYH - LKK/ SGQ206B & SHC4767J ACC ON 27.09.19

### Without Prejudice

Our Reference: CMTD1904538/SYH  
Your Reference: SHC4767J

Hi Shanti,

We acknowledged receipt of your claim documents.

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205.

Please be informed, we have appointed LKK AUTO to survey the above vehicle.

Aside to LKK AUTO,

Please make arrangement to conduct the survey for SHC4767J on a without Prejudice and any admission of liability basis.

Please submit your report via Merimen upon completion of survey

Best Regards

**Grace Teo**

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to [motorsurvey@sompo.com.sg](mailto:motorsurvey@sompo.com.sg)



**SOMPO**  
INSURANCE

**A Century of Trust**

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

**Website:** [www.sompo.com.sg](http://www.sompo.com.sg) | **Facebook:** [www.facebook.com/SompoSG](https://www.facebook.com/SompoSG)

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG

Download now @



or



<sup>1</sup>For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

**Disclaimer:** This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

**Privacy Policy Notice:** Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

---

**From:** Shanti B Thaiyal Nayagi (Auto Svcs/Claims & IA/Claims & IA/Taxis) [mailto:BThaiyalN@smrt.com.sg]

**Sent:** Monday, September 30, 2019 8:21 AM

**To:** 'motorsurvey@sompo.com.sg'

**Cc:** Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis); Kok Tuck Foo (Auto Svcs/ARC/ARC/Taxis); Koo Yew Chung (Auto Svcs/ARC/ARC); Grace Ng Siu Ching (Auto Svcs/ARC/ARC/Taxis); Chin Kim Ming (Auto Svcs/ARC/ARC/Taxis); Keith Ang Bang Kien (Auto Svcs/ARC/ARC/Taxis)

**Subject:** RE: SHC4767J - Sompo Insurance

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHC4767J** within 48 hours according to GIA guide line, involving your insured **SGQ206B**

**Vehicle in Woodlands**

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | [bthaiyaln@smrt.com.sg](mailto:bthaiyaln@smrt.com.sg)



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/09/2019 08:16
Date Of Accident	27/09/2019 19:35
Exact Location Of Accident	TELOK BLANGAH TOWARDS PASIR PANJANG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4767J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

### Driver

Name of Driver	LEK CHOON SENG
NRIC No	S1651058J
Date Of Birth	17/02/1964
Occupation	OUTDOOR
Date Of Driving Pass	21/11/1985
Driving Experience	33 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS STATIONARY ALONG TELOK BLANGAH ROAD TOWARDS PASIR PANJANG WITH 4 PASSENGERS(COUPLE/CHILDREN MALAY) ON BOARD AS IT WAS THE RED TRAFFIC LIGHT. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SGQ206B HAD COLLIDED ONTO THE REAR OF MY TAXI. WHEN I ALIGHTED I REALISED THAT IT WAS A CHAIN COLLISION INVOLVING THREE VEHICLES INCLUDING MINE.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGQ206B
Vehicle Make/Model/Colour	



Details Of Properties

Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SKB431Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan Pg. 1

### SKETCH PLAN

Telok Blangah Road

vivacity  
Bus stop

BUS LANE

A- SHC 4767 J

B-SGA 206B

G-SKB431Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is a vertical margin line on the left side, creating a narrow left margin. The paper appears to be from a notebook or a standard ruled sheet. At the very bottom left corner, there is a small, faint circular mark, possibly a hole punch reinforcement.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

*27/09/19*

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

*28/9/2019*

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

### Vehicle Details

Vehicle No.:	SHC4767J
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR1666805
Chassis No.:	JTDKN36U705767384
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	05 Feb 2016
First Registration Date:	05 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2024
PARF Rebate Amount:	\$3,750.00

### Intended COE Rebate Details

COE Expiry Date:	04 Feb 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$43,040.00
COE Rebate Amount:	\$23,375.00
<b>Total Rebate Amount:</b>	<b>\$27,125.00</b>

### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Sep 2019

OK



## Case Details

**Case Reference Number :** TAX/09/19/2109  
**Type of Repair :** Accident Repair  
**Vehicle Registration Number :** SHC4767J

**Company Type :** SMRT Taxis Pte Ltd  
**Estimation ID :** EST-8677-ID  
**Assigned By :** Taxi Claims Manager Team

**Insurance Company Name :** Sompo Insurance Singapore Pte. Ltd  
**Accident Date and Time :** 27/09/2019 11:38 AM  
**Vehicle Age(In Months) :** 43

## Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

## Estimation Details

### Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace * / PD
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace * / NEC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace * / NEC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check * X NN
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Giv * X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Not Giv * X SVC
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Giv * X SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	10.00	162.00	Replace	0	0	Check * X NN.
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Giv * X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Giv * X SVC

Total Spare Part Cost 3,477.07

Surveyor Total 651.38

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 2,380.04

Final Sur Total 521.10

## SMRT Recommendation

## Surveyor Approval

SOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	• / BT
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0	Not Give	• X SVC
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0	Not Give	• X SVC

Total Spare Part Cost 3,477.07

Surveyor Total 651.38

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 2,380.04

Final Sur Total 521.10

2243.60

## Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	678.00	200	
Total:			678.00	200.00	

576

250

## Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			738.00	200.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY REAR PANEL	180.00	0	
<b>Total:</b>			<b>738.00</b>	<b>200.00</b>	
			938	350	

**Other Cost Detail**

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ Nec
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ Nec
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec
5	Main	TO WASH AND VACUUM	60.00	0	
<b>Total:</b>			<b>460.00</b>	<b>60.00</b>	

**Summary**

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	2,360.04	521.10
Total Labour Cost	678.00	200.00
Total Spray Painting	738.00	200.00
Other	460.00	60.00
Overall Total	4,254.04	1,111.38
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	4,250.00	1,100.00
Surveyor Approved Amount		1,100.00
No of Repair Days*	6	2
Remarks	-	Lump Sum Repair, Take After Spray.
Surveyor Name		STEVE CHEN

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature



Save

Clear

Survey Date

30/09/2019

Steve  
30/09/2019.  
Lump Sum Repair.  
Take After spray

TP without Prejudice.

  
7/10/19

Repair Days - 2 days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





*Fik*

## Section A - Accident Details

Registration Number	SHC4767J
Case Reference Number	TAX/09/19/2109
Registration Date	5/2/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LEK CHOON SENG
Type of Accident	Head to Rear
Accident Date and Time	27/9/2019 7:38 PM
Accident Reported Date and Time	28/9/2019 8:24 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103580
Special Instruction to ARC, if any	DROVE IN/ TP / REAR PORTION
Prepared Date and Time	26/9/2019 2:48 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$876.00	\$350.00
Total Spray Cost	\$938.00	\$350.00
Total Spare Part Cost	\$3,216.59	\$956.05
Total Other Cost	\$460.00	\$60.00
TOTAL COST	\$5,490.59	\$1,716.05
Lump Sum Total	\$5,500.00	\$1,700.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / Sampo
ARC / Surveyor Sign Off Date	02/10/2019 3:42 PM	02/10/2019 1:25 PM
Signature		
Remarks	Total number of repair days = 3 days. SUP = + 1 day.	Lump Sum Repair, Take After Spray.

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0145	Invoice Number	
Quotation Date	10.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$200.00	\$150.00 (Supp)
TO REPAIR REAR PORTION	\$676.00	\$200.00
Total Labour	\$876.00	\$350.00

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$200.00	\$150.00 (Supp)
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$938.00	\$350.00

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$460.00	\$60.00

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52016-47030	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Not Given
		89997-30070	ANTENNA ELECTRICAL LOWER REAR	0.00	\$157.40	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check
		52578-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given
		52591-47021	BUMPER SEAL, RR RH	0.00	\$85.70	0.00	\$0.00	Replace	Not Given

		76068-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
		76067-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given	X
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace	X
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
		58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Not Given	X
			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	X
		68350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	0.00	\$0.00	Replace	Not Given	X
		81551-47180	TAIL LAMP RH	0.00	\$557.80	0.00	\$0.00	Replace	Not Given	X
Total					\$4,325.80		\$651.38			

Added Spare Parts / Material Usage After Surveyor Signed off										
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace	DD
		52016-47030	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	BT
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace	BT
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	SHO
Total					\$684.90		\$43.68			

$$\begin{array}{r}
 1195.06 \\
 - 202 \\
 \hline
 956.05 \\
 + 350.00 \\
 + 410.00 \\
 \hline
 1716.05 \\
 \text{US \$1700/-}
 \end{array}$$

# REQUEST FOR SUPPLEMENT PARTS

Contractor:			
Accident Case Number	TAX/09/19/2109	Date of Collection	1 / 1
Vehicle No	SUC 4767 J	Date of Request	01/10/2019
Vehicle Model	TOYOTA PRIUS	Number of Days to Extend (If any)	31

S/N	Part Number	Part Description	Quantity	Unit Price
		BUMPER REINFORCEMENT REAR	1pc	\$154.28
		ARM SUB ASSY, REAR BUMPER RH	1pc	\$104.70
		ARM SUB ASSY, REAR BUMPER LH	1pc	\$104.70
		SENSOR REVERSE	1pc	\$180
	LABOR	TO REPAIR REAR END PANEL		\$200
	LABOR	TO SPRAY REAR END PANEL		\$200


/ 00  
 / BT  
 / BT  
 / Short  
 150 /  
 150 /

<<<Please submit photographs for damaged parts>>>

I, (Name) Steve CLKK

(Position) \_\_\_\_\_

do solemnly and sincerely declare that:- Supplementary Parts are raised for replacement for the aforesaid vehicle.

  
 Signature of person making this declaration  
 (to be signed in front of an authorised witness)

1/10/19 8.00pm

I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the charges of perjury.

For SMRT Staff

Acknowledge By	ARC Executive / Supervisor / SA	
Approval By	Surveyor / In-house Staff	
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted	YES / NO	Date of submission

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Sep 2019		30 Sep 2019 11:22 <a href="#">Edit Adj Rpt</a>	<b>S\$1,700.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,700.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CHEONG KUO YEW, ID: S7831047B, Tel: +6581337642, Email: CHEONGHOUSE@YAHOO.COM		
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHC47673	Date of Loss:	27/09/2019 19:00 - :59 [43 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1904538	Policy/Cover Note No.:	D19MTPV01011467 (Comprehensive)
Vehicle Reg. No. (Insured):	SGQ206B	Policy No. (Claimant):	
		Excess:	
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 09/10/2019]		
Driver/Custodian (Insured):	CHEONG KUO YEW (40 / Male), NRIC: S7831047B, Tel: +6581337642 Email: CHEONGHOUSE@YAHOO.COM		
Adj Asg. Remarks:	WS: SHANTI 68662671/2		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SHC4767J (CMTD1904538)  
[SGQ206B]


















TP

SMRT TAXIS PTE LTD

Sep 27 2019 7:00PM

[CHEONG KUO YEW]

Smrt Automotive Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print	
1	30/09/19 11:21	<b>Accident Statement</b> <small>From: SC - Reg. No: SGQ206B, Claimant: CHEONG KUO YEW</small>	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	07/10/19 18:14	<b>Adjuster Immediate Advice</b>	 Load HTM		
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Resorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
2	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
3	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
4	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
5	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
6	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
7	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
8	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
9	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
10	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
11	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
12	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
13	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
14	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
15	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
16	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
17	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
18	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
19	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
20	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
21	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
22	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
23	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
24	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
25	08/10/19 08:42	<b>Chassis Number</b>	 Load JPG	<input checked="" type="checkbox"/>	
26	08/10/19 08:42	<b>Odometer Reading</b>	 Load JPG	<input checked="" type="checkbox"/>	
27	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
28	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
29	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
30	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
31	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
32	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
33	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
34	08/10/19 08:42	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
35	08/10/19 08:43	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>	
36	08/10/19 08:43	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>	
37	08/10/19 08:43	<b>Photographs of Damaged Parts</b>	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
38	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	08/10/19 08:43	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
48	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
49	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
50	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
51	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
52	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
53	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
54	08/10/19 08:43	After Repair Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	30/09/19 11:20	TP - SAS		<input checked="" type="checkbox"/>
2	30/09/19 11:20	TP - ACK+ASSIGN LKK		<input checked="" type="checkbox"/>
3	08/11/19 16:50	CMTD1904538 - PD LOD DT 14.10.19 FROM SMRT AUTOMOTIVE - SHC4767J		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/11/19 10:05	Supplementary		<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19017127/EYF3E2

Date: 28/11/2019

## REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01011467
Claimant Vehicle No :	SHC4767J	Insured Vehicle No :	SGQ206B
Date of Loss:	27/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904538

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SHC4767J		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR1666805
Reg. Date:	05/02/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U705767384
Colour:	Maroon	Odometer:	390641 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,069.60	1,195.06	3,874.54	76.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,274.00	760.00	1,514.00	66.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,343.60</b>	<b>1,955.06</b>	<b>5,388.54</b>	<b>73.38</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,700.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,343.60</b>	<b>1,700.00</b>	<b>5,643.60</b>	<b>76.85</b>

## INSPECTION

Date of Assignment:	30/09/2019	
Date Inspected:	30/09/2019 Inspected At:	Smrt Automotive Services Pte Ltd (HQ) 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG



*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2019)
<b>Parts:</b>	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC4767J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Dented	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) (10PCS)	Necessary	21.00 F	*15.75 F
3	1		*BUMPER LIP REAR (DISC 25%)	Bent	228.90 F	*171.68 F
4	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Dented	205.70 F	*154.28 F
5	1		*ARM SUB-ASSY. RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
6	1		*ARM SUB-ASSY. RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
7	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
8	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
9	1		*ARM SUB-ASSY. RR BUMPER RH	Serviceable	139.60 F	*- F
10	1		*ARM SUB-ASSY. RR BUMPER LH	Serviceable	139.60 F	*- F
11	1		*ANTENNA, ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
12	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
13	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
14	1		*BUMPER SEAL, RR LH	Serviceable	88.90 F	*- F
15	1		*BUMPER SEAL, RR RH	Serviceable	65.70 F	*- F
16	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
17	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
18	1		*UNDER COVER SUB-ASSY, RR FLOOR	Serviceable	514.50 F	*- F
19	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
20	1		*END PANEL	Serviceable	602.10 F	*- F
21	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
22	1		*TAILGATE DOOR LOCK	Serviceable	444.10 F	*- F
23	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
24	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
25	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
Total Parts (S\$)					5,069.60	1,195.06

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	876.00	350.00
2	SPRAY PAINT	New	938.00	350.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	20.00
5	TO REPLACE SUNDRY PARTS	New	100.00	20.00
6	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
7	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			2,274.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >