

(08/11/13) wef

REF:

ASS. REC. BY: MAGUS

C3/MSG 19017137/UVF3N2

MS16/

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

4yrs.

LTA 12/29 we 2-10-2023 A44 (267)

11/10/19 Email GIA to MS16

30/10/19 L/S A 11,500 confirmed with Mr. (Red 25, 411-30, 699)

31/10/19 Send preli revised via merimen

RECEIVED 8 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

10

1)

☐

: Final Report

Resurvey No. of Trip:

2

Survey Fee:

Date/Time, File Return to?

Transportation:

2) 31/10 - typist

Add Fee:

☐

: Site Insp (\$

) S+RS \$

250

☐

: Interview (\$

) Photos

11

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format: merimenLump Sum / I.B.I: (\$ 11,500/2)

TOTAL

261

Veh No:

SJK 908E

Yr Regn: 3/10/08

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or Car

Make:

Toyota corolla Axio C.G. 1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading:

259494

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NZE1416096762

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65-15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

6

Rear:

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

30/9/19

D.O.I.

30/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &amp; Rfr

The U/C / Chassis frame / Body Structure affected due to collision.

# LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd,  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: NG CHEN HOW

Date: 31 Oct 2019

## Preliminary Advice

Insured Vehicle No	: SLT4238H	Accident Date	: 30/09/2019
TP Vehicle No	: SJK908E	Assignment Date	: 03/10/2019
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 10.00
Date of Inspection	: 30/09/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,911.30
Revised Amount	:S\$	11,500.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,500.00

Lump Sum Repair	:S\$	
-----------------	------	--

## Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

## Remarks

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2019 16:52		03 Oct 2019 16:59 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Main Claimant:	TOH HONG MOH, ID: S7905207H								
Vehicle Reg. No.:	SJK908E	Date of Loss:	30/09/2019 06:00 - :59 [131 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 607285	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLT4238H	Policy No. (Claimant):	10858056						
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by NG CHEN HOW - 6643 1391]								
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 04/10/2019]								
Driver/Custodian (Insured):	KAMAL BIN ISMAIL (51 / Male) , NRIC: S6808857G, Tel: +6583393095 Email:								
Adj Asg. Remarks:	Direct Survey by LKK Auto on 30/09/2019.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 1 October 2019 11:14 AM  
**To:** 'motorsurvey'; SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 30/9/2019, SJK 908E (TP VEHICLE), SLT 4238H (OI VEHICLE)  
**Attachments:** GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SJK 908E at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 30/9/2019

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



axio

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home > Used Cars > ABS Auto Capital Pte Ltd > Toyota Corolla Axio 1.5A X (COE till 05/2023)

Toyota Corolla Axio 1.5A X (COE till 05/2023)

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

PREMIUM AD

Price	\$22,588		
Depreciation	\$6,250 /yr	Reg Date	13-May-2008 (3yrs 7mths 12days COE left)
Mileage	108,479 km (9.5k /yr)	Manufactured	2008
Road Tax	\$750 /yr	Transmission	Auto
Dereg Value	\$13,812 as of today (change)	OMV	\$13,322
COE	\$19,096	ARF	\$13,322
Engine Cap	1,496 cc	Power	81.0 kW (108 bhp)
Curb Weight	1,130 kg	No. of Owners	2
Type of Vehicle	Mid-Sized Sedan		

**Features**  
Responsive 16 Valves 4 Cylinder VVT-i DOHC Engine, Low Fuel Consumption, ABS, Dual SRS Airbags. View specs of the Toyota Corolla Axio (2007-2012)


**Accessories**  
Leather Seats, Sports Rims, Solar Film, Immobilizer, Reverse Sensor, Audio System.

**Description**  
We Are The COE Specialist. No Gimmicks, Honest Dealing, 2 Owners With Low Mileage Clocked. Car In Very Good Condition. Full Loan Available, 100% Approval. Trade In Welcome, Bank Loan Available. Call Our Friendly Salesman For An Appointment At Our Showroom Today.


**Category**  
COE Car, Premium Ad Car, Low Mileage Car

**Status**  
Available

Resources



Vehicle Evaluation  
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free  
Find out the market value of your existing car for free. Get started



Price Chart

Click on the point to view the vehicle

- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

Company

ABS Auto Capital Pte Ltd  
• dealer's profile

Posted on: 09-Sep-2019 | Last updated on: 09-Sep-2019

Upfront Payment Compare

• more Financial Info

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.

Advertise it for sale at just \$58, list till sold.

axioPrice Range▼Depreciation▼> 10 year▼Vehicle Type▼SubmitAdvanced Search

Home » Used Cars » L-Motors Pte Ltd » Toyota Corolla Axio 1.5A X (COE till 05/2023)

Toyota Corolla Axio 1.5A X (COE till 05/2023)

OverviewFinancialInsuranceAccessoriesSimilarResearchPhotosMap

Price	\$24,800		
Depreciation	\$6,760 /yr	Reg Date	03-Jun-2008 (3yrs 8mths 1day COE left)
Mileage	N.A.	Manufactured	2008
Road Tax	\$750 /yr	Transmission	Auto
Dereg Value	\$14,011 as of today (change)	OMV	\$12,360
COE	\$19,096	ARF	\$12,360
Engine Cap	1,496 cc	Power	81.0 kW (108 bhp)
Curb Weight	1,130 kg	No. of Owners	2
Type of Vehicle	Mid-Sized Sedan		

Features

View specs of the Toyota Corolla Axio (2007-2012)

Description

New Air Con Compressor, New Air Con Cooling Coil, New Tie Rod End, New Engine Mounting, New Shock Absorber, New Lower Arm, New Drive Shaft Cover, New Rear Shock Absorber. Clean And Neat Interior. One Owner Only.


Category

COE Car

Status


Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more.



Car Valuation - Free

Find out the market value of your existing car for free. Get started.



Price Chart

Click on the point to view the vehicle

ShortlistCompareAdd note

Report ErrorMore Actions

Seller Information

Company

L-Motors Pte Ltd

• dealer's prceelist

• 0 vehs sold | 2 vehs available

Address

24 Sin Ming Lane #04-1008

Search cars nearby this location

Upfront Payment		+ more Financial info
Transfer Fee	\$25	
Down Payment	\$7,440 (change)	Maximum 70% Loan
1st Instalment	\$449	Based on 3.75% interest rate

> **Back to OneMotoring**

**Enquire PARF/COE Rebate for Registered Vehicle**

**Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	207H

**Vehicle Details**

Vehicle No.:	SJK908E
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1NZD191486
Chassis No.:	NZE1416096762
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$12,603.00
Original Registration Date:	03 Oct 2008
First Registration Date:	03 Oct 2008
Transfer Count:	2
Actual ARF Paid:	\$12,603.00

**Intended PARF Rebate Details**

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	02 Oct 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$15,142.00
COE Rebate Amount:	\$12,129.00
<b>Total Rebate Amount:</b>	<b>\$12,129.00</b>

**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Sep 2019

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	30/09/2019 11:53
Date Of Accident	30/09/2019 06:45
Exact Location Of Accident	BKE TOWARDS PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK908E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TOH HONG MOH
NRIC No	S7905207H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96169611
Alternative Phone No	OFFICE-96169611

### Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10858056
Cover Note Number	

### Driver

Name of Driver	TOH HONG MOH
NRIC No	S7905207H
Date Of Birth	01/03/1979
Occupation	INDOOR
Date Of Driving Pass	02/10/2000
Driving Experience	18 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96169611
Fax Number	
Contact Number	OFFICE-96169611
EMail Address	NOEMAIL



Address	407B FERNVALE ROAD #19-05
Postcode	S792407
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE STATED DATE AND TIME. I WAS DRIVING MY CAR ALONG BKE TOWARDS PIE. VEHICLE C STOP. I FOLLOW. SUDDENLY VEHICLE B HIT ON MY REAR AND CAUSE MY CAR TO PUSH FORWARD AND HIT ON VEHICLE C. THERE WERE 5 CARS INVOLVED IN AN ACCIDENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT4238H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SLM4271Y  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)


**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number GBA6041M  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number SLV7660R  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time. I was driving my car along BKE toward PIE. vehicle C stop. I fellow suddenly vehicle B hit on my rear and cause my car to push forward and hit on vehicle C. There were 5 cars involved in an accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

FASTECT AUTO PTE LTD  
BLK1 KAKI BUKIT AVE 6  
#01-46,48,50 AUTOBAY  
SINGAPORE 417883

Not Authorized  
26th  
4/5 \$11,500  
30/9/19 10 Lg.

VEHICLE NO: SJK 908E

QTY	PARTICULAR			
1 PCS	BOOTLID	899.10	sent/sec	\$1,021.10 ✓
1 PCS	BOOTLID REAR LOGO		rec	\$68.60 ✓
1 PCS	BOOTLID 'AXIO' EMBLEM		rec	\$65.00 ✓
1 PCS	BOOTLID 'X' EMBLEM		rec	\$48.00 ✓
1 PCS	BOOTLID LOCK STRIKER		11	\$66.80 X
1 PCS	BOOTLID INNER LOCK	145.50	twi	\$288.20 ✓
1 PCS	BOOTLID WEATHERSTRIP		twi	\$299.20 ✓
1 PCS	BOOTLID INNER TRIM		2c/10.1n	\$315.00 ✓
2 PCS	BOOTLID HINGES @\$145.00		Sec	\$290.00 X
1 PCS	BOOTLID OUTER HANDLE		c/a	\$366.50 ✓
1 PCS	REAR BUMPER	655.10	2c/0.15	\$788.10 ✓
2 PCS	REAR BUMPER SIDE HOLDERS @\$66.50		N/S sent	\$133.00 ✓
2 PCS	REAR BUMPER BRACKETS @\$95.00		sent	\$190.00 ✓
1 SET	REAR BUMPER CLIPS		rec	\$50.00 ✓
1 PCS	REAR END PANEL	468.00	100% 100	\$665.20 ✓
1 PCS	REAR END PANEL TOP GARNISH	206.50	twi	\$345.50 ✓
2 PCS	TAILLAMPS @\$650.10	455.10 x 2 = 910.20	c/a	\$1,300.20 ✓
2 PCS	TAILLAMP LOWER BRACKETS @\$45.00		sent/c/a	\$90.00 ✓
2 PCS	TAILLAMP HOUSING PANELS @\$305.00		rec	\$610.00 X
1 PCS	REAR FLOOR PANEL		rec	\$911.40 X
1 PCS	REAR FLOOR PANEL TOP BOARD	566.10	2c/10.1n	\$615.00 ✓
2 PCS	REAR FENDERS @\$899.10		rec	\$1,798.20 X
2 PCS	REAR FENDER INNER TRIMS @\$366.50		2c/10.1n	\$733.00 ✓
1 PCS	REAR WINDSCREEN MOULDING		11	\$141.00 X
1 PCS	REAR EXHAUST		11	\$882.50 X
2 PCS	REAR EXHAUST MOUNTINGS @\$60.00		11	\$120.00 X
1 PCS	REAR AIR VENT		11	\$69.50 X
2 PCS	REAR BUMPER SPLASH SHIELDS @\$89.50		11	\$139.00 X
1 PCS	BONNET		sent/sec	\$1,055.10 ✓
2 PCS	BONNET HINGES @\$105.00		11	\$210.00 X
1 PCS	BONNET RUBBER		rec	\$68.20 ✓
1 PCS	BONNET INSULATOR		11	\$244.20 X
1 SET	BONNET INSULATOR CLIPS		11	\$50.00 X
1 PCS	BONNET LOCK		twi	\$166.20 ✓
1 PCS	FRONT BUMPER	685.10	11	\$755.10 ✓
1 PCS	FRONT BUMPER SPONGE	202.00	11	\$288.20 ✓
1 PCS	FRONT BUMPER REINFORCEMENT		11	\$455.20 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS @\$65.00		sent	\$130.00 ✓
1 PCS	FRONT BUMPER CENTRE GRILLE		11	\$105.20 X
1 SET	FRONT BUMPER CLIPS		rec	\$50.00 ✓
1 PCS	FRONT GRILLE	381.40	c/a	\$688.00 ✓
1 PCS	FRONT GRILLE LOGO	68.50	rec	\$78.00 ✓
2 PCS	HEADLAMPS @\$1250.00	766.10 x 2 = 1532.20	c/a	\$2,500.00 ✓
1 PCS	FRONT SUPPORT PANEL	899.10	sent	\$1,078.10 ✓
1 PCS	FRONT BRACE PANEL	151.50	twi	\$211.20 ✓
1 PCS	AIR CON CONDENSER		rec	\$1,488.20 X

257

1 PCS	RADIATOR
1 PCS	RADIATOR FAN ASSY
1 PCS	HORN UNIT
1 PCS	FRONT BUMPER LOWER TRAY
2 PCS	FRONT FENDERS @\$781.10
2 PCS	FRONT FENDER INNERSHIELDS @\$188.50

11	\$1,866.20	X
11	\$1,050.00	X
11	\$99.50	X
11	\$315.50	X
11	\$1,582.20	X
ok Re	\$377.00	1PC
	<b>\$27,301.30</b>	

(257)

S.NETT	
1 SET	REAR BUMPER REVERSE SENSOR
1 SET	REAR BUMPER LOWER SKIRTING
1 PCS	REAR END PANEL SEALANT
1 PCS	REAR LICENCE PLATE W/HOLDER
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	FRONT LICENCE PLATE W/HOLDER
1 SET	FRONT BUMPER LOWER SKIRTING

Shaded	\$280.00	200
C.R.	\$1,280.00	800
all	\$50.00	50
surf/any	\$50.00	40
shad	\$380.00	300
11	\$50.00	X
C.R.	\$50.00	40
11	<b>\$1,280.00</b>	X

**LABOUR CHARGES:**

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACING REVERSE SENSOR	\$80.00	50
TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00
TO DISMANTLE & REFIX REAR WINDSCREEN	11	\$150.00
TO DISMANTLE & REFIX REAR EXHAUST		\$100.00
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY		\$150.00
TO SPRAY RUST PROOFING		\$150.00
TO REFIL AIR CON GAS		\$120.00
TO TRANSFER BOOTLID MECHANISM		\$80.00
LABOUR FOR PANEL BEATING & REPLACING PARTS		\$2,400.00
TO PUTTY & SPRAY PAINTING		\$2,500.00

	\$80.00	30
	\$80.00	50
11	\$380.00	X
11	\$150.00	X
	\$100.00	60
	\$150.00	80
	\$150.00	100
	\$120.00	100
	\$80.00	60
	\$2,400.00	1500
	\$2,500.00	1900
<b>TOTAL</b>	<b>\$36,911.30</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To be surveyed before/after spray painting
- To be surveyed during/after putty during resurvey
- Repair work is subject to confirmation
- This quote survey is on a "Without Prejudice" basis
- Facilitate modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19017137/UVF3N2

Date: 05/11/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SJK908E	Insured Vehicle No :	SLT4238H
Date of Loss:	30/09/2019	Nature of Claim:	TP
		Claim No:	607285

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SJK908E	Engine No:	1NZD191486
Make & Model:	TOYOTA COROLLA, 1.5 AXIO (A)	Chassis No:	NZE1416096762
Reg. Date:	03/10/2008 (Man. Year: 2008)	Odometer:	259494 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	30,721.30	10,563.72	20,157.58	65.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,190.00	3,880.00	2,310.00	37.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>36,911.30</b>	<b>14,443.72</b>	<b>22,467.58</b>	<b>60.87</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>11,500.00</b>		
<b>(\$\$)</b>	36,911.30	11,500.00	25,411.30	68.84
<b>+ GST 7.00/7.00% (\$\$)</b>	2,583.79	805.00	1,778.79	68.84
<b>Nett Amount (\$\$)</b>	<b>39,495.09</b>	<b>12,305.00</b>	<b>27,190.09</b>	<b>68.84</b>

## INSPECTION

Date of Assignment:	03/10/2019	
Date Inspected:	30/09/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

*knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2019)
<b>Parts:</b>	143	TOYOTA COROLLA 1.5 AXIO (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJK908E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent/Buckled	1,021.10 F	*899.10 FL
2	1		*BOOTLID REAR LOGO	Necessary	68.60 F	*68.60 FL
3	1		*BOOTLID AXIO EMBLEM	Necessary	65.00 F	*65.00 FL
4	1		*BOOTLID X EMBLEM	Necessary	48.00 F	*48.00 FL
5	1		*BOOTLID LOCK STRIKER	Not Necessary	66.80 F	*- FL
6	1		*BOOTLID INNER LOCK	Twisted	288.20 F	*145.50 FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	299.20 F	*299.20 FL
8	1		*BOOTLID INNER TRIM	Deformed/Torn	315.00 F	*315.00 FL
9	2		*BOOTLID HINGES	Serviceable	290.00 F	*- FL
10	1		*BOOTLID OUTER HANDLE	Cracked	366.50 F	*366.50 FL
11	1		*REAR BUMPER	Deformed/Distorted	788.10 F	*655.10 FL
12	1		*REAR BUMPER SIDE HOLDERS	N/s Bent	133.00 F	*66.50 FL
13	2		*REAR BUMPER BRACKETS	Bent	190.00 F	*190.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	1		*REAR END PANEL	Badly Dented	665.20 F	*468.00 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	345.50 F	*206.50 FL
17	2		*TAILLAMP	Cracked	1,300.20 F	*910.20 FL
18	2		*TAILLAMP LOWER BRACKETS	Bent/Cracked	90.00 F	*90.00 FL
19	2		*TAILLAMP HOUSING PANELS	Repair	610.00 F	*- FL
20	1		*REAR FLOOR PANEL	Repair	911.40 F	*- FL
21	1		*REAR FLOOR PANEL TOP BOARD	Deformed/Torn	615.00 F	*566.10 FL
22	2		*REAR FENDERS	Repair	1,798.20 F	*- FL
23	2		*REAR FENDER INNER TRIMS	Deformed/Torn	733.00 F	*733.00 FL
24	1		*REAR WINDSCREEN MOULDING	Not Necessary	141.00 F	*- FL
25	1		*REAR EXHAUST	Not Necessary	882.50 F	*- FL
26	2		*REAR EXHAUST MOUNTINGS	Not Necessary	120.00 F	*- FL
27	1		*REAR AIR VENT	Not Necessary	69.50 F	*- FL
28	2		*REAR BUMPER SPLASH SHIELDS	Not Necessary	139.00 F	*- FL
29	1		*BONNET	Bent/Buckled	1,055.10 F	*1,055.10 FL
30	2		*BONNET HINGES	Not Necessary	210.00 F	*- FL
31	1		*BONNET RUBBER	Necessary	68.20 F	*68.20 FL
32	1		*BONNET INSULATOR	Not Necessary	244.20 F	*- FL
33	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
34	1		*BONNET LOCK	Twisted	166.20 F	*166.20 FL
35	1		*FRONT BUMPER	Distorted	755.10 F	*685.10 FL
36	1		*FRONT BUMPER SPONGE	Torn	288.20 F	*205.00 FL
37	1		*FRONT BUMPER REINFORCEMENT	Bent	455.20 F	*455.20 FL
38	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*130.00 FL
39	1		*FRONT BUMPER CENTRE GRILLE	Not Necessary	105.20 F	*- FL
40	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
41	1		*FRONT GRILLE	Cracked	688.00 F	*381.40 FL
42	1		*FRONT GRILLE LOGO	Necessary	78.00 F	*68.50 FL
43	2		*HEADLAMPS	Cracked	2,500.00 F	*1,532.20 FL
44	1		*FRONT SUPPORT PANEL	Bent	1,078.10 F	*899.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT BRACE PANEL	Twisted	211.20 F	*151.50 FL
46	1		*AIR CON CONDENSER	Serviceable	1,488.20 F	*- FL
47	1		*RADIATOR	Not Necessary	1,866.20 F	*- FL
48	1		*RADIATOR FAN ASSY	Not Necessary	1,050.00 F	*- FL
49	1		*HORN UNIT	Not Necessary	99.50 F	*- FL
50	1		*FRONT BUMPER LOWER TRAY	Not Necessary	315.50 F	*- FL
51	2		*FRONT FENDERS	Repair	1,562.20 F	*- FL
52	1		*FRONT FENDER INNERSHIELDS	O/s Deformed	377.00 F	*188.50 FL
53	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
54	1		*SET REAR BUMPER LOWER SKIRTING	Cracked	1,280.00 FS	*800.00 FS
55	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
56	1		*REAR LICENCE PLATE W/HOLDER	Bent/Missing	50.00 FS	*40.00 FS
57	1		*REAR REVERSE CAMERA	Shorted	380.00 FS	*300.00 FS
58	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
59	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
60	1		*SET FRONT BUMPER LOWER SKIRTING	Repair	1,280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>30,721.30</b>	<b>13,608.30</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>3,044.58</b>

<b>Total Parts (\$\$)</b>	<b>30,721.30</b>	<b>10,563.72</b>
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	60.00
6	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
7	TO SPRAY RUST PROOFING	New	150.00	100.00
8	TO REFILL AIR CON GAS	New	120.00	100.00
9	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
10	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,400.00	1,500.00
11	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,900.00
<b>Gross Labour Cost (S\$)</b>			<b>6,190.00</b>	<b>3,880.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >