

ASS. REC. BY:

REF: CS/SMO19017/39/ V9f3 n2

Special Instructions:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Gnoli Pau Loong of SMODate/Time: 30.9.19 14.21 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JQT 2246Insured: SLA 8057Lat Workshop m/s FastechTel: 6746 5405of 1 Kaki Bukit Ave 6 #01-46Policy No: D19MTPV01003167Claim No: CMTD 1904546

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 28.9.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 30.9.19 2.45 p.mPerson Contacted: Nancy

H.O.D. Endorsement: _____

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
2/10-	Sent compose mail pending estimate.
29/10/19 @ 11.20am	revised to Gnoli Pau Loong via Messenger.

08/11/13 wef

REF:

ASS. REC. BY: Marcus

ASSIGNMENT

11/1/2015

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/ Instruction

25/10/13 4/5 \$15,500, confirmed with Aler
used \$24890.20, 63%

RECEIVED 25 OCT 2019

Date/Time, File Pass to?

25/10/2013
Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

)

TOTAL

Report Format:

Lump Sum / J.B.I: (\$ 15500)

450
11
461

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 25 Oct 2019

Preliminary Advice

Insured Vehicle No	: SLA8057L	Accident Date	: 28/09/2019
TP Vehicle No	: JQT2246	Assignment Date	: 30/09/2019
Make	: HYUNDAI ELANTRA	Est. Duration of Repair	: 9.00
Date of Inspection	: 30/09/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,390.20
Revised Amount	:S\$	19,659.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	19,659.24
Lump Sum Repair	:S\$	15,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Sep 2019		30 Sep 2019 14:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	LIEW LEE YEW, ID: S12046173																							
Main Claimant:	HOO BOON KEE, ID: 920403-01-6499																							
Vehicle Reg. No.:	JQT2246	Date of Loss:	28/09/2019 00:00 - :59																					
Claim Type:	TP / CMTD1904546	Policy/Cover Note No.:	D19MTPV01003167																					
Vehicle Reg. No. (Insured):	SLA8057L	Policy No. (Claimant):																						
		Excess:																						
Repairer:	- Not Applicable - (-)																							
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2019]																							
Adj Asg. Remarks:	WS: NANCY 6746 5405 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

View Sent Message

This mail is associated with :

***JQT2246 (CMTD1904546)**
[SLA8057L]

TP
HOO BOON KEE
Sep 28 2019 12:00AM
[LIEW LEE YEW]
Fastech Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 02/10/2019 16:23 PM.
To pauloong.gnoh@sompo.com.sg
Subject *JQT2246 (CMTD1904546) [SLA8057L]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle JQT 2246 on 30/09/2019
We are pending estimate from repairer.

Best Regards,
Denise Tay | Case Handler
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents.



SINGAPORE POLICE FORCE



T/20190928/2098

1 of 4

Report No. T/20190928/2098

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/09/2019 14:54		Vide Report No.: G/20190928/0092	Station Diary No.: 22
Informant's Particulars			
Name of Informant: HOO BOON KEE		Address: 558 ANG MO KIO AVENUE 10 #13-1778 SINGAPORE 560558	
ID Type / ID No.: FIN NO / G2025201X		Contact No.: Home/Office: Mobile: 96469711	
Nationality: MALAYSIAN		Email:	
Sex: Male	Age: 27	Date of Birth: 03/04/1992	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: Air-conditioning/Refrigeration engineering technician		Driving Licence Information: Class: 2B,3 Date of Expiry: 03/04/2024	

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 28/09/2019 09:20	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Tuas before KPE exit				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBC6779H	Motorcycle	HONDA		Black		0
JQT2246	Car	HYUNDAI	ELANTRA	White	Slightly Damaged	0
SJL3906K	Car	MAZDA		Grey	Slightly Damaged	1
SLA8057L	Car	NISSAN		Grey	Slightly Damaged	2



SINGAPORE POLICE FORCE

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999



T/20190928/2098

2 of 4

Report No. T/20190928/2098

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL			
Driver		Use of Pedestrian Crossing: NA	
Name	HOO BOON KEE	ID No.	G2025201X
Related Vehicle	JQT2246 (Car)	Contact No.	96469711
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: 03/04/2024
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	TAN HENG LIN	ID No.	S7715773E
Related Vehicle	SJL3906K (Car)	Contact No.	97772922
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIEW LEE YEW	ID No.	S1204617J
Related Vehicle	SLA8057L (Car)	Contact No.	96225676
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 28/09/2019 at about 0920hrs, I was travelling along PIE towards Tuas. I was travelling on lane 1 of the expressway. As I was approaching KPE exit, the traffic was slow moving and I was travelling at speed of 40 km/hr. The vehicle in front of me (SJL3906K) came to a stop and I managed to stop behind the vehicle. However, after I stopped, I felt an impact from behind and I noticed that the car (SLA8057L) which collided into my car have already went into lane 2 of the expressway. Due to the impact, my car also collided into the car in front of my car. I then alighted from the car and then I discovered that there was also a rider and motorcycle which was already on the road due to the accident.



**SINGAPORE
POLICE FORCE**



T/20190928/2098

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

3 of 4

Report No. T/20190928/2098

CONTINUATION OF REPORT

I wish to state that the drivers of the cars involved in the accident were not injured. The rider was injured from the accident and an ambulance came to convey the rider to hospital. Due to the accident, the front and rear of my car was damaged.



**SINGAPORE
POLICE FORCE**



T/20190928/2098

4 of 4

Report No. T/20190928/2098

Police Station Of Origin:
Clementi NPP
427 Clementi Avenue 3 #01-456
SINGAPORE 120427
Tel No: 1800-7759999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
D /
Sr Staff Sgt MUHAMMAD KHAIRULDIN BIN
SAMIAN

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / GIT /
Staff Sgt YAN MINGSHENG DANIEL
Contact No.: 65476252

Signature Of Informant:

Date/Time:
28/09/2019 14:54

Classification Of Case:

SN 40

Authentication Stamp
NP168

SINGAPORE
POLICE FORCE



Zurich General Insurance Malaysia Berhad (1249516-V)
Level 23A, Mercu 3, No. 3, Jalan Bangsar, KL Eco City, 59200 Kuala Lumpur, Malaysia
Tel: 03-2109 6000 Fax: 03-2109 6888 Call Centre: 1-300-888-622

Code / Kod 18 MX1

CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT, 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS, RULES 1959 (MALAYSIA)
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT
(CAP 189) (REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF
SINGAPORE)
THE MOTOR VEHICLES INSURANCE (THIRD PARTY RISKS) ACT (CAP 90) NEGARA BRUNEI DARUSSALAM

SIJIL INSURANS

AKTA PENGANGKUTAN JALAN RAYA, 1987 (MALAYSIA)
PERATURAN KENDERAAN MOTOR (RISIKO PIHAK KETIGA) 1959 (MALAYSIA)
AKTA KENDERAAN MOTOR (RISIKO DAN PAMPASAN PIHAK KETIGA) (CAP 189) (REPUBLIK SINGAPURA)
PERATURAN KENDERAAN MOTOR (RISIKO DAN PAMPASAN PIHAK KETIGA) 1960 (REPUBLIK
SINGAPURA)
AKTA INSURANS KENDERAAN MOTOR (RISIKO PIHAK KETIGA) (CAP 90) NEGARA BRUNEI
DARUSSALAM

Certificate No. (No. Sijil) : 521500010669-04

D14636-000

1. Index Mark and Registration Number of Vehicle : JQT2246
(Tanda Indeks dan Nombor Pendaftaran Kenderaan) : HYUNDAI MD ELANTRA 1.6 MT ST NCD : 30.00 %
2. Name of Policyholder (Nama Pemegang Polisi) : HOO BOON KEE
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance of
Enactment : 19 MAR 2019
4. Date of Expiry of the Insurance (Tarikh Insurans Tamat) : 18 MAR 2020
5. Persons or Classes of Persons entitled to drive* (Orang atau Kelas Orang yang berhak memandu) :

a) Policyholder b) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to
drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by
reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitation on Usage

Use only for social, domestic and pleasure purposes and for the policyholder's business or profession. The
policy does not cover :- Use for hire or reward, racing, pace-making, reliability trial, speed- testing, or
the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in
connection with Motor Trade.

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore or Section 7
of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam are not to be included under these heading.

* Had - had yang tidak lagi berkuatkuasa kerana Seksyen 95 Akta Pengangkutan Jalan Raya, 1987 (Malaysia) atau Seksyen 8 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189)
Republik Singapura atau Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam tidak boleh dimasukkan di bawah tajuk ini.

Insured in pursuance to cover Note No : D14636-19000064

Dikeluarkan mengikut Nota lindungan No :

I / We hereby certify that the Policy to which the Certificate is issued in accordance
with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), Motor
Vehicles (Third Party Risks & Compensation) Act (Cap 189) Republic of Singapore
and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei
Darussalam.

Saya / Kami dengan ini mengesahkan bahawa Polisi yang berkaitan dengan Sijil
ini dikeluarkan selaras dengan peruntukan - peruntukan Bahagian IV Akta
Pengangkutan Jalan Raya, 1987 (Malaysia), Akta Kenderaan Motor (Risiko Dan
Pampasan Pihak Ketiga) (Cap 189) Republik Singapura dan Akta Insurans
Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam.

For and on behalf of / Untuk dan bagi pihak
ZURICH GENERAL INSURANCE MALAYSIA BERHAD

David Fike
Chief Executive Officer



Zurich General Insurance Malaysia Berhad (1249516-V)
Level 23A, Mercu 3, No. 3, Jalan Bangsar, KL Eco City, 59200 Kuala Lumpur, Malaysia
Tel: 03-2109 6000 Fax: 03-2109 6888 Call Centre: 1-300-888-622

**PRIVATE CAR
KERETA PERSENDIRIAN**

THE SCHEDULE

FINANCIAL COPY

**JADUAL
SALINAN KEWANGAN**

Agent Code (Kod Ejen)	: D14636-000 (BATU PAHAT) ONE BP CITY TRADING	Date (Tarikh)	: 02 MAR 2019
Replacing Cover Note No. (Menggantikan Nota Lindung No.)	: D14636-19000064	Receipt No. (No. Resit)	:
Policy No. (No. Polisi)	: 521500010669-04	ACT (ACT)	: RM 86.96
The Policyholder (Yang Diinsuranskan)	: HOO BOON KEE	Basic Premium	: RM 1,987.23
Address (Alamat)	: NO 15, JALAN PUTERI JAYA 27, TAMAN PUTERI JAYA, 83000 BATU PAHAT, JOHOR DARUL TAKZIM	NCD:30.00%	: RM 596.17
Business Reg. No. (No. Sykt.)	:	Extra Cover	: RM 300.00
I/C No. New (No. K/P Baru)	: 920403-01-6499 Old I/C No. (No. K/P Lama) :	Gross Premium	: RM 1,691.06
Business / Profession (Perniagaan / Pekerjaan)	: OTHERS	SST: 6.00%	: RM 101.46
Hire Purchase Owners (Pemilik Sewa Beli)	: CIMB BANK BERHAD	Stamp Duty (DUTI SETEM)	: RM 10.00
Employer / Lessors (Majikan / Pemajak)	:	Total Premium (JUMLAH)	: RM 1,802.52
Period of Insurance (Tempoh Insurans)	(a) From (Dari) : 19 MAR 2019 To (Hingga) : 18 MAR 2020 Termasuk kedua-dua Time (Masa) : 12:01AM To (Hingga) : 11:59PM tarikh dan masa (b) Any subsequent period for which you shall pay and we shall agree to accept a renewal premium Sebarang tempoh selanjutnya untuk mana anda membayar dan kami bersetuju menerima premium pembaharuan Any of the following (Mana - mana daripada yang berikut):		

The Motor Vehicle

Registration No. No. Pendaftaran	Make Buatan & Jenis Badan	Type of Body Jenis Badan	Cubic Capacity Keupayaan Enjin	Year of Manufacture Tahun Diperbuat	Seating Capacity Including Driver Muatan Tempat Duduk termasuk Pemandu	Your Estimate of Value Including Accessories Nilai Anggaran Anda termasuk Aksesori
JQT2246	HYUNDAI MD ELANTRA	SALOON	1591.00 CC	2015	5	RM64,000.00

Date of Signature of Proposal and Declaration
Tarikh Cadangan dan Perakuan Ditandatangani

EXCESS : RM 0.00
(LEBIHAN)

Engine (Enjin) : G4FGEU433246
CHASSIS (KASIS) : PP32M41GRF1000454

Subject to the terms and conditions of the Policy and endorsement as numbered below :
Tertakluk kepada peraturan - peraturan dan syarat - syarat Polisi dan pengendorsesan seperti disenaraikan di bawah :

Named Driver : 1) THE INSURED 2) HOO HUA KEE 3) HOO AI KEE
4) RAJA PALINI MUTTAPAH

Include Endorsement No : 07, 15, 100, 106, 2f, 89, FINANCIALSERVICESACT2013, 87

Additional Extra Coverage/Endorsements :-

Code Description	Value	Premium
07 ADDITIONAL DRIVERS	0.00	0.00
89 BREAKAGE OF GLASS IN WINDSCREEN, WINDOW OR SUNROOF	2000.00	300.00

Endt 87 - Agreed Value

We will pay to you the agreed amount as specified in the Schedule of the policy in the event Your Vehicle is stolen or totally destroyed during the Period of Insurance provided we are liable to pay for such loss or destruction under the Terms and Conditions of Our policy. Subject otherwise to the Terms of this Policy.

LEGISLATION:-

Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore Motor Vehicles (Third Party Risks and Compensation) Rules (Republic of Singapore), Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam (the reference to legislation under the heading "Avoidance of Certain Terms and Right of Recovery" is limited to Section 94, 95 and 96 of the Road Transport Act 1987 (Malaysia) Section 7, 8 and 9 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore and Section 7 of the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

UNDANG - UNDANG:-

Akta Pengangkutan Jalan Raya, 1987 Malaysia, Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, Peraturan Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) 1960 Republik Singapura, Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam (rujukan kepada undang - undang di bawah tajuk "Pengelakan Peraturan - Peraturan Dan Hak Tuntutan Tertentu" adalah terhad kepada Seksyen 94, 95 dan 96 Akta Pengangkutan Jalan Raya, 1987 Malaysia, Seksyen 7, 8 dan 9 Akta Kenderaan Motor (Risiko Dan Pampasan Pihak Ketiga) (Cap 189) Republik Singapura, dan Seksyen 7 Akta Insurans Kenderaan Motor (Risiko Pihak Ketiga) (Cap 90) Negara Brunei Darussalam).

**Limits of Liability:-
Had Tanggungan:-**

Limit of the amount of Our Liability under Section B-1(a) Had jumlah tanggungan Kami di bawah Seksyen B-1(a)	Unlimited
Limit of the amount of Our Liability under Section B-1(b) Had jumlah tanggungan Kami di bawah Seksyen B-1(b)	RM3,000,000.00

**Limitation as to Use
Had Penggunaan**

: As shown in the Certificate of Insurance
Seperti ditunjukkan dalam Sijil Insurans

**Geographical Area
Had Wilayah**

: Malaysia, Republic of Singapore and Negara Brunei Darussalam
Malaysia, Republik Singapura dan Negara Brunei Darussalam

**Authorised Driver
Pemandu Yang Dibenarkan**

: As shown in the Certificate of Insurance
Seperti ditunjukkan dalam Sijil Insurans

For and on behalf of / Untuk dan bagi pihak
Zurich General Insurance Malaysia Berhad

David Fike
Chief Executive Officer

[Home](#) / [Used Cars](#) / [Hyundai](#) / [Elantra](#) / [Premium](#)

Updated on: September 20, 2019

RM 736/month

RM 56,800

2015 Hyundai Elantra (A) 1.8 Premium

Updated on: September 20, 2019

 Dealer 
 Johor » Johor Bahru »


Seller Information

 Dealer 
 Johor » Johor
Bahru

Key details

	Car type	Used Car
	Make	Hyundai
	Model	Elantra
	Variant	Premium
	Year	2015
	Engine Capacity	1797 cc
	Transmission	Automatic
	Seat Capacity	5
	Mileage	40000
	Colour	Red

[View All 123 Cars From Thi](#)

Seller's comments

Say Carlist.my for the best deal

Home / Used Cars / Hyundai / Elantra
/ Premium

Updated on: September 05, 2019

2015 Hyundai Elantra 1.8 Premium Sedan

Updated on: September 05, 2019

 Sales Agent

 Johor » Johor Bahru »

RM 853/month

RM 65,800

Seller Information

 Sales Agent

 Johor » Johor
Bahru

Key details

 Car type
Used Car

 Make
Hyundai

 Model
Elantra

 Variant
Premium

 Year 2015

 Engine
Capacity 1797 cc

 Transmission
Automatic

 Seat
Capacity 5

 Mileage
88000

 Colour Silver



FASTECT AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

LKK Auto Consultants hence notify the Repairer of the following:

- * To resurvey before/after spray painting
- * To display damaged part(s) during resurvey
- * Part(s) to be repaired subject to confirmation
- * This survey is on a "Without Prejudice" basis
- * No repair modification(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Not Authorized
LKK
2/5 \$15,500
30/9/19
to be paid After repair
9/27

VEHICLE NO: JQT 2246

QTY	PARTICULAR	
1 PCS	BOOTLID	1048.00
1 PCS	BOOTLID REAR LOGO	
1 PCS	BOOTLID LOCK STRIKER	
2 PCS	BOOTLID REFLECTORS @\$520.30	385.20 x 2 = 770.40
1 PCS	BOOTLID INNER LOCK	145.00
1 PCS	BOOTLID WEATHERSTRIP	166.30
1 PCS	BOOTLID INNER TRIM	
1 SET	BOOTLID INNER TRIM CLIPS	
2 PCS	BOOTLID HINGES @\$105.00	
1 PCS	REAR BUMPER	666.80
1 PCS	REAR BUMPER REINFORCEMENT	455.80
2 PCS	REAR BUMPER REINFORCEMENT TOP BRACKETS @\$30.00	
2 PCS	REAR BUMPER REINFORCEMENT LOWER BRACKETS @\$30.00	
1 SET	REAR BUMPER CLIPS	
2 PCS	REAR BUMPER REFLECTORS @\$95.00	35 x 2 = 70
2 PCS	REAR BUMPER SIDE RETAINERS @\$45.00	
2 PCS	REAR BUMPER BRACKETS @\$201.00	105 x 2 = 210
1 PCS	REAR BUMPER SPONGE	
1 PCS	REAR END PANEL	442.80
1 PCS	REAR END PANEL TOP GARNISH	133.60
2 PCS	TAILLAMPS @\$850.00	785 x 2 = 1570
2 PCS	TAILLAMP HOUSING PANELS @\$455.00	210
2 PCS	REAR FENDERS @\$1807.00	
2 PCS	REAR FENDER INNER TRIMS @\$405.00	285 x 2 = 570
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL TOP BOARD	415.00
1 PCS	REAR WINDSCREEN MOULDING	
1 PCS	REAR EXHAUST	
1 PCS	BONNET	1105.30
2 PCS	BONNET HINGES @\$85.00	
1 PCS	BONNET RUBBER	
1 PCS	BONNET LOCK	
1 PCS	FRONT BUMPER	691.00
1 PCS	FRONT BUMPER SPONGE	145
1 PCS	FRONT BUMPER REINFORCEMENT	455.20
2 PCS	FRONT BUMPER SIDE RETAINERS @\$60.00	45 x 2 = 90
1 PCS	FRONT BUMPER CENTRE GRILLE	188.20
1 SET	FRONT BUMPER CLIPS	
2 PCS	FRONT BUMPER FOG LAMP GARNISHS @\$105.00	
1 PCS	FRONT GRILLE	266.50
1 PCS	FRONT GRILLE LOGO	
2 PCS	HEADLAMP ASSY LEDS @\$1950.00	1758 x 2 = 3512
2 PCS	HEADLAMP LOWER BRACKETS @\$85.00	62 x 2 = 124
1 PCS	FRONT SUPPORT PANEL	
1 PCS	FRONT TOP RETAINER	185.00
1 PCS	AIR CON CONDENSER	892.00

body	\$1,507.30	
re	\$42.80	
11	\$66.80	X
one	\$1,040.60	
twi	\$211.50	
twi	\$311.30	
11	\$322.60	X
11	\$50.00	X
Sur	\$210.00	X
11	\$788.20	
11	\$485.10	
twi	\$60.00	
one	\$60.00	
re	\$50.00	
one	\$190.00	
Sur	\$90.00	
Sur	\$402.00	
NZ	\$211.20	X
body	\$892.20	
twi	\$288.30	
one	\$1,700.00	
N/S Sur	\$910.00	1PC
re	\$3,614.00	X
Del/Bm	\$810.00	
re	\$1,145.00	X
warped	\$525.30	
11	\$188.20	X
11	\$899.20	X
Sur	\$1,361.90	
Sur	\$170.00	X
re	\$66.80	
twi	\$145.50	
re	\$699.20	
to.n	\$289.50	
Sur	\$892.30	
Sur	\$120.00	
twi/to.n	\$288.20	
re	\$50.00	
to.n	\$210.00	
one	\$425.50	
re	\$48.80	
one	\$3,900.00	
Sur/one	\$170.00	
twi/Sur	\$994.30	
re	\$322.00	
Sur/Pur	\$988.50	

20%

2 PCS AIR CON SIDE GARNISHS @\$205.00 65x2=130
 1 PCS RADIATOR 868
 1 PCS RADIATOR FAN ASSY
 2 PCS FRONT FENDERS @\$671.00
 2 PCS FRONT FENDER INNERSHIELDS @\$188.20

(202)
 Del/Torn \$410.00
 Bent/Put \$1,055.20
 11 \$882.50 X
 11 \$1,342.00 X
 0152 \$376.40 1PL
 \$32,280.20

S.NETT
 1 SET REAR BUMPER REVERSE SENSOR
 1 SET REAR BUMPER LOWER SKIRTING
 1 SET REAR BUMPER LOWER SKIRTING EXHAUST CHROME
 1 PCS REAR BUMPER TOP BLACK STICKER
 1 SET REAR REVERSE CAMERA
 1 PCS REAR LICENCE PLATE
 1 PCS REAR WINDSCREEN SEALANT
 1 PCS FRONT LICENCE PLATE
 1 SET FRONT BUMPER LOWER SKIRTING
 1 PCS BONNET BLACK STICKER
 1 BOT RADIATOR COOLANT

should \$380.00 200
 dis \$1,200.00 600
 Bent \$200.00 150
 11 \$150.00 X
 should \$480.00 300
 11 \$25.00 X
 11 \$50.00 X
 11 \$25.00 15
 11 \$1,200.00 600
 11 \$280.00 180
 11 \$50.00 30

LABOUR CHARGES:

TO CHECK WIRING
 TO DISMANTLE & REPLACING REVERSE SENSOR
 TO MOUNT VEHICLE ON CAR O-LINER
 TO DISMANTLE & REFIX REAR WINDSCREEN
 TO DISMANTLE & REFIX REAR EXHAUST
 TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY
 TO SPRAY RUST PROOFING
 TO REFIL AIR CON GAS
 TO DISMANTLE & REFIX PETROL TANK
 LABOUR FOR PANEL BEATING & REPLACING PARTS
 TO PUTTY & SPRAY PAINTING

\$80.00 30
 \$80.00 50
 11 \$380.00 X
 11 \$150.00 X
 11 \$100.00 X
 \$150.00 80
 \$180.00 100
 \$150.00 100
 11 \$100.00 X
 \$2,200.00 1400
 \$2,500.00 1800
 TOTAL \$42,390.20

S.N. 2075
 L-3560

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19017139/UQF3N2

Date: 30/10/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01003167
Claimant Vehicle No :	JQT2246	Insured Vehicle No :	SLA8057L
Date of Loss:	28/09/2019	Nature of Claim:	TP
		Claim No:	CMTD1904546

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JQT2246	Engine No:	G4FGEU433246
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)	Chassis No:	PP32M41GRF1000454
Reg. Date:	01/01/2015 (Man. Year: 2015)	Odometer:	65798 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	36,320.20	16,099.24	20,220.96	55.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,070.00	3,560.00	2,510.00	41.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	42,390.20	19,659.24	22,730.96	53.62
Approved Total (Overridden) (\$\$)		15,500.00		
(\$\$)	42,390.20	15,500.00	26,890.20	63.43
+ GST 7.00/7.00% (\$\$)	2,967.31	1,085.00	1,882.31	63.43
Nett Amount (\$\$)	45,357.51	16,585.00	28,772.51	63.43

INSPECTION

Date of Assignment:	30/09/2019	
Date Inspected:	30/09/2019 Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2019)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JQT2246)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Badly Dented	1,507.30 F	*1,048.00 FL
2	1		*BOOTLID REAR LOGO	Necessary	42.80 F	*42.80 FL
3	1		*BOOTLID LOCK STRIKER	Not Necessary	66.80 F	*- FL
4	2		*BOOTLID REFLECTORS	Cracked	1,040.60 F	*770.40 FL
5	1		*BOOTLID INNER LOCK	Twisted	211.50 F	*145.00 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	311.30 F	*166.30 FL
7	1		*BOOTLID INNER TRIM	Not Necessary	322.60 F	*- FL
8	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
9	2		*BOOTLID HINGES	Serviceable	210.00 F	*- FL
10	1		*REAR BUMPER	Distorted	788.20 F	*666.80 FL
11	1		*REAR BUMPER REINFORCEMENT	Distorted	485.10 F	*455.80 FL
12	2		*REAR BUMPER REINFORCEMENT TOP BRACKETS	Twisted	60.00 F	*60.00 FL
13	2		*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Cracked	60.00 F	*60.00 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
15	2		*REAR BUMPER REFLECTORS	Cracked	190.00 F	*70.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Bent	90.00 F	*90.00 FL
17	2		*REAR BUMPER BRACKETS	Bent	402.00 F	*210.00 FL
18	1		*REAR BUMPER SPONGE	Not fitted	211.20 F	*- FL
19	1		*REAR END PANEL	Badly Dented	892.20 F	*442.80 FL
20	1		*REAR END PANEL TOP GARNISH	Twisted	288.30 F	*133.60 FL
21	2		*TAILLAMPS	Cracked	1,700.00 F	*1,570.00 FL
22	1		*TAILLAMP HOUSING PANELS	N/s Bent	910.00 F	*210.00 FL
23	2		*REAR FENDERS	Repair	3,614.00 F	*- FL
24	2		*REAR FENDER INNER TRIMS	Deformed/Torn	810.00 F	*570.00 FL
25	1		*REAR FLOOR PANEL	Repair	1,145.00 F	*- FL
26	1		*REAR FLOOR PANEL TOP BOARD	Warped	525.30 F	*415.00 FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	188.20 F	*- FL
28	1		*REAR EXHAUST	Not Necessary	899.20 F	*- FL
29	1		*BONNET	Buckled	1,361.90 F	*1,105.30 FL
30	2		*BONNET HINGES	Serviceable	170.00 F	*- FL
31	1		*BONNET RUBBER	Necessary	66.80 F	*66.80 FL
32	1		*BONNET LOCK	Twisted	145.50 F	*145.50 FL
33	1		*FRONT BUMPER	Deformed	699.20 F	*691.00 FL
34	1		*FRONT BUMPER SPONGE	Torn	289.50 F	*145.00 FL
35	1		*FRONT BUMPER REINFORCEMENT	Bent	892.30 F	*455.20 FL
36	2		*FRONT BUMPER SIDE RETAINERS	Bent	120.00 F	*90.00 FL
37	1		*FRONT BUMPER CENTRE GRILLE	Twisted/Torn	288.20 F	*188.20 FL
38	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
39	2		*FRONT BUMPER FOG LAMP GARNISHS	Torn	210.00 F	*210.00 FL
40	1		*FRONT GRILLE	Cracked	425.50 F	*266.50 FL
41	1		*FRONT GRILLE LOGO	Necessary	48.80 F	*48.80 FL
42	2		*HEADLAMP ASSY LEDS	Cracked	3,900.00 F	*3,512.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*HEADLAMP LOWER BRACKETS	Bent/Cracked	170.00 F	*124.00 FL
44	1		*FRONT SUPPORT PANEL	Twisted/Bent	994.30 F	*994.30 FL
45	1		*FRONT TOP RETAINER	Distorted	322.00 F	*185.00 FL
46	1		*AIR CON CONDENSER	Bent/Punctured	988.50 F	*892.00 FL
47	2		*AIR CON SIDE GARNISHS	Deformed/Torn	410.00 F	*130.00 FL
48	1		*RADIATOR	Bent/Punctured	1,055.20 F	*866.00 FL
49	1		*RADIATOR FAN ASSY	Not Necessary	882.50 F	*- FL
50	2		*FRONT FENDERS	Repair	1,342.00 F	*- FL
51	1		*FRONT FENDER INNERSHIELDS	O/s Deformed	376.40 F	*188.20 FL
52	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
53	1		*SET REAR BUMPER LOWER SKIRTING	Distorted	1,200.00 FS	*600.00 FS
54	1		*SET REAR BUMPER LOWER SKIRTING EXHAUST CHROME	Bent	200.00 FS	*150.00 FS
55	1		*REAR BUMPER TOP BLACK STICKER	Not Necessary	150.00 FS	*- FS
56	1		*SET REAR REVERSE CAMERA	Shorted	480.00 FS	*300.00 FS
57	1		*REAR LICENCE PLATE	Not Necessary	25.00 FS	*- FS
58	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
59	1		*FRONT LICENCE PLATE	Cracked	25.00 FS	*15.00 FS
60	1		*SET FRONT BUMPER LOWER SKIRTING	Torn	1,200.00 FS	*600.00 FS
61	1		*BONNET BLACK STICKER	Necessary	280.00 FS	*180.00 FS
62	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 36,320.20 19,605.30
 - List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 3,506.06

Total Parts (\$\$) 36,320.20 16,099.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	150.00	80.00
7	TO SPRAY RUST PROOFING	New	180.00	100.00
8	TO REFILL AIR CON GAS	New	150.00	100.00
9	TO DISMANTLE & REFIX PETROL TANK	New	100.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	2,200.00	1,400.00
11	TO PUTTY & SPRAY PAINTING	New	2,500.00	1,800.00
Gross Labour Cost (S\$)			6,070.00	3,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >