



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 1

Vehicle No. **SGS6230E TOYOTA CAMRY 2.4A**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear bootlid		1149.00	X nn
1	Rear bootlid Hinge @\$107.00		214.00	X nn
1	Rear bumper		1035.00	de 946.00
1set	Rear bumper side retainer @\$98.00		196.00	14-de 14-X nn 98
1	Rear bumpe sponge		461.00	7 Xnn
1	Rear bumper reinforcement		738.20	X nn
2	Rear bumper brackets @\$171.00		342.00	X nn
1	Rear end panel		982.00	X nn
1	Rear end panel top garnish		216.00	X nn
			5333.20	0.00
less 25%			1333.30	25% 0.00
			3999.90	0.00
<u>SPECIAL NETT ITEMS</u>				
1set	Rear bumper clips		80.00	30
1set	Rear End Panel Inner Garnish Clips		70.00	X nn
1set	Reverse sensor		220.00	200 7 nw ✓
1	Rear end panel sealant		120.00	X nn
1	Rear number plate		75.00	X nn
TOTAL PARTS			4564.90	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

Tayhi 9745749
wp
30/9/19 @ 3pm.
Lumpsum
Resurvey after repair
02 days
sur @ (Mantawon)



AMA Autocare Pte Ltd
Enterprise Hub 36 Toh Guan Road East #01-36
Singapore (608580)
E: ama.claim@gmail.com
T: 87783636

Page No. 2

Vehicle No. **SGS6230E TOYOTA CAMRY 2.4A**

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1200.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1000.00	250
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	160.00	X nn
4	To remove and refix/replace rear trims, garnish and fittings so as to facilitate repairs at rear compartment	180.00	X nn
5	To remove and replace reverse sensors	150.00	30
6	To provide anti-rust treatment on affected areas	120.00	X nn
Labour Total :		2810.00	
TOTAL (PARTS & LABOUR):		7374.90	

480

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

783
230
480
total 1493
L/S\$1200
2 DAYS