



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)
Comfort Transportation Pte Ltd

Singapore

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP029092019
Policy No:		Date of Loss:	27/09/2019
Vehicle Reg. No.:	SGV145S	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAN KENG WAH	Driver (Insured):	YEO KIN PEOW
Make/Model:	HONDA STREAM, 1.8 (A)	Vehicle Reg. Date:	30/05/2007
Vehicle Colour:	RED	Chassis No:	RN61031108
Engine No:	R18A1734847		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		

Description of Accident/Loss

ON 27.09.2019 AT ABOUT 0820HOURS, I WAS DRIVING MY VEHICLE (A: SGV145S) ALONG EXTREME LEFT LANE OF YIO CHU KANG ROAD TOWARDS SERANGOON DIRECTION. UPON REACHING THE JUNCTION OF YIO CHU KANG ROAD AND HOUGANG AVENUE 2, THE TRAFFIC LIGHT STILL SHOWN GREEN IN MY FAVOUR THEREFORE I PROCEED STRAIGHT. SUDDENLY, A TAXI (B: SHA1221Y) WHICH WAS TRAVELLING FROM THE OPPOSITE DIRECTION MADE A RIGHT TURN TOWARDS ME. I QUICKLY SWAYED TO THE LEFT BUT THE SAID TAXI ALREADY COLLIDED WITH MY VEHICLE'S FRONT RIGHT PORTION. WHILE ON MY WAY, I START TO FEEL UNWELL. VEHICLE A (SGV145S): 1 FEMALE PASSENGER ON BOARD. VEHICLE B (SHA1221Y): NO PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

	Amount
Parts	11,722.32
Miscellaneous Items	11.00
Labour	1,910.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	14,843.32
+ GST 7.00% (S\$)	1,039.03
Nett Amount (S\$)	15,882.35

This claim is handled by: OW CAYMEN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Sep 2019)

Parts: M1-MPV HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/SGV145S/27/09/2019 18:37

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*bonnet / <i>buc</i>	20.00	0.00	616.9 *880.00 FL /
2	1		*Bonnet lock / <i>BT.</i>	20.00	0.00	68.5 *107.10 FL /
3	1		*Bonnet lock stay X <i>NN</i>	20.00	0.00	*12.30 FL
4	1		*Bonnet lock cable X	20.00	0.00	*55.10 FL
5	1		*Bonnet insulator / <i>re</i>	20.00	0.00	*110.20 FL /
6	8		*Bonnet insulator clips / <i>mc.</i>	20.00	0.00	*30.00 FL /
7	1		*Bonnet underseal weatherstrip with clip - outer / <i>Tui</i>	20.00	0.00	*22.90 FL /
8	4		*Bonnet underseal weatherstrip inner clip / <i>mc.</i>	20.00	0.00	*61.20 FL /
9	1		*Bonnet stopper LH / <i>mis</i>	20.00	0.00	*7.80 FL /
10	1		*front support panel / <i>BT.</i>	20.00	0.00	466.3 *581.40 FL /
11	1		*Bumper, front / <i>CRA</i>	20.00	0.00	635.7 *1,132.20 FL /
12	1		*front bumper beam X <i>NN</i>	20.00	0.00	*275.40 FL
13	2		*Bumper retainer, front / <i>CRA</i>	20.00	0.00	*49.80 FL /
14	8		*front bumper fastener clips / <i>mc.</i>	20.00	0.00	*28.00 FL
15	1		*front bumper reinforcement / <i>BT.</i>	20.00	0.00	268.9 *350.00 FL /
16	1		*front bumper fog lamp / <i>mis</i>	20.00	0.00	286.7 *413.10 FL /
17	1		*front bumper fog lamp garnish / <i>CRA</i>	20.00	0.00	*55.60 FL /
18	1		*front bumper centre air grille / <i>TN</i>	20.00	0.00	85.6 *107.60 FL /
19	1		*front bumper lower splashshield cover / <i>TN</i>	20.00	0.00	*165.70 FL /
20	6		*front bumper lower splashshield cover clips / <i>mc.</i>	20.00	0.00	*22.80 FL /
21	2		*headlamp / <i>BT</i>	20.00	0.00	589.3 *1,760.00 FL /
22	2		*headlamp lower bracket / <i>CRA</i>	20.00	0.00	73 *111.80 FL /
23	1		*radiator assy / <i>BT</i>	20.00	0.00	1284.2 *1,866.60 FL /
24	1		*radiator coolant / <i>mc.</i>	0	0.00	*20.00 FS /
25	1		*radiator fan assy / <i>?</i>	20.00	0.00	98.7 *620.00 FL
26	1		*radiator grille / <i>mc.</i>	20.00	0.00	195.54 *214.20 FL /
27	1		*radiator grille emblem badge / <i>mc.</i>	20.00	0.00	*30.60 FL /
28	1		*radiator grille garnish / <i>CRA</i>	20.00	0.00	219.35 *244.80 FL /
29	4		*radiator grille clips / <i>mc.</i>	20.00	0.00	*14.00 FL /
30	2		*radiator top mounting bracket / <i>BT.</i>	20.00	0.00	*25.00 FL /
31	2		*radiator top mounting bushing / <i>mc.</i>	20.00	0.00	*9.80 FL /
32	1		*radiator bottom mounting bushing / <i>mc.</i>	20.00	0.00	*12.60 FL /
33	1		*radiator top hose X <i>NN</i>	20.00	0.00	*36.70 FL
34	1		*radiator expansion tank / <i>re</i>	20.00	0.00	*39.80 FL /
35	1		*horn high pitch X <i>NN</i>	20.00	0.00	*73.50 FL
36	1		*horn low pitch X	20.00	0.00	*61.20 FL
37	1		*aircon condenser / <i>BT.</i>	20.00	0.00	826.4 *1,040.40 FL /
38	2		*aircon condenser top mounting bracket / <i>BT.</i>	20.00	0.00	*15.60 FL /
39	2		*aircon condenser top mounting bushing / <i>mc.</i>	20.00	0.00	*8.40 FL /
40	2		*aircon condenser bottom bushing / <i>mc.</i>	20.00	0.00	*9.20 FL /
41	1		*aircon hose - condenser to compressor / <i>?</i>	20.00	0.00	*275.40 FL
42	1		*aircon pipe - condenser to evaporator / <i>?</i>	20.00	0.00	*214.20 FL
43	1		*aircon fan assy / <i>?</i>	20.00	0.00	85.1 *566.00 FL
44	1		*windscreen washer tank X <i>NN</i>	20.00	0.00	*107.10 FL
45	1		*windscreen washer tank motor X <i>NN</i>	20.00	0.00	*82.60 FL
46	1		*windscreen washer tank cover X	20.00	0.00	*55.00 FL
47	1		*exhaust manifold heat shield X	20.00	0.00	*76.50 FL
48	1		*air cleaner tank - intake hose	20.00	0.00	*85.70 FL /
49	1		*wiper tank / <i>re</i>	20.00	0.00	*89.70 FL /
50	1		*wiper tank motor	20.00	0.00	*90.90 FL /
51	1		*o/s front shock absorber X	20.00	0.00	*413.10 FL
52	1		*o/s front shock absorber top mount X <i>NN</i>	20.00	0.00	*89.90 FL

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
53	1		*lower arm X NN	20.00	0.00	*350.00 FL
54	1		*o/s engine mount top V TN	20.00	0.00	*199.70 FL ✓
55	1		*o/s engine mount rear	20.00	0.00	*208.10 FL
56	1		*n/s gearbox mount X NN	20.00	0.00	*198.70 FL ✓
57	1		*o/s front fender / Bulc	20.00	0.00	*550.00 FL ✓
58	1		*o/s front fender inner cowling / TN	20.00	0.00	*90.90 FL ✓
59	5		*o/s front fender inner cowling clips / MC	20.00	0.00	*21.00 FL ✓
60	1		*o/s front fender top garnish / LL	20.00	0.00	*55.80 FL ✓
61	4		*o/s front fender top garnish clips / MC	20.00	0.00	*15.20 FL ✓
62	1		*front number plate / CA	0	0.00	*80.00 FS ✓
63	1		*front number plate garnish / CA	20.00	0.00	*30.00 FL ✓
Sub Total (\$\$)						14,627.90
- List Item Discount on L Items (\$\$)						2,905.58
Total Parts (\$\$)						11,722.32

F=Franchise part. S=SpcNett. L=ListItemDisc.

Tan Lim Motor Pte Ltd/SGV145S/27/09/2019 18:37. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

7378.69

rel/c: 5902.95

60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion.	New 1000	1,200.00
<u>Labour Items</u>			
2	Towing charges.	New 50	80.00
3	To check electrical lighting concerned.	New 30	60.00
4	To check steering geometry and computer wheel alignment.	New NN X	80.00
5	To rust-proofing of the affected areas.	New 60	150.00
6	To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	New NN X	150.00
7	To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	New 80	120.00
8	To remove and refit radiator	New 40	70.00
9	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 1000	1,200.00
Gross Labour Cost (S\$)			3,110.00

Tan Lim Motor Pte Ltd/SGV145S/27/09/2019 18:37. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1 Defu Lane 6 Singapore 539365
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

7 Days.

Impress repair.

After repair photos.

Eno Q: ang - 82880282

30/9/19.

8222.95
20%: 6500 (4000)

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: