

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
 Tel : 64663022 Fax : 68966591
 Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE dated 27/09/2019

INDIA INT'L INS	ACCIDENT DATE	: 09/10/2019 @ 17:35
ATTN: MOTOR CLAIMS DEPT	VRN	: SLG7887H
	MODEL	: LEXUS ES250 LUXURY
	TP VRN	: SHB4355U

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 FRONT BUMPER	1	\$ 935.00	\$ 935.00	de ✓
2 FRONT BUMPER CLIP	10	\$ 5.50	\$ 55.00	ner ✓
3 FRONT BUMPER SIDE REATINER RH	1	\$ 65.00	\$ 65.00	ne ✓
4 HEADLAMP RH	1	\$ 6,115.00	\$ 6,115.00	ant ✓
5 FRONT FENDER RH	1	\$ 1,314.00	\$ 1,314.00	bt ✓
6 FRONT FOG LAMP CHROME RH	1	\$ 98.00	\$ 98.00	? ✓
7 FRONT FENDER SHIELD RH	1	\$ 285.00	\$ 285.00	? ✓
8 FRONT FENDER SHIELD CLIP RH	10	\$ 5.50	\$ 55.00	? ✓
9 BOOT LID	1	\$ 865.00	\$ 865.00	bt ✓
10 BOOT LID LOGO	1	\$ 75.00	\$ 75.00	ner ✓
11 BOOT LID LOGO "LEXUS"	1	\$ 56.00	\$ 56.00	ne ✓
12 BOOT LID LOGO "ES 250"	1	\$ 68.00	\$ 68.00	ner ✓
13 BOOT LID CHROME	1	\$ 348.00	\$ 348.00	ant ✓
14 BOOT LID INSULATOR	1	\$ 650.00	\$ 650.00	X **INDENT
15 BOOT LID INSULATOR CLIP	10	\$ 5.50	\$ 55.00	X
16 BOOT LID HINGE R/L	2	\$ 201.00	\$ 402.00	Rp
17 BOOT LID LOCK	1	\$ 551.00	\$ 551.00	ant ✓
18 BOOT LID LAMP R/L	2	\$ 541.00	\$ 1,082.00	LH-ant, RH-?
19 REAR BUMPER	1	\$ 766.00	\$ 766.00	de ✓
20 REAR BUMPER CLIP	10	\$ 5.50	\$ 55.00	ner ✓
21 REAR BUMPER SIDE RETAINER R/L	2	\$ 98.00	\$ 196.00	ner ✓
22 REAR BUMPER REFLECTOR R/L	2	\$ 60.00	\$ 120.00	LH-ner, RH-X
23 REAR BUMPER SPONGE	1	\$ 107.00	\$ 107.00	ner ✓
24 REAR BUMPER REINFORCEMENT	1	\$ 381.00	\$ 381.00	bt ✓
25 REVERSE SENSOR	2	\$ 341.00	\$ 1,364.00	ner ✓
26 TAILLAMP R/L	2	\$ 605.00	\$ 1,210.00	LH-ner, RH-?
27 TAILLAMP LOWER BRACKET R/L	2	\$ 95.00	\$ 190.00	LH-dis, RH-X
28 EXHAUST TAILPIPE CHROME LH	1	\$ 313.00	\$ 313.00	de ✓
29 TAILLAMP WHITE CLIP R/L	2	\$ 5.90	\$ 11.80	ner ✓
30 REAR LH FENDER	1	\$ 1,460.00	\$ 1,460.00	Rx
31 REAR WINDSCREEN MOULDING	1	\$ 78.00	\$ 78.00	? ✓
32 BOOT LID WEATHERSTRIP	1	\$ 226.00	\$ 226.00	ner ✓
33 REAR BUMPER SIDE COVER LH	1	\$ 12.00	\$ 12.00	ner ✓
34 REAR END PANEL	1	\$ 752.00	\$ 752.00	bt ✓
35 REAR END PANEL TOP GARNISH	1	\$ 323.00	\$ 323.00	ner ✓
36 SPARE TYRE COMPARTMENT	1	\$ 907.00	\$ 907.00	Rx
37 SPARE TYRE COMPARTMENT BOARD	1	\$ 658.00	\$ 658.00	X

38 SPARE TYRE PANEL LH	1	\$	298.00	\$	298.00	Ry **INDENT
39 SPARE TYRE SPONGE R/L	2	\$	235.00	\$	470.00	LH on RH
				\$	22,971.80	
Discount -10%				\$	2,297.18	
				\$	20,674.62	
Special Nett						
40 REAR LICENSE PLATE W CASING	1	\$	45.00	\$	45.00	bt
41 REAR WINDSCREEN SEALANT	1	\$	40.00	\$	40.00	?
				\$	85.00	
42 FRONT DOOR RH			Repair & Blending			
43 REAR FENDER RH			Repair & Blending			
			PARTS TOTAL	\$	20,759.62	

2. Labour Charges

Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of FRONT Affected Area	\$	750.00	500.
Panel Beat, Cut, Weld, Re-align & Replace Damaged Parts Of REAR Affected Area	\$	3,250.00	1500.
Putty, Blend And Spray Paint on FRONT Affected Area	\$	1,000.00	500
Putty, Blend And Spray Paint on REAR Affected Area	\$	2,000.00	1250
Check Wiring, Re-align Headlamps & Taillamps, Ensure Proper Functioning	\$	80.00	40.
Remove & Reinstall Cushions, Seats, Backrests, Inner Trim, Garnish, Roof Lining and/or Upholstery to Facilitate Repair	\$	180.00	60.
Remove and Replace Rear Windscreen to Facilitate Repair	\$	180.00	120?
Remove and Refit Rear End Panel Lining and Garnish to Facilitate Repair	\$	150.00	60
Remove and Reinstall Rear Trim Compartment to Facilitate Cutting and Repairing Work	\$	150.00	x
Dismantle and Transfer Boot Lid Fittings & Mechanisms to New Boot Lid	\$	180.00	60
Remove and Replace Exhaust Pipe/System to Facilitate Repair	plus \$	250.00	100?
Remove and Reinstall Reverse Sensors	\$	120.00	30
Remove and Reinstall Rear Reverse Camera	\$	120.00	30
Cavity Treatment on New Parts	\$	120.00	60.
Conduct Water Seepage Test	\$	120.00	40.

LABOURS TOTAL \$ 8,650.00

Grand Total : \$ 29,409.62
Add 7% GST : \$ 2,058.67
Nett Total : \$ 31,468.29

No. of repair days: 24

Taufik 9749749
wp
30/9/11 @ 11:15 am
Resurvey before paint.
12 days

taufik@lkhauto.com
sur@lkhauto.com



HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: