

Kd

Lump \$2,100.00 - 3 days

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

H.L. Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLT 9907 C
Make : Toyota C-HR
Year : 2017

Fax : 64816131

Not Notarized
61 Days @ 1700/hr 2100
Murray After Paint
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy
1 pc	Rear tail-gate inner lock sensor
1 pc	Rear bumper
1 pc	Rear bumper reinforcement
1 pc	Rear bumper center garnish
1 pc	Rear lower bumper
2 pcs	Rear bumper side retainer
1 pc	Rear end panel
1 pc	Rear end panel inner garnish

photo

	\$1,237.20 X
	\$105.70 X
	\$1,183.60 ✓
	\$483.20 ✓
	\$125.00 X
	\$655.70 ✓
\$75.10	\$150.20 X
	\$725.70 X
	\$355.60 X
	\$5,102.50
Less 25 %	\$1,275.63
	\$3,826.87
	2,333.50
	580.63
	1,749.87

S Nett

15 pcs	Rear bumper clip
1 pc	Rear reverse sensor

\$2.00	\$30.00 ✓
	\$200.00 ✓
	\$230.00
	230.00

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00 2501

To putty & spray paint on accident affected portion

\$800.00 4001

Check and reconnect wiring

\$40.00 152

To anit- rust proofing

	\$100.00 X
Total	\$5,796.87
	468.00