

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

H.L. Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLT 9907 C
Make : Toyota C-HR
Year : 2017

Fax : 64816131

Not Notarized
11 Days @ 1
Money After Repair
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate assy
1 pc	Rear tail-gate inner lock sensor
1 pc	Rear bumper
1 pc	Rear bumper reinforcement
1 pc	Rear bumper center garnish
1 pc	Rear lower bumper
2 pcs	Rear bumper side retainer
1 pc	Rear end panel
1 pc	Rear end panel inner garnish

<i>R</i>	\$1,237.20	<i>X</i>
<i>Sm</i>	\$185.70	<i>X</i>
<i>Bm</i>	\$1,183.60	<i>✓</i>
	\$483.20	<i>?</i>
<i>Sm</i>	\$125.60	<i>X</i>
<i>Net</i>	\$655.70	<i>✓</i>
\$75.10	\$150.20	<i>X</i>
<i>R</i>	\$725.70	<i>X</i>
<i>Sm</i>	\$355.60	<i>X</i>
	\$5,102.50	
Less 25 %	\$1,275.63	
	\$3,826.87	

S Nett

15 pcs	Rear bumper clip
1 pc	Rear reverse sensor

\$2.00	<i>Net</i>	\$30.00	<i>✓</i>
	<i>Shen</i>	\$200.00	<i>✓</i>
		\$230.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$800.00 *2500*

To putty & spray paint on accident affected portion

\$800.00 *4000*

Check and reconnect wiring

\$40.00 *150*

To anti-rust proofing

Net \$100.00 *X*

Total \$5,796.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: