

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
 #02-37 Premier @ Kaki Bukit
 Singapore 415875
 Tel : 94513429

EQ Insurance Co Ltd
 5 Maxwell Road
 #17-00 Tower Block MND Complex
 Singapore 069110
 Attn: Motor Claims Department

ESTIMATE

Vehicle No : SKR 7864C
 Make/Model: PEUGEOT 308
 Accident Date 28.09.2019

*not Allowed
 later
 Repair Sum \$2200
 3 day.
 1/10/19*

Parts

01) Rear bumper	\$	<i>20/12</i>	950.00	✓
02) Rear bumper clips	\$	<i>20</i>	60.00	✓
03) Rear bumper retainer rh	\$	<i>11</i>	125.00	α
04) Rear bumper bracket rh	\$	<i>11</i>	98.00	α
05) rear bumper reinforcement	\$	<i>Best</i>	280.50	?
06) Rear bumper tow cover rh	\$	<i>80</i>	98.00	α
	\$		1,611.50	
	\$		(161.15)	
	\$		1,450.35	

S/Nett

07) Reverse sensor	\$	<i>shhd</i>	380.00	<i>200</i>
08) Rear bumper top chrome	\$	<i>bul</i>	350.00	✓
	\$		730.00	

Labour Charges

11) To check wiring	\$		100.00	<i>50</i>
24) To knock out dents on affected areas and renew parts	\$		900.00	<i>300</i>
25) To putty & respray painting	\$		1,000.00	<i>400</i>
	\$		2,000.00	

\$ 4,180.35

for JA AUTOCARE PTE LTD



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

*9-1290.50
 102
 1161.45
 2461.45
 10%
 2215*