



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

GBH 3089 J

Parts	(a) Cost / List Price Items	_____
	Plus/Less	_____
	Total of Cost / List	_____
	(b) Nett Price Items	\$ 3,352.90
	Less 10%	\$ 335.29
	Total of Nett Item	\$ 3,017.61
	(c) Special Nett Items	\$ 429.00
Total Parts Cost		\$ 3,446.61
Labour		\$ 2,890.00
Total		\$ 6,336.61

The above total will be subjected to 7% G.S.T.

Not Authorized

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 11/10/19 at 11-200m

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Sc Date: 11/10/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **GBH 3089 J**
Make & Model : **NISSAN NV200**
Chassis No : **VSKYBAM20Z0156680**

Submit By : **JENNY**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>SL</i>	1	\$294.00	S.N	X
2	Rear bumper <i>R</i>	1	\$624.80	N	X
3	Rear bumper clip <i>nn</i>	10	\$35.00	N	X
4	Rear bumper side retainer LH <i>SL</i>	1	\$45.50	N	X
5	Rear bumper side retainer RH <i>SL</i>	1	\$45.50	N	X
6	Rear bumper bracket LH <i>R</i>	1	\$38.80	N	X
7	Rear bumper bracket RH <i>R</i>	1	\$38.80	N	X
8	Rear bumper reinforcement <i>R</i>	1	\$186.60	N	X
9	Tail door LH <i>R</i>	1	\$1,404.90	N	X
10	Tail door lock <i>R</i>	1	\$95.90	N	X
11	Tail door Hinge LH - Upper <i>R</i>	1	\$90.90	N	X
12	Tail door Hinge LH - Lower <i>R</i>	1	\$90.90	N	X
13	Tail door emblem <i>nn</i>	1	\$65.00	N	✓
14	Tail door garnish (Black) <i>SL</i>	1	\$361.50	N	X
15	Wording "NV200" <i>nn</i>	1	\$70.00	N	✓
16	70/KM sticker <i>nn</i>	1	\$20.00	S.N	1512
17	"6" PAX" sticker <i>nn</i>	1	\$20.00	S.N	X
18	Tail door glass moulding LH	1	N/A		
19	Tail door glass sealant LH <i>nn</i>	1	\$50.00	S.N	X
20	Tail Lamp LH <i>SL</i>	1	\$158.80	N	X
21	Rear number plate <i>SL</i>	1	\$45.00	S.N	X
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **GBH 3089 J** Submit By : **Carmen Lim**
Make & Model : **NISSAN NV200** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (TAL DOOR LH, TAIL DOOR RH, REAR BUMPER, END PANEL)	\$1,000.00	2000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (TAIL DOOR LH, TAIL DOOR RH, REAR BUMPER, END PANEL)	\$1,000.00	2000
3	TO check wiring <i>nn</i>	\$50.00	X
4	To remove & refit reverse sensor	\$120.00	X
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	X
6	To tuff coat. <i>nn</i>	\$150.00	X
7	To transfer boot mechanism to new boot <i>nn</i>	\$150.00	X
8	To conduct water leakage tests to ensure proper air and sealing <i>nn</i>	\$120.00	X
9	To do art work. (Tail door RH) <i>nn</i>	\$150.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.