

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@proccarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S: AUTO FLEETLEASE PTE LTD
 1 FULLERTON ROAD
 #02-01 ONE FULLERTON
 SINGAPORE 049213

ATTN: FIRST CAPITAL
 Your RefNo: TP 0919-5697
 Claim Type: Third Party
 Accident Date: 26/09/2019
 TP Veh Reg No: SHD 8573 U

Estimate No: EST1505305
 Date: 24 Oct 2019
 Policy No: 999994171
 Veh Reg No: SLM6578A
 Make/Model: TOYOTA SIENTA
 Chassis No: -
 Engine No:
 Reg. Date:

Estimate Repair Cost to Vehicle No :SLM6578A

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
List Price				
1 REAR FENDER INNER TRIM - LH	608.00	1 PC	608.00✓	
2 COOLER COVER	147.00	1 PC	147.00✓	
3 TRY LUGGAGE COMPARTMENT	419.00	1 PC	419.00✓	
4 REAR BUMPER INNER SENSOR KEYLESS	151.00	1 PC	151.00✓	
5 REAR BOOT INNER HANDER COVER - RH	48.00	1 PC	48.00✓	
6 REAR BOOT STOPPER - LH & RH	30.00	2 PCS	60.00✓	
			1,433.00	
	Less 25%		358.25	1,074.75
Labour				
7 TO REMOVE, REFILL AIRCON GAS	100.00	1 JOB	100.00✓	
			100.00	100.00
			Total	S\$ 1,174.75
			GST Amount	S\$ 82.23
			Total Amount Payable	S\$ 1,256.98

For Progressive Car Care Pte Ltd

AUTHORISED SIGNATURE

Supp 1174.75
 Parts 8502.83 8639.07
 SN 410.00
 LAB. 4600.00
 14687.58 - 14623.82