

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimmala D/O Raja Singam

Date: 01 Oct 2019

Preliminary Advice

Vehicle No	: SMF7653J	Accident Date	: 01/09/2019
Make	: VOLKSWAGEN GOLF GTI	Policy No.	: 29109660
Assignment Date	: 01/10/2019	Excess	: S\$1,500.00
Date of Inspection	: 30/09/2019	Est. Duration of Repair	: 26 days
Inspection At	: Volkswagen Group Singapore Pte Ltd (HQ) No: 17 Tuas Ave 9 Singapore 639197		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	93,730.80
Revised Amount	:S\$	64,595.13
Check Items (Estimated)	:S\$	17,484.42
Total	:S\$	82,079.55
Lump Sum Repair		:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	58,697.00
Salvage Value	:S\$	
Margin for Repair	:S\$	86,303.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.
- (X) Remarks : Repairer able to undertake the repair cost not exceeding \$ 86,000.00 on part by part basis.