

ASS. REC. BY:

REF:

CS/LPC/190172261/04f352

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Gerald Poh

of

LPC

Date/Time: 1.10.19 9.53a.m

Merimen

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCY 8860P

Insured:

at Workshop m/s

Kan Fook Sing

Tel:

67479560

of NO 61 Refu Lane 12

Policy No: 219P05022523

Claim No:

19/19/191 VP05/022435

Sum Insured:

Excess:

#0.

Make of Veh:

D.O.A 27.9.19

(Client's Record)

CA (REV) REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 1.10.19 10.53a.m

Person Contacted:

Yen

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SCY 8860P: X

7/10/2019@16:20: Revert via merimen

7/10/2019@17:12- authorise repair by Beng Kee

8/10/2019: 8:54am Email Kfs authorise repair excess \$0

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CS/LPC19017 226/443

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

① TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SC/8860P*at Workshop m/s *1575*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: *?*

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *40k.*

IDAC Accident Rpt: _____

Consistent? : Yes or No

① A / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: *4* days

Res.: Yes or No

Lum Sum: *131* %

3 Val.: Yes or No

CA ① REP. / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: *not 8211*

Date / Time

Action / Instruction

*11/10/19 1431789**workshop went p/p because no second hand parts**(Red: 4493.85 : 58%)**17/10/19 confirmed price by \$3170.65 w/h Alice.**18/10/19 - Gerald say go ahead as 1st approval is higher the final inclusive supplementary.*

RECEIVED 16 OCT 2019

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee: *250*

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

) S+RS: \$ _____

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

☐ : Weekend (\$ _____)

)

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Sep 2019 Sendback Est	01 Oct 2019 09:35 S\$7,423.00	01 Oct 2019 09:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	MAUREEN NEO BEE LUAN, ID: S7228238H								
Vehicle Reg. No.:	SCY8860P	Date of Loss:	27/09/2019 20:00 - :59 [108 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 19/19/19/VP05/022435	Policy/Cover Note No.:	Z19P05022523 (Comprehensive)						
		Excess:	S\$0.00						
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560								
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/10/2019]								
Driver/Custodian:	HENG SOON NGEE (56 / Male), NRIC: S1550206A, Tel: +6590912929 Email: maureen.nbl@gmail.com								
Adj Asg. Remarks:	SURVEY & REVERT								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 8 October 2019 8:54 AM
To: alicechau@kanfs.net
Cc: SUR
Subject: SCY 8860P / OD / LONPAC / DOA: 27/09/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SCY 8860P (Excess \$0.00/-). Part by Part.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Gerald Poh

Date: 07 Oct 2019

Preliminary Advice

Vehicle No : SCY8860P
Make : MERCEDES-BENZ E250
Assignment Date : 01/10/2019
Date of Inspection : 07/10/2019
Inspection At : KAN FOOK SING MOTOR WORKSHOP (DEFU)
NO. 61 DEFU LANE 12
SINGAPORE 539147

Accident Date : 27/09/2019
Policy No. : Z19P05022523
Excess : S\$0.00
Est. Duration of Repair : 4.00

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,423.00
Revised Amount	:S\$	3,198.25
Check Items (Estimated)	:S\$	2,294.25
Total	:S\$	5,492.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	40,000.00
COE / PARF Rebate	:S\$	31,789.00
Salvage Value	:S\$	
Margin for Repair	:S\$	8,211.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Repairer is asking of part by part as there is no 2nd hand parts

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/09/2019 11:13
Date Of Accident	27/09/2019 20:10
Exact Location Of Accident	X PUNGGOL CENTRAL & EDGEDALE PLAIN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCY8860P
Insured/Policyholder	
Name Of Registered Owner	MAUREEN NEO BEE LUAN
NRIC No	S7228238H
Email Address	MAUREEN.NBL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98170028
Alternative Phone No	OFFICE-98170028

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z19P05022523
Cover Note Number	

Driver

Name of Driver	HENG SOON NGEE
NRIC No	S1550206A
Date Of Birth	20/11/1962
Occupation	INDOOR
Date Of Driving Pass	29/03/1980
Driving Experience	39 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90912929
Fax Number	
Contact Number	
Email Address	MAUREEN.NBL@GMAIL.COM

Address	70 PUNGGOL WAL #15-44 S828785
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : EDEN HENG GENDER: : FEMALE
Passenger 2	NAME: : MAUREEN NEO BEE LUAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer to attached report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME5045H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
	NA
Address	NA

Postcode	NA
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

Punggol Central

A: SCY 8860P -
P: SME 5045H

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At the slip road, vehicle B in front suddenly stop.
I could not stop in time As a result hit onto
the rear portion of vehicle B.

INSURER: Longac.
VEHICLE: SCY 8860P.
DOA: 27/9/19
CLAIM TYPE: OAD.
WORKSHOP: KFS.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: _____
NRIC/FIN No.: _____



Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	30 Sep 2019 15:51	Clm Veh Model Changed	(202017) MERCEDES-BENZ E250 1.8 CGI (A).	[R] MT Tan
2	30 Sep 2019 15:51	Clm Created	Reg No: SCY8860P, Policy No: Z19P05022523, Acct Date: 2019/09/27. Claim Type: OD, Insurer: Lonpac Insurance Bhd (HQ). Workshop: Kan Fook Sing Motor Workshop (Defu). Created from SAS:MKFS19128909	[R] MT Tan
3	01 Oct 2019 09:35	Clm Submitted	7423.00.	[R] MT Tan
4	01 Oct 2019 09:53	Clm Registration Modified	Excess: -> 0.00.	[I] Gerald Poh
5	01 Oct 2019 09:53	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):SURVEY & REVERT	[I] Gerald Poh
6	01 Oct 2019 09:53	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/10	[I] Gerald Poh
7	01 Oct 2019 09:53	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[I] Gerald Poh
8	01 Oct 2019 10:50	Assignment 1st Accessed		[A] LEE SU THING
9	01 Oct 2019 11:24	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
10	07 Oct 2019 14:47	Adj Adjuster Assigned	ADRIAN LING -> MARCUS CHUA	[A] LEE SU THING
11	07 Oct 2019 16:10	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
12	07 Oct 2019 16:20	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/10/10	[A] DENISE TAY KWEE CHENG
13	07 Oct 2019 16:20	Adj Mandate Request	Cur.Req:5492.50:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
14	07 Oct 2019 17:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/10	[I] Chew Beng Kee
15	07 Oct 2019 17:12	Adj Mandate Set	Approved:5492.50.	[I] Chew Beng Kee

Date From



Date To



Audit Type None

Go

ACTIVITY

[01/10/2019 10:54] LEE SU THING:

Please be informed vehicle not in the workshop, repairer will arrange.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2296116	30 Sep 2019 15:51:45	OD/TP Case (Repairer)	Motor	Kan Fook Sing Motor Workshop	Kan Fook Sing Motor Workshop (Defu)	SCY8860P		xx.xx
2304645	07 Oct 2019 16:10:59	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SCY8860P		11.77

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	238H
Vehicle Details	
Vehicle No.:	SCY8860P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250CGI
Primary Colour:	Brown
Manufacturing Year:	2010
Engine No.:	27186030089102
Chassis No.:	WDD2120472A255690
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$56,996.00
Original Registration Date:	08 Sep 2010
First Registration Date:	08 Sep 2010
Transfer Count:	1
Actual ARF Paid:	\$56,996.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Sep 2020
PARF Rebate Amount:	\$28,498.00
Intended COE Rebate Details	
COE Expiry Date:	07 Sep 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$35,909.00
COE Rebate Amount:	\$3,291.00
Total Rebate Amount:	\$31,789.00

The information contained herein is correct as at 07 Oct 2019

OK

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Singapore NRIC

238H

Vehicle Details

SCY8860F

No

07 Oct 2019

MERCEDES BENZ

E 250CGI

Brown

2010

27186030089102

WDD2120472A255690

150.0 kW (201 bhp)

\$56,996.00

08 Sep 2010

08 Sep 2010

1

\$56,996.00

Intended PARF Rebate Details

Yes

07 Sep 2020

\$28,498.00

Intended COE Rebate Details

07 Sep 2020

B - Car (1601cc & above)

10

\$35,909.00

\$3,291.00

\$31,789.00

The information contained herein is correct as at 07 Oct 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



e250

Price Range

Depreciation

2010

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Direct Owners » Mercedes-Benz E-Class E250 CGI Avantgarde

Mercedes-Benz E-Class E250 CGI Avantgarde

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Price	\$43,800		
Depreciation	\$28,890 /yr View models with similar depre	Reg Date	01-Jun-2010 (7mths 24days COE left)
Mileage	80,000 km (8.6k /yr)	Manufactured	2010
Road Tax	\$974 /yr	Transmission	Auto
Dereg Value	\$26,614 as of today (change)	OMV	\$50,081
COE	\$24,229	ARF	\$50,081
Engine Cap	1,796 cc	Power	150.0 kW (201 bhp)
Curb Weight	1,650 kg	No. of Owners	3
Type of Vehicle	Luxury Sedan		

Features

Powerful 1.8L Turbocharged CGI Engine. Sunroof, Leather Seats, Cruise Control, ESP, ABS, LED Running Lights.
View specs of the Mercedes-Benz E-Class Saloon (2009-2013)

Accessories

Alloy Sports Rims, Electric Memory Seats, Multi Function Steering, 2 Zone Climate Control, Cruise Control, Audio With Bluetooth Telephony, Sunroof.

Description

Very Good Condition. Lowest In The Market. Low Mileage Done. Original Paintwork. Accident Free. Black On Black Leather Seats With Sunroof. Price Negotiable.

Category

PARF Car, Direct Owner Sale, Low Mileage Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 25-Sep-2019 | Last Updated on: 02-Oct-2019

Upfront Payment
Compare

» more Financial info



Price Chart

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Contact Person(s) Johnny

Contact No. 96902933

Enquiry Contact Seller

ESSENTIAL TRANSACTION FORMS

» Indemnity form

» Sales agreement

» Receipt

» Hand-over form

» Ownership Transfer

e250

Price Range

Depreciation

2010

Vehicle Type



Submit

Advanced
Search

Home » Used Cars » Otua Auto Pte Ltd » Mercedes-Benz E-Class E250 CGI

Mercedes-Benz E-Class E250 CGI

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Price

\$44,000

Depreciation

\$16,370 /yr

View models with similar depre

Reg Date

01-Oct-2010

(11mths 23days COE left)

Mileage

107,000 km (11.9k /yr)

Manufactured

2010

Road Tax

\$974 /yr

Transmission

Auto

Dereg Value

\$32,084 as of today (change)

OMV

\$55,808

COE

\$42,501

ARF

\$55,808

Engine Cap

1,796 cc

Power

150.0 kW (201 bhp)

Curb Weight

1,650 kg

No. of Owners

2

Type of Vehicle

Luxury Sedan

Features

Powerful Turbocharged 1.8L 4 Cylinders Inline CGI Blue Efficiency Engine, 201Bhp, SRS Airbags, ABS, Multi-Function Steering With Cruise Control. View specs of the Mercedes-Benz E-Class Saloon (2009-2013)

Accessories

Sports Rims, Leather Seats, Factory Fitted Audio System, Reverse Sensors, Fog Lamps, Electric Side Mirror Indicators, Rear Aircon.

Description

Consignment Code: A204. Serviced With MBM Wheel Power. Flexible And Attractive Loan Packages Available To Choose From. Trade-Ins Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

Price Chart

Summary

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

Otua Auto Pte Ltd

» dealer's pricelist

» 136 vehs sold | 77 vehs available

Address

157 Sin Ming Road #01-04

Search cars nearby this location

Posted on: 07-Oct-2019 | Last Updated on: 07-Oct-2019

Compare



簡福星噴漆工廠 KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

Business Reg. No. 22148900X
GST Reg. No. A997000333EINSURER: **Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z19P05022523	Date of Loss:	27/09/2019
Vehicle Reg. No.:	SCY8860P	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MAUREEN NEO BEE LUAN		
Driver:	HENG SOON NGE		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	08/09/2010
Vehicle Colour:	METALLIC MAROON	Chassis No:	WDD2120472A255690
Engine No:	27186030089102		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO ATTACHED REPORT		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

*not allowed
Lian
The photo taken
partly.
Excess?
Hahy-*

COST OF CLAIMS

	Amount
Parts	6,233.00
Miscellaneous Items	30.00
Labour	580.00
Paintwork Labour	580.00
Towing	0.00
Gross Total (S\$)	7,423.00
+ GST 7.00% (S\$)	519.61
Nett Amount (S\$)	7,942.61

This claim is handled by: **MT TAN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

7664.50*

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Oct 2019)
Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Kan Fook Sing Motor Workshop/SCY8860P/01/10/2019 09:35
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BONNET <i>2</i>	0.00	0.00	*1,380.00 F	X
2	1		*FRONT BONNET LOCK <i>8uc</i>	0.00	0.00	*45.00 F	X
3	1		*FRONT TOP PANEL <i>2</i>	0.00	0.00	*90.00 F	X
4	1		*FRONT BRACE PANEL <i>8uc</i>	0.00	0.00	*30.00 F	X
5	1		*FRONT HEADLAMP LH <i>8uc</i>	0.00	0.00	*1,800.00 F	X
6	1		*FRONT GRILEL <i>Cne</i>	55.5	0.00	*570.00 F	✓
7	1		*FRONT BUMPER <i>m/or</i>	720	0.00	*830.00 F	✓
8	1		*FRONT BUMPER WIPER COVER LH <i>mcs</i>	38	0.00	*80.00 F	✓
9	1		*FRONT BUMPER WIPER NOZZLE LH <i>8uc</i>	0.00	0.00	*120.00 F	X
10	1		*FRONT BUMPER FOAM <i>To.1</i>	55	0.00	*65.00 F	✓
11	1		*FRONT BUMPER REINFORCEMENT <i>huf</i>	265	0.00	*305.00 F	✓
12	1		*FRONT NUMBER PLATE GARNISH <i>To.1</i>	88	0.00	*105.00 F	✓
Sub Total (S\$)						5,420.00	
+ Margin on L,N Items 15.00% (S\$)						813.00	
Total Parts (S\$)						6,233.00	

F=Franchise part.

Kan Fook Sing Motor Workshop/SCY8860P/01/10/2019 09:35 Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

c74

p-1931

 157
 2220.65

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	<i>one</i> 30.00
Sub Total (S\$)			30.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	<i>500</i> 580.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	<i>20</i> 30.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	<i>400</i> 550.00
Gross Labour Cost (S\$)			1,160.00

Kan Fook Sing Motor Workshop/SCY8860P/01/10/2019 09:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

TOTAL \$3170.65

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2019)

Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SCY8860P/17/10/2019 10:41

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET STRIKER	0.00	0.00	*23.00 F ✓
2	1		*FRONT GRILLE SUPPORT	0.00	0.00	*13.00 F ✓
3	1		*FROTN BUMPER SENSOR	0.00	0.00	*138.00 F ✓
4	1		*FRONT BUMPER INNER FRAME	0.00	0.00	*36.00 F ✓
Sub Total (S\$)						210.00
+ Margin on L,N Items 15.00% (S\$)						31.50
Total Parts (S\$)						241.50

Kan Fook Sing Motor Workshop/SCY8860P/17/10/2019 10:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



簡福星摩車工廠 KAN FOOK SING MOTOR WORKSHOP

81 Chua Lane 10, Singapore 620047
Tel : (65) 0747 2930, 0358 2128, 0390 4361

Fax : (65) 0748 1039, 0251 0120

E-mail: kfs@pacific.net.sg • Website: www.kfsworks.com.sg

INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z19P05022523	Date of Loss:	27/03/2019
Vehicle Reg. No.:	SCY8860P	Driveable?	
Driver Age/Info:	56 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MAUREEN NEO BEE LUAN		
Driver:	HENG SOON NGEE		
Make/Model:	MERCEDES-BENZ E250, 1.8 CGI (A)	Vehicle Reg. Date:	08/08/2010
Vehicle Colour:	METALLIC MAROON		
Engine No:	27186030089102	Chassis No:	VDD2120472A255690
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO ATTACHED REPORT		
Present Location:	KAN FOOK SING MOTOR WORKSHOP (DEFU)		

*not affected
Lian
The 3rd party
party
Express?
Haly*

COST OF CLAIMS

	Amount
Parts	6,233.00
Miscellaneous Items	30.00
Labour	580.00
Paintwork Labour	580.00
Towing	0.00
Gross Total (S\$)	7,423.00
+ GST 7.00% (S\$)	519.61
Nett Amount (S\$)	7,942.61

This claim is handled by: MT TAN

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Oct 2019)
 Parts: 143 MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Kan Fook Sing Motor Workshop/SCY8660P/01/10/2019 09:35
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk: *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET <i>R</i>	0.00	0.00	*1,380.00 F <i>X</i>
2	1		*FRONT BONNET LOCK	0.00	0.00	*45.00 F <i>?</i>
3	1		*FRONT TOP PANEL <i>R</i>	0.00	0.00	*90.00 F <i>X</i>
4	1		*FRONT BRACE PANEL	0.00	0.00	*30.00 F <i>?</i>
5	1		*FRONT HEADLAMP LH	0.00	0.00	*1,800.00 F <i>?</i>
6	1		*FRONT GRILLEL <i>Che</i>	0.00	0.00	*570.00 F <i>---</i>
7	1		*FRONT BUMPER <i>SP/DR</i>	0.00	0.00	*830.00 F <i>---</i>
8	1		*FRONT BUMPER WIPER COVER LH <i>WCS</i>	0.00	0.00	*80.00 F <i>---</i>
9	1		*FRONT BUMPER WIPER NOZZLE LH	0.00	0.00	*120.00 F <i>?</i>
10	1		*FRONT BUMPER FOAM <i>Thin</i>	0.00	0.00	*65.00 F <i>---</i>
11	1		*FRONT BUMPER REINFORCEMENT <i>Thin</i>	0.00	0.00	*305.00 F <i>---</i>
12	1		*FRONT NUMBER PLATE GARNISH <i>Thin</i>	0.00	0.00	*105.00 F <i>---</i>

F=Franchise part.

Sub Total (\$\$) 5,420.00
 + Margin on L,N Items 15.00% (\$\$) 813.00
Total Parts (\$\$) 6,233.00

Kan Fook Sing Motor Workshop/SCY8660P/01/10/2019 09:35. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repairer Estimates

Page 3 of 3

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NUMBER PLATE	CAR 30.00
Sub Total (S\$)			30.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAYPAINTING CHARGES	New	500 580.00
<u>Labour Items</u>			
2	TO CHECK WIRING SYSTEM	New	20 30.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	400 550.00
Gross Labour Cost (S\$)			1,160.00

Kan Fook Sing Motor Workshop/SCY8860P/01/10/2019 09:35. Not valid without Reference section.
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

明義純車私人有限公司

MIN GHEE AUTO PTE LTD

8, Jalan Lembuh Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO.		8164196
DATE	08/10/2019	PAGE 1
TERM	30 Days Net	SALESMAN Ong Hai Choon
CUSTOMER REF.	SCY8860P	OUR REF. 47037

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER : KANFOOK1 TIME:09:21
KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147

539147
Telephone No : 67479560

ROUTE
UB11

DELIVER TO :

KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA212 885 01 36	BRACING	1B-07F	1 PC	13.00	13.00
2 MBA212 898 02 32	U-SHAPED STRIKER	1E-7C	1 PC	23.00	23.00
3 MBA212 817 00 78	LICENSE PLATE MOULDING W212	1B-6J	1 PC	88.00	88.00
4 MBA212 505 14 30	AIR BUFFLE	1D-4I	1 PC	36.00	36.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor

HDK
Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046

Account No.: 503-309-511-3
*Please send a screen shot of your payment/
transfer confirmation to
account@minghee.com.

SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.



For MIN GHEE AUTO PTE. LTD.

TOTAL	SIN	160.00
ADD GST	7%	11.20
AMOUNT DUE	SIN	171.20

TAX INVOICE

INVOICE NO. **8164461**

DATE	09/10/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SCY8860P	OUR REF.	47037

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: KANFOOK1 TIME:17:04
KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147

539147
Telephone No : 67479560

ROUTE
UB11

DELIVER TO :

KAN FOOK SING MOTOR WORKSHOP
61,DEFU LANE 12,
SINGAPORE 539147



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA212 860 01 08 9999	COVERING	1B-03G	1 PC	38.00	38.00
2 MBA212 620 15 00	CROSS MEMBER FRT	3B-02D	1 PC	265.00	265.00
				TOTAL	303.00
				ADD GST	21.21
				AMOUNT DUE	324.21

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor



Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
*Please send a screen shot of your payment/
transfer confirmation to
account@minghee.com


SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.



For MIN GHEE AUTO PTE. LTD.



明義純車私人有限公司
MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 6118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 8164539

DATE	10/10/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SCY8860P	OUR REF.	47037

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: KANFOOK1 TIME:11:22

KAN FOOK SING MOTOR WORKSHOP
61, DEFU LANE 12,
SINGAPORE 539147

539147

Telephone No : 67479560

ROUTE
UB12

DELIVER TO :

KAN FOOK SING MOTOR WORKSHOP
61, DEFU LANE 12,
SINGAPORE 539147



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA212 880 10 83 9040	RADIATOR GRILLE AVANTGARDE	1D-8L	1 PC	555.00	555.00
2 MBA212 885 18 37	IMPACT ABSORBER	1A-05K	1 PC	55.00	55.00
3 MBA212 542 00 18 9999	SENDER UNIT	1C-9A	1 PC	138.00	138.00

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

Exclusive Distributor



Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd

Branch Code: 046

Account No.: 503-309-511-3

*Please send a screen shot of your payment/

transfer confirmation to

account@minghee.com




SIGN & COMPANY'S STAMP

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.



For MIN GHEE AUTO PTE. LTD.



明義純車私人有限公司
MIN GHEE AUTO PTE LTD

8, Jalan Lembah Kallang, #01-01 Min Ghee Building Singapore 339564
Main Tel: 6298 3888 Fax: 6291 2172, 6294 1450 Accounts Tel: 6291 G118 Accounts Fax: 6297 0863
Email: info@minghee.com (Main), account@minghee.com (Accounts)
Website: http://www.minghee.com

TAX INVOICE

INVOICE NO. 8164415

DATE	09/10/2019	PAGE	1
TERM	30 Days Net	SALESMAN	Ong Hai Choon
CUSTOMER REF.	SCY8860P	OUR REF.	47037

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: KANFOOK1 TIME:14:11
KAN FOOK SING MOTOR WORKSHOP
61, DEFU LANE 12,
SINGAPORE 539147

539147

Telephone No : 67479560

ROUTE
UB11

DELIVER TO:

KAN FOOK SING MOTOR WORKSHOP
61, DEFU LANE 12,
SINGAPORE 539147



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA212 880 19 40 9999	FR BUMPER W212 AVANTGARDE	61-2	1 PC	720.00	720.00
TOTAL					720.00
ADD GST					50.40
AMOUNT DUE					770.40

GOODS RECEIVED IN GOOD ORDER
AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S
PREVAILING LENDING RATE
CASH INVOICE MUST BE PAID WITHIN 7 DAYS
FROM DATE OF INVOICE.

SIGN & COMPANY'S STAMP

[Signature]

Exclusive Distributor



Stockists

Payment via telegraphic transfer to
Name of Bank: United Overseas Bank
Account Name: Min Ghee Auto Pte Ltd
Branch Code: 046
Account No.: 503-309-511-3
*Please send a screen shot of your payment/
transfer confirmation to
account@minghee.com



DATE
ALL CHEQUES MUST BE MADE PAYABLE TO
MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE. LTD.

簡福星摩哆工廠
KAN FOOK SING MOTOR WORKSHOP
61 DEFU LANE 12
SINGAPORE 539147
TEL: 67479560, 68582126, 68584361
FAX: 67481006, 62818428

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

INVOICE NO : TEST

DATE : 14-10-2019

VEHICLE NO. : SCY8860P
ACCIDENT DATE : 27-09-2019 20:10
THIRD PARTY REF. : SME5045H

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEICLE SCY8860P MERCEDES-BENZ E250

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT BONNET STIKER	23.00 *
1	FRONT GRILLE SUPPORT	13.00 *
1	FRONT GRILLE	555.00 —
1	FRONT BUMPER	720.00 —
1	FRONT BUMPER WIPER COVER LH	38.00 —
1	FRONT BUMPER FOAM	55.00 —
1	FRONT BUMPERR REINFORCEMENT	265.00 —
1	FRONT NUMBER PLATE GARNISH	88.00 —
1	FRONT BUMPER SENSOR	138.00 *
1	FRONT BUMPER INNER FRAME	36.00 *
		1,931.00
	ADD 15 %	289.65
	TOTAL (A)	2,220.65

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	20.00 —
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI- TTING NEW PARTS	400.00 —
1	SPRAYPAINTING CHARGES	500.00 —

TOTAL (D)	920.00
TOTAL REPAIR COST :	3,170.65
G S T % :	221.94
INVOICE AMOUNT :	3,392.59

S/N

1 FRT NO. PLATE \$ 30.00 —

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Sep 2019 Sendback Est	01 Oct 2019 09:35 \$57,423.00	01 Oct 2019 09:53 Edit Adj Rpt	\$53,170.65 Edit Estimates	\$53,170.65 View Rpt		Pending for Survey Report Cancel Case
Supp #1	17 Oct 2019 10:40	17 Oct 2019 10:41 \$5241.50	17 Oct 2019 10:41			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured: MAUREEN NEO BEE LUAN , ID: S7228238H	
Vehicle Reg. No.: SCY8860P	Date of Loss: 27/09/2019 20:00 - :59 [108 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 19/19/19/VP05/022435	Policy/Cover Note No.: Z19P05022523 (Comprehensive)
	Excess: S\$0.00
Repairer: Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560	
Handling Insurer: Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/10/2019]	
Driver/Custodian: HENG SOON NGEE (56 / Male) , NRIC: S1550206A, Tel: +6590912929 Email: maureen.nbl@gmail.com	
Adj Asg. Remarks: SURVEY & REVERT	

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- LONPAC_HQ (07/10/2019): Alert - Adj Mandate Approved (\$5492.50) - SCY8860P - Claim Handler: Gerald Poh

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SCY8860P (19/19/19/VP05/022435)

OD

Sep 27 2019 8:00PM

[MAUREEN NEO BEE LUAN]

Kan Fook Sing Motor Workshop

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	01/10/19 09:35	Repairer Estimates	Load HTM	
2	17/10/19 10:41	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 16:20	Adjuster Immediate Advice	Load HTM	
2	17/10/19 14:53	Adjuster Immediate Advice	Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/10/19 14:50	General View	Load JPG	☒
2	17/10/19 14:50	General View	Load JPG	☒
3	17/10/19 14:50	General View	Load JPG	☒
4	17/10/19 14:50	General View	Load JPG	☒
5	17/10/19 14:50	General View	Load JPG	☒
6	17/10/19 14:50	General View	Load JPG	☒
7	17/10/19 14:50	General View	Load JPG	☒
8	17/10/19 14:50	General View	Load JPG	☒
9	17/10/19 14:50	General View	Load JPG	☒
10	17/10/19 14:50	General View	Load JPG	☒
11	17/10/19 14:50	General View	Load JPG	☒
12	17/10/19 14:50	General View	Load JPG	☒
13	17/10/19 14:50	General View	Load JPG	☒
14	17/10/19 14:50	General View	Load JPG	☒
15	17/10/19 14:50	General View	Load JPG	☒
16	17/10/19 14:50	General View	Load JPG	☒
17	17/10/19 14:50	General View	Load JPG	☒
18	17/10/19 14:50	General View	Load JPG	☒
19	17/10/19 14:50	General View	Load JPG	☒
20	17/10/19 14:50	General View	Load JPG	☒
21	17/10/19 14:50	General View	Load JPG	☒
22	17/10/19 14:50	General View	Load JPG	☒
23	17/10/19 14:50	General View	Load JPG	☒
24	17/10/19 14:50	General View	Load JPG	☒
25	17/10/19 14:50	General View	Load JPG	☒
26	17/10/19 14:50	General View	Load JPG	☒
27	17/10/19 14:50	General View	Load JPG	☒
28	17/10/19 14:50	General View	Load JPG	☒
29	17/10/19 14:50	General View	Load JPG	☒
30	17/10/19 14:50	General View	Load JPG	☒
31	17/10/19 14:50	General View	Load JPG	☒
32	17/10/19 14:50	General View	Load JPG	☒
33	17/10/19 14:50	General View	Load JPG	☒
34	17/10/19 14:50	General View	Load JPG	☒
35	17/10/19 14:50	General View	Load JPG	☒

Assessment Reports			1 per page	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
36	17/10/19 14:50	General View	 Load JPG	☒
37	17/10/19 14:50	General View	 Load JPG	☒
38	17/10/19 14:50	General View	 Load JPG	☒
39	17/10/19 14:50	General View	 Load JPG	☒
40	17/10/19 14:50	General View	 Load JPG	☒
41	17/10/19 14:50	General View	 Load JPG	☒
42	17/10/19 14:50	General View	 Load JPG	☒
43	17/10/19 14:50	General View	 Load JPG	☒
44	17/10/19 14:50	General View	 Load JPG	☒
45	17/10/19 14:50	General View	 Load JPG	☒
46	17/10/19 14:50	General View	 Load JPG	☒
47	17/10/19 14:50	General View	 Load JPG	☒
48	17/10/19 14:50	General View	 Load JPG	☒
49	17/10/19 14:50	General View	 Load JPG	☒
50	17/10/19 14:50	General View	 Load JPG	☒
51	17/10/19 14:50	General View	 Load JPG	☒
52	17/10/19 14:50	General View	 Load JPG	☒
53	17/10/19 14:50	General View	 Load JPG	☒
54	17/10/19 14:50	General View	 Load JPG	☒
55	17/10/19 14:50	General View	 Load JPG	☒
56	17/10/19 14:50	General View	 Load JPG	☒
57	17/10/19 14:50	General View	 Load JPG	☒
58	17/10/19 14:50	General View	 Load JPG	☒
59	17/10/19 14:50	General View	 Load JPG	☒
60	17/10/19 14:50	General View	 Load JPG	☒
61	17/10/19 14:50	General View	 Load JPG	☒
62	17/10/19 14:50	General View	 Load JPG	☒
63	17/10/19 14:50	General View	 Load JPG	☒
64	17/10/19 14:50	General View	 Load JPG	☒
65	17/10/19 14:50	General View	 Load JPG	☒
66	17/10/19 14:50	General View	 Load JPG	☒
67	17/10/19 14:50	General View	 Load JPG	☒
68	17/10/19 14:50	General View	 Load JPG	☒
69	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
70	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
71	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
72	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
73	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
74	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
75	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
76	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
77	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
78	17/10/19 14:50	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	30/09/19 15:53	E-filed GIA report	 Load PDF	
2	17/10/19 13:43	Repairer's Bill	 Load PDF	
3	17/10/19 13:43	Signed DV	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/10/19 16:10	ESTIMATE	 Load PDF	
2	17/10/19 14:49	SUPPLEMENTARY	 Load JPG	☒
3	21/10/19 09:50	WORKSHOP INVOICE	Load PDF	
4	21/10/19 09:50	PARTS INVOICE	Load PDF	

Linked Accident Report Documents

			View	View In Browser ▼
Assessment Reports			1 per page ▼	✓
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	30/09/19 12:36	Accident Statement	 Load HTM	
			3 per page ▼	✓
Photos/Images				
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	30/09/19 12:31	Accident Photo	 Load JPG	✓
2	30/09/19 12:31	Accident Photo	 Load JPG	✓
3	30/09/19 12:31	Accident Photo	 Load JPG	✓
4	30/09/19 12:31	Accident Photo	 Load JPG	✓
5	30/09/19 12:31	Accident Photo	 Load JPG	✓
6	30/09/19 12:31	Accident Photo	 Load JPG	✓
7	30/09/19 12:31	Accident Photo	 Load JPG	✓
8	30/09/19 12:31	Accident Photo	 Load JPG	✓
9	30/09/19 12:31	Accident Photo	 Load JPG	✓
10	30/09/19 12:31	Accident Photo	 Load JPG	✓
			1 per page ▼	✓
Documentation				
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	30/09/19 12:34	Accident Sketch Plan	 Load TIF	
2	30/09/19 12:34	Accident Sketch Plan	 Load TIF	
3	30/09/19 12:34	Identification Card	 Load TIF	
4	30/09/19 12:34	Identification Card	 Load TIF	
5	30/09/19 12:34	ci	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC19017226/UTF3S2**Date:** 21/10/2019REFERENCE

Insured/Claimant: MAUREEN NEO BEE LUAN Policy No: Z19P05022523
Date of Loss: 27/09/2019 Nature of Claim: OD Claim No: 19/19/19/VP05/022435

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCY8860P**
Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A) Engine No: 27186030089102
Reg. Date: 08/09/2010 (Man. Year: 2010) Chassis No: WDD2120472A255690
Colour: Brown Odometer: 146170 km
Engine Capacity: 1796 cc
Market Value/New Car Price: S\$40,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 ZR17 Rear Tyre Size: 245/45 ZR17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,474.50	2,220.65	4,253.85	65.70
Miscellaneous Items	30.00	30.00	0.00	0.00
Labour	580.00	420.00	160.00	27.59
Paintwork Labour	580.00	500.00	80.00	13.79
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,664.50	3,170.65	4,493.85	58.63
+ GST 7.00/7.00% (S\$)	536.52	221.95	314.57	58.63
Nett Amount (S\$)	8,201.02	3,392.60	4,808.42	58.63

INSPECTION

Date of Assignment: 01/10/2019 Present Location: Kan Fook Sing Motor Workshop (Defu)
Date Inspected: 07/10/2019 Inspected At: Kan Fook Sing Motor Workshop (Defu)
Estimated Period of Repair: 4.0 days No. 61 Defu Lane 12
Singapore 539147

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2019)
Parts:	143	MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCY8860P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Repair	1,380.00 F	*- F
2	1		*FRONT BONNET LOCK (WCP)	Serviceable	45.00 F	*- F
3	1		*FRONT TOP PANEL (WCP)	Repair	90.00 F	*- F
4	1		*FRONT BRACE PANEL (WCP)	Serviceable	30.00 F	*- F
5	1		*FRONT HEADLAMP LH (WCP)	Serviceable	1,800.00 F	*- F
6	1		*FRONT GRILEL (WCP)	Cracked	570.00 F	*555.00 F
7	1		*FRONT BUMPER (WCP)	Dented / Deformed	830.00 F	*720.00 F
8	1		*FRONT BUMPER WIPER COVER LH (WCP)	Missing	80.00 F	*38.00 F
9	1		*FRONT BUMPER WIPER NOZZLE LH (WCP)	Serviceable	120.00 F	*- F
10	1		*FRONT BUMPER FOAM (WCP)	Torn	65.00 F	*55.00 F
11	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	305.00 F	*265.00 F
12	1		*FRONT NUMBER PLATE GARNISH (WCP)	Torn	105.00 F	*88.00 F
Supplementary #1						
13	1		*FRONT BONNET STRIKER (WCP)	Bent	23.00 F	*23.00 F
14	1		*FRONT GRILLE SUPPORT (WCP)	Cracked	13.00 F	*13.00 F
15	1		*FRONT BUMPER SENSOR (WCP)	Cracked	138.00 F	*138.00 F
16	1		*FRONT BUMPER INNER FRAME (WCP)	Cracked	36.00 F	*36.00 F

F=Franchise part.

Sub Total (S\$)	5,630.00	1,931.00
+ Margin on L,N Items 15.00/15.00% (S\$)	844.50	289.65
Total Parts (S\$)	6,474.50	2,220.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRONT NUMBER PLATE (CRACKED)	30.00	30.00
Sub Total (S\$)			30.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	SPRAYPAINTING CHARGES	New	580.00	500.00
Labour Items				
2	TO CHECK WIRING SYSTEM	New	30.00	20.00
3	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	New	550.00	400.00
Gross Labour Cost (S\$)			1,160.00	920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >