

ASS. REC. BY:

REF:

CS/FCI19017239/Kes302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Marina Chia

of

FCI

Date/Time: 1/10/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV4265T

Insured: SHC7220A

at Workshop in/s RC Auto

Tel: 97619383

of 160 S/M 206-20

Policy No:

Claim No: D19006253MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 27/9/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 1/10

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction
	SLV4265T-X
	SHC7220A-X
02/10/19	@ 16:41 pm revised PA to Marina Chia via email.

ASS. REC. BY:

REF:

PC21

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/TOYO/YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

10/10/19 @ 2000 encl & confirm
(\$918.00 Red - 31%)

RECEIVED 15 OCT 2019

Date/Time, File Pass to?

15/10/19

1)

Date/Time, File Return to?

2)

☐ : Prell. Report☒ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

2,000/- 45

110

50

50

14

224



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006253MFSH

Date: 02 October 2019

Our Ref: CS/FCI19017239/Ksf3

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLV 4265T

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/10/2019 at the premises of M/s RC Auto and have the following to report:-


Workshop Estimate Amount	: S\$ 2,918.00 .
Revised Estimate Amount	: S\$ 2,758.00 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the n/s front door portion.

Comments/ Present Status:

Damages Consistent.
Repair days: 3 days



Yours faithfully

Kenneth Kong
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	30-09-2019	Our Ref No. D19006253MFSH
Accident Date	27-09-2019	Claim Type. Third Party
Insured Vehicle	SHC7220A	Third Party Vehicle. SLV4265T
Survey Location	160 SIN MING DRIVE #06-20 SIN MING AUTOCARE	
Contact Person.	MR TAN	
Contact No.	97619383/ 97619383	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RC AUTO	Attention. NIL
Cc : TP Solicitor	KSCGP JURIS LLP	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

Veh In

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Re: SURVEY ASSESSMENT - D19006253MFSH/1

Shirley Hiew (LKK Auto)

Wed 2/10/2019 4:41 PM

To: 'Merina Chia San San' <MerinaChia@msfirstcapital.com.sg>; 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>

Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

 1 attachments (80 KB)

PRELI ADVISE - SLV 4265T.pdf;

Dear Merina,

Enclosed preliminary revised of vehicle SLV 4265T.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Wednesday, 2 October 2019 2:41 PM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Subject:** FW: SURVEY ASSESSMENT - D19006253MFSH/1

Best Regards

G.NIVTHA**LKK Auto Consultants Pte Ltd**Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]**Sent:** Tuesday, 1 October 2019 11:34 AM**To:** ASSIGNMENTS@LKKAUTO.COM**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722
Tel : 97619383 Email: rcauto5555@gmail.com
Reg. No. 53199168K

*Not Withrain
Uly & 2000h
Purvey After Peim
3 days*

SLV 4265 T

Date : 28/9/2019

Quantity	Description/Particular	Unit Price	Amount	
	FRONT DOOR		<i>R</i> 960	00 ✓
	FRONT DOOR GLASS		<i>G</i> 450	00 ✓
	FRONT DOOR CHROME		<i>R</i> 210	00 ✓
	FRONT DOOR SIDE MIRROR ASSY		<i>CM</i> 650	00 ✓
	FRONT DOOR RUBBER		<i>G</i> 150	00 ✓
		TOTAL	2420	00
		LESS <i>20</i>	2178	00
	SPRAY PAINTING		250	00 ✓
	TO RENEW ABOVE PARTS		400	00 <i>250</i>
	TO CHECK WIRING		30	00 <i>20</i>
	TO TRANSFER DOOR ACCESSORIES		60	00 ✓
		TOTAL	2918	00

Received the above goods in good order and condition

Received by

E.&.O.E.

LKK Auto Consultants hence notify the Repairer of the following:
for **RC AUTO**
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised Signature

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017239/Ksf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7220A	Veh. Inspected	SLV 4265T	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006253MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA	Assign Date	01/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0158310	Colour	METALLIC GREY	
Odometer	46560	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	BRIDGESTONE	8 mm	
L/H Front Tyre	205/60 R16	BRIDGESTONE	8 mm	
R/H Rear Tyre	205/60 R16	BRIDGESTONE	8 mm	
L/H Rear Tyre	205/60 R16	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT DOOR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2019	Inspection Date	01/10/2019	
Survey held at	R C AUTO BLK 18 SIN MING INDUSTRIAL ESTATE SECTOR A #01-43 SINGAPORE 575676			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4265T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR	BENT	960.00	960.00
1	FRONT DOOR GLASS	CUT	450.00	450.00
1	FRONT DOOR CHROME	DENTED	210.00	210.00
1	FRONT DOOR SIDE MIRROR ASSY	CRACKED	650.00	650.00
1	FRONT DOOR RUBBER	CUT	150.00	150.00
	LESS 10% DISCOUNT		-242.00	-
	LESS 20% DISCOUNT		-	-484.00
			2,178.00	1,936.00
LABOUR				
	SPRAY PAINTING.		250.00	250.00
	TO RENEW ABOVE PARTS.		400.00	250.00
	TO CHECK WIRING.		30.00	20.00
	TO TRANSFER DOOR ACCESSORIES.		60.00	60.00
			740.00	580.00
GRAND TOTAL			2,918.00	2,516.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/FCI19017239/Ksf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.