ASS. REC. BY:	REF:	CS   SM01901725	7 1A99312	Special Instruction:
Surveyor Adman		ASSIGNMEN		
From (Person); Grau	TUO	of SMO		Date/Time: 1.10-19 2.07p.
Estimated Cost:			Bill to:	
OD TIP (WS/TP RES) To Inspect Vehicle No:				Insured: Sq 5 3110M
nt Workshop m/s MG				Tel: 67444165
of 23 Kaki Bubi	+ AVL 4	#02-03B		- 1 5510
Policy No: DI9MTPYO			Claim No: (	(mi) 19 v4570
Sum Insured:			Excess:	
Make of Veh:				D.O.A. 30.9.11
(Client's Record) CA / REV / REP. / R Dute/Time: 1-10-19 2		mon Contacted:	ms Hon	H.O.D. Fudorsement:
Date/Time Action/Ins	truction ( 🗸	) Estimute		•
SGS 300	n. X			
335 541	17 X			
03/10/19C 11.20a	n Informed	elvene me	ave per	ading asseriate from nepais
18 4/19 2 11.09	a vevisi	d to Put	h Chan	na Marinen.
				1.85, 60%)
7 4	107-1 6	The same	4 - 10	1 60/0)

ASS ( TE BY

### Note: This document has not been finalised.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Pava Ubi Industrial Park

Singapore 408933

Attn:

Ruth Chua Gek Tiang

Date:

15 Nov 2019

### Preliminary Advice

Insured Vehicle No : SGS3110M

TP Vehicle No

: SJS8412Z

Accident Date

: 30/09/2019

Make

: TOYOTA COROLLA ALTIS

Assignment Date

:01/10/2019

Date of Inspection : 02/10/2019

Est. Duration of Repair

: 6.00

Inspection At

: MG SOLUTION PTE LTD (HQ)

23 KAKI BUKIT AVENUE 4 #02-03B, VICOM INSPECTION CENTRE

SINGAPORE 415933

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,631.85
Revised Amount	:S\$	4,890.43
Check Items (Estimated)	:S\$	0,00
Total	:S\$	4,890,43
Lump Sum Repair	:S\$	3,900,00

**Total Loss Consideration** 

Lump Sum Repair

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

1.00	The vehicle is repairable at our let us have your authorisation.	adjusted	amount.	We ha	ive also	confirmed	excess	and	policy	coverage.	Kindly

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

## ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subm	itted	tins Auth ed	New Assignment Cancel Case		
Main	01 Oct 2019		01 Oct 2019 14:03 Assign							
	Main	Re	ference	Cia	im Details		Docume	nts	Show All	
CLAIM S	UBFOLDER DET	TAILS					[Cre	ated by insu	rer]	
insured:		TAN S	AU SIAK, ID: 57	806268A, T	st: +65923211	23, Em	all: SAUSIAK@GI	MAIL.COM		
Main Clair	mant:	LEOW	CHYE HUAT, II	D: 51716194F						
Vehicle Re	eg. No.:	53584	112Z	Di	ite of Lass:		30/0	9/2019 08:00	:59	
Claim Typ	se:	TP / 0	MTD1904570	Po	licy/Cover Nati	e No.:	1000	D19MTPV01008091 (Comprehensive)		
Vehicle Re	eg. No. (Insured)	SG531	10M	Pe	licy No. (Claim	ent):				
				E	cess:					
Repairer		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	lution Pte Ltd (H 886931	(Q) 23 Kaki Bu	kit Avenue 4 #	02-038,	VICOM Inspectio	on Centre, 4159	933 Kaki Bukit	
Handling	Insurer:	Sompo 6322 4	Insurance Sing 615]	apore Pte. Lt	d. (HQ) - Tel:	6461 65	55 [Handled b	y IRENE JAM	ES HENRY -	
Adjuster:		LKK A	uto Consultants							
Driver/Cu	stodian (Insured)		U SIAK (41 / Maio				2321123 Email: 5			
Adj Asg. R	Remarks:	WS: M	S HONG 6744 416	5						
ASSOCI	ATED MAIL REC	EIVED					View Al	Compo	se Case Mail	
There are	no mail for this	case.								
E ALL ASS	SOCIATED TAS	cs			View All	Search	Tasks Cre	rate New Task	Complete	
		100	Tenun Cubin	. Mandian	11:30:3711		Completed On			
Due Da	ite Priority	Type Task	Froup Subjec	t Handler	Assigned	DY	completed on	Created	on Dune	

### Summer Lee (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 1 October, 2019 2:02 PM

To: MG Solution; Henry, Irene James; 'admin-d@lkkauto.com';

'assignments@lkkauto.com'

Subject: CMTD1904570/JJH - LKK/ SGS3110M & SJS8412Z -DOA ON 30/09/2019

#### Without Prejudice

Our Reference: CMTD1904570/IJH

Your Reference: SJS8412Z

Hi Ms. Hong,

We acknowledged receipt of your claim documents.

Please be informed that Ms. Irene Henry is the handler of this case who can be contacted at 63224 618.

As requested, we will appoint LKK AUTO to survey the above vehicle.

#### Aside to LKK AUTO,

Please make arrangement to conduct the survey for <u>SJS8412Z</u> on a without Prejudice and any admission of liability basis.

Please submit your report via Merimen upon completion of survey.

Best Regards
Grace Teo
Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission<sup>1</sup> & Product Purchase<sup>2</sup> via Sompo SG





<sup>1</sup> For Travel, Personal Accident & Home Insurance | <sup>2</sup> For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential

and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: MG Solution [mailto:mg3solution@gmail.com]

Sent: Tuesday, October 01, 2019 11:07 AM

To: Claims - Motor Survey

Subject: SJS8412Z-( PRE-INSPECTION); YOUR REF: SGS3110M -DOA ON 30/09/2019

Dear Person-Incharge

Please refer to attach file and arrange for pre-inspection.

we prefer our single joint expert as below:

ADRIAN LING WAI PING

LKK AUTO CONSULTANTS PTE LTD

Thank You.

Best Regards,

Ms Hong

#### MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing)

#02-03B Vicom Inspection Centre

Singapore 415933

Tel: 6744 4165

Fax: 6744 4604

### Shiau Chan (LKKAuto)

From:

Do-Not-Reply <do-not-reply@merimen.com>

Sent:

Thursday, 3 October 2019 11:20 AM

To:

do-not-reply@merimen.com

Cc:

SUR

Subject:

TP VEHICLE SJS 8412Z (YOUR REF: CMTD1904570)

This mail is associated with: \*SJS8412Z (CMTD1904570) [SGS3110M]

TP LEOW CHYE HUAT Sep 30 2019 8:00AM [TAN SAU SIAK] MG Solution Pte Ltd

Dear Irene,

Please be informed that we have inspected the vehicle SJS 8412Z.

We are pending estimate from repairer.

Thanks & Regards,


Shiau Chan (Ms) LKK Auto Consultants Pte Ltd Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software. www.avg.com



## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars Owner ID Type:	Singapore NRIC	
Owner ID:	194F	
Vehicle Details	194F	_
Vehicle No.:	5J58412Z	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	03 Oct 2019	
Vehicle Make:	TOYOTA	
Vehicle Model:	COROLLA ALTIS 1.6 AUTO	
Primary Colour:	Blue	
Manufacturing Year:	2009	
Engine No.:	3ZZ4931518	
Chassis No.:	MR053ZEE106154983	
Maximum Power Output:	80.0 kW (107 bhp)	
Open Market Value:	\$17,853.00	
Original Registration Date:	10 Sep 2009	
First Registration Date:	10 Sep 2009	
Transfer Count:	2	
Actual ARF Paid:	\$17,853.00	
Intended PARE Repair Details		
PARF Eligibility:	Forfeited	
PARF Eligibility Expiry Date:		
PARF Rebate Amount:	\$0.00	
Intended COE Robert Dutalls		
COE Expiry Date:	09 Sep 2024	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	5	
PQP Paid:	\$14,743.00	
COE Rebate Amount:	\$14,546.00	
Total Rebate Amount:	\$14,546.00	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 03 Oct 2019

### SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 2. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- Any false reporting may be referred to the Police for investigation.
   This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the certife and to copies of the report being made available

aforesaid.	
Carl Winds a land Court	ACCIDENT STATEMENT
Date Of Report	01/10/2019 10:22
Date Of Accident	30/09/2019 08:55
Exact Location Of Accident	ALEXANDRA ROAD TOWARDS QUEENSWAY
Country/State of Loss	SINGAPORE
The second secon	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SJS8412Z
Insured/Policyholder	
Name Of Registered Owner	LEOW CHYE HUAT
NRIC No	S1716194F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90053648
Alternative Phone No	OFFICE-90053648
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5112395271 TPFT
Cover Note Number	
Driver	
Name of Driver	LEOW CHYE HUAT
NRIC No	S1716194F
Date Of Birth	24/04/1965
Occupation	OUTDOOR
Date Of Driving Pass	01/09/1984
Orlving Experience	35 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90053648
Fax Number	The state of the s
Contact Number	OFFICE-90053648
EMail Address	NOEMAIL

Address BLK 372 #03-18 TAMPINES STREET 34

Postcode 520372

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver) †

**Details of Police Action** 

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

NO

Vehicle Registration Number SGS3110M

Vehicle Make/Model/Colour VOLVO / S40 2.0L AT ABS D/AB 2WD 4DR

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1** 

Name LEOW CHYE HUAT

Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address

Postcode

BACK & NECK PAIN SJS8412Z

#### Sketch Plan

#### SKETCH PLAN

#### MEDRIANT NOTICE

- Repair of a preserve and a property medical state of the party medical and a state of
- This Form must be completed by the Bodgstelder and for the Astronomy Drive.
- Information property and the supported and extended parameters are not by the property of the control of the property controls to installing parties (which is before).
- Pelmant expension from a current resolution to make legislation of a first travel.
- Low folia removale may be allowed to the finding for montanting.
- The report will be three right to the individual of the distribution of Committee and the Committee of the C
- The thick begins that the state of the state
- 1. Consert of fair Co. Remarks to the Francisco Co. Rept. 1.
  - collected and an expension of the second of the
  - If y more, my emission and the Cone of more and appears of impoure [Tak\*] may be personal information of indicate and for the personal information provided by me or possessed by my insurer [collectively the "Personal information"] and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
    - The state of the s
    - II with the second second
    - A first year and made coming with my contractions or responsing to any enquiries by may
    - (N) some latering my claims (expecting the making of compactnesses, tratements, involves, reports or natives to me, which pauld minite declarate of certain personal data about me to bring about dalway of the same as well as on the other above of converse and converse of converse of
    - Personal Committee of the Committee of t
  - The state of the second self-material and the second secon


  - THE RESIDENCE OF STREET STREET, STREET
  - The state of the s
  - interests the second of the second parties as reasonably regulation the automatical of
  - If for complying with incurrence under any regulations, laws or court orders.

19

- 1 OCT 2019

Divers Signature Of diversional policy solicy Date & Times IDAC KAKI BUKIT (C) 23 Kaki Bukit 4 2-02 Singapore 2233 Tel: 67416607

Email: unit h Reparting Comma Personnells Signature Name: SIRCHIN Na



Con 30/09/2019 at about 0855 her at along Alexandra

Road towards Queensway basicle unit no. 438 Alexandra

TechnoPark. I was travelling on the centre Lone and
when my front vehicle slow down and stop olive to
howy traffic hence I follow suit. Suddenly I felt
a great impact from behind and when I dighted, I

realised that it was Vehicle (B) who hit outo my

Rear Portion of my Vehicle (B) causing damage to my

Vehicle.

(A) SJS 8412 Z (B) SGS 3110 M

Note: Please note that your insurer may have 14 days time frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check your policy for more information.

-1 OCT 2019 Control of the control o

We the trial through the later than

IDAC KAKI BURTI (1 23 Kaki Bukit Ave 4 #0 Bingapore 4 1 Tet 87418897 Fac 87

## MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933 Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO

: SOMPO

DATE

: 1-Oct-19

UNIT LIST TOTAL LIST

ATTENTION

: MOTOR CLAIMS DEPT

JOB TYPE : T/P CLAIM

ESTIMATE REPORT

VEHICLE DETAILS

X100 Chan

VEHICLE NO

: SJS8412Z

MODEL

: TOYOTA COROLLA ALTIS 1.6 MROS3ZEE106/5 4583

CHASSIS NO

ACCIDENT DETAILS

DATE: 30-Sep-19

TIME : 08:55HRS

THIRD PARTY REQUESTOR / CONTACT :

JACK

CLAIM DETAIL : PARTS

S/N	DESCRIPTION		PRICE			PRICE	
1	BOOTLID Buckled	11	S	844.75	s	844.75	V
2	BOOTLID LOGO NE	1	\$	80.00	s	_80.00	1 5
3	BOOTLID '1.6' EMBLEM	1	\$	52.00	S	52.00	/
4	BOOTLID COROLLA EMBLEM 4	1	s	45.57	s	45.57	
5	BOOTLID 'ALTIS' EMBLEM	1	\$	44.17	s	44.17	-
6	BOOTLID 'LX' EMBLEM	197	s	44.17	S	44.17	-
7	BOOTLID LOCK De 6.	व	S	189.20	s	189.20	1
8	BOOTLID WEATHERSTRIP Cut	-1	s	211.30	s	211,30	1
9	REAR BUMPER Del-d	4	\$	598.60	\$	598.00	3.52
10	REAR BUMPER REFLECTOR AM NOC	2	s	85.30	s	170.60	F
11	REAR BUMPER BRACKET RENTED	2	s	103.00	s	206.00	/
12	REAR BUMPER RH SIDE RETAINER(FRONT)	2	s	109.50	\$	219.00	S MM
13	REAR BUMPER RH SIDE RETAINER(LOWER)	2	s	109.50	s	219.00	-
14	REAR END REINFORCEMENT BAR Sect	14:	s	211.30	s	211.30	-
15	REAR END REINFORCEMENT SPONGE amld	9	\$	91.20	s	91.20	-
16	TAILLAMP LH COLCE	2	\$	480.30	\$	960.60	34
17	TAILLAMP PANEL PLY	2	s	135.00	s	270.00	X
18	END PANEL RENTED	4	s	685.00	\$ (	685.00	58

19 END PANEL INNER GARNISH 2	1	s	220.00	S	(220:00)
20 REAR FLOOR PANEL 14	- 1	\$	920.00	\$	920.00
21 REAR FLOOR PANEL TOP BOARD XHC	1	\$	280.00	s	280.00
368191	TOTA	L PRIC	Œ	\$	6,562.46
776143	LESS	25%	5% \$ 1.640	S	1.640.62
110 -	SUB 1	TOTAL	PRICE	\$	4,921.85

SPECIAL NETT ITEMS

S/N	DESCRIPTION QTY UNI	UNIT S/NETT		TOTAL S/NETT		
1	REAR NUMBER PLATE NO W	1	s	50.00	s	50.00
2	REAR BUMPER CLIPS(SET)	31	s	20.00	s	20.00
3	REAR END PANEL INAULATOR SEAL New	1	\$	120.00	s	120,00
4	REAR END PANEL INNER GARNISH CLIPS (1 SET)	1	\$	30.00	s	3 <del>0.00</del>
5	REAR FLOOR PANEL INAULATOR SEAL M	.1	\$	150.00	s	150.00
6	REVERSE SENSOR Dannyed	1	s	220.00	s	220.00
	290	)	TOTA	AL	s	540.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING ( REAR)

PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1.80000 850
TO SPRAY PAINT AFFECTED AREA	\$ 1,800,00 800
3 TUFF COAT	\$ 25900 60
WIRING CHECK	\$ 100,00 30
REMOVE AND REFIX BOOTLID MNECHANISM	\$ 120.90 60
REMOVE AND REFIX REVERSE SENSOR	\$ 100,00 50

TOTAL

\$4,170.00

### ESTIMATE REPORT

TOTAL PARTS COST LKK Auto Consultants beace agrify the Repairer of the following:

To resurvey heteretather spray painting TOTAL LABOUR COST To display damaged cart(s) during res. . Third party survey is on a "Althout Prejudice" basis. TOTAL REPAIR COST. SupSementary ments on 9,631,85 eyed and

APPROVED DETAILS
Acknowledged by Repairer Signature:

is subject to final approval from Insurance Company

Adrian Li total: 485143 L/s 02/10/19 4/5.3850 06 Days

9681.84

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM : NO OF DAYS

23

### LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25. Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

D19MTPV01008091

Engine No:

Odometer:

Chassis No:

CS/SMO19017257/AQF3N2

3ZZ4931518

129338 km

MR053ZEE106154983

Date:

18/11/2019

REFERENCE

Date of Loss:

Handling Insurer:

Sompo Insurance Singapore Pte.

Ltd.

Claimant Vehicle No:

SJS8412Z

30/09/2019

Policy No:

Insured Vehicle

No:

Nature of Claim: TP

SGS3110M

Claim No:

CMTD1904570

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SJS8412Z

Make & Model: Reg. Date:

TOYOTA COROLLA ALTIS, 1.6 (A)

10/09/2009 (Man. Year: 2009)

Blue

Colour: **Engine Capacity:** 

1598 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side: Front Right Side: 195/65 R15 Yokohama 6 mm Yokohama 6 mm Rear Tyre Size: Rear Left Side:

195/65 R15 Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,511.84	3,090.43	2,421.41	43.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	1,800.00	2,370.00	56.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,681.84	4,890.43	4,791.41	49.49
Approved Total (Overridden) (S\$)		3,850.00	90.43 4,791.41 50.00	
(S\$)	9,681.84	3,850.00	5,831.84	60.23
+ GST 7.00/7.00% (S\$)	677.73	269.50	408.23	60.23
Nett Amount (S\$)	10,359.57	4,119.50	6,240.07	60.23

INSPECTION

Date of Assignment:

01/10/2019

Date Inspected:

02/10/2019 Inspected At:

MG Solution Pte Ltd (HQ)

23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre

Singapore 415933

Estimated Period of Repair:

6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Reference

# REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Nov 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJS8412Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Re	com	me	nde	ed Parts
Ma	Otto	Dart	No	Particulars

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	844.75 FL	*755.00 FL
2	1		*BOOTLID LOGO	Necessary	80.00 FL	*55.00 FL
3	1		*BOOTLID 1.6 EMBLEM	Necessary	52.00 FL	*52.00 FL
4	1		*BOOTLID COROLLA EMBLEM	Necessary	45.57 FL	*45.57 FL
5	1		*BOOTLID ALTIS EMBLEM	Necessary	44.17 FL	*44.17 FL
6	1		*BOOTLID LX EMBLEM	Necessary	44.17 FL	*44.17 FL
7	1		*BOOTLID LOCK	Damaged	189.20 FL	*189.20 FL
8	1		*BOOTLID WEATHERSTRIP	Cut	211.30 FL	*211.30 FL
9	1		*REAR BUMPER	Deformed	598.60 FL	*524.00 FL
10	2		*REAR BUMPER REFLECTOR	Not Necessary	170.60 FL	*-FL
11	2		*REAR BUMPER BRACKET	Dented	206.00 FL	*206.00 FL
12	2		*REAR BUMPER RH SIDE RETAINER (FRONT)	Not Necessary	219.00 FL	*-FL
13	2		*REAR BUMPER RH SIDE RETAINER (LOWER)	Necessary	219.00 FL	*219.00 FL
14	1		*REAR END REINFORCEMENT BAR	Bent	211.30 FL	*211.30 FL
15	1		*REAR END REINFORCEMENT SPONGE	Cracked	91.20 FL	*91.20 FL
16	1		*TAILLAMP	N/s Cracked	960.60 FL	*342.00 FL
17	2		*TAILLAMP PANEL	Repair	270.00 FL	*-FL
18	1		*END PANEL	Dented	685.00 FL	*585.00 FL
19	1		*END PANEL INNER GARNISH	Deformed	220.00 FL	*159.00 FL
20	1		*REAR FLOOR PANEL	Repair	920.00 FL	*-FL
21	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	280.00 FL	*-FL
22	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*-FS
23	1		*SET REAR BUMPER CLIPS	Necessary	20.00 FS	*20.00 FS
24	1		*REAR END PANEL INSULATOR SEAL	Necessary	120.00 FS	*60.00 FS
25	1		*SET REAR END PANEL INNER GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
26	1		*REAR FLOOR PANEL INSULATOR SEAL	Not Necessary	150.00 FS	*-FS
27	1	6-6-4	*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
r=rtt	anchise	part a=apci	Nett. L=ListItemDisc.		02022022	41224124
	Sub Total (S\$) - List Item Discount on L Items 25.00/25.00% (S\$)					<b>4,023.91</b> 933.48
				Total Parts (S\$)	5,511.84	3,090.43

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,800.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	100,00	30.00
5	REMOVE AND REFIX BOOTLID MECHANISM	New	120.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR	New	100.00	50.00
	Gross Labo	Gross Labour Cost (S\$)		1,800.00
	Report was unsubmitted dur	ing this print-out.		

< END OF ESTIMATES >