

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKZ 176J
Vehicle Model : HONDA VEZEL
Accident Date : 26.09.2019
Original Reg Date : 05.01.2016

Date : 30.09.2019
Chassis : RU31115657
TP Ins. **AIG**

ESTIMATE

1	1 pc	Tailgate		bt	1,685.50
2	1 pc	Tailgate Outer Garnish		x	290.00
3	1 set	Tailgate Outer Garnish Clip		x	40.00
4	1 pc	Tailgate Badge		net	56.00
5	1 pc	Tailgate Emblem VEZEL		net	80.00
6	1 pc	Tailgate Emblem HYBRID		net	96.20
7	2 pcs	Tailgate Lamps	285.00	cut	570.00
8	2 pcs	Tailgate Lamp Inner Sealer	38.00	net	76.00
9	2 pcs	Tailgate Lamp Clips	25.00	net	50.00
10	1 pc	Tailgate Inner Trim		cut	325.00
11	1 set	Tailgate Inner Trim Clips		net 10	30.00
12	1 pc	Tailgate Inner Lock		bt	340.30
13	1 pc	Tailgate Auto Lock Actuator		X	172.20
14	1 pc	Tailgate Lock Catch		X	56.00
15	1 pc	Tailgate Weatherstrip		cut	196.80
16	1 pc	Rear Windscreen Moulding		net	128.00
17	1 pc	Rear Windscreen Inner Seal		net	60.00
18	1 pc	Rear Bumper		de	1,185.00
19	2 pcs	Rear Bumper Side Retainers LH-net, RH-X	46.00		92.00
20	2 pcs	Rear Bumper Attachment Retainers LH-net, RH-X	42.00		84.00
21	1 set	Rear Bumper Clips		30 net	50.00
22	2 pcs	Rear Bumper Side Pad LH-de, RH-X	289.50	Rx	579.00
23	1 pc	Rear Bumper Lower Cover		de	196.00
24	1 set	Rear Bumper Lower Cover Clip		net	30.00
25	1 pc	Spare Tyre Panel Top Board		x	381.00
26	1 pc	Spare Tyre Panel Top Tool Tray		cut	351.00
27	2 pcs	Taillamps	680.00	at	1,360.00
28	2 pcs	Taillamps Inner Sealer	38.00	net	76.00
29	2 sets	Taillamps Clips	25.00	net	50.00
30	1 pc	End Panel		bt	695.50
31	1 pc	End Panel Top Trim		de	176.00
32	1 set	End Panel Top Trim Clips		net 10	30.00

C/D

9,587.50

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SKZ 176J

B/F

9,587.50

1	1 pc	Alarm Sensor Speaker		<i>200</i> 150.00
2	1 pc	Rear Key Antenna Sensor		<i>8</i> 175.00
3	2 pcs	Rear Fender Inner Trim	335.00	<i>x</i> 670.00
4	1 set	Rear Fender Inner Trim Clip		<i>x</i> 30.00

10,612.50

Less 20% 2,122.50

8,490.00

Special Nett

1	1 pc	Rear Windscreen Sealant	<i>net</i>	60.00
2	1 set	Body Panel Joint Sealant		<i>40</i> 120.00
3	1 set	Rear Camera	<i>x</i>	450.00
4	1 set	Reverse Sensor	<i>200</i>	<i>net</i> 250.00

Labour charge

Panel Beating	<i>600.</i>	1,000.00
Spray painting	<i>700.</i>	1,000.00
Check Wiring	<i>30.</i>	50.00
Anti rust	<i>30.</i>	100.00
Remove and install rear winscreen.	<i>120.</i>	140.00
Remove and install tailgate parts.	<i>60.</i>	90.00
Remove and install carpet and seat.	<i>60.</i>	120.00
Remove and install rear exhaust.		<i>x</i> 120.00
Remove and install reverse camera	<i>30</i>	120.00
Remove and install reverse sensor	<i>30.</i>	90.00

12,200.00

Less 20% 2,440.00

Lump sum 9,760.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Taufik 97495449
- WP
01/10/19 @ 12pm
Lump sum
Resurvey after repair
5 days
taufik@lkhauto.com
sur@lkhauto.com