

ASS. REC. BY:

REF

CS/C7219017261/uf3n2

Special Instructions:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): ong chin kat

of 011

Date/Time: 1.10.19 14.28 p.m.

~~Estimated Cost:~~

Bill for

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: **686 8656E**

Insured: CB FAIRZ

at Workshop m/s Euro Success

Tel: 9828 9277

of 1 Kanki Bulok Ave 6 # 02-03

Policy No. DM BLSN173457/9022

Claim No: SNM1902045J2C02

Sum Insured:

Figure 1

Make of Veh:

D.O.A. 29.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2.10.19 2.39 p.m

Person Contacted

Ah Huat

Vehicle ☒ IN ☐ OUT[illegible]

(08/11/13) wef
ASS. REC. BY: *Marcus*

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *GBE8686E*
at Workshop m/s *Euro*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

N/S	O/S

48k.

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

190m

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

GBE8686E

Yr Regn:

416

cm

Toyota hiace

white

180746

KDH 201 018797K

Good

In order

In order

Nil

195 R 15

6

6

28/9/19

1/10/19

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

RECEIVED 30 OCT 2019

Date/Time, File Pass to?

28/10/19

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

_____ \$ + RS _____ \$

_____ \$ Photos

_____ \$ Others

_____ \$

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$ _____)

MEP-TI

9000

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Oct 2019		01 Oct 2019 14:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	K T TRANSPORT SERVICES , Co. Reg. No.: 53083215A								
Main Claimant:	SHENGDE TRADING PTE LTD , Co. Reg. No.: 201116190M								
Vehicle Reg. No.:	GBE8656E	Date of Loss:	28/09/2019 11:00 - :59 [41 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D204572C02	Policy/Cover Note No.:	DMB1SN17345719022						
Vehicle Reg. No. (Insured):	C87913Z	Policy No. (Claimant):	DMCPHQ19-001991						
		Excess:	S\$1,000.00						
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Claimant's Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/10/2019]								
Driver/Custodian (Insured):	YEO KEK HOCK (64 / Male), NRIC: S1124974D Email:								
Adj Asg. Remarks:	please assign Marcus Chua for SJE. thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal Coe Honda Fit 1.3A G



2.88% P.A \$0 Down, \$0 Admin,
Monthly Fm \$438, Sta "B" 2 Yrs
Warranty Engine
GV Credit Pte Ltd StarAd



Browse by Category:

• Back (1 2) Next •

Sort by Date Posted

20 results/page

25 vehicles

hiace

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	hiace		Any	Any	2016	Any	Any	Any	Available
	Toyota	Hiace 3.0A	\$52,500	\$7,700 /yr	27-Jul-2016	2,982 cc	45,000 km	Van	Available
Fuel Type: Diesel Very Nicely Freshly Out From Oven Candy Red Iron Man Color! Using Top Quality PPG Lacquer. Well Taken Car By Owner. Selling Due T... Posted: 30-Sep-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0A Super GL	\$66,800	\$10,270 /yr	13-Jun-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel 100% Loan Available! Instalment As Low As \$1019 Monthly, Z20 Ready Toyota Hiace Super GL Mid Roof With Modelista Kit! 13+1 Seate... Car (S) Pte Ltd Posted: 30-Sep-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0A DX	\$63,800	\$8,870 /yr	09-Dec-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel 1 Careful Owner! Full Accessories! Good Condition! View To Believe! Call Now Before It's Gone! Net Link Partners Pte Ltd Posted: 30-Sep-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0M DX	\$47,800	\$6,920 /yr	29-Aug-2016	2,982 cc	30,000 km	Van	Available
Fuel Type: Diesel Shocking Low KM. Very Underutilized 5 Door Van. 1 Owner. No Good Was Carried By Previous Owner. Interior Like New. New Paintwork... Posted: 28-Sep-2019 Tags: 2016 Toyota hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hi-Roof Modelista Front Grill							
Brand New Hi Roof Modelista Front Grill For sale. More info about this product									
	Toyota	Hiace 3.0A Super GL	\$64,500	\$9,530 /yr	07-Jul-2016	2,982 cc	-	Bus	Available
Fuel Type: Diesel Can Convert To Private Bus, Excursion Bus And Private Hire Bus No Problem. Luxury Seat, Customer Sell Due To No Driver Driving The C... ABWIN Bus Pte Ltd Posted: 27-Sep-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota	Hiace 3.0M DX	\$51,800	\$7,620 /yr	18-Jul-2016	2,982 cc	-	Van	Available
Fuel Type: Diesel Rare Sport Model Unit That Comes With Rear Aircon! Very Well Maintained, Confirm A Hassle Free Unit You Can Consider! You Really Ha... ABWIN Bus Pte Ltd Posted: 27-Sep-2019 Tags: 2016 Toyota Hiace, 2016 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 190M

Vehicle Details

Vehicle No.: GBE8656E

Vehicle to be Exported: No

Intended Deregistration Date: 01 Oct 2019

Vehicle Make: TOYOTA

Vehicle Model: REGIUS ACE 3.0DX A

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 1KD2583282

Chassis No.: KDH2010187974

Maximum Power Output: -

Open Market Value: \$31,837.00

Original Registration Date: 12 Apr 2016

First Registration Date: 12 Apr 2016

Transfer Count: 0

Actual ARF Paid: \$1,592.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 Apr 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$34,391.00

COE Rebate Amount: \$22,449.00

Total Rebate Amount: \$22,449.00

The information contained herein is correct as at 01 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	30/09/2019 16:44
Date Of Accident	28/09/2019 11:30
Exact Location Of Accident	DEFU LANE 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBE8656E
Insured/Policyholder	
Name Of Registered Owner	SHENGDE TRADING PTE LTD
Co Reg No	201116190M
Email Address	XDETOX32@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-92370354
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ19-001991
Cover Note Number	
Driver	
Name of Driver	WONG KAI KWEE
NRIC No	S1517312B
Date Of Birth	29/04/1962
Occupation	INDOOR
Date Of Driving Pass	10/10/1987
Driving Experience	31 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88161316
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 424 HOUGANG AVE 6 #02-84
Postcode	530424
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE ABOVE STATED DATE AND TIME, I WAS TRAVELING ALONG DEFU LANE AVENUE 1. I WAS TRAVELING STRAIGHT WHEN SUDDENLY VEHICLE B CAME OUT FROM DEFU LANE 10 AND COLLIDED ONTO MY VEHICLE FRONT AND REAR LEFT PORTION. VEHICLE B WROTE A BLACK AND WHITE STATEMENT SAYING THAT ITS HIS FAULT. ON TOP OF THE DURING THE IMPACT MY VEHICLE SWIRL TO THE RIGHT AND COLLIDED ON THE CURB.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camers?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB7913Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	97600928
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

*We deliver the ongoing partnership with us in every respect.



2000

Driver's Signature: _____
 (If driver is not the police officer)
 Date & Time: _____



Reporting Centre Personnel's Signature: _____
 Date: _____
 Initials: _____







EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: GBE8656E

Model: TOYOTA HIACE

not Authorized
1/10/19
The price after rep-
4/5 @ 9000
11 day.

QTY	List Items	Price \$
1	FRONT R/H UPPER ARM	11 489.62 X
1	FRONT R/H LOWER ARM	11 599.84 X
1	FRONT R/H STAY BAR	11 236.65 X
1	FRONT R/H SHOCK ABSORBER	11 288.64 X
1	FRONT R/H KNUCKLE ARM	11 589.64 X
1	FRONT R/H KNUCKLE ARM WHEEL BEARING	11 278.56 X
1	REAR L/H FENDER	Sody 1489.96
1	REAR L/H FENDER INNER BOARD	11 305.50 X
1	REAR L/H FENDER INNER PANEL	11 759.84 X
1	REAR L/H FENDER CENTRE PILLAR	Bod 699.65
1	REAR L/H FENDER RAILTRACK TOP	11 300.60 X
1	REAR L/H FENDER RAILTRACK CTR	11 380.80 X
1	REAR L/H FENDER RAILTRACK BTM	11 400.80 X
1	REAR L/H FENDER GLASS	Shat 988.57
1	REAR L/H FENDER GLASS MOULDING	NS 126.64 X
1	REAR L/H SHOCK ABSORBER	11 279.94
1	REAR AXEL Axle beam	3005.10
1	REAR L/H SHAFT	611.50
1	REAR L/H SLIDING DOOR	Sody 1570.86
1	REAR L/H SLIDING DOOR ROLLER CTR	11 409.84
1	REAR L/H SLIDING DOOR ROLLER TOP	11 196.18 X
1	REAR L/H SLIDING DOOR ROLLER BTM	11 298.84 X
1	REAR L/H SLIDING DOOR RUBBER	11 218.18
1	REAR L/H SLIDING DOOR INNER BOARD	oe/nerp 318.18
1	REAR L/H SLIDING DOOR OUTER HANDLE	11 88.89 X
1	REAR L/H SLIDING DOOR INNER HANDLE	11 98.18 X
1	REAR L/H SLIDING DOOR INNER LOCK	11 356.62
1	REAR L/H SLIDING DOOR INNER SENSOR	NS 303.30 X
1	REAR L/H SLIDING DOOR CENTRE LOCK MOTOR	clutd/ 418.18
1	REAR L/H SLIDING DOOR GLASS	Shat 909.86
1	REAR L/H SLIDING DOOR GLASS MOULDING	NS 133.36 X
1	REAR LONG SHAFT	NS 1818.64 X
1	REAR L/H SPRING	11 1618.18 X
1	REAR L/H WHEEL BEARING	Day 326.26

TOTAL \$23,329.16
LESS 25% \$5,832.29
TOTAL \$17,496.87

11370.77
2572
P. 852807
S.N 290.00
L- 2440.00
1128807
257
9006-86

<u>Specia Nett Items</u>		
1	FRONT R/H TYRE	11 250.00 X
1	FRONT R/H RIM	11 400.00 X
1	FRONT R/H TYRE HUBCAGE	11 180.00 X
10	REAR L/H FENDER INNER BOARD CLIP @3	11 30.00 ✓
1	REAR L/H FENDER GLASS SEALANT	11 100.00 40
1	REAR L/H TYRE	11 250.00 X
1	REAR L/H RIM	11 400.00 X
1	REAR L/H TYRE HUBCAGE	11 180.00 ✓
1	REAR L/H SLIDING DOOR GLASS SEALANT	11 100.00 40
1 TIN	GEAR OIL	11 50.00 X
1 TIN	BRAKE OIL	11 50.00 X
TOTAL		\$1,990.00 290

<u>Labour Charges</u>		
TOWING		150.00 50
TO TRANSFER SIDEDOOR MECHANISM AND WIRING		200.00 50
TO REMOVE AND REFIX L/H FENDER AND L/H GLASS DOOR		300.00 200
TO APPLY UNDERCOATING ON ACCIDENT PARTS		450.00 80
TO CONDUCT WATER LEAKAGE TEST		11 100.00 X
TO REMOVE & REFIX REAR AXLE, SPRING & LONG SHAFT		450.00 300
TO REMOVE & REFIX ROOF, SEAT & CARPET		11 400.00 X
TO RE-ALIGN ALL WHEEL		250.00 60
TO RESPRAY PAINT ON ACCIDENT PARTS		1800.00 700
TO PANEL BEAT, WORKMANSHIP, REMOVE AND REPLACING ABOVE PARTS		2500.00 1000
		\$6,600.00 2440

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$26,086.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after repair painting
- To display damaged parts during resurvey
- Parts must be subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119017261/UQF3N2

Date: 31/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN17345719022		
Claimant Vehicle No :	GBE8656E	Insured Vehicle No :	CB7913Z		
Date of Loss:	28/09/2019	Nature of Claim:	TP	Claim No:	SNM19D204572C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE8656E	Engine No:	1KD2583282
Make & Model:	TOYOTA HIACE, 3.0 (A)	Chassis No:	KDH2010187974
Reg. Date:	12/04/2016 (Man. Year: 2016)	Odometer:	180746 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,486.87	8,818.08	10,668.79	54.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,600.00	2,440.00	4,160.00	63.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,086.87	11,258.08	14,828.79	56.84
Approved Total (Overridden) (S\$)		9,000.00		
Nett Amount (S\$)	26,086.87	9,000.00	17,086.87	65.50

INSPECTION

Date of Assignment:	01/10/2019	
Date Inspected:	01/10/2019	Inspected At: Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883
Estimated Period of Repair:	11.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Oct 2019)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE8656E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT R/H UPPER ARM	Not Necessary	489.62 FL	*- FL
2	1		*FRONT R/H LOWER ARM	Not Necessary	599.84 FL	*- FL
3	1		*FRONT R/H STAY BAR	Not Necessary	236.65 FL	*- FL
4	1		*FRONT R/H SHOCK ABSORBER	Not Necessary	288.64 FL	*- FL
5	1		*FRONT R/H KNUCKLE ARM	Not Necessary	589.64 FL	*- FL
6	1		*FRONT R/H KNUCKLE ARM WHEEL BEARING	Not Necessary	278.56 FL	*- FL
7	1		*REAR L/H FENDER	Badly Dented	1,489.96 FL	*1,489.96 FL
8	1		*REAR L/H FENDER INNER BOARD	Not Necessary	305.50 FL	*- FL
9	1		*REAR L/H FENDER INNER PANEL	Repair	759.84 FL	*- FL
10	1		*REAR L/H FENDER CENTRE PILLAR	Badly Dented	699.65 FL	*699.65 FL
11	1		*REAR L/H FENDER RAILTRACK TOP	Not Necessary	300.60 FL	*- FL
12	1		*REAR L/H FENDER RAILTRACK CTR	Not Necessary	380.80 FL	*- FL
13	1		*REAR L/H FENDER RAILTRACK BTM	Not Necessary	400.80 FL	*- FL
14	1		*REAR L/H FENDER GLASS	Shattered	988.57 FL	*988.57 FL
15	1		*REAR L/H FENDER GLASS MOULDING	No such part	126.64 FL	*- FL
16	1		*REAR L/H SHOCK ABSORBER	Twisted	279.94 FL	*169.75 FL
17	1		*REAR AXLE BEAM	Bent/Twisted	4,563.84 FL	*3,005.10 FL
18	1		*REAR L/H SHAFT	Bent	1,466.52 FL	*611.50 FL
19	1		*REAR L/H SLIDING DOOR	Badly Dented	1,570.86 FL	*1,570.86 FL
20	1		*REAR L/H SLIDING DOOR ROLLER CTR	Twisted/Jammed	409.84 FL	*288.10 FL
21	1		*REAR L/H SLIDING DOOR ROLLER TOP	Not Necessary	196.18 FL	*- FL
22	1		*REAR L/H SLIDING DOOR ROLLER BTM	Not Necessary	298.84 FL	*- FL
23	1		*REAR L/H SLIDING DOOR RUBBER	Torn	218.18 FL	*218.18 FL
24	1		*REAR L/H SLIDING DOOR INNER BOARD	Deformed/Warped	318.18 FL	*318.18 FL
25	1		*REAR L/H SLIDING DOOR OUTER HANDLE	Not Necessary	88.89 FL	*- FL
26	1		*REAR L/H SLIDING DOOR INNER HANDLE	Not Necessary	98.18 FL	*- FL
27	1		*REAR L/H SLIDING DOOR INNER LOCK	Twisted	356.62 FL	*356.62 FL
28	1		*REAR L/H SLIDING DOOR INNER SENSOR	No such part	303.30 FL	*- FL
29	1		*REAR L/H SLIDING DOOR CENTRE LOCK MOTOR	Shorted/Jammed	418.18 FL	*418.18 FL
30	1		*REAR L/H SLIDING DOOR GLASS	Shattered	909.86 FL	*909.86 FL
31	1		*REAR L/H SLIDING DOOR GLASS MOULDING	No such part	133.36 FL	*- FL
32	1		*REAR LONG SHAFT	No such part	1,818.64 FL	*- FL
33	1		*REAR L/H SPRING	Not Necessary	1,618.18 FL	*- FL
34	1		*REAR L/H WHEEL BEARING	Damaged	326.26 FL	*326.26 FL
35	1		*FRONT R/H TYRE	Not Necessary	250.00 FS	*- FS
36	1		*FRONT R/H RIM	Not Necessary	400.00 FS	*- FS
37	1		*FRONT R/H TYRE HUBCAGE	Not Necessary	180.00 FS	*- FS
38	10		*REAR L/H FENDER INNER BOARD CLIP	Necessary	30.00 FS	*30.00 FS
39	1		*REAR L/H FENDER GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
40	1		*REAR L/H TYRE	Serviceable	250.00 FS	*- FS
41	1		*REAR L/H RIM	Serviceable	400.00 FS	*- FS
42	1		*REAR L/H TYRE HUBCAGE	Cut	180.00 FS	*180.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR L/H SLIDING DOOR GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
44	1		*TIN GEAR OIL	Not Necessary	50.00 FS	*- FS
45	1		*TIN BRAKE OIL	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					25,319.16	11,660.77
- List Item Discount on L Items 25.00/25.00% (\$\$)					5,832.29	2,842.69
Total Parts (\$\$)					19,486.87	8,818.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	150.00	50.00
2	TO TRANSFER SIDEDOOR MECHANISM AND WIRING	New	200.00	50.00
3	TO REMOVE AND REFIX L/H FENDER AND L/H GLASS DOOR	New	300.00	200.00
4	TO APPLY UNDERCOATING ON ACCIDENT PARTS	New	450.00	80.00
5	TO CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
6	TO REMOVE & REFIX REAR AXLE, SPRING & LONG SHAFT	New	450.00	300.00
7	TO REMOVE & REFIX ROOF, SEAT & CARPET	New	400.00	0.00
8	TO RE-ALIGN ALL WHEEL	New	250.00	60.00
9	TO RESPRAY PAINT ON ACCIDENT PARTS	New	1,800.00	700.00
10	TO PANEL BEAT, WORKMANSHIP, REMOVE AND REPLACING ABOVE PARTS	New	2,500.00	1,000.00
Gross Labour Cost (S\$)			6,600.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >