

ASS. REC. BY:

REF:

CS/Fc219019265/123 f3n2

Special Instructions:

Surveyor: Taufiq

ASSIGNMENT (Office)

From (Person): Minna ching San san of FC1

Date/Time: 30.9.19 5:4p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDD 1663L

Insured: SHA 8056 L

at Workshop m/s Performana

Tel: 63190174

of 303 Alexandra Road

Policy No:

Claim No: A9006239 MF54

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 1.10.19 2.45p.m

Person Contacted:

Caroline

H.O.D. Endorsement:

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 8056 L
	SDD 1663 L CC31R26W0138891R2CD3 Reg. CC10512/19
02/11/19 @ 16:24 pm	revised PA to moving via email.

ASS. REC. BY:

Tang

REF: FC1

ASSIGNMENT

Front

Date

5.11.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDD 1663L

at Workshop n/s Performance

of 303 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SDD 1663L

Yr Regn: 2017 April

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X3

c.c.

1997

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

37085

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBH WY9 202.00799898

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45 R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

5/11/19 @ 405pm

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/11/19

Rasul Confirmed P/P \$ 1,982.40 @ 3 days with Sharon
(\$ 788.15 Red - 28%)

RECEIVED 22 NOV 2019

21/11/2019

Date/Time, File Pass to?

22/11/19

1)

Type 4

Date/Time, File Return to?

2)

Rep. Form

Lump Sum P/P

\$ 1,982.40 P/P

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Wheel end (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

110

50

50

18

228



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006239MFSH

Date: 07 November 2019

Our Ref: CS/FCI19017265/T1sf3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SDD 1663L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/11/2019 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S\$ 2,762.15
Revised Estimate Amount	: S\$ 1,934.00
"Check" Items Amount	: S\$ 80.00
Market Value	: S\$ -
LTA Reimbursement Value	: S\$ -
Nett Value	: S\$ -

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 days

Yours faithfully

Mohamad Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	30-09-2019	Our Ref No. D19006239MFSH
Accident Date	27-09-2019	Claim Type. Third Party
Insured Vehicle	SHA8056L	Third Party Vehicle. SDD1663L
Survey Location	303 ALEXANDRA ROAD SIME DARBY PERFORMANCE CENTRE	
Contact Person.	CAROLINE	
Contact No.	63190174/ 0	Fax No. 64794601
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PERFORMANCE MOTORS LIMITED	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 22 November 2019 9:01 am
To: Sharon Heng L K
Cc: Toh Jing Xuan; Bernard Wan Chong Huat
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SDD1663L

Dear Sharon,

Confirmed final fig \$ 1,982.40 @ 3 day of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>

Sent: Wednesday, 20 November 2019 3:51 pm

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>; Bernard Wan Chong Huat <bernard.wan@simedarby.com.sg>

Subject: DIRECT SETTLEMENT FINAL REPORT - SDD1663L

Dear Taufikh

For your perusal :

Labor	\$1974.00
Parts	\$ 8.40
Total	\$1982.40

Owner is claiming CAR RENTAL - \$256.80 (2 DAYS).

Note : 3 working days.

Please reply me directly.

Best Regards

Sharon Heng

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 7 November 2019 4:24 pm
To: 'Merina Chia'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19006239MFSH/1
Attachments: PRELI ADVISE - SDD 1663L.pdf

Dear Merina,

Enclosed preliminary revised of vehicle SDD 1663L

Thank you,

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 1 October 2019 3:02 pm
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006239MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Monday, 30 September, 2019 5:41 PM

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197461339W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63445773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

30 SEP 2019

ESTIMATE

Estimate No. : b1 52894
Date Estimated : 28/09/2019
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Chiong Chow Joo
53 Hillview Avenue
#09-05 Hillington Green

Singapore 669566

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD1663L	WBAWY920200R99898	21/04/2017	X3 sDrive20	0

DESCRIPTION

To remove and install rear bumper and attachment include knocking cause by the accident

VALUE
85 1,275.00

Painting rear bumper

43 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

15 177.00

Sundries.

40 80.00

Total Labour 1: 2,570.00

DESCRIPTION

RR BUMPER RH MOUNT

QTY	PRIC	VALUE
1	192.15	nn X 192.15

Total Parts : 192.15

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time: 5/11/19 04:30pm Excess \$: _____

Surveyor's Name: Tanjun Sign: [Signature]

Surveyor's Tel: 97443769 Authorised Yes / No

Authorised Date: 28/9/19 Time: _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail: Tanjun@pml.com.sg

Working Days Recommendation: 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Labour 1 by Repairer	:	2,570.00
Parts	:	192.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	193.35
Grand Total	:	2,955.50

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52894**
Date Estimated : **28/09/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Chiong Chow Joo
53 Hillview Avenue
#09-05 Hillington Green

Singapore 669566

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD1663L	WBAWY920200R998	21/04/2017	X3 sDrive20	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET BLACK	1.40	6.00	0	8.40 (A) NEL

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	8.40
Total Labour & Parts :	8.40



Final Report

Estimate No. : **b1 52894**
Date Estimated : **28/09/2019**
Prepared By : **Gary Poh Chai Hoon**

- ESTIMATE REPAIR FOR -

Chiong Chow Joo
53 Hillview Avenue
#09-05 Hillington Green

Singapore 669566

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDD1663L	WBAWY920200R998	21/04/2017	X3 sDrive20	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To remove and install rear bumper in order to carry out painting job.	850.00	0	850.00
To respray rear bumper.	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
Sundries.	40.00	0	40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET BLACK	1.40	6.00	0	8.40

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	8.40
Total Labour & Parts :	1,982.40
GST @7%:	138.77
Grand Total :	2,121.17

TO	DATE	REMARKS
TO	20/11/19	3

Taufiq
LKK

CAR RENTAL = \$256.80 (2 DAYS)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017265/T1s/f3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 22-11-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8056L	Veh. Inspected	SDD 1663L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006239MFSH	Excess (\$)	0.00	
Assign From	MERINA CHIA SAN SAN	Assign Date	30/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X3	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBAWY920200R99898	Colour	GREY	
Odometer	37085	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R19	PIRELLI	6 mm	
L/H Front Tyre	245/45 R19	PIRELLI	6 mm	
R/H Rear Tyre	245/45 R19	PIRELLI	6 mm	
L/H Rear Tyre	245/45 R19	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2019	Inspection Date	05/11/2019	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDD 1663L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	80.00	40.00
1	RR BUMPER RH MOUNT (SN)	NOT NECESSARY	192.15	-
6	EXPANDING RIVET BLACK (ADDITIONAL)(SN)	NECESSARY	8.40	8.40
			280.55	48.40
LABOUR				
	TO REMOVE AND INSTALL REAR BUMPER AND ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT.		1,275.00	850.00
	PAINTING REAR BUMPER.		1,038.00	934.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			2,490.00	1,934.00
GRAND TOTAL			2,770.55	1,982.40
RECOMMENDED COST OF REPAIRS				1,982.40

Report Ref No. CS/FCI19017265/T1sf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.