

LCRF Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 01/10/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH4117L
CHASSIS NO : JTDKB3FU303562133
MAKE / MODEL : Toyota Pirus Hybrid
DATE OF ACCIDENT : 26/09/2019
YOUR INSURED VEHICLE NUMBER : SLC6865Z
Mileage: 212321km

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1 Front support panel upper RH / DD.	1PC	\$ 76.10	\$ 76.10 /
2 Washer tank / CR4.	1PC	\$ 181.80	\$ 181.80 /
3 F/R fender apron seal Xsvc.	1PC	\$ 49.70	\$ 49.70 X
4 F/R fender 1/4 garnish / Mis.	1PC	\$ 80.00	\$ 80.00 65
5 RH side skirt / CRA	1PC	\$ 680.00	\$ 680.00 /
		LIST TOTAL S\$: \$	1,067.60 1,002.9
		25%DISCOUNT S\$: \$	266.90
		TOTAL S\$: \$	800.70
		7% GST \$	56.05
		GRAND TOTAL S\$: \$	856.75

P = 6,761.8
supp = 1,002.90
7,764.7
-25% 1,941.18
5,823.52
+ Labour 1430.
7253.52

\$ 7253.52

Parts 8,000.50
less 25% 2,000.12
6,000.37
Labr 1,430.00
7,430.37
Net

LCRF Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date: 01/10/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH4117L
CHASSIS NO : JTDKB3FU303562133
MAKE / MODEL : Toyota Pirus Hybrid
DATE OF ACCIDENT : 26/09/2019
YOUR INSURED VEHICLE NUMBER : SLC6865Z
Mileage: 212321km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1 F/R fender	1PC	\$ 933.10	\$ 933.10	/ CRU
2 F/R fender Hybrid emblem	1PC	\$ 52.30	\$ 52.30	/ Nec
3 F/R fender inner liner	1PC	\$ 194.30	\$ 194.30	/ CRU
4 Front bonnet	1PC	\$ 938.40	\$ 938.40	/ DP
5 Front bonnet insulator	1PC	\$ 393.30	\$ 393.30	
6 F/R headlamp	1PC	\$ 2,530.10	\$ 2,530.10	/ CRH
7 F/R headlamp retainer	1PC	\$ 33.20	\$ 33.20	/ CRH
8 Radiator grille	1PC	\$ 331.90	\$ 331.90	
9 Front bumper reinforcement	1PC	\$ 691.10	\$ 691.10	/ BT 520
10 Front bumper energy absorber	1PC	\$ 69.80	\$ 69.80	/ CRU
11 Front bumper	1PC	\$ 495.50	\$ 495.50	/ CRU
12 Front bumper RH side bracket	1PC	\$ 56.80	\$ 56.80	/ Nec
13 Front bumper RH tow cover	1PC	\$ 28.10	\$ 28.10	/ Mis
15 F/R fog lamp	1PC	\$ 910.20	\$ 910.20	/ Mis
<i>with front / BT</i>				
		LIST TOTAL S\$:	\$ 6,719.80	6,761.8
		25% DISCOUNT S\$:	\$ 1,679.95	1,690.45
			\$ 5,039.85	5,071.35

LABOUR CHARGES

1 To labour charge for removing out F/R fender, front bumper to facilitate replacement of damaged parts and include straightening support panel	\$ 900.00	
2 To respray front bonnet, front bumper, F/R fender and support panel (Pearl Paint)	\$ 1,000.00	700
3 To check lighting system	\$ 80.00	30
4 Towing fee	\$ 50.00	50.00
Repair day - 4 days 6 days.		
LABOUR TOTAL S\$:		\$ 2,030.00 1,430
TOTAL S\$:		\$ 7,069.85
7% GST		\$ 494.89
GRAND TOTAL S\$:		\$ 7,564.74

Sun Pin / 8661 2627
01/10/2019

~~Temp Sun P/P Repair~~
Resurvey ~~at~~ spray
Before.

TP without Prejudice.

LCRF Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
 Date: 01/10/2019
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLH4117L
 CHASSIS NO : JTDKB3FU303562133
 MAKE / MODEL : Toyota Pirus Hybrid
 DATE OF ACCIDENT : 26/09/2019
 YOUR INSURED VEHICLE NUMBER : SLC6865Z
 Mileage: 212321km

<u>PARTS DISCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1 F/R fender	1PC	\$ 933.10	\$ 933.10 CRU ✓	
2 F/R fender Hybrid emblem	1PC	\$ 52.30	\$ 52.30 Nec ✓	
3 F/R fender inner liner	1PC	\$ 194.30	\$ 194.30 cut ✓	
4 Front bonnet	1PC	\$ 938.40	\$ 938.40 DP ✓	
5 Front bonnet insulator	1PC	\$ 393.30	\$ 393.30 X	
6 F/R headlamp	1PC	\$ 2,530.10	\$ 2,530.10 CRH ✓	
7 F/R headlamp retainer	1PC	\$ 33.20	\$ 33.20 CRH ✓	
8 Radiator grille	1PC	\$ 331.90	\$ 331.90 X	
9 Front bumper reinforcement	1PC	\$ 691.10	\$ 691.10 BT 520	
10 Front bumper energy absorber	1PC	\$ 69.80	\$ 69.80 CRU ✓	
11 Front bumper	1PC	\$ 495.50	\$ 495.50 CRU ✓	
12 Front bumper RH side bracket	1PC	\$ 56.80	\$ 56.80 Nec ✓	
13 Front bumper RH tow cover	1PC	\$ 28.10	\$ 28.10 Mis. ✓	
15 F/R fog lamp	1PC	\$ 910.20	\$ 910.20 Mis. ✓	
		LIST TOTAL S\$: \$		6,719.80 6,932.90
		25% DISCOUNT S\$: \$		1,679.95
				\$ 5,039.85

LABOUR CHARGES

1 To labour charge for removing out F/R fender, front bumper to facilitate replacement of damaged parts and include starightening support panel	\$ 900.00	700
2 To respray front bonnet, front bumper, F/R fender and support panel (Pearl Paint)	\$ 1,000.00	700
3 To check lighting system	\$ 80.00	30
4 Towing fee	\$ 50.00	/Nec.
LABOUR TOTAL S\$: \$		2,030.00
TOTAL S\$: \$		7,069.85
7% GST \$		494.89
GRAND TOTAL S\$: \$		7,564.74

Repair day - 4 days
 Sun Pin / 8661 2627
 01/10/2019
 Lamp Sun P/P Repair
 Resurvey after spray
 Before

Supp Item
 1) Front RH headlamp top panel \$76.10
 2) Wiper washer tank 18.15
 3) Front RH fender 1/4 gloss
 4) RH side skirt
 5) Fender apron mudguard RH


TP without Prejudice.

Oi Sun Pin (LKK Auto)

From: Siak Tong Sim <siaktong@lioncityrentals.com.sg>
Sent: Thursday, 21 November, 2019 10:30 AM
To: Oi Sun Pin (LKK Auto)
Subject: Re: Final Bill: SLH4117L

Dear sir
Ok confirmed \$7,253.52/6days

Regards
S.T.Sim (65-97422188)
Manager
Accident Reporting Center
60 Jalan Lam Huat
#04-35/36 Carros Centre
Singapore 737869



On Thu, Nov 21, 2019 at 10:05 AM Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com> wrote:

Dear Mr Sim,

Kindly refer the finalize amount \$7253.52. Repair days 6 days (P/P repair, before gst).

If agree please reply ASAP.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)