

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SKW5336Y

No.	Qty	List Items
1	1	Rear bumper
2	1	Rear bumper LH reflector
3	1	Rear bumper LH inner side bracket
4	2	Rear bumper side retainer
5	2	Rear bumper corner retainer
6	1 set	Rear bumper clips
7	1	Rear boot lid
8	1	Rear boot outer handle garnish
9	1	Rear boot centre "TOYOTA" logo
10	1	Rear boot LH "VIOS" emblem
11	1	Rear boot RH "E" emblem
12	1	Rear boot top lock
13	1	Rear boot lower lock catch
14	1	Rear boot weatherstrip
15	1	LH taillamp panel
16	2	Taillamp
17	1	Rear end panel
18	1	Rear end panel top garnish

\$	Bu	451.60	✓
\$	Sn	92.90	X
\$	Bu	56.30	✓
\$	al/di	171.20	✓
\$		86.00	?
\$	mu	30.00	✓
\$	Bu	589.10	✓
\$	way	175.00	✓
\$	mu	48.10	✓
\$	mu	55.60	✓
\$	mu	45.30	✓
\$	nd	121.35	✓
\$	R	41.40	X
\$	Sn	176.80	X
\$		128.50	?
\$	Cal/cm	655.20	✓
\$		575.00	?
\$		211.40	?
\$		3,710.75	
Less 25%		\$ 927.69	
Total :		\$ 2,783.06	

Special Nett Items

19	1 set	Reverse sensors
20	1 set	Rear end panel sealant

\$	250.00	?
\$	50.00	?
Total :	\$ 300.00	

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.
2	To putty and spray Spray Paintings charges.
3	To check wirings and lightings.
4	To remove, refit reverses sensors.
5	To remove, refit rear boot lid fittings.
6	To remove, refit rear upholstery and attachments.
7	To supply and apply anti rust treatment

\$	1,000.00	?
\$	1,000.00	600
\$	40.00	200
\$	80.00	500
\$	80.00	500
\$	120.00	800
\$	80.00	?
Total :	\$ 2,400.00	

Total :	\$ 5,483.06
---------	-------------

LKK Auto Consultants hence notify the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: