

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398

Cecilia



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4367
Date Estimated : 30/09/2019
Prepared By : Andy Ooi Lee Keong

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -

Chur Siew Noi
84 Riverina Crescent

Singapore 518313

- ACCOUNT - 35

India Int'l Insurance Pte Ltd
64 Cecil Street #04/05
IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS9431M	WF05XXGCC5HR82332	12/10/2017	Foc 1.0 5Dr	0

DESCRIPTION

TO CONDUCT TP CLAIM-INDIA INT AGAINST SHC8325A.
DOA.28/08/19

SUNDRIES

LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN FRONT
BUMPER, FRONT FENDER LH, HEADLAMP LH, AND ALL
AFFECTED AREA.

LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, FRONT
FENDER LH, AND ALL AFFECTED AREA.

TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT
CODES, RESTORE ALL PROGRAMME MODULE. (NETT)

Resue
Hp 90010068
4 3 days 30 150.00
02/10/19 @ 1500 1200 1500.00
Repairing 1200 1500.00
before paint 600.00
Total Labour 1: 3,750.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB17757AJX	FRONT BUMPER <i>scr</i>	1	1,530.00	10.00	1,377.00
WAA					
F1EB17B635AB	BUMPER FRONT LOWER EXTENSION ? <i>Xscr</i>	1	360.00	10.00	324.00
C1BB8B262BA	FRONT EMBLEM (FORD OVAL) <i>na</i>	1	86.00	10.00	77.40
PBM51A16009A	LHF FENDER ASSY <i>bt</i>	1	562.00	10.00	505.80
G					
F1EB13006BF	HEADLAMP ASSY LH ? <i>Xscr</i>	1	2,893.00	10.00	2,603.70
Total Parts :					4,887.90

Labour 1	:	3,750.00
Parts	:	4,887.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	604.65
Grand Total	:	9,242.55

Customer Name & Signature / Company Stamp

Date

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

REGENT MOTORS

(A Division of Vantage Automotive Limited)
Co. Regs. No. 53055563L GST Regs. No. M2-0000551-1

305 Alexandra Road
Vantage Automotive Centre
Singapore 159942
Service Booking: 6477 7399
Parts: 6477 7420
Vantage 24-Hour Assist: 6473 8588
Fax: 6477 7300



FINALISATION REPORT

REPAIR ORDER NO. BG 153110	Date IN 08/10/2019 Payment Term 30 Days From Invoice Customer Service Advisor Chua Syahirul Syazwani Irwan	Invoice Number Invoice Date ?? Invoice By Chua Syahirul Syazwani Irwan	Page No. 1 of 1		
CUSTOMER INFORMATION Chur Siew Noi 84 Riverina Crescent Singapore 518313		INVOICE TO 35 India Int'l Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711			
REGISTRATION No. SLS9431M	CHASSIS No. WF05XXGCC5HR82332	STOCK No. 15617	REGISTRATION DATE 12/10/2017	MODEL Foc 1.0 5Dr	MILEAGE 70000

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM-INDIA INT AGAINST SHC8325A. DOA.28/08/19	0	0.00	0.00
	SUNDRIES	0	0.00	30.00
	LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN FRONT BUMPER, FRONT FENDER LH, HEADLAMP LH, AND ALL AFFECTED AREA.	0	0.00	1,200.00
	LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, FRONT FENDER LH, AND ALL AFFECTED AREA.	0	0.00	1,200.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE. (NETT)	2	0.00	600.00
724	TO CONDUCT FOUR WHEEL ALIGNMENT.	1	0.00	300.00
Sub-Total :				3,330.00

CODE	DESCRIPTION	UNITS	DISC %	NETT
C1B88B262BA	FRONT EMBLEM (FORD OVAL)	1	10.00	77.40
F1EB17757AJXWAA	FRONT BUMPER	1	10.00	1,377.00
PBM51A16009AG	LHF FENDER ASSY	1	10.00	505.80
Sub-Total :				1,960.20

Attending CSO : Syasya
Should you require further explanation, please reach me at 92782710

Service Packages	0.00	Total Labour/Parts/Service Package Charges	S\$	5,290.20
Labour Charges	3,330.00	Less Insurance Excess	S\$	0.00
Parts Charges	1,960.20	GST @ 7%	S\$	370.31
Lubricant/Misc	0.00	Invoice Total Amounts	S\$	5,660.51
		Less Deposit/Voucher	S\$	0.00
Computer generated invoice. No signature is required.		Amount Payable	S\$	5,660.51

All amounts are in Singapore Dollars.
Work was carried out subject to the Company's Terms and Conditions of Service.
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.
For credit purchases, interest @1% per month will be debited on overdue amounts.



Vantage Automotive Limited

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road Singapore 159942

Tel: 64777409 Fax: 64777398



Car Reg No: SLS9431M

RO Number: 153110

Date: 11/10/19

NO.	Supplementary / Check Items Parts	Part Number	Qty	U / Price	Disc %	Ext Price
1						
2						
3						
Parts Total:						\$0.00

NO.	Supplementary Labour Charges	Price
1	To conduct four wheel alignment.	\$300.00
Total Labour:		\$300.00
Total Parts & Labour:		\$300.00
GST @ 7%:		\$21.00
Grand Total:		\$321.00

Raised By Technician	Approved By CSA SYASYA	Acknowledge By Parts Assistant	BO Parts: Yes / No ETA: _____
-------------------------	----------------------------------	-----------------------------------	--------------------------------------

Measurement printout

Car standard measurement

Beissbarth © * ML 8 Easy

M * R- * A1R0 * OK * USER // 81 / C

Date: 11.10.2019 12:25:22



Version (program) v5.0b3201/v5.0b3201	Version (CCD) v5.0b3200	Version (target data) USER	Serial number C10000942	Last service 16.11.2018
--	----------------------------	-------------------------------	----------------------------	----------------------------

VANTAGE AUTOMOTIVES LIMITED
305 ALEXANDRA ROAD
SINGAPORE

Customer

Vehicle

Registration: SLS 9431 M
Odometer: 42064

Order

Vehicle: USER

FORD * FOCUS 1.6 * All except wagon * Production: 1998 - 2005

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-1°14'	-1°19' [-1°26'] +1°19'	-1°12'
	right	-2°05'		-2°00'
Cross Camber		+0°51'	[1°15']	+0°48'
Individual Toe	left	+0°10'	-0°04' [+0°12'] +0°05'	+0°11'
	right	+0°10'		+0°10'
Total Toe		+0°19'	-0°09' [+0°23'] +0°09'	+0°21'
Setback		+0°08'		+0°09'
Geometrical driving axis		+0°00'		
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+4°32'	-1°06' [+2°59'] +1°06'	+4°34'
	right	+4°10'		+4°11'
K.P.I. 20°	left	+5°45'		
	right	+5°13'		
Toe out on turns	left	-1°27'		
	right	-1°33'		
Camber	left	-0°42'	-1°19' [-0°32'] +1°19'	-0°45'
	right	-1°20'		-1°17'
Cross Camber		+0°38'	[1°15']	+0°31'
Individual Toe	left	-0°09'	-0°04' [+0°06'] +0°05'	+0°09'
	right	-0°09'		+0°08'
Total Toe		-0°17'	-0°09' [+0°12'] +0°09'	+0°18'
Setback		+0°21'		+0°09'
Included Angle 20°	left	+5°04'		
	right	+3°52'		