

INS. CASE OWNER:

ASSIGNMENT

Surveyor: STEVE

DOI: 30/09/2019

Date / Time: 30/09/2019

Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No.: GBB 9650E

Claim No.: SNM19D204639

Name of Insured: Song Meng Metal Works

Policy No.: _____

Insured Tel No.: _____ HP: _____

Make / Model: 1. DYNA

Excess Sec II :SS

D.O.A: 27/09/2019 15:15

Place of Accident: DEFU LANE 10 CAR PARK

Is driver the owner? (YES / NO)

Nature of Accident: _____

If NO, Driver Name / Age: _____

Driver Tel No.: _____

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHD 6462U

INSRS:
WSP: SMRT, WL
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	10/10/19 - vic
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☐
	LOD	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐
10/10/19	SHD 6462U - CC3/AIG13004343/R1v1b3q2; DOA:28.2.13 GBB 9650E - CS3/CTI19009293/Gcd3e2; DOA:20.5.19 PLUS RECOVERED. OI REPORTED HE RECOVERED OUT FROM C/P LOT WHEN TP ALSO RECOVERED TO PARK ON THE BEHIND C/P LOT. TP REPORTED HE WAS STATIONARILY. SEND LETTER TO OI TO NOTIFY TP CLAIM & NCD ISSUES. TO GET TP EVIDENCE. MINUSSED REPORT DONE TP LOD IN BY EMAIL 21/01/2020 EMAIL TP & REQUEST FOR EVIDENCE TP NO EVIDENCE. 02/02/2020 SEND 1ST OFFER TO TP 10/02/2020 TP ACCEPTED OFFER. ALL DONE IN OKBOL. TO CLOSE.	
PRELIMINARY ADVICE	Date/Time: 02/10/19	Sent By: AS
FINALIZATION	Date/Time: _____	Confirm with: _____
Repair Cost: P/P	SS 2,480.36 (3 days) Reduction: 79 %	Confirm by: _____
FINAL SETTLEMENT	Date/Time: 10/02/20	Confirm with: LTB GOR NIL
Final Liability:	% 50 (Agreed / Assessed) BOLA S/N No.:	
Repair Cost:	\$2,480.36 SS 1,240.18	
Loss of Rental (LOR):	\$294.25 (5 days) x \$117.70	
Loss of Use (LOU):	SS - (\$ x days)	
Loss of Income (LOI):	\$100.00 (\$60 x 5 days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒	[Tick only one]	
GIA/LTA Search	\$7.00 SS 7.00	
Medical:	SS -	
Disbursement:	SS - (e.g. Tow/ Independent)	
Legal Cost:	SS -	
Total: \$3,575.86	SS 1,691.43	Global Sum SS: 1,690.00
FINAL PAYMENT	Date/Time: _____	Confirm with: _____
Payee 1:	SS 1,690.00	Name 1: SMRT TAXI PTE LTD
Payee 2: (Strike if N.A.)	SS -	Name 2: -
Payee 3: (Strike if N.A.)	SS -	Name 3: -

COPY SENT
11/1/2020

China Taiping.

Steve.

ASSIGNMENT

Form

Date:

30.9.2019

Engine No:

CD / TP / WS / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 6462 U

at Workshop no: SMRT

of

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Est. or Market Value:

D.O. Accident Report: Consistent? : Yes or No

G/A / PR. Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Turn Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

up'

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHD 6462 U

of Regn: 19/Dec/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Toyota Prius 4.

C.G. 1798

Colour: Maroon.

A/C: Insured / Std / NI / NA

Sp. Reading: 147486

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKB3FU803577047

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 / 65 R15

R: 195 / 65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake.

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 27/09/2019

D.O.I. 30/9/2019

Survey held at SMRT.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop of

Rear Left

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP

09/19/2108

GBB9650E

PLP *2,400.36
 CRIP: 49,386.25 / 79.1%

Cost/Time Fee (Pre)

☐

: Preli. Report

Cost/Time Fee (Return)

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S-RS 31

Taxes:

Others:

Add Fee:

☐

Site Insp. IS

☐

Interview IS

☐

Tech. Insp. IS

☐

Work. Insp. IS

30/10



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/CTI19017273/Eha3

Date: 2/10/19

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHD 6462U

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 30/09/2019 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

Workshop Estimate Amount	: S\$	11,866.61
Revised Estimate Amount	: S\$	3,280.32
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	3,280.32

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
N/S Rear Portion and Rear N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

STEVE CHEN
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHD6462U
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Sep 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8263841
Chassis No.:	JTDKB3FU803577047
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$26,537.00
Total Rebate Amount:	\$30,287.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Sep 2019

OK

Section A - Accident Details

Registration Number	SHD8462U
Case Reference Number	TAX/09/19/2108
Registration Date	19/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	QUAH PECK HUA (KE BIHUA)
Type of Accident	Others
Accident Date and Time	27/9/2019 3:15 PM
Accident Reported Date and Time	27/9/2019 4:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle Is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24103572
Special Instruction to ARC, if any	BP
Prepared Date and Time	28/9/2019 9:10 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$300.00
Total Spray Cost	\$2,574.00	\$530.00
Total Spare Part Cost	\$7,667.61	\$1,570.36
Total Other Cost	\$780.00	\$80.00
TOTAL COST	\$11,866.61	\$2,480.36 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Tuck Foo Kok	STEVE CHEN (LKK) / China Taiping
ARC / Surveyor Sign Off Date	28/09/2019 10:29 AM	30/09/2019 3:32 PM
Signature		
Remarks		P/P Repair, Take Before Spray.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1910-0308	Invoice Number	
Quotation Date	16.10.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION LH	\$845.00	\$300.00 ✓
Total Labour	\$845.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY REAR SPARE TYRE PANEL	\$180.00	\$0.00
TO RESPRAY REAR FLOOR SIDE PANEL LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$80.00 ✓
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$150.00 ✓
TO RESPRAY REAR SPOILER	\$180.00	\$100.00 ✓
TO RESPRAY TROUGH BACK DOOR LH	\$180.00	\$0.00
TO RESPRAY REAR FENDER LH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$2,574.00	\$530.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO REMOVE AND REFIT WIRE HARDESS	\$200.00	\$20.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$780.00	\$80.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93 ✓	Replace	Replace
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25 ✓	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70 ✓	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70 ✓	Replace	Replace

DD
nec
nec
nec

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757708
Fax Number: 63055592
Estimator Telephone Number: 68662623
Accident Reporting Number: 68662672

Date Generated: 17/10/2018

User ID: PehJuan

52462470	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	hec
52191470	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given	gvc
52023470	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	un
	SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	gvc
	PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	hec
52576470	RETAINER, RR BUMPER, LH	1.00	\$111.50	25.00	\$83.63	Replace	Replace	BR
52566479	FILLER, RR BUMPER, LH	1.00	\$119.90	100.00	\$0.00	Replace	Repair	un
52453470	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Not Given	gvc
52461470	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace	hec
81591470	LENS & BODY ASSY, RR BUMPER, LH	1.00	\$486.80	10.00	\$438.12	Replace	Replace	cro
58399470	COVER, REAR FLOOR UNDER, LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	
66259470	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	
90467170	CLIP, FLOOR UNDER COVER, NO.1	0.00	\$2.60	0.00	\$0.00	Replace	Not Given	
90467170	CLIP, FLOOR UNDER COVER, NO.2	0.00	\$3.20	0.00	\$0.00	Replace	Not Given	
52592470	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	
67005474	TAIL GATE PANEL SUB-ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	
76801471	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB.	1.00	\$891.20	100.00	\$0.00	Replace	Repair	
67881470	TAIL GATE WEATHERSTRIP, BACK	0.00	\$360.70	0.00	\$0.00	Replace	Not Given	
75403480	EMBLEM SUB-ASSY REAR	1.00	\$46.30	25.00	\$34.73	Replace	Replace	
75441470	NAME PLATE (HYBRID), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	
75442471	NAME PLATE (PRIUS), LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	
	SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	
	STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	
58307470	END PANEL SUBASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given	
	SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	
58311471	SPARE TYRE PANEL, PAN, REAR FLOOR	0.00	\$564.80	0.00	\$0.00	Replace	Not Given	
58316470	EXTENSION, REAR FLOOR SIDE PANEL, LH	0.00	\$76.20	0.00	\$0.00	Replace	Not Given	
64740471	PANEL ASSY, DECK TRIM SIDE, LH	0.00	\$344.70	0.00	\$0.00	Replace	Not Given	
62940470	DUCT ASSY, QUARTER VENT, RH & LH	0.00	\$65.00	0.00	\$0.00	Replace	Not Given	
61602471	PANEL SUB-ASSY, FENDER REAR LH	0.00	\$824.60	0.00	\$0.00	Replace	Not Given	
81561471	LENS & BODY, REAR COMBINATION LAMP, LH	1.00	\$438.10	10.00	\$394.29	Replace	Replace	
61622470	TROUGH, BACK DOOR, LH	0.00	\$99.80	0.00	\$0.00	Replace	Not Given	
81498470	COVER, REAR COMBINATION LAMP, LH	1.00	\$54.00	25.00	\$40.50	Replace	Replace	
65638470	LINER, REAR FENDER, LH	0.00	\$135.80	0.00	\$0.00	Replace	Not Given	
76085479	SPOILER SUB-ASSY, REAR	1.00	\$1,322.10	100.00	\$0.00	Replace	Repair	
Total			\$9,787.10		\$1,570.36			

1570.36
+ 300.00
+ 610.00
gvc
2480.36
cro
gvc
cro
gvc
un

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									



Case Details

Case Reference Number :

TAX/09/19/2108

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6462U

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-8668-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 27/09/2019 07:15 AM

Vehicle Age(In Months) : 21

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Repair/ Replace	Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Disa(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	✓ DO
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	✓ Nec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Giv	• X SVC
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check	• X NN
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Giv	• X SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ Nec
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace	✓ BR
Total Spare Part Cost											Surveyor Total			
											1,570.32			
Lump Sum Discount (%)											Lump Sum Dis (%)			
											0			
Final Spare Part Cost											Final Sur Total			
											1,570.32			

SMRT Recommendation											Surveyor Approval			
BOB Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FILLER, RR BUMPER, LH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	X NN
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	/ NEC
One Time Key In	Main			LENS & BODY ASSY, RR BUMPER, LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	/ CRU
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.1	6	2.50	15.60	25.00	11.70	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			CLIP, FLOOR UNDER COVER, NO.2	6	3.20	19.20	25.00	14.40	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	X NN
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.52	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	/ NEC
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/ NEC
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/ NEC

Total Spare Part Cost 7,667.61

Lump Sum Discount (%) 0.00

Final Spare Part Cost 7,667.61

Surveyor Total 1,570.32

Lump Sum Dis (%) 0

Final Sur Total 1,570.32

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	* / NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	* / NEC
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			EXTENSION, REAR FLOOR SIDE PANEL , LH	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	344.70	25.00	258.52	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	* / CR4.
One Time Key In	Main			TROUGH, BACK DOOR , LH	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	1	40.50	Replace	* / CR4.
One Time Key In	Main			LINER, REAR FENDER , LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Giv	* X SVC
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	0	Repair	* X NN
Total Spare Part Cost											Surveyor Total			
										7,667.61	1,570.32			
Lump Sum Discount (%)										0.00	Lump Sum Dis (%)			
											0			
Final Spare Part Cost										7,667.61	Final Sur Total			
											1,570.32			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			845.00	300.00	

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	200 0	
3	Main	TO RESPRAY REAR PANEL	180.00	200 0	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	200 0	
5	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	200 0	
6	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	80	
7	Main	TO RESPRAY TAIL GATE	378.00	0	
8	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	150	
9	Main	TO RESPRAY REAR SPOILER	180.00	100	
10	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
11	Main	TO RESPRAY REAR FENDER LH	378.00	0	
Total:			2,574.00	1,320.00 530	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ Nec
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	/ Nec
6	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ Nec.
Total:			780.00	80.00	

9/30/2019

<https://vacswb.smrt.com.sg/Estimation.aspx>

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			780.00	80.00	

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,667.61	1,570.32
Total Labour Cost	845.00	300.00
Total Spray Painting	2,574.00	1,330.00
Other	780.00	80.00
Overall Total	11,866.61	3,280.32
Lump Sum Repair Option		
Lump Sum Total	0.00	3,280.32
Surveyor Approved Amount		3,280.32
No of Repair Days*	6	3
Remarks		P/P Repair, Take Before Spray.
Surveyor Name		STEVE CHEN
Signature		
Survey Date	30/09/2019	Save Clear

Steve.
30/09/2019
P/P Repair
Take Before Spray
TP without Prejudice.

Repair Days - 3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Case Details

Case Reference Number :

TAX/09/19/2108

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6462U

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-8668-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 27/09/2019 07:15 AM

Vehicle Age(In Months) : 21

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace ▾	✓ DO
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace ▾	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	✓ Nec
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace ▾	✓ nec
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	0	0	Not Giv ▾	✗ SVC
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0	Check ▾	✗ NM
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Giv ▾	✗ SVC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	✓ Nec
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	1	83.63	Replace ▾	✓ BR

Total Spare Part Cost 7,667.61

Surveyor Total 1,570.32

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 7,667.61

Final Sur Total 1,570.32

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	1	0	Repair	X NN
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	/ NEC
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	/ CRU
One Time Key In	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			CLIP , FLOOR UNDER COVER , NO.1	6	2.60	15.60	25.00	11.70	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			CLIP , FLOOR UNDER COVER , NO.2	6	3.20	19.20	25.00	14.40	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0	Repair	X NN
One Time Key In	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.52	Replace	0	0	Not Giv	X SVC
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	/ NEC
One Time Key In	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/ NEC
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	/ NEC

Total Spare Part Cost 7,667.61

Surveyor Total 1,570.32

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 7,667.61

Final Sur Total 1,570.32

SMRT Recommendation											Surveyor Approval			
BOC Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	✓ NEC
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	✓ Nec
One Time Key In	Main			END PANEL SUBASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			SPARE TYRE PANEL , PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			EXTENSION, REAR FLOOR SIDE PANEL , LH	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	344.70	25.00	258.52	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			DUCT ASSY, QUARTER VENT , RH & LH	1	65.00	65.00	25.00	48.75	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			PANEL SUB- ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	✓ CR4.
One Time Key In	Main			TROUGH, BACK DOOR , LH	1	99.80	99.80	25.00	74.85	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	1	40.50	Replace	✓ CR4.
One Time Key In	Main			LINER, REAR FENDER , LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Giv	✗ SVC
One Time Key In	Main			SPOILER SUB- ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	0	Repair	✗ NN
Total Spare Part Cost									7,667.61	Surveyor Total 1,570.32				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0				
Final Spare Part Cost									7,667.61	Final Sur Total 1,570.32				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			845.00	300.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	845.00	300	
Total:			845.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	200	
3	Main	TO RESPRAY REAR PANEL	180.00	200	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	200	
5	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	200	
6	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	80	
7	Main	TO RESPRAY TAIL GATE	378.00	0	
8	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	150	
9	Main	TO RESPRAY REAR SPOILER	180.00	100	
10	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0	
11	Main	TO RESPRAY REAR FENDER LH	378.00	0	
Total:			2,574.00	1,330.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	/ Nec
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20	/ Nec
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
5	Main	TO REMOVE AND REFIT WIRE HARDESS	200.00	20	/ Nec
6	Main	TO REPLACE SUNDRY PARTS	100.00	20	/ Nec.
Total:			780.00	80.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	Man	TO WASH AND VACUUM	60.00	0	
Total:			780.00	80.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	7,667.61	1,570.32
Total Labour Cost	845.00	300.00
Total Spray Painting	2,574.00	1,330.00
Other	780.00	80.00
Overall Total	11,866.61	3,280.32
Lump Sum Repair Option		
Lump Sum Total	0.00	3,280.32
Surveyor Approved Amount		3,280.32
No of Repair Days*	6	3
Remarks	-	P/P Repair, Take Before Spray.
Surveyor Name		STEVE CHEN
Signature		
Survey Date	30/09/2019	

Save

Clear

Steve.
30/09/2019
P/P Repair
Take Before Spray
TP without Prejudice.

Repair Days - 3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Thursday, 3 October, 2019 5:18 PM
To: Mei Kwan (LKKAUTO); Vic (LKKAUTO)
Subject: RE: OUR REF: SNM19D204639-GBB9650E-CBS -Direct Settlement - Accident Involving GBB9650E (OI : CTI - TBA) and SHD6462U (TP : LKK REF - CC3/CTI19017273/Eha3) on 27/09/2019
Attachments: insured report.PDF
Categories: HMK

Dear Sir,

Please find insured report.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Thursday, October 3, 2019 4:55 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>

Subject: OUR REF: SNM19D204639-GBB9650E-CBS -Direct Settlement - Accident Involving GBB9650E (OI : CTI - TBA) and SHD6462U (TP : LKK REF - CC3/CTI19017273/Eha3) on 27/09/2019

Dear Boon Sen,

Please revert LKK.

Note : officer in charge – Boon Sen

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
T: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI19017273/Eha3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 13-02-2020	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 9650E	Veh. Inspected	SHD 6462U	
Policy No.	DMCVSN303234190	Coverage (\$)	0.00	
Claim No.	SNM19D204639	Excess (\$)	0.00	
Assign From		Assign Date	30/09/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS 4	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU803577047	Colour	MAROON	
Odometer	147486	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	5 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2019	Inspection Date	30/09/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 6462U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COVER ,RR BUMPER ASSY (DISC 25%)	DENTED	423.90	317.93
10	CLIPS PIECE ,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
2	PAD ,RR BUMPER,RH & LH,1 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD ,RR BUMPER,RH & LH,2 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
2	PAD ,RR BUMPER ,RH & LH,3 @\$3.80 (DISC 25%)	NECESSARY	7.60	5.70
1	RETAINER ,RR BUMPER ,LH (DISC 25%)	BROKEN	111.50	83.63
3	PAD ,RR BUMPER ,CTR @\$2.20 (DISC 25%)	NECESSARY	6.60	4.95
1	EMBLEM SUB-ASSY REAR (DISC 25%)	NECESSARY	46.30	34.73
1	NAME PLATE (HYBRID) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.23
1	NAME PLATE (PRIUS) LUGGAGE COMPARTMENT (DISC 25%)	NECESSARY	52.30	39.23
1	COVER ,REAR COMBINATION LAMP ,LH (DISC 25%)	CRACKED	54.00	40.50
1	LENS & BODY ASSY ,RR BUMPER ,LH (DISC 10%)	CRACKED	486.80	438.12
1	LENS & BODY ,REAR COMBINATION LAMP ,LH (DISC 10%)	CRACKED	438.10	394.29
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
2	SEAL ,RR BUMPER ARM ,RH & LH	SERVICEABLE	11.00	-
1	SENSOR REVERSE	SERVICEABLE	180.00	-
1	GUARD ,RR BUMPER LOWER	SERVICEABLE	558.30	-
1	COVER ,REAR FLOOR UNDER ,LH	SERVICEABLE	234.30	-
1	COVER ,REAR FLOOR UNDER CENTER	SERVICEABLE	222.60	-
1	CLIP ,FLOOR UNDER COVER ,NO.1	SERVICEABLE	2.60	-
1	CLIP ,FLOOR UNDER COVER ,NO.2	SERVICEABLE	3.20	-
1	SEAL ,RR BUMPER ,LH	SERVICEABLE	85.20	-
1	TAIL GATE PANEL SUB-ASSY ,BACK DOOR	SERVICEABLE	929.60	-
1	TAIL GATE WEATHERSTRIP ,BACK	SERVICEABLE	360.70	-
1	END PANEL SUBASSY ,BODY LOWER BACK	SERVICEABLE	629.80	-
1	SEALANT SIKAFLEX	SERVICEABLE	37.00	-
1	SPARE TYRE PANEL ,PAN ,REAR FLOOR	SERVICEABLE	564.80	-

Report Ref No. CC3/CTI19017273/Eha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXTENSION ,REAR FLOOR SIDE PANEL ,LH	SERVICEABLE	76.20	-
1	PANEL ASSY ,DECK TRIM SIDE ,LH	SERVICEABLE	344.70	-
2	DUCT ASSY ,QUARTER VENT ,RH & LH	SERVICEABLE	65.00	-
1	PANEL SUB-ASSY ,FENDER REAR LH	SERVICEABLE	824.80	-
1	TROUGH ,BACK DOOR ,LH	SERVICEABLE	99.80	-
1	LINER ,REAR FENDER ,LH	SERVICEABLE	135.80	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	FILLER ,RR BUMPER ,LH	TO REPAIR SEE LABOUR	119.90	-
1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB	TO REPAIR SEE LABOUR	891.20	-
1	SPOILER SUB-ASSY ,REAR	TO REPAIR SEE LABOUR	1,322.10	-
			9,876.40	1,570.36
	LABOUR			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF FILLER ,RR BUMPER ,LH,TAIL GATE BACK DOOR OUTSIDE GARNISH SUB AND SPOILER SUB-ASSY ,REAR.		845.00	300.00
	SPRAY PAINT.		2,574.00	530.00
	TO CHECK WIRING AND SYSTEM FUNCTION .		80.00	20.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR .	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING ,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT WIRE HARDESS.		200.00	20.00
	TO REPLACE SUNDRY PARTS .		100.00	20.00
	TO WASH AND VACUUM .	NOT NECESSARY	60.00	-
	-		-	-
	-		-	-
	-		-	-
			4,199.00	910.00
	GRAND TOTAL		14,075.40	2,480.36

Report Ref No. CC3/CT119017273/Eha3n2



RECOMMENDED COST OF REPAIRS			2,480.36
-----------------------------	--	--	----------

Report Ref No. CC3/CTI19017273/Eha3n2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.