

12/10/2019

ASS. REC. BY

REF:

03/CTI19017279/KTR3 n2

Special Instructions:

SURVIVOR

Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 1/10/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 2991 K

Insured: GBC 3950 Z

at Workshop m/s Yee Auto

Tel: 64575768

of 160 S/M #02-17

Policy No: DMCVSN3029201901

Claim No: SNM190204558

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27/9/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

2/10/2019.

H.O.D. Endorsement:

Date/Time: 1/10

Person Contacted:

A

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

GBH 2991 K - X

GBC 3950 Z - X.

17/1 L1 Pny B 3100L email & confirmed (Red: 6011.30; 65%)

No. In: Kennedy.

CTI

ASSIGNMENT

From:

Date:

2/10

Estimated Cost:

OO / TP / WS / TP RES / OO RES / EVA / INV / MV

To inspect Vehicle No:

GBH 2991K

at Workshop n/s:

Yee Auto

of 160 S/M #02-17

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

2/10/2019 Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lim Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH 2991K

Regn:

04 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Dmg

C/C:

2882

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp Reading:

18980

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

K0Y 231

8032431

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size:

F:

175/75R15

R:

155R12x8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

2

mm

R/Bal:

2

mm

U/Bal:

2

mm

U/Bal:

2

mm

D.O.A.

27/9/19

D.O.A.

2/10/19

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 22 JAN 2020

Date/Time, File Path to:



Prel. Report



Final Report

Date/Time, File Path to:

g

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp

r\$



Interview

r\$



Tech. Insp

r\$



Workday

r\$

Survey Fee:

Transportation:

3-PS 20

Fines:

Other:

220

Report Format:

TP

Lump Sum / Hourly:

3100

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 1 October 2019 2:32 PM
To: bonnie kwok
Cc: assignments
Subject: RE: OUR REF: SNM19D204558-GBC3950Z-CBS - PRI - Acc Inv: GBH 2991 K & GBC 3950 Z ON 27 SEPTEMBER 2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Tuesday, October 1, 2019 2:12 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D204558-GBC3950Z-CBS - PRI - Acc Inv: GBH 2991 K & GBC 3950 Z ON 27 SEPTEMBER 2019

Dear Boon Sen,

We refer to your email dated 1 October 2019.

Our client has no objection of appointing the motor surveyor LKK stated in your said list to conduct the joint pre-repair survey as a single joint expert.

Regards,

June



Virus-free. www.avg.com

On Tue, 1 Oct 2019 at 09:02, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice

Dear Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, September 30, 2019 5:32 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; litigation@bonniekwok.com

Subject: OUR REF: SNM19D204558-GBC3950Z-CBS - PRI - Acc Inv: GBH 2991 K & GBC 3950 Z ON 27 SEPTEMBER 2019

Dear Boon Sen,

Please conduct PRS for GBH2991K.

Note : officer in charge – Boon Sen 63896171.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok [<mailto:litigation@bonniekwok.com>]

Sent: Monday, September 30, 2019 4:05 PM

To: Claims Dept of CTI

Subject: PRI - Acc Inv: GBH 2991 K & GBC 3950 Z ON 27 SEPTEMBER 2019

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle GBH 2991 K at M/s Yee Auto Pte Ltd, 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722. Contact number 6457 5768.

Regards,

June

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



Virus-free. www.avg.com

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S: China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 27/09/2019

TP Veh Reg No: GBC3950Z

Estimate No: ES1900090

Date: 01 Oct 2019

Policy No:

Veh Reg No: GBH2991K

Make/Model: TOYOTA DYNA 3.0
DIESEL TURBO M/T
2WD LORRY

Chassis No: KDY2318032431

Engine No: 1KD2780249

Reg. Date: 12/04/2018

Estimate Repair Cost to Vehicle No :GBH2991K

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR NUMBER PLATE	60.00	1 PC	60.00	20.00
2 SPEED LIMIT STICKER '70KM/H'	20.00	1 PC	20.00	15.00
			80.00	80.00
Spare Parts				
3 REAR CARGO WHEEL PANEL - LH	185.50	1 PC	185.50	X
4 REAR END PANEL	465.50	1 PC	465.50	X
5 REAR END PANEL REFLECTOR - LH	55.00	1 PC	55.00	✓
6 REAR END PANEL REFLECTOR - RH	55.00	1 PC	55.00	✓
7 REAR END PANEL STICKER 'DYNA'	45.00	1 PC	45.00	✓
8 REAR END PANEL STOPPER - LH	57.60	1 PC	57.60	X
9 REAR END PANEL STOPPER - RH	57.60	1 PC	57.60	✓
10 REAR EXHAUST	450.60	1 PC	450.60	✓
11 REAR NUMBER PLATE BRACKET	175.20	1 PC	175.20	✓
12 REAR NUMBER PLATE LAMP	70.00	1 SET	70.00	X
13 REAR SIDEGATE PILLAR SAFETY HINGE - LH	255.20	1 PC	255.20	✓
14 REAR SIDEGATE PILLAR SAFETY HINGE - RH	255.20	1 PC	255.20	✓
15 REAR TAILGATE	1,537.10	1 PC	1,537.10	✓
16 REAR TAILGATE ALUMINIUM	480.00	1 PC	480.00	X
17 REAR TAILGATE ALUMINIUM RIVET	3.00	20 PCS	60.00	✓
18 REAR TAILGATE STICKER '1500KG'	65.90	1 PC	65.90	✓
19 REAR TAILGATE STICKER 'Miyagi - TOYOTA'	75.10	1 PC	75.10	✓
20 REAR TAILLAMP - LH	575.60	1 PC	575.60	✓
21 REAR TAILLAMP - RH	575.60	1 PC	575.60	✓
22 REAR TAILLAMP PANEL - LH	248.20	1 PC	248.20	X
23 REAR TAILLAMP PANEL - RH	248.20	1 PC	248.20	X
24 REAR TOOL BOX - LH	410.20	1 PC	410.20	✓
25 REAR WHEEL MUFFLER - LH	98.00	1 PC	98.00	X
			6,501.30	6,501.30
Labour				
26 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	5501
27 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,200.00	1 JOB	1,200.00	5001
28 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	80.00	1 JOB	80.00	301

Not Authorized

11 Sep 831001

Runway After Paint

4 days

118.90

265.30

285.30

258



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 27/09/2019
TP Veh Reg No: GBC3950Z

Estimate No: ES1900090
Date: 01 Oct 2019
Policy No:
Veh Reg No: GBH2991K
Make/Model: TOYOTA DYNA 3.0
DIESEL TURBO M/T
2WD LORRY
Chassis No: KDY2318032431
Engine No: 1KD2780249
Reg. Date: 12/04/2018

Estimate Repair Cost to Vehicle No :GBH2991K

Description	U/Price	Quantity	List Price	Amount
29 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	SS 50.00	SS 20/-
			2,530.00	2,530.00
			Total	SS 9,111.30
			Add GST @ 7%	637.79
			Total Amount Payable	SS 9,749.09

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SEVEN HUNDRED FORTY NINE AND CENTS NINE ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE

LIC Auto Consultants hereby notify the Repairer of the following:

- To survey vehicle for any damage
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No damage acknowledgment is allowed
- Supplementary item(s) must be approved and subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119017279/KTF3N2

Date: 29/01/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30070819000
Claimant Vehicle No :	GBH2991K	Insured Vehicle No :	GBC3950Z
Date of Loss:	27/09/2019	Nature of Claim:	TP
		Claim No:	SNM19D204558C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH2991K	Engine No:	1KD2780249
Make & Model:	TOYOTA DYNA, 3.0 D (M)	Chassis No:	KDY2318032431
Reg. Date:	12/04/2018 (Man. Year: 2017)	Odometer:	18980 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/75 R15	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,581.30	2,792.15	3,789.15	57.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,100.00	1,430.00	56.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,111.30	3,892.15	5,219.15	57.28
Approved Total (Overridden) (S\$)		3,100.00		
Nett Amount (S\$)	9,111.30	3,100.00	6,011.30	65.98

INSPECTION

Date of Assignment:	03/10/2019	Yee Auto Pte Ltd (HQ) 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY Singapore 575722
Date Inspected:	02/10/2019 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jan 2020)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2991K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	60.00 FS	*20.00 FS
2	1		*SPEED LIMIT STICKER 70KM/H	Necessary	20.00 FS	*15.00 FS
3	1		*REAR CARGO WHEEL PANEL -LH	Repair	185.50 F	*- FL
4	1		*REAR END PANEL	Repair	465.50 F	*- FL
5	1		*REAR END PANEL REFLECTOR -LH	Cracked	55.00 F	*55.00 FL
6	1		*REAR END PANEL REFLECTOR -RH	Broken	55.00 F	*55.00 FL
7	1		*REAR END PANEL STICKER DYNA	Necessary	45.00 F	*45.00 FL
8	1		*REAR END PANEL STOPPER -LH	Serviceable	57.60 F	*- FL
9	1		*REAR END PANEL STOPPER -RH	Missing	57.60 F	*57.60 FL
10	1		*REAR EXHAUST	Bent	450.60 F	*450.60 FL
11	1		*REAR NUMBER PLATE BRACKET	Bent	175.20 F	*175.20 FL
12	1		*SET REAR NUMBER PLATE LAMP	Serviceable	70.00 F	*- FL
13	1		*REAR SIDEGATE PILLAR SAFETY HINGE -LH	Repair	255.20 F	*- FL
14	1		*REAR SIDEGATE PILLAR SAFETY HINGE -RH	Bent	255.20 F	*118.90 FL
15	1		*REAR TAILGATE	Bent	1,537.10 F	*1,537.10 FL
16	1		*REAR TAILGATE ALUMINIUM	Serviceable	480.00 F	*- FL
17	20		*REAR TAILGATE ALUMINIUM RIVET	Necessary	60.00 F	*60.00 FL
18	1		*REAR TAILGATE STICKER 1500KG	Necessary	65.90 F	*65.90 FL
19	1		*REAR TAILGATE STICKER MIYAGI-TOYOTA	Necessary	75.10 F	*75.10 FL
20	1		*REAR TAILLAMP -LH	Scratched	575.60 F	*285.30 FL
21	1		*REAR TAILLAMP -RH	Cracked	575.60 F	*285.30 FL
22	1		*REAR TAILLAMP PANEL -LH	Repair	248.20 F	*- FL
23	1		*REAR TAILLAMP PANEL -RH	Repair	248.20 F	*- FL
24	1		*REAR TOOL BOX -LH	Bent	410.20 F	*410.20 FL
25	1		*REAR WHEEL MUFFLER -LH	Serviceable	98.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,581.30	3,711.20
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	919.05
Total Parts (S\$)	6,581.30	2,792.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,200.00	550.00
2	TO PUTTY ,APPLY PRIMER & SPRAY -PAINT ON THE AFFECTED PORTION	New	1,200.00	500.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	80.00	30.00
4	TO CHECK WIRING FUNCTIONS	New	50.00	20.00
Gross Labour Cost (\$\$)			2,530.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >