

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER:
 TP INSURER: India International Insurance Singapore
 POLICY NO: 5108970168
 REFERENCE: TP CLAIM
 DOA: 30/09/2019

REPAIR ESTIMATE

Est. No. : E19090007
 Date : 30/09/2019
 Vehicle Num. : SMK8589D
 Make/Model : HONDA, SHUTTLE 1.5G
 CVT
 Chassis/Eng# : GK82001222
 Yr. of Manu : 2018

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	RH Front Door	1.00	757.20	757.20
2	RH Rear Door	1.00	703.40	703.40
3	RH Side Skirting	1.00	363.10	363.10

Amt S\$ 1,823.70
 Discount (20.00%) S\$ 364.74
 Subtotal S\$ 1,458.96

Section: LABOUR				
4	To Panel Beat The Necessary Damaged Parts	1.00	600.00	600.00
5	To Dismantle and Reinstall Door Components	1.00	160.00	160.00
6	To Sand Down, Putty and Spray Paint on Necessary Damaged Part	1.00	880.00	880.00

Amt S\$ 1,640.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 1,640.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 1,458.96
 LABOUR Subtotal S\$ 1,640.00
 Total S\$ 3,098.96