

ASS. REC. BY:

REF: CS3/SPF19017284/HV302

Special Instruction:

Surveior Hock Ann ASSIGNMENT (Office)From (Person): Hafizul Farhan Rahmat of SPF Date/Time: 1.10.19 4.17p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 44394 Insured: QX 299Cat Workshop m/s my car consultant Tel: 9846000of 53 Ubi Ave 1 Pagar Ubi Industrial Park #01-33Policy No: _____ Claim No: AEMD/105/009/2019/096

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A 27.9.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 1.10.19 4.17p.m Person Contacted: Kai Ling H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SJX 44394-NA/19017284/24 RMA-27/09/2019</u>
	<u>QX 299C-NA/19017284/24 RMA-27/09/2019</u>
	<u>Pending Claim number</u>
<u>31/01/19</u>	<u>Submit LS \$2200, 3 days</u>
	<u>upper range \$2200 - \$2800</u>

Do Not Finalise

22/3/21 To re-open & re-submit LS \$3250, 3 days Celine 22/03/2021

Upper range \$3200-\$3500

SPF

PRS

ASSIGNMENT

1.10.2019

Veh No: SJX 4439 Y Reg: 15/06/2010

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: MITSUBISHI LANCER GIX DO 1584

Colour: Grey W/O: Insured / Std / NI / NA

Sp. Reading: 165774 km T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYSRCS3AA4000398

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orMod: Nil ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 205/55/R16

R: 205/55/R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 5 - FALKEN mm

L/Bal: 5 - FALKEN mm

D.O.A: 22/9/19

Survey held at

Des. of Damages: Frt / Rear / O/S ☒ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Insurance Type

CD RES / TP RES / CD RES / EVA / INV / MV

To Insure Vehicle No: SJX 4439 Y

To Insure Name: my car consultant

53 ubi Ave 1 Daya Ubi # 01-33

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

Client's Record:

M:

Veron case

Handle



D.V.D Accident Report

Consistent? : Yes or No

G.V. / P.R. Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Veh Sum:

20

%

3 Val.: Yes or No

CA / REV / REP / 14 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

RECEIVED 4 OCT 2019

DAR - ✓ ok

Range - 2.2 - 2.8 km

repair days - 3 day

MV - 16000

PV - 1860

NV - 7140

* SJX 4439 Y NON

Estimate (PRS) case

3/10/2019

Do Not Finalise

Time For Pass:



: Prel. Report



: Final Report

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

200

Transportation:

: 3 - P.R. / O/S

: Travel

: Other

Add Fee:



: Site Insp. \$



: Interview \$



: Tech. Insp. \$



: Total \$

3/10 - typist

200

Veron Chen (LKKAUTO)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Tuesday, 16 March 2021 12:27 AM
To: Admin-D (LKKAUTO); assignments; SUR
Cc: Cui Fen ENG (SPF); Lai Kuen LUI (SPF); Hazel PEH (SPF)
Subject: RE: RTA involving QX299C and SJX4439Y on 27/9/2019


Dear LKK,

Any updates on the matter?

Best Regards,

Hafizul Farhan Bin Rahmat
Assistant Logistics Support Officer
Logistics Support and Services Division
Tel: 6842 8429
Police Logistics Department | Singapore Police Force

DOI: 1/10/2019
RES: 2/10/2019
After print: 3/10/19
Final assessment



Singapore Police Force

W police.gov.sg FB [fb.com/singaporepoliceforce](https://www.facebook.com/singaporepoliceforce)

IG [Instagram.com/singaporepoliceforce](https://www.instagram.com/singaporepoliceforce)

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Hafizul Farhan RAHMAT (SPF)
Sent: Thursday, 11 March 2021 2:54 PM
To: 'Admin-D (LKKAUTO)' <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Cui Fen ENG (SPF) <ENG_Cui_Fen@spf.gov.sg>; Lai Kuen LUI (SPF) <LUI_Lai_Kuen@spf.gov.sg>; Hazel PEH (SPF) <Hazel_PEH@spf.gov.sg>
Subject: RE: RTA involving QX299C and SJX4439Y on 27/9/2019

Dear LKK,

Reference to to the PRI on SJX4439Y.

<< File: LKK 2019-096.pdf >> << File: LOD 2019-096(PD).pdf >>

In LKK report attached, there are 2 components i.e. front fender L/H and fender inner panel indicated as 'crushed'. However, there is no cost indicated. What does this means; no need to repair? LKK also check the wheel bearing but what's the outcome? What does (NPA) means?

need to replaced

In the claimant's assessor report. This was assessed to be repaired at the total cost of about \$1,243. We seek your clarifications on the matter. Thank you.

NPA meaning no price available

LKK Report

<< OLE Object: Picture (Device Independent Bitmap) >>

Claimant's Assessor Report

<< OLE Object: Picture (Device Independent Bitmap) >>

Best Regards,

Den

Hafizul Farhan Bin Rahmat

Assistant Logistics Support Officer

Logistics Support and Services Division

Tel: 6842 8429

Police Logistics Department | Singapore Police Force

At the time of our inspection, the repair estimate was not provided to us.

<< OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >>

Singapore Police Force

W police.gov.sg FB fb.com/singaporepoliceforce

IG Instagram.com/singaporepoliceforce

hence a preliminary assessment

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

of the damage of the cost of repair.

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Thursday, 3 October 2019 8:58 AM

To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>

Subject: RE: RTA involving QX299C and SJX4439Y on 27/9/2019

Please forward the photos taken by the repairer's surveyor

Dear Farhan,

in order for us to re-assess the cost of repair.

Noted with thanks.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>

Sent: Thursday, 3 October, 2019 8:53 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>

Subject: RE: RTA involving QX299C and SJX4439Y on 27/9/2019

Message Classification: Unclassified

Hi,

The ref no: AEMD/105/009/2019/096

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4848

<< OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >>

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Wednesday, 2 October 2019 3:07 PM

To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>

Subject: RE: RTA involving QX299C and SJX4439Y on 27/9/2019

Dear Farhan,

Kindly assist to provide us the claim number for SJX 4439Y.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hafizul Farhan RAHMAT (SPF) [mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg]

Sent: Tuesday, 1 October 2019 4:17 PM

To: assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>

Subject: RTA involving QX299C and SJX4439Y on 27/9/2019

Hi,

Kindly conduct pre-repair survey of SJX4439Y at:

My Car Consultant Pte Ltd

**53 Ubi Avenue 1
Paya Ubi Industrial Park
#01-33 S(408934)**

Tel: +65 9868 6000 / Fax: 6925 5219

Thank you.

Best Regards,

*Hafizul Farhan Bin Rahmat
AEMD / PLD
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848*

<< OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >>

WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: My Car Consultant <admin@mycar.sg>
Sent: Tuesday, 1 October 2019 3:54 PM
To: Hafizul Farhan RAHMAT (SPF) <[Hafizul Farhan RAHMAT@spf.gov.sg](mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg)>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Subject: re: RTA involving QX299C and SJX4439Y on 27/9/2019

WITHOUT PREJUDICE

Hi,

We are located at ,
53 Ubi Avenue 1, Paya Ubi Industrial Park
#01-33 Singapore 408934

**Warm Regards,
Kai Ling**

CONFIDENTIALITY NOTICE: This message (including any attachments) is confidential and may be privileged. It may be read, copied and used only by the intended recipient. If you have received it in error please contact the sender (by return e-mail) immediately and delete this message. Any unauthorized use or dissemination of this message in whole or in parts is strictly prohibited.



From: "Hafizul Farhan RAHMAT (SPF)" <[Hafizul Farhan RAHMAT@spf.gov.sg](mailto:Hafizul_Farhan_RAHMAT@spf.gov.sg)>
Sent: Tuesday, October 1, 2019 3:51 PM
To: "admin@mycar.sg" <admin@mycar.sg>
Cc: "Frankie THAY (SPF)" <Frankie_THAY@spf.gov.sg>
Subject: RTA involving QX299C and SJX4439Y on 27/9/2019

Hi,

We spoke, kindly provide us the location of your workshop.

We will arrange for our surveyor to inspect the vehicle.

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4848

<< OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >> << OLE Object: Picture (Device Independent Bitmap) >>

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.
www.avg.com

WG APPRAISAL SERVICES

Blk 224B, Compassvale Walk, #07-647, Singapore 542224
Email: winsonggk@hotmail.com Contact: 9747 0063
Company Register No. 53326249J

ACCIDENT DAMAGED VEHICLE INSPECTION REPORT

M/S : MOHAMAD FIRDAUZ BIN SAMSUDIN
C/O MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park
Singapore 408934

Date : 13 November 2019
Our Ref : WG/TP/2019-433

REFERENCE PARTICULARS

Date of Accident : 29 September 2019
Date of Inspection : 01 October 2019

Type of Inspection : Third Party Claim
Date of Re-Inspn : 02 October 2019

VEHICLE PARTICULARS

Registration No : SJX4439Y
Make : MITSUBISHI
Model : LANCER 1.6 GLX AUTO ABS
Year : 2009

Engine No : 4G18KD4553
Chassis No : JMYSRCS3AAU000398
Odometer : 165974km
Colour : Grey

CONDITION OF VEHICLE (STATIC CHECKS AT TIME OF INSPECTION ONLY)

Engine condition : Good
Foot Brake : Serviceable
Hand Brake : Serviceable

General Body Work : Good
Steering : Serviceable
Lightings : Serviceable

TYRE CONDITION (Remaining estimated life of tyre in mm)

	Make	Size
Front Near side	Falken	215/55R16
Front Off Side	Falken	215/55R16
Rear Near Side	Falken	215/55R16
Rear off Side	Falken	215/55R16

Thread Balance
5 mm
5 mm
5 mm
5 mm

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained damage at the front left portion.
For details, refer to assessment for repairs and photographs attached.

ASSESSMENT SUMMARY

Our assessment of the repair costs to pre-accident condition was S\$4,700.00 (net at lump sum basis. (Subject to GST if applicable)
Under normal circumstances, estimated period required for repairs : Five (05) working days.

Enclosed Forty-four (44) photographs depicting damage to the vehicle.

Inspection conducted at : MY CAR CONSULTANT PTE LTD
53 Ubi Ave 1, #01-33, Paya Ubi Industrial Park : Singapore 408934

In accordance to your instruction, we have not authorise repairs and inspection
was conducted strictly on a "WITHOUT PREJUDICE BASIS".

VEHICLE NO : SJX4439Y
MODEL : LANCER 1.6 GLX AUTO ABS AIRBAG 2WD 4DR

Our Ref : WG/TP/2019-433

ASSESSMENT OF REPAIRS AND SPARE PARTS COSTS

DESCRIPTION OF PARTS AND NATURE OF REPAIRS

SPARE PARTS	QTY C/SET	ASSESSED CONDITION	ORIGINAL QUOTATION	REVISED QUOTATION
1 FRONT BUMPER	1	CRACKED	\$ 710.00	\$ 710.00
2 FRONT BUMPER SIDE BEAM	2	NECESSARY	\$ 80.00	\$ 80.00
3 FRONT LH FOG LAMP COVER	1	NOT NECESSARY	\$ 45.00	\$ -
4 FRONT LH FENDER	1	DENTED	\$ 561.00	\$ 561.00
5 FRONT LH FENDER INNER SHIELD	1	TORN	\$ 101.00	\$ 101.00
6 FRONT LH HEADLAMP	1	CRACKED	\$ 630.00	\$ 630.00
7 FRONT BUMPER LOWER LIP	1	CRACKED	\$ 653.00	\$ 653.00
8 FRONT LH SHOCK ABSORBER	1	BENT	\$ 495.00	\$ 495.00
9 FRONT LH KNUCKLE ARM	1	BENT	\$ 410.00	\$ 410.00
10 FRONT LH WHEEL BEARING	1	JAMMED	\$ 169.00	\$ 169.00
11 FRONT LH LOWER ARM	1	BENT	\$ 392.00	\$ 392.00
			\$ 4,246.00	\$ 4,201.00
		Less 10%	\$ 424.60	\$ 420.10
			\$ 3,821.40	\$ 3,780.90
B) <u>S/NETT ITEM</u>				
12 FRONT BUMPER CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
13 FRONT FENDER INNER TRIM CLIP	1 SET	NECESSARY	\$ 30.00	\$ 20.00
14 RIM	1	GRAZED	\$ 600.00	\$ 500.00
15 BRAKE FULD	1 ROT	NECESSARY	\$ 60.00	\$ 50.00
			\$ 720.00	\$ 590.00
		Parts Total:	\$ 4,541.40	\$ 4,370.90
C) <u>LABOUR CHARGES & MISC</u>				
16 CHECK FRONT WIRING AND LIGHTNING SYSTEM			\$ 60.00	\$ 50.00
17 COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT			\$ 150.00	\$ 120.00
18 REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS			\$ 200.00	\$ 180.00
19 PANEL BEATING ON AFFECTED AREAS			\$ 600.00	\$ 500.00
20 SPRAY PAINTING ON AFFECTED AREAS			\$ 700.00	\$ 600.00
21 APPLY ANTI RUST ON AFFECTED AREAS			\$ 100.00	\$ 80.00
		Labour Total:	\$ 1,810.00	\$ 1,530.00
		Total Parts and Labour:	\$ 6,351.40	\$ 5,900.90
<u>FINAL LUMP SUM ADJUSTMENT</u>				\$ 4,700.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION			Ref: CS3/SPF19017284/Hvf3e2	
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333			Date: 14/10/2019	
ATTN : HAFIZUL FARHAN RAHMAT			Code: SPF	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	QX 299C	Veh. Inspected	SJX 4439Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/096	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	01/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI LANCER GLX	c.c	1584	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JMYSRCS3AAU000398	Colour	GREY	
Odometer	165974 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FALKEN	5 mm	
L/H Front Tyre	205/55 R16	FALKEN	5 mm	
R/H Rear Tyre	205/55 R16	PIRELLI	5 mm	
L/H Rear Tyre	205/55 R16	PIRELLI	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/09/2019	Inspection Date	01/10/2019	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 4439Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	CRUSHED	-	858.00
1	SET FRT BUMPER CLIPS	NECESSARY	-	30.00
1	SET FRT BUMPER RIVET	NECESSARY	-	30.00
1	FRT BUMPER SIDE RETAINER L/H	CRUSHED	-	56.00
1	FRT HEADLAMP ASSY L/H	CRUSHED	-	792.00
1	FRT LOWER ARM L/H	DAMAGED	-	292.00
1	FRT BUMPER LOWER SPOILER (NPA) <i>380 s/n</i>	SCRATCHED <i>Rx</i>	-	-
1	FRT SPORT RIM L/H (NPA) <i>380 s/n</i>	SCRATCHED	-	-
1	FRT FENDER L/H (NPA) <i>561</i>	CRUSHED	-	-
1	FRT FENDER INNER PANEL L/H (NPA) <i>552'</i>	CRUSHED <i>Rx</i>	-	-
1	FRT WHEEL BEARING L/H WITH KNUCKLE <i>480</i>	* CHECK <i>604</i>	-	-
	LESS 10% DISCOUNT		-	-205.80
			-	1,852.20
	<u>LABOUR</u>			
	REMOVE AND INSTALL UNDER CARRIAGE.		-	80.00
	CHECK WIRING.		-	20.00
	WHEEL ALIGNMENT.		-	60.00
	SPRAY PAINT LABOUR.		-	400.00
	SPRAY PAINT SPORT RIM.		-	80.00
	LABOUR.		-	300.00
			-	940.00
	GRAND TOTAL		-	2,792.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (EXCLUDE CHECK ITEMS S\$252.00 NETT)			2,200.00

Report Ref No. CS3/SPF19017284/Hvf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,200-\$2,800

LEE HOCK ANN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.