

ASS. REC. BY:

REF:

C8/FCI19017288/R190302

Special Instruction:

Surveyor: Rasu

ASSIGNMENT (Office)

From (Person): Sithara

of

FCI

Date/Time: 1/10/2019

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBP 5022X

Insured: 8HC 7131Z

at Workshop m/s Southern Motor

Tel: 62730369

of Blk 1006 Bt Merah Lane 2 #06-10

Policy No:

Claim No: D19006140MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2/19/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

2/10/2019.

H.O.D. Endorsement:

Date/Time: 1/10

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

FBP 5022X-X

8HC 7131Z-X

03/10/19@ 11.10am revised to Sithara by email.

14/10/19@ 3.28pm Mr Lim said the price still under repair.

23/10/19@ 10.53am Repair finalised vs \$1850, 4 days (Pen to 731.30, 28%/-)

ASSIGNMENT

From:

Date:

2.10.2019

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBP 5022 X

at Workshop m/s Southern Motor

of BIK 1006 Bt Merah #01-10.

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBP 5022 X

Yr Regn:

2019 / APR

Type: M.Car ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA SNIPER T150

c.c

150

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

19920

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MH3UG0740K0152966

Gen. Cond: Good ☒ / Fair / Poor / BurntSteering: Inorder ☒ / Jammed / Leaked / Burnt orBrake: Inorder ☒ / Jammed / Leaked / Burnt orModi: Nil ☒ / S/Rim / STD A/Rim or

Tyre Size:

F:

80/90-17

R:

120/60-17

B8 / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/09/19

D.O.I.

02/10/19

Survey held at

Southern Motor

Des. of Damages: Frt / Rear ☒ / ☒ / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 25 OCT 2019

Date/Time, File Pass to?

1) 25/10/2019

Date/Time, File Return to?

2)



: Prel. Report

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + PS \$

Photos

Others

TOTAL

110

50

50

119

119

119

119

119

119

119

119

Report Format:

TP

Lump Sum / Hourly:

1850



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006140MFSH

Date: 03 October 2019

Our Ref: CS/FCI19017288/R1qf3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBP 5022X .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/10/2019 at the premises of M/s SOUTHERN MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 2,581.30 .
Revised Estimate Amount	: S\$ 1,674.30 .
"Check" Items Amount	: S\$ 684.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the o/s & n/s body.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	24-09-2019	Our Ref No. D19006140MFSH
Accident Date	21-09-2019	Claim Type. Third Party
Insured Vehicle	SHC7131Z	Third Party Vehicle. FBP5022X
Survey Location	BLK 1006 #01-10 BUKIT MERAH LANE 2	
Contact Person.	NA	
Contact No.	62730369/ 0	Fax No. 62746614
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SOUTHERN MOTOR	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Rasul (LKKAuto)

From: Southern Motor <soumotor@hotmail.com>
Sent: Wednesday, 23 October, 2019 10:53 AM
To: Rasul (LKKAuto)
Subject: Re: FBP 5022X DOA : 21/09/19

Dear Mr Rasul ,
We confirm your offer for finalised
amount is \$1850/4 days lump sum .

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Wednesday, October 23, 2019 9:49 AM
To: Southern Motor <soumotor@hotmail.com>
Subject: FBP 5022X DOA : 21/09/19

Hi Mr Lim,

Refer to attachment
Finalised amount is \$ 1,850 / 4 days lump sum
Kindly confirm


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 3 October 2019 11:10 AM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19006140MFSH/1
Attachments: CSFCI19017288R1qf3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of FBP 5022X.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 1 October 2019 4:37 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19006140MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 1 October 2019 3:52 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006140MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,



南方摩哆 SOUTHERN MOTOR

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2. #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

30th September 2019

MS First Capital Insurance Limited
36 Robinson Road #16-01
City House
Singapore (068877)

Dear Sirs,

RE: Cost of repair to Yamaha Sniper T150 - FBP5022X

1pc of Handle Bar ? bt ✓		S\$	85.00
1pc of Clutch Lever sc ✓			25.00
1pc of Balancer cut ✓			15.00
1pc of Mirror sc ✓			85.00
1pc of IU Unit cut ✓			165.00
1pc of IU Bracket bt ✓			15.00
1pc of Front Footrest sc ✓			28.00
1pc of Front Footrest Bar repair ✓			65.00 X
1pc of Front Signal Light sc ✓			48.00
1pc of Gear Lever bt ✓			48.00
1pc of Rear Switch Arm sc ? bt ✓			380.00
1pc of Switch Arm Boost ? (BUSH) nu ✓			75.00
1pc of Rear Chain Guard ca ✓			65.00
1pc of Front Box sc ✓			68.00
1pc of Rear Murguard Complete sc ✓			180.00
1pc of Cover Set Complete sc ✓			680.00
2pc of Fork ? bt ✓			220.00
1pc of Rear Signal Light sc ✓			35.00
1pc of Front Exhaust Pipe Cover X sc ✓			60.00 X
1pc of Clutch Cover sc ✓			120.00
1pc of Rear Exhaust Pipe Cover X sc ✓			45.00 X

Less 10%
Nett

Transport
Rear Number Plate
Labour

S\$ 2,581.30

Yours Faithfully,
Southern Motor

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

2337
10%
2103.30

2103.30

255.00

2358.30

20%

1886.64

45-1,850 4 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19017288/R1qf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7131Z	Veh. Inspected	FBP 5022X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006140MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	01/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA SNIPER T150	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MH3UG0740K0152966	Colour	BLUE	
Odometer	19920	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	80/90-17	BRIDGESTONE	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/60-17	BRIDGESTONE	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/09/2019	Inspection Date	02/10/2019	
Survey held at	SOUTHERN MOTOR BLOCK 1006 BUKIT MERAH LANE 2 #01-10 SINGAPORE 159762			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 5022X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HANDLE BAR	BENT	85.00	85.00
1	CLUTCH LEVER	SCRATCHED	25.00	25.00
1	BALANCER	CUT	15.00	15.00
1	MIRROR	SCRATCHED	85.00	85.00
1	IU UNIT	CUT	165.00	165.00
1	IU BRACKET	BENT	15.00	15.00
1	FRONT FOOTREST	SCRATCHED	28.00	28.00
1	FRONT FOOTREST BAR	TO REPAIR SEE LABOUR	65.00	-
1	FRONT SIGNAL LIGHT	SCRATCHED	48.00	48.00
1	GEAR LEVER	BENT	48.00	48.00
1	REAR SWITCH ARM	BENT	380.00	380.00
1	SWITCH ARM BOOST	NECESSARY	75.00	75.00
1	REAR CHAIN GUARD	CRACKED	65.00	65.00
1	FRONT BOX	SCRATCHED	68.00	68.00
1	REAR MURGUARD COMPLETE	SCRATCHED	180.00	180.00
1	COVER SET COMPLETE	SCRATCHED	680.00	680.00
2	FORK	BENT	220.00	220.00
1	REAR SIGNAL LIGHT	SCRATCHED	35.00	35.00
1	FRONT EXHAUST PIPE COVER	SERVICEABLE	60.00	-
1	CLUTCH COVER	SCRATCHED	120.00	120.00
1	REAR EXHAUST PIPE COVER	SERVICEABLE	45.00	-
	LESS 10% DISCOUNT		-250.70	-233.70
			2,256.30	2,103.30
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	BENT	35.00	15.00
			35.00	15.00
LABOUR				
	TRANSPORT.		40.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR.INCLUSIVE OF THE REPAIR OF FRONT FOOTREST BAR.		250.00	200.00
			290.00	240.00
GRAND TOTAL			2,581.30	2,358.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,850.00

Report Ref No. CS/FCI19017288/R1qf3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.